RAPID RESERVOIR SEDIMENTATION OF FOUR HISTORIC THIN ARCH DAMS IN AUSTRALIA

by H. CHANSON¹ and P. JAMES²

Abstract : Since the discovery of the Australian continent by Europeans, the development of the country has been closely linked with the development of water resources. At the end of the 19th century, several arch dams were built in New South Wales, four of which are described in this paper. The four dams (Moore Creek, Gap, Korrumbyn Creek, Quipolly) had similar features : i.e., water supply storage with thin concrete arch wall. Despite their technological sophistication at the time, they became fully-silted very quickly with each one being used for less than 25 years. Although their structural design was advanced, the design of the reservoir systems (dam, lake and catchment) was a failure. The designers did not take into account correctly the soil erosion and sediment transport processes, and no soil conservation practice was considered. The experience gained from these failures may be of use today to prevent practicing engineers from making similar mistakes.

INTRODUCTION

Since the discovery of the Australian continent by Europeans, the water supply of the early settlements was always an important concern. The first inland expeditions usually followed the major rivers. The new settlers were attracted further inland by the search for better pasture and later by the discovery of gold. The economical development of the colony, however, was significantly affected by the lack of regular water supply.

The early settlements took place in the South-East (Victoria, New South Wales) (Fig. 1) and numerous dams were built to provide regular water supply throughout the year. Nearly 90% of the 19th century reservoirs were built for water supply (drinking water, stocking and irrigation primarily) but also for the mining industry (e.g. the two Sheba dams 1888, Junction Reefs dam 1897). Smaller dams were built for water supply for railway steam engines, at the end of the 19th and beginning of the 20th centuries (e.g. Gap weir, 1902). By tradition most Australian large dams were earth embankments following the English experience. However several thin arch dams were built, in New South Wales primarily (e.g. Moore Creek dam, 1898, Redbank Creek, 1899).

ARCH DAMS IN AUSTRALIA IN THE 19TH CENTURY AND EARLY 20TH CENTURY

One of the first significant dam structures built in Australia is the Parramatta dam, near Sydney. Built between 1851 and 1856, the 12.5-m high³ wall was contemporary to the Zola dam, in France. The dam was designed by P. SIMPSON (1789-1877), E.O. MORIARTY (1824-1896) and W. RANDLE (ASH et HEINRICHS 1996) with a cylinder shape. It

¹ Senior Lecturer, Fluid Mechanics, Hydraulics and Environmental Engineering, Department of Civil Engineering, The University of Queensland, Brisbane QLD 4072, Australia.

² Environmental Consultant, 5/2 Hardie St, Neutral Bay NSW 1089, Australia.

³before dam heightening of 3.35 m in 1898 (WADE 1909).

is worth noting that SIMPSON was a former officer of the Royal Navy and MORIARTY was a naval engineer. The authors believe that both engineers were familiar with the calculations of shells and ship hulls, hence with the thin cylinder formula (see Appendix I).

The Parramatta dam is the precursor of a series of thin arch dams built in New South Wales by the NSW Public Works Department under the successive supervisions of C.W. DARLEY, L.A.B. WADE and E.M. de BURGH between 1896 and 1920 (WADE 1909, de BURGH 1917). Altogether, more than 20 thin arch dams were built by the NSW Public Works Department and the arch dam design example was followed in other states (e.g. Barossa dam, 1902, South Australia; Sorell Creek dam, 1916, Tasmania) and by the NSW Railway Department.

The design of the Australian thin arch dams was based on the thin cylinder formula (WADE 1909, de BURGH 1917) and it is probably a world-first in the standardization of this design technique. At the time, the dams were recognized as advanced designs in Europe and in the USA (SCHUYLER 1909, WADE 1909, WEGMANN 1922, see also SMITH 1971, SCHNITTER 1994). WEGMANN (in the discussion of WADE 1909) stated that, in his opinion, "the curved dams built [...] in New South Wales had been designed more logically" than any other arch dams or curved-gravity dams.

Contemporary arch dams include the Zola dam (France, 1854), Abbeystead dam (UK, 1881), Bear Valley dam (USA, 1884), Sweetwater dam (USA, 1888) and Upper Otay dam (USA 1900). All were single-arch designs similar to the Australian dams. The first double-curved arch dam was completed in 1903 (Ithaca dam, USA) and the first variable radius arch dam was built in 1914 (Salmon Creek, USA) (WEGMANN 1922, SCHNITTER 1994).

RESERVOIR SEDIMENTATION

The primary characteristics of water supply dams is the reservoir storage capacity which is an economical and political asset. A reservoir interacts, however, with its catchment, often acting as a sediment trap, and the life expectancy of a reservoir is usually less than 100 years because of siltation. Reservoir sedimentation results from soil erosion, sediment transport and sediment trapping by the reservoir. It is affected by the climate and hydrology of the catchment, water and sediment chemistry, vegetation cover and land use including man-made erosion.

Altogether, reservoir sedimentation is associated with a loss of reservoir capacity and often with loss of fertile soils.

Several Australian thin arch dams are still in use today : e.g., the Parramatta dam. However some were used for less than 25 years despite their advanced structural design. The reservoirs silted up very rapidly and the dams have become a source of embarrassment. In the present paper, the authors describe the history of four reservoirs built between 1897 and 1932 and which are fully-silted today (Fig. 2 to 5). Later they analyze the causes of failure.

HISTORY OF FOUR DAMS

OVERVIEW

The characteristics of four reservoirs and dams are summarized in Tables 1 and 2. In Table 3, the chronology of main dates are summarized and compared with major climatic events which affected the Australian continent: El-Niño, La Nina, and drought. The El-Niño current and Southern Oscillation (ENSO) is a global climatic change caused by warmer

waters in the Pacific Ocean which alternates with colder conditions called La Nina. In Eastern Australia, droughts are experienced habitually during an El-Niño while floods are often observed during a La Nina.

Three dams were designed by the NSW Public Works Department; the fourth dam (Gap weir) was built by the NSW Railways Department. Three reservoirs are located within inland catchments forming the Murray-Darling basin. The fourth reservoir (i.e. Korrumbyn Creek) is within the Tweed River catchment which drains to the Pacific ocean (Fig. 1).

MOORE CREEK DAM

The Moore Creek dam was completed in 1898 to supply water to the town of Tamworth, NSW. The 18.6-m high dam was designed with advanced structural features : i.e. thin single-arch wall (7.7-m thick at base, 0.89-m thick at spillway crest, 0.87-m thick at dam crest), made of Portland cement concrete (Table 2). The arch wall has a vertical downstream face and a battered upstream face (Fig. 2). The thin arch extends with a left-bank gravity cross-section with downstream inclined face. The dam was equipped with an overfall spillway and two bottom outlets (a scour valve⁴ and a pipe outlet).

Between 1898 and 1911, the reservoir was filled with $85,000 \text{ m}^3$ of sediment. Observations recorded at the time suggested that most siltation took place during the floods of February 1908 and January 1910. In 1924 the reservoir ceased completely to supply water because it was fully silted. The dam is still standing today and listed in ICOLD (1984).

GAP WEIR

Completed in 1902, the Gap weir is located near the Gap railway station, five kilometers from the railway junction of Werris Creek (Fig. 3). It was built to supply water to the steam engines.

The dam wall is a single-arch concrete structure with upstream vertical face and inclined (battered) downstream face (\sim 73° angle with horizontal). The original spillway was an overfall spillway extending over most of the weir crest and followed by a relatively deep plunge pool, but no scour outlet was built (although a drawing prior to construction showed one).

The reservoir became fully-silted by 1924. It was abandoned and replaced by available water supply from Quipolly Creek and later from the Quipolly dam⁵. Since 1924, the dam wall was blasted twice to facilitate the passage of flood flow and to limit upstream flooding. Interestingly, the reservoir is located downstream of a long flat flood plain (slope < 0.2 degrees, streamwise length > 6 km). The river, cutting through into the reservoir sediment, highlights the silty material caught by the weir, suggesting a siltation process by suspended-load.

⁴A scour valve is a bottom outlet structure used to release silty waters and to reduce the sedimentation rate.

⁵The change to engine motors occured in the 1970s and did not affect the decision.

KORRUMBYN CREEK DAM

The Korrumbyn Creek dam is located on the Korrumbyn Creek, a tributary of the Tweed river. The dam was completed late 1918 to supply water to the town of Murwillumbah, NSW. The 14.1-m high⁶ dam is a single arch wall (61-m radius in plan) with a left-bank tangent of gravity cross-section (Fig. 4). It was equipped with two bottom outlets (a pipe outlet and a scour valve) and an overfall spillway. The catchment area is only about 3 km² for an original volume of 27,280 m³.

The dam was rapidly abandoned because a log jammed the scour pipe entrance during a flood. It could not be removed and the reservoir silted up very quickly by bed-load. Further, during dry periods, the water level used to drop, the water would turn green and foul as it warmed up, making it unfit for use. The dam still stands today, the reservoir being occupied by an overgrown tropical forest (Fig. 4).

QUIPOLLY DAM

The Quipolly dam⁷ was completed in 1932 to supply water to the town of Werris Creek, NSW : drinking water, irrigation, water for railway steam engines. The dam wall is a concrete single-arch (1.08-m thickness at crest) (Fig. 5). The design of the dam arch is elegant in comparison with Moore Creek dam and Korrumbyn Creek weir, both designed with a (thicker) gravity section. The reservoir was equipped with two bottom outlets and an overfall spillway.

Between 1932 and 1941, 130,000 m³ of sediment had accumulated (15% of initial reservoir capacity). In 1943 the siltation volume amounted to 290,000 m³ (34% of initial capacity). By 1952, more than half of the initial storage had been lost. The reservoir was abandoned in 1955 at the completion of a new dam (Quipolly dam No. 2), built 3 km downstream, and the reservoir is fully silted today. Although the dam is 'officially' useless, it acts, in fact, as a sediment trap to prevent or reduce the sedimentation of the new Quipolly dam.

Note the large spillway capacity (150-m long crest, $Q \sim 240 \text{ m}^3/\text{s}$). This suggests that the design engineers were well aware of large flood events. For comparison, the second Quipolly dam was equipped with a 380-m³/s spillway capacity. It is worth noting that the maximum spillway capacity of Moore Creek dam (i.e. 250 m³/s) was comparable but the catchment area was smaller (i.e. 51 km²) (Tables 1 and 2).

CAUSES OF FAILURE

The four dams were built with advanced structural features, at their time : thin arch walls, very unusual designs, and concrete construction, despite the problems in cement supply and difficulties to bring it on-site. Their stories highlight errors in the design of the reservoirs, their interactions with the catchment and the lack of consideration of siltation resulting from sediment transport processes.

The Gap weir was built without a bottom outlet and thus it could not be scoured. Note, further, that the spillway capacity (35 to 40 m^3/s) was small compared to the Moore Creek and Korrumbyn Creek dams, which both have a smaller catchment.

⁶de BURGH (1917) indicated a 12.4-m maximum dam height. But the first author saw the drawings prior to construction and after construction. He noted several significant changes in design including the dam height.

⁷also known as old Quipolly dam and Coeypolly Creek dam No. 1 (ICOLD 1984).

The Korrumbyn Creek dam had an insufficient catchment area (3 km²). Although the mean annual flow rate could 'theoretically' fulfill the water need of Murwillumbah, it was known that the stream discharge was very irregular : in 1916, the average weekly flow rate ranged from 0.75 L/s (2-8 Jan. 1916) to 886 L/s (8-15 April 1916), and the spillway was sized for a 125,000 L/s flood. Altogether the reservoir never properly supplied Murwillumbah with water. Furthermore the catchment is very steep : the stream bed slope is larger than 7.6° (0.133V/1H) in the 2 first kilometres upstream of the dam ! This caused significant sediment load in the creek. Today the river bed still exhibits a wide range of sediment materials (fig. 4(C)), and bed-load siltation could be predicted with contemporary experience (in the opinion of the authors, after inspection of the river bed).

The catchment of Moore Creek dam is characterized by a thin layer of fertile soil. At the end of the 19th century, the forest was cleared for grazing. Further it seems that a substantial increase in sheep livestock number took place at the same time. Both the clearing of the catchment and the increase of stocking rate increased the erodibility of the soils and contributed to the rapid sedimentation of the reservoir.

The siltation of Quipolly reservoir also is probably related to improper land management of the catchment.

DISCUSSION

Because of sedimentation, the four reservoirs had an useful life of less 25 years. Why ? Several factors contributed to the sedimentation : a sub-tropical climate characterized by intense summer rainfall, streams with significant sediment loads, land use and poor land management practices (by current standards), which devastated the native pasture and enhanced soil erosion (e.g. Moore Creek), design mistakes (e.g. Gap) and improper selection of site (Korrumbyn Creek). Additional considerations must also be taken into account and are discussed below.

CLIMATIC EFFECT

Northern New South Wales is characterized by a sub-tropical climate with a dry season (winter) and a wet season (summer). This annual cycle is, however, subjected to inter-annual climatic events : the El-Niño and La Nina. Usually the El-Niños coincide with drought periods in Australia and India (DIAZ and MARKGRAF 1992) while La Ninas are associated with flooding in Australia. This pattern was clearly established between 1878 and 1888 by Sir Charles TODD, South Australia Government Observer, and well documented by H.C. RUSSELL, NSW Government Observer (GROVE 1995, p. 17). The main information is summarized in Table 3, where Australian droughts, El-Niño and La Nina events are listed in chronological order, as well as important dates in the history of the four reservoirs. The information on floods and siltation is based on local observations of floods and spillway use, and surveys of the reservoirs in the following dry periods.

In terms of soil erosion and sediment load, the most extreme hydrological events are exceptional floods following a long drought period (associated with an El-Niño). Dry conditions retard the growth of vegetation cover and the following wet conditions erode the bare unprotected soil. Further, soil management and conservation practices are not often applied by farmers and graziers during long droughts : overgrazing of pastures followed by failure of pasture regeneration increase drastically the erodibility of the un-vegetated ground. The following torrential rains easily wash away the soils and, as a result, the streams carry a large sediment load which deposits in dam reservoirs.

Table 3 illustrates examples of such extreme events : the flood of February 1908 at Moore Creek (column 5), the floods of 1919 at Gap weir (column 6), and the floods of 1942-43 at Quipolly (column 8). Each flood event followed a long drought period, and heavy siltation was recorded in each case.

SEDIMENT TRANSPORT PROCESSES AND DESIGN

Basically, the stories of the four reservoirs reflect a lack of understanding of sediment transport processes and soil conservation practices. Each dam must be considered as an engineering failure. The reservoirs failed because the designers did not understand the basic concepts of sediment transport and reservoir sedimentation.

First let us remember that the knowledge of sediment process and movable-boundary hydraulics was 'embryonic' in the 1900s. The fundamental concepts of sediment transport were developed in the late 19th century and first half of 20th century : e.g., du BOYS (1879), SCHOKLITSCH (1914,1930), EINSTEIN (1942,1951), MEYER PETER (1949,1951).

However, it is surprising to note that the designers of Korrumbyn Creek dam and Quipolly dam did not learn from the experience of Moore Creek dam and Gap weir. By 1912 the sedimentation of Moore Creek dam was well advanced and documented : the information was available prior to the construction of Korrumbyn Creek dam. Similarly the experience of Gap weir (located less than 20 km from Quipolly dam) should have influenced the design of Quipolly dam : e.g., with the choice of a larger scour outlet. It appears also that the land management practices applied to Quipolly catchment in the period 1930-1950 were identical to those of Moore Creek catchment in 1900-1910 (JAMES 1997).

Moore Creek, Korrumbyn Creek and Quipolly reservoirs were designed and built by the same organization (i.e. NSW Public Works Department). It is surprising that the experience of reservoir siltation was not shared among colleagues and used to improve the design technique.

OPINION

The authors feel that each failure should be a learning experience, illustrating poor understanding of movable-boundary hydraulics. The mistakes could have been prevented with today's knowledge. In one case (Gap weir), the addition of a scour valve would have been sufficient. In another (Korrumbyn Creek), the site was unsuitable because of the heavy bed load carried by the stream. At Moore Creek, a soil conservation policy should have been introduced in the catchment, as at Quipolly reservoir.

Three reservoirs have now no purpose and they are considered, by the public, as engineering failures. Only one dam (Quipolly) may be considered as still partially useful : i.e., sediment trap for Quipolly dam No. 2.

CONCLUSION

During the European settlement of Australia in the 19th and 20th centuries, a series of thin arch dams was built in South-East Australia for water supply purposes. Among these, four dams were silted very rapidly and were abandoned in less than 25 years.

After a brief history of each reservoir, the authors have discussed the main causes of reservoir siltation : extreme climatic conditions and streams with heavy sediment load, but also improper soil conservation practices and design mistakes.

Although the dams had advanced structural features, their stories reflect a lack of understanding of sediment transport processes by the designers. The authors wish that these four examples can be used as pedagogic examples by professionals and students to improve future hydraulic designs.

ACKNOWLEDGEMENTS

The authors wish to thank the following people for their assistance and help : Mr N. BEDFORD, Tamworth NSW, Ms CHOU Y.H., Brisbane QLD, Mr and Mrs D. DAVIDSON, Murwillumbah NSW, Dr M.R. GOURLAY, Brisbane QLD, Mr P. HEINRICHS, Sydney NSW; Ms C. LITCHFIELD, Brisbane QLD, Mr G. RYAN, Tamworth NSW.

APPENDIX I. THE THIN CYLINDER FORMULA

For a circular pipe of radius R and thickness e, the compression stress σ_c in the pipe wall equals :

$$\sigma_{\rm c} = \frac{{\rm R} * {\rm P}}{{\rm e}} \tag{I-1}$$

where P is the water pressure.

Equation (I-1) may be applied to thin arch dams. Results are summarized in Table I-1 and the calculations are compared with the concrete strengths stated by WADE (1909) and de BURGH (1917). Note that the concrete strengths (Table I-1, column 6) were very close (too close?) to the required compression strengths with hydrostatic pressure loads (Table I-1, column 7). Discussions of WADE's (1909) paper suggested that "the factor of safety (...) was too low". More recently SCHNITTER (1994) mentioned also the "narrow safety of margin".

First the experience shows that the dams are still standing today and inspections have shown that the walls are in good condition. Further the dam walls are subjected nowadays to pressure loads (on the upstream face) substantially larger than the hydrostatic pressure because of the reservoir siltation (Table I-1, column 8). It is thought that the concrete strengths (Table I-1, column 6) underestimate the actual material properties.

APPENDIX II. REFERENCES

- ASH, R., and HEINRICHS, P. (1996). "Parramatta Single Arch Dam From 1856 and Still Going Strong." Proc. 1st Intl and 8th Australian Engineering Heritage Conf., 29 Sept.-2 Oct., Newcastle, Australia, pp. 9-19.
- BOYS, P.F.D. du (1879). "Etude du Régime et de l'Action exercée par les Eaux sur un Lit à Fond de Graviers indéfiniment affouillable." ('Study of Flow Regime and Force Exerted on a Gravel Bed of Infinite Depth.') Ann. Ponts et Chaussées, Paris, France, série 5, vol. 19, pp. 141-195 (in French).
- BURGH, E.M. de (1917). "Some Notes on the Construction of Curved Dams in New South Wales." *Concrete and Constructional Engineering*, Vol. 12, No. 2, pp. 83-90.

- CYBERSKI, J. (1971). "Accumulation of Debris in Water Storage Reservoirs of Central Europe." Proc. Intl Symp. on Man-Made Lakes, Their Problems and Environmental Effects, ICSU, Knoxville TN, USA (also in "Man-Made Lakes : Their Problems and Environmental Effects.", ACKERMANN, W.C., WHITE, G.E., WORTHINGTON,E.B., and LOREENA-IVENS, J. editors, AGU Publ., Washington DC, USA, 1973, pp. 359-363).
- DIAZ, H.F., and MARKGRAF, V. (1992). "EL NIÑO. Historical and Paleoclimatic Aspects of the Southern Oscillations." *Cambridge University Press*, UK.
- EINSTEIN, H.A. (1942). "Formulas for the Transportation of Bed-Load." Transactions, ASCE, Vol. 107, pp. 561-573.
- EINSTEIN, H.A. (1950). "The Bed-Load Function for Sediment Transportation in Open Channel Flows." US Dept. of Agriculture Techn. Bulletin No. 1026, Soil Conservation Service, Washington DC, USA.
- GROVE, R.H. (1995). "The East India Company, the Australians and the El-Niño : Colonial Scientists and Analysis of the Mechanisms of Global Climatic Change and Teleconnections between 1770 and 1930." *Working Paper No. 182*, Working Papers in Economic History, Australian Nat. Univ., Canberra, Australia, March.
- International Commission on Large Dams (1984). "World Register of Dams Registre Mondial des Barrages ICOLD." *ICOLD*, Paris, France, 753 pages.
- JAMES, P. (1997). "Catchment Erosion and Sediment Filled Dams." ANCOLD Bulletin, No. 106, Aug...
- MEYER-PETER, E. (1949). "Quelques Problèmes concernant le Charriage des Matières Solides." (Some Problems related to Bed Load Transport.') *Soc. Hydrotechnique de France*, No. 2 (in French).
- MEYER-PETER, E. (1951). "Transport des matières Solides en Général et problème Spéciaux." *Bull. Génie Civil d'Hydraulique Fluviale*, Tome 5 (in French).
- SCHNITTER, N.J. (1994). "A History of Dams : the Useful Pyramids." Balkema Publ., Rotterdam, The Netherlands.
- SCHOKLITSCH, A. (1914). "Über Schleppkraft un Geschiebebewegung." *Engelmann*, Leipzige, Germany (in German).
- SCHOKLITSCH, A. (1930). "Handbuch des Wasserbaues." ('Handbook of Hydraulic Structures.') Springer, Vienna, Austria.
- SCHUYLER, J.D. (1909). "Reservoirs for Irrigation, Water-Power and Domestic Water Supply." *John Wiley & sons*, 2nd edition, New York, USA.
- SMITH, N. (1971). "A History of Dams." The Chaucer Press, Peter Davies, London, UK.
- WADE, L.A.B. (1909). "Concrete and Masonry Dam-Construction in New South Wales." *Min. of Proc. of Instn. of Civil Engineers*, London, Vol. 178, No. 9, Paper 3791, pp. 1-26. Discussion : Vol. 178, No. 9, pp. 27-110.
- WEGMANN, E. (1922). "The Design and Construction of Dams." John Wiley & Sons, New York, USA, 7th edition.

APPENDIX III. NOTATION

- e wall thickness (m);
- P pressure (Pa);
- Q water discharge (m3/s);
- R arch radius (m);
- θ opening angle (i.e. central angle);

 σ_c compression stress (Pa) in wall.

Table 1 - Characteristics of reservoirs

Reservoir	Location	Stream	Volume of reservoir m ³ (¹)	Catchment area km ²	Use	Remarks
(1)	(2)	(3)	(4)	(5)	(6)	(7)
Moore Creek dam, 1898	20 km North of Tamworth, NSW	Moore Creek	220×E+3	51	Water supply for the town of Tamworth.	Complete reservoir siltation by 1924 (and probably earlier). Bed-load siltation primarily.
Gap weir, 1902	5 km West of Werris Creek, NSW	Werris Creek		160	Water supply for railway purposes.	Sedimentation by suspension load. Fully silted in 1924.
Korrumbyn Creek dam, 1917- 1918	Mount Warning National Park, 20 km West of Murwillumbah	South Korrumbyn Creek	27.28×E+3	3	Water supply for the town of Murwillumbah.	Rapid bed-load sedimentation associated with jammed scour valve.
Quipolly dam, 1932	20 km South-East of Werris Creek, NSW	Quipolly Creek	860×E+3	70	Water supply of the town of Werris Creek.	Sedimentation volume larger than half of the initial storage by 1952. Disused since 1955.

Note : (1) : original capacity.

Table 2 - Technical characteristics of the dams

Dam	Maximum height	Crest length m	Construction	Spillway and dam outlets
(1)	(2)	(3)	(4)	(5)
Moore Creek, 1898	18.6	155	Thin arch dam (single arch : $R = 75$ m) with vertical downstream wall and battered upstream wall, extending with a left-bank gravity section. Portland cement concrete construction. Wall thickness :0.87 m at crest, 7.7 m at base.	Overfall spillway : $Q \sim 250 \text{ m}^{3}/\text{s}$. 2 bottom outlets : scour valve and pipe outlet.
Gap, 1902	6 to 10 (²)	45 to 50 (²)	Thin arch dam (single arch) with vertical upstream wall and battered downstream wall. Concrete construction. Wall thickness : 0.94 m at crest.	Overfall spillway : $Q \sim 35 \text{ à } 40 \text{ m}^3/\text{s}$. No bottom outlet.
Korrumbyn Creek, 1917-1918	14.1		Thin arch dam (single arch : $R = 61 \text{ m}$, $\theta \sim 47^{\circ}$) with vertical upstream face and battered downstream face, with left-bank tangent of gravity cross-section. Portland cement concrete construction. Wall thickness : 1.1 m at crest, 5.2 m at base.	Overflow spillway : $Q \sim 125 \text{ m}^3/\text{s}$. Bottom outlets : one scour valve and one pipe outlet (12 L/s).
Quipolly, 1932	19	184	Thin arch dam (single arch : $R = 61 \text{ m}$, $\theta = 93^{\circ}$) with vertical upstream wall and battered downstream face extending with a short right- bank gravity section. Concrete construction. Wall thickness : 1.08 m at crest, 6.99 m at base.	Overflow spillway : $Q \sim 240 \text{ m}^3/\text{s}$. Bottom outlets : one scour valve and one pipe outlet.

Notes : $(^1)$: height above lowest foundation; $(^2)$: estimated from site inspection.

Q: maximum overflow capacity without dam overtopping; R : curvature radius of the cylinder; θ : opening angle (i.e. central angle).

Table 3 - Chronology of reservoir sedimentation

Date	El-Niño	Australian	La Niña	Moore Creek	Gap	Korrumbyn	Quipolly
		drought				Creek	
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
	1997 90	1884-86					
	1891	1000					
	1897	1896					
1898				Completion			
	<u>1899-1900</u>	1899					
1902	1902	1902			Completion		
			1903-04				
	1904-05	1905	1006.05				
	1007	1007	1906-07				
1008	1907	1907	1008.00	ELOOD AND			
1908			1908-09	HEAVY SILTATION			
1910				FLOOD AND			
				HEAVY SILTATION			
	1911-12	1912					
	1914-15	1914					
			1916-17				
1918	1918-19	1918				Completion	_
1919					FLOOD AND		
			1020.21		HEAVY SILTATION		
	1923	1923	1920-21				
1924	1725	1725		Fully silted	Fully silted	Disused ?	
			1924-25	T unij Shivu	T ung shiteu	Distora .	
	1925-26	1925					
			1928-29				
	1930-31	1930					
1022	1022	1022	1931-32				
1932	<u>1932</u>	1932	1029 20				Completion
	1020		1938-39				
	1940-41	1940					
1942-43		17.10	1942-43				FLOOD AND
							HEAVY SILTATION
	1943	1943					
			1949-50				
10.50	1951	1951					
1952							Sedimentation =
	1052	1052					50%
1955	1755	1755					Disused
1755				1			Disuscu

Ref. : DIAZ et MARKGRAF (1992).

Note : underlined years correspond to 'strong' or 'very strong' El-Niños (DIAZ et MARKGRAF 1992, pp. 129-131).

Dam	R	e (crest)	e (base)	Maximum	Concrete	Compression	Compression
				height	strength	stress (¹)	stress (²)
						EQ. (I-1)	EQ. (I-1)
	m	m	m	m	MPa	MPa	MPa
(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)
Moore Creek	75	0.87	7.7	18.6	2.15	1.8	3.6
Gap		0.94	~ 3.5	6-10			
Korrumbyn Creek	61	1.1	5.2	14.1	1.61	1.62	3.3
Quipolly	61	1.08	7.0	19		1.62	3.3

Table I-1 - Thin cylinder formula calculations applied to arch dams

References : WADE (1909), de BURGH (1917)

Notes : $(^1)$: assuming hydrostatic pressure on the upstream face; $(^2)$: assuming a 2,650-kg/m³ sediment density and a 0.38 soil porosity.

Figure 1 - Reservoir locations



Figure 2 - Moore Creek dam (1898)

(A) Sketch of the dam arch cross-section



Figure 2 - Moore Creek dam (1898)

(B) Downstream vertical wall. View from the right bank. Photograph taken on 14 June 1997 (by H. CHANSON)



(C) View from downstream. Note the overfall spillway section. The scour valve is at the bottom of the wall, behind the left-most tree. Photograph taken on 14 June 1997 (by H. CHANSON)



Figure 3 - Gap weir (1902)

(A) View from downstream. Photograph taken in the 1960s by N. BEDFORD. The dam opening is smaller than in Figure 3(B).



(B) View from the left bank. The creek flows from the right to the left. Photograph taken on 13 June 1997 (by H. CHANSON)



Figure 4 - Korrumbyn Creek dam (1918)

(A) View in plan (from original drawing after construction)



(B) View from downstream. Note the bottom outlet system on the left and the pipe to Murwillumbah. Photograph taken on 25 April 1997 by H. CHANSON.



Figure 4 - Korrumbyn Creek dam (1918)

(C) View of Korrumbyn Creek 1.5 km upstream of the dam wall, looking upstream. Note the coarse sediment material. Photograph taken on 25 April 1997 by H. CHANSON.



Figure 5 - Quipolly dam (1932)

(A) Elevation in plan (after original drawing)



(B) View from the left bank. Note the outlet system at the downstream wall bottom. Photograph taken on 13 June 1997(by H. CHANSON)



LIST OF CAPTIONS

Figure 1 - Reservoir locations

Figure 2 - Moore Creek dam (1898)

(A) Sketch of the dam arch cross-section

(B) Downstream vertical wall. View from the right bank. Photograph taken on 14 June 1997 (by H. CHANSON)

(C) View from downstream. Note the overfall spillway section. The scour valve is at the bottom of the wall, behind the left-most tree. Photograph taken on 14 June 1997 (by H. CHANSON)

Figure 3 - Gap weir (1902)

(A) View from downstream. Photograph taken in the 1960s by N. BEDFORD. The dam opening is smaller than in Figure 3(B).

(B) View from the left bank. The creek flows from the right to the left. Photograph taken on 13 June 1997 (by H. CHANSON)

Figure 4 - Korrumbyn Creek dam (1918)

(A) View in plan (from original drawing after construction)

(B) View from downstream. Note the bottom outlet system on the left and the pipe to Murwillumbah. Photograph taken on 25 April 1997 by H. CHANSON.

(C) View of Korrumbyn Creek 1.5 km upstream of the dam wall, looking upstream. Note the coarse sediment material. Photograph taken on 25 April 1997 by H. CHANSON.

Figure 5 - Quipolly dam (1932)

(A) Elevation in plan (after original drawing)

(B) View from the left bank. Note the outlet system at the downstream wall bottom. Photograph taken on 13 June 1997 (by H. CHANSON)