The figure shows a magnetic circuit. Find the self and mutual inductances of the two windings and the magnetic flux Φ . Consider a thickness δ for the air gaps, a length L for the columns and a constant iron normal section S. N₁=100; N₂=200; δ =1mm; L=100mm; S=100cm²; μ_0 =1.257 10^{-6} H/m, μ_{Fe} =2000, i₁=2A, i₂=3A

R: $L_1=57$ mH; $L_2=228$ mH; $M_{12}=M_{21}=114$ mH, $\Phi=4.57$ mWb.


The figure shows a magnetic circuit. Find the self and mutual inductances of the two windings considering infinitive the relative permeability of the ferromagnetic material. Consider a thickness δ for the air gaps and a constant normal section S for the branches of the magnetic circuit. N₁=150; N₂=210; δ =6mm; S=20cm²; μ_0 =1.257 10⁻⁶ H/m.


R: $L_1=6.284$ mH; $L_2=12.32$ mH; $M_{12}=M_{21}=-4.4$ mH.


The figure shows a magnetic circuit. Find the self and mutual inductances of the two windings considering infinitive the relative permeability of the ferromagnetic material and the magnetic flux Φ . Consider a thickness δ and 3δ for the air gaps and a constant normal section S for the branches of the magnetic circuit. N₁=120; N₂=200; δ =0.8mm; S=160cm²; μ_0 =1.257 10⁻⁶ H/m; i₁=1.2A, i₂=4A.

brought to you by

CORE







The figure shows a magnetic circuit. Find the three magnetic fluxes Φ_1 , Φ_2 and Φ_3 , which flow through the three vertical columns considering infinitive the relative permeability of the ferromagnetic material. Find the self and mutual three inductances of the windings. Consider a thickness δ for the air gaps and a constant normal section S for the branches of the magnetic circuit.

