



46TH TURBOMACHINERY & 33RD PUMP SYMPOSIA
HOUSTON, TEXAS | DECEMBER 11-14, 2017
GEORGE R. BROWN CONVENTION CENTER

Inlet Bay Flow Turbulence


<p>Monroe Voyles ITT Industrial Process Fort Worth, TX Tel: (225-573-2445) Monroe.Voyles@itt.com</p>	<p>Paul Behnke, PE ITT Industrial Process, Goulds Pump ESLA 3951 Capitol Ave City of Industry, CA 90601 Tel: (562) 908-4155 Paul.Behnke@itt.com</p>
<p>Landon Worrell, P.Tech. (Eng.), PMP ITT Goulds Pumps Canada Inc. PRO Services Edmonton, AB, Canada Tel: (780) 224-0470 Landon.Worrell@itt.com</p>	<p>Lisa Buttar SaskPower Corporation 2211 Spadina Cres W Saskatoon, Sk Tel: (306) 361-3648 Lbuttar@saskpower.com</p>



Vertical Circulating Water Pump


Pressure Sensors
27.7' from
Suction

Water Level
17.7' from
Suction



NOTES

- 1 REFER DRAWING D1088IF FOR ASSEMBLY STEPS
- 2 FIELD ASSEMBLY ONLY - USE LOCTITE 518 GASKET ELIMINATOR FLANGE SEALANT AS SHOWN IN DETAIL F
- 3 WITH NICKEL ANTI SEIZE LUBRICANT. REQUIRED TORQUE FOR FASTENERS = 283 FT-LB (39.1 KG-M)
- 4 WITH NICKEL ANTI SEIZE LUBRICANT. REQUIRED TORQUE FOR FASTENERS = 919 FT-LB (127 KG-M)
- 5 WITH NICKEL ANTI SEIZE LUBRICANT. REQUIRED TORQUE FOR FASTENERS = 459 FT-LB (63.5 KG-M)
- 6 WITH NICKEL ANTI SEIZE LUBRICANT. REQUIRED TORQUE FOR FASTENERS = 299 FT-LB (41.3 KG-M)
- 7 WITH NICKEL ANTI SEIZE LUBRICANT. REQUIRED TORQUE FOR FASTENERS = 66 FT-LB (9.1 KG-M)
- 8 WITH NICKEL ANTI SEIZE LUBRICANT. REQUIRED TORQUE FOR FASTENERS = 65 FT-LB (9.0 KG-M)
- 9 WITH NICKEL ANTI SEIZE LUBRICANT. REQUIRED TORQUE FOR FASTENERS = 3 FT-LB (0.4 KG-M)
- 10 WITH LOCTITE 242 THREADLOCKER. REQUIRED TORQUE FOR FASTENERS = 15 FT-LB (2.1 KG-M)



CUSTOMER DATA

CUSTOMER: BURNS AND MCDONNELL FOR SASK POWER
 GOULDS SERIAL NO.: 314990
 CUSTOMER P.O. NO.: 73113-2128
 PUMP ITEM NO.: DESOR-RE-P-004
 SERVICE: CIRCULATING WATER PUMP

X-SECTIONAL DRAWING

ITT GOULDS PUMPS

DRAWING SCALE: NONE DIMENSIONS IN INCHES(MM)
 DRAWN AND CHECKED BY: [Signature] APPROVED BY: [Signature] COPYRIGHT © 2013
 DATE: 01/11/13 DRAWING NO.: PCD314999 SHEET: 1 OF 1

REVISOR	DATE	REASON	ENGINEERING SEAL	CONTRACT INFORMATION	<p>SaskPower</p> <p>X-SECTIONAL DRAWING MODEL VCW VIT-FF (U/G) PUMPHOUSE CIRCULATING WATER PUMP #6 QUEEN ELIZABETH POWER STATION</p>
D				CONTRACT No. S-2128 CONTRACT NAME: CIRCULATING WATER PUMP DESIGN DEPT. DESIGNED BY: AUTHORIZED BY: APPROVED BY: SEALED BY: DATE: 00	



Background / Problem

A 58,000gpm single-stage vertically suspended cooling water pump experienced power and discharge pressure oscillations. Vibration and performance testing indicated power and pressure oscillations were caused by turbulence and vortex formation in the inlet bay. Physical hydraulic model testing confirmed that the flow entering the pump suction bell was indeed turbulent and unsteady. A vortex suppressor was used to straighten the flow from the inlet bay structure. The power and TDH variations with time were essentially eliminated




Observations

- The system resistance is constant; however, significant power, vibration, and discharge pressure variations were observed.
- There was a strong correlation between power, vibration, and discharge pressure changes with time.
- The most likely explanation for these oscillations was variable hydraulic load due to inlet flow pre-rotation/turbulence.
- The motor was used as a sensor in this test; current is proportional to power consumed by the pump.




CWP 6 Motor Current V.S. Vibration 5-12-16

Data Acquisition Time = 0.8 seconds




CWP 6 Motor Current V.S. Vibration 5-12-16

Data Acquisition Time = 0.8 seconds




CWP 6 Motor Current V.S. Pressure Pulsation 5-12-16

Data Acquisition Time = 0.8 seconds



Pump Top Axial Waterfall



Physical Hydraulic Model Study



Photo 5-1 Unsteady Flow Around the Pump



Photo 5-1 Unsteady Flow Around the Pump




Photo 5-5 Floor Vortex



Photo 5-2 Stalling and Lifting in Front of Pump - Flow Should Towards Pump




Photo 5-2 Stalling and Lifting in Front of Pump - Flow Should Towards Pump







Photo 5-6 Surface Vortex at El. 13-ft

Modification


Vortex Suppressor



TDH Curve





Zoom Operating Flow Range




Power Curve

Zoom Operating Flow Range




Compare Performance Data

Original Condition



With Suppressor



VIDEO

Surface Vortex Before



After Suppressor Installation



Lessons Learned

- The vortex suppressor did not eliminate all inlet bay flow issues; however, flow into the pump inlet was more uniform.
- Power and vibration oscillations were essentially eliminated.
- Reduced fluid pre-rotation caused a larger increase in TDH at low flow rates.
- Pump efficiency was improved.
- The suppressor resolved the flow issues without extensive inlet bay modifications.

