

# Case Study

---

## Solving a Coupling Unbalance Problem in the Field

**Author:**           **Quraisy A. Shatri P.E.**  
Maintenance Superintendent – Machinery and Reliability  
RasGas Company Limited  
PO Box 24200, Doha, State of Qatar  
Tel: (+974) 4492 3209  
Mobile: (+974) 5583 8706  
e-mail: [qashatri@rasgas.com.qa](mailto:qashatri@rasgas.com.qa)

**Author:**           **Joseph P. (Joe) Corcoran**  
Manager, Global Services and Training  
Kop-Flex Emerson Industrial Automation  
7565 Harmans Road  
Hanover, MD USA 21076  
Tel: (+1) 410 787 8522  
Mobile (+1) 443 831 1811  
e-mail: [j.corcoran@emerson.com](mailto:j.corcoran@emerson.com)

# Abstract

---

*When a large (3.4 meters long) diaphragm coupling was suspected of causing excessive (120 microns p-p) 1X unbalance vibration between a 90+ Megawatt Gas Turbine and a Propane Compressor in an LNG plant, there was not time to ship the coupling back to a distant factory or service center for troubleshooting. Simple field diagnostic techniques were used to discover the problem, which then led to a field correction and repair so that the unit was able to be quickly restarted with minimum downtime.*

# Process Background

- In an LNG Plant, After all impurities such as Hg, H<sub>2</sub>S, H<sub>2</sub>O are removed in upstream units, sweet feed gas enters the *gas chilling & liquefaction unit*.
- Two major pieces of equipment in *this* unit are the Scrub Column (SC) & the APCI Main Cryogenic Heat Exchanger
- SC is a distillation column, steam re-boiled, to remove C<sub>5</sub>+ and provide streams for producing refrigerants (C<sub>2</sub> and C<sub>3</sub>).
- OH gas of the SC goes in to MCHE mid-bundle for liquefaction. The medium to cool is MR or Multi Component Refrigerant (MCR - ***C1+C2+C3+N2***)


# Process Background

---


- The *MR circuit* is cooled (and partially liquefied) by Propane. The *Propane refrigeration circuit* is also tasked to cool Feed Gas in the gas chilling section, De-C2 condenser and the reinjection stream from the refrigerant preparation unit.
- The two (2) main refrigeration compression circuits – MR & Propane – are illustrated in the next page.
- If either of these 2 strings are down, there'll be no production from the *gas chilling & liquefaction unit*, and no LNG is produced.

# Simplified schematics

## Propane System



# Main Refrigeration Compression Strings



# RCA


- The string comprises of 4 coupled rotors: 7EA GT rotor, 88M and 56MB compressor rotors – HM rotor
- Bearings: 3 radial bearings for a single shaft 7EA rotor, 2 radial bearings each of 88M and 56MB rotors, and 2 radial bearings of the HM.
- Only DE radial vibration of the 88M rotor was extremely high – increasing rapidly with increasing speed / load; other bearings-vibe readings were normal.
- Refurbished 7EA rotor and upgraded (new) 88M rotor were installed during the turn-around. The GT operating data indicated “perfect”; factory dimensional and high-speed balance data of the 88M rotor and as-installed records indicated everything was acceptable.
- Strong suspect was load coupling #5.5 MSMH-J based on possible coupling imbalance as seen via 88M DE vibe plots: new spools & adapter but *old coupling-hub* were assembled; wrong pre-stretch gap; and poor run-out. Coupling components individual balance records observed to be “perfect”.
- On attending the unit, installed couplings run-out checks clearly showed the coupling straightness was grossly out-of- straightness (0.018”) in mid-span point.
- Plans to index, change-out of coupling hub was cancelled; previously-installed spacers were re-installed after all necessary checks were done and certified acceptable. Run-out checks of the installed coupling was then checked and certified acceptable for services.
- The whole string was started-up, sent in to normal operations satisfactorily.

# High Vibration – Coupling Suspected

Location	Before coupling spacer replacement (At 70% Load on 09-Jun-11, 07:28 hrs)		
	Overall Vibration (Microns, Pk-Pk)	1X Amplitude (Microns, Pk-Pk)	Phase (Degrees)
36VI6120X	165	163	174
36VI6120Y	67	64	233
36VI6121X	46	35	59
36VI6121Y	24	16	202
Speed	3421 RPM (95 % Speed)		



# High Vibration – Coupling Suspected




# ***Before Disassembling Coupling Installed Runout was Checked***

- This is Not Normally Done but Can Provide Important Information
- Sometimes Difficult to Turn Over Machines
  - Many Ways to Overcome
    - Jog Motor (If Motor)
    - Use Turning Gear
    - Even Overhead Crane can be Used with Long Strap Wound Around Coupling or Shaft

**Run Out Should Typically be No Greater Than  
0.002” TIR at Flange Connections**

**0.001” TIR at Hub Bodies**


# Field Installed Run Out Check of Coupling Confirm a Problem



# Next, Previously Installed Coupling was Checked to Reinstall to Get Train Running

All the dimensions are in mm

## 36 KT-004 COUPLING SPACER



Is the Available Field Repair Equipment Acceptable?


Checked on Calibrated Acceptable Balance Machine

Minor Issue w/ Length Capacity of Available Balance Machine

Run Outs O K

# *Then Dye Penetrant Checks of Diaphragms*



**Important Check On Used Diaphragms After Handling**



**No Indications, Cracks, or Unacceptable Scratches**


# ***Install Replacement Coupling Center Section***

- Use Existing Turbine Adapter and Compressor Rigid from the First Coupling
- Do a High Spot Check
- Line Up High Spots of Male and Female Pilots
- Remember that “High Spot” Definition is the Spot Furthest from the Center of Rotation



**This Guarantees the Best Balance Condition  
From a Concentricity to Center of Rotation  
Perspective**


# Installed Replacement Coupling Run Out Checks



**No Problem**


# Runout Checks are Good and New Vibration Plots are Good

Figure 1: 36-K004 Compressor, Turbine Bearing # 3 radial vibration and Speed trend





# Proof: Vibration Plots are Good



17  
Before and After

# Proof: Vibration Plots are Good


Table-1: 36-K004 Vibration levels before and after coupling spacer replacement:

Location	Before coupling spacer replacement (At 70% Load on 09-Jun-11, 07:28 hrs)			After coupling spacer replacement (At 90% Load on 17-Jun-11, 09:00hrs)		
	Overall Vibration (Microns, Pk-Pk)	1X Amplitude (Microns, Pk-Pk)	Phase (Degrees)	Overall Vibration (Microns, Pk-Pk)	1X Amplitude (Microns, Pk-Pk)	Phase (Degrees)
36VI6120X	<b>165</b>	<b>163</b>	174	<b>43</b>	<b>28</b>	14
36VI6120Y	67	64	233	21	11	179
36VI6121X	46	35	59	25	15	291
36VI6121Y	24	16	202	20	8	50
Speed	3421 RPM (95 % Speed)			3636 RPM (101 % Speed)		

# Next - Check of Problem Coupling

All the dimensions are in mm

36 KT-004 NEW COUPLING SPACER T S



**OK Too !!**

**What is the Problem ??**




# ***What Could Have Been the Problem?***

- Installed Run Outs at Positions Other Than Spacer - OK
- Mounting Flange and Adapter - OK
- Hub Mounting Surfaces - OK
- Then we remembered a comment about the difficulty of connecting to the Turbine flange
- Re-look at Coupling/Turbine Mounting Surfaces



# ***Aha !! ; Clear Evidence of a Mounting Problem***


**Connecting Flanges were not Contacting and were out of Square Even Though Bolts Were Tightened Properly**



**This out of Square caused the Mounted Center Flange High Runout**

# Recommendations

- Improve Existing Turbine Flange Connection for Ease of Assembly
  - Reduce Width of Guard Pilot
  - Reduce Amount of Interference at Pilot
- Improve Overall Flange Connection Design
  - Use Standard Design Bolting
- Improve Procedure
  - Leave Coupling Adapter in Place
- Handle Diaphragms “Gingerly”



# ***Lessons Learned***

---

- If Coupling Balance is Suspected, Check Installed Run-outs
- If Replacing Non-Match Marked Components, Find “High Spots” and Match Them
- Dye Check or MPI used and/or handled Coupling Diaphragms
- Carefully Handle any Diaphragm
  - Do not lay face down on rough surface
- Understand Installation Potential Difficulties When Designing Coupling