

Research Report  
KTC-95-2

FIELD PERFORMANCE REPORT  
ON PVC PIPE CAMPBELL COUNTY

by

L. John Fleckenstein  
Senior Research Investigator

and

David L. Allen  
Chief Research Engineer

Kentucky Transportation Center  
College of Engineering  
University of Kentucky  
Lexington, Kentucky

in cooperation with  
Transportation Cabinet  
Commonwealth of Kentucky

and

Federal Highway Administration  
U.S. Department of Transportation

The contents of this report reflect the views of the authors who are responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the official views or policies of the University of Kentucky, the Kentucky Transportation Cabinet, nor the Federal Highway Administration. This report does not constitute a standard, specification, or regulation. The inclusion of manufacturer names and trade names are for identification purposes and are not to be considered as endorsements.

March 1995

1. Report No. KTC-95-2		2. Government Accession No.		3. Recipient's Catalog No.	
4. Title and Subtitle  FIELD PERFORMANCE REPORT ON PVC PIPE, CAMPBELL COUNTY				5. Report Date March 1995	
				6. Performing Organization Code	
7. Author(s) L. John Fleckenstein and David L. Allen				8. Performing Organization Report No.6 KTC-95-2	
9. Performing Organization Name and Address  Kentucky Transportation Center College of Engineering University of Kentucky				10. Work Unit No. (TRAVIS)	
				11. Contract or Grant No. Federal Aid Research Task 61	
				13. Type of Report and Period Covered	
12. Sponsoring Agency Name and Address Kentucky Transportation Cabinet State Office Building				14. Sponsoring Agency Code	
15. Supplementary Notes		Publication of this report was sponsored by the Kentucky Transportation Cabinet in cooperation with the U.S. Department of Transportation, Federal Highway Administration			
16. Abstract  This report documents the installation and performance of PVC pipe installed on KY 9 in Campbell County. The pipe installed was Perma-Loc, manufactured by J-M Manufacturing Company, Inc.  Pipes appear to be performing well with the clean coarse sand backfill. It is apparent the pipe is brittle at lower temperatures, and caution should be exercised during cold weather construction.  It is apparent that the contractor achieved substantial compaction around the haunches and the side of the pipe which is helping to reduce pipe deflection.  In July 1995, the pipes will have been installed for approximately two years. Minor changes in pipe deflection are still occurring in approximately 40 percent of the pipes. The other 60 percent appear to be stabilized.					
17. Key Words Backfill Compaction Deflection			18. Distribution Statement  Unlimited		
19. Security Classif. (of this report)		20. Security Classif. (of this page)		21. No. of Pages  38	22. Price

## EXECUTIVE SUMMARY

This report documents the installation and performance of PVC pipe installed during construction of KY 9 in Campbell County. The pipe installed was Perma-Loc pipe manufactured by J-M Manufacturing Company, Inc..

It is apparent the pipe is brittle at lower temperatures, and caution should be exercised during cold weather construction.

The pipes appear to be performing well with the clean coarse sand backfill. It is also apparent that the contractor achieved substantial compaction around the haunches and the side of the pipe which is likely helping to reduce pipe deflection.

In July of 1995, the pipes will have been installed for approximately 2 years. Minor changes in pipe deflection are still occurring in approximately 40 percent of the pipes. The other 60 percent appear to be stabilized.

## TABLE OF CONTENTS

FORM DOT 1700.7 (8-72) .....	i
EXECUTIVE SUMMARY .....	ii
TABLE OF CONTENTS .....	iii
LIST OF FIGURES .....	iv
INTRODUCTION .....	1
CONSTRUCTION .....	1
PERFORMANCE .....	1
PIPE DEFLECTIONS .....	2
CONCLUSIONS .....	2
RECOMMENDATIONS .....	2
REFERENCES .....	2
APPENDIX A (Pipe Deflection Measurements) .....	9

## **LIST OF FIGURES**

- Figure 1. Severely Damaged PVC Pipe
- Figure 2. Damaged Exterior Rib
- Figure 3. Impact Strength of PVC Pipe
- Figure 4. Installation of 1.2 m Pipe at Station 104+70
- Figure 5. Installation of 0.76 m Pipe at Station 162+00
- Figure 6. Elevation Profiles
- Figure 7. Outlet End of PVC Pipe at Station 129+72
- Figure 8. Outlet End of PVC Pipe at Station 129+72
- Figure 9. Crack in Wall of PVC Pipe at Station 129+72

## INTRODUCTION

The Kentucky Transportation Center was requested by the Kentucky Transportation Cabinet to monitor the field performance of Polyvinyl Chloride (PVC) Pipe on KY 9 in Campbell County (Project NO. FSP 019 0009 013-015 C-DE-STPM 0020 (804)).

Included in this report are construction and performance information. A video tape is also provided showing the final inspection of the pipe with a Cues Mini Camera.

## CONSTRUCTION

Prior to installation, on December 11, 1992 the PVC pipe was inspected in the stockyard at the construction site on KY 9 shortly after delivery. Approximately 19 out of 65 pipe sections had been slightly to significantly damaged during delivery (Figures 1 and 2). The Resident Engineer indicated that several of the pipes had fallen off the truck during unloading. The pipes were fairly brittle at the time they were being unloaded due to the cold temperatures (approximately  $-9^{\circ}\text{C}$  ( $15^{\circ}\text{F}$ )). Figure 3 was derived from the Uni-Bell Handbook (1) and extrapolated to colder temperatures. Figure 3 indicates the impact strength of the pipe could be as much as 40 percent lower when comparing strength properties at  $23^{\circ}\text{C}$  and  $-9^{\circ}\text{C}$  ( $73.4^{\circ}\text{F}$  and  $15^{\circ}\text{F}$ ).

The construction project was postponed due to unstable embankment conditions and only a portion of the pipes were installed. Prior to the project being postponed, six cross drains had been installed. The pipes were backfilled with a clean sand slightly over the crown of the pipe (Figures 4 and 5). Since the final fill elevations were not achieved, the fill heights were established by survey (Figure 6). The maximum fill height obtained during construction was approximately 4 meters (12 feet) at Station 160+00.

## PERFORMANCE

The cross drains were monitored during construction, and have been visually inspected several times since installation. The pipes were last inspected in December 1994 with a Cues Mini Camera. A majority of the cross drains appear to performing well. Significant distress was observed in one of the cross drains. The distress was observed in a 0.61 m (24 inch) cross drain at Station 129+72. Distress was observed toward the outlet end of the cross drain. During a visual inspection shortly after installation, approximately 2.4 meters (8 feet) of pipe on the outlet end was unsupported (Figure 7). It was apparent that the pipe had not been cut off and/or the fill around the pipe had eroded. In October, 1993, at a later inspection, it was apparent that this section of pipe had been covered during the reshaping of a sliding embankment (Figure 8). It appears that in this process the pipe was bent down causing the pipe to crack and deflect approximately 8.3 percent (Figure 9).

## **Pipe Deflections**

Pipe deflection measurements have been taken on the six cross drains since installation (Appendix A). Pipe deflections were monitored at 29 locations. In approximately 67 percent of the pipes that were monitored, the vertical dimension was greater than the horizontal after installation. It is apparent that the pipe was compressed horizontally during the backfilling around the sides and haunches of the pipe. The average pipe deflection recorded was 2.74 percent.

## **CONCLUSIONS**

It is apparent the pipe is brittle at lower temperatures, and caution should be exercised during cold weather construction.

The pipes appear to be performing well with the clean coarse sand backfill. It is also apparent that the contractor achieved substantial compaction around the haunches and the springline of the pipe. This has helped to keep pipe deflection at a minimum.

In July of 1995, the pipes will have been installed for approximately 2 years. Minor changes in pipe deflection are still occurring in approximately 40 percent of the pipes. The other 60 percent appear to be stabilized.

## **RECOMMENDATIONS**

It is recommended that these pipes continue to be monitored for long-term performance.

It is recommended that this pipe be used as an alternative to concrete, steel, aluminum, and polyethylene pipe .

It is also recommended that future installations be monitored for short-and long-term performance.

## **REFERENCES**

1. "Handbook of PVC Pipe, Design and Construction", Third Edition, Uni-Bell PVC Pipe Association, Dallas, September 1991, pp. 213.




Figure 1. Severely Damaged PVC Pipe





Figure 2. Damaged Exterior Rib



Figure 3. Effect of Cool Temperatures on Impact Strength of PVC Pipes






**Figure 4. Installation of 1.2m Pipe at Station 104+70**




**Figure 5. Installation of 0.76 m Pipe at Station 162+00**

Figure 6. Elevation Profiles


Station 100 + 72 (0.61 m pipe diameter)  
(Installed 7-1-93)




Station 104 + 70 (1.22 m pipe diameter)  
(Installed 7-6-93)




Station 129 + 72 (0.61 m pipe diameter)  
(Installed 6-28-93)




Station 132 + 94 (0.46 m pipe diameter)  
(Installed 6-21-93)



Station 160 + 00 (0.61 m pipe diameter)  
(Installed 4-23-93)



Station 162 + 00 (0.76 m pipe diameter)  
(Installed 7-14-93)





**Figure 7. Outlet End of PVC Pipe at Station 129+72**




**Figure 8. Outlet End of PVC Pipe at Station 129+72**



**Figure 9. Crack in Interior Wall of Pipe at Station 129+72**


**APPENDIX A**  
**(PIPE DEFLECTION MEASUREMENTS)**

(Station 100+72)



Note: Measurements for day 0 are assumed.


(Station 100+72)



Note: Measurements for day 0 are assumed.




(Station 100+72)



■ 1Z: VERTICAL      ◆ 2Z: HORIZONTAL


Note: Measurements for day 0 are assumed.

(Station 104+70)




Note: Measurements for day 0 are assumed.


(Station 104+70)



(Station 104+70)




(Station 104+70)




Note: Measurements for day 0 are assumed.

(Station 104+70)




Note: Measurements for day 0 are assumed.

(Station 104+70)




(Station 104+70)



Note: Measurements for day 0 are assumed.




(Station 104+70)




Note: Measurements for day 0 are assumed.

(Station 104+70)




Note: Measurements for day 0 are assumed.

(Station 104+70)




Note: Measurements for day 0 are assumed.

(Station 104+70)



Note: Measurements for day 0 are assumed.


(Station 129+72)



■ AV: VERTICAL      ◆ AH: HORIZONTAL

Note: Measurements for day 0 are assumed.


(Station 129+72)



■ BV: VERTICAL      ◆ BH: HORIZONTAL

Note: Measurements for day 0 are assumed.


(Station 129+72)



■ CV: VERTICAL      ◆ CH: HORIZONTAL

Note: Measurements for day 0 are assumed.

(Station 129+72)




■ DV: VERTICAL      ◆ DH: HORIZONTAL

Note: Measurements for day 0 are assumed.




(Station 132+94)




Note: Measurements for day 0 are assumed.

(Station 132+94)




Note: Measurements for day 0 are assumed.

(Station 132+94)




Note: Measurements for day 0 are assumed.

(Station 132+94)




Note: Measurements for day 0 are assumed.

(Station 160+00)




Note: Measurements for day 0 are assumed.

(Station 160+00)



Note: Measurements for day 0 are assumed.


(Station 160+00)



■ 3B: VERTICAL      ◆ 3A: HORIZONTAL

Note: Measurements for day 0 are assumed.

(Station 160+00)




■ 4B: VERTICAL      ◆ 4A: HORIZONTAL

Note: Measurements for day 0 are assumed.




(Station 160+00)



Note: Measurements for day 0 are assumed.

(Station 162 + 00)



(Station 162 + 00)

