

Seismic performance of bridges during the 2016 Central Italy earthquakes

Di Sarno L., da Porto, F. , Guerrini, G., Calvi, P.M., Camata, G. and Prota, A.

ABSTRACT

This paper focuses on the structural performance of existing masonry and reinforced concrete bridges which were surveyed in the aftermath of the 2016 Central Italy earthquakes. Typical bridge vulnerabilities are first reviewed, as they provide a reference for the response of the bridges that were damaged by the 2016 earthquake swarm. Case studies are then discussed and preliminary numerical analyses are carried out to interpret the observed failure modes. In general, all surveyed masonry bridges experienced some extent of damage, particularly when built with poor-quality materials and subjected to geotechnical-induced effects. However, they offered a robust response in terms of collapse prevention. The majority of existing reinforced concrete bridges, although designed primarily for gravity loads, exhibited acceptable performance; however, local damage due to the poor maintenance of the structural systems was observed, which affected primarily the non-structural components of the bridges.

1 INTRODUCTION

Three major earthquake events occurred in Central Italy in 2016. The first event, with magnitude M6.1, took place on August 24, the second one (M5.9) on October 26, and the third one (M6.5) on October 30. Each event was followed by many aftershocks [1, 2]. The August-October 2016 earthquake sequence occurred on mapped normal faults in the Apennine Mountain range in central Italy, a region with a long history of destructive earthquakes. Nevertheless, widespread damage was caused by the 2016 seismic sequence to the built environment. Several collapses of masonry and reinforced concrete (RC) residential buildings were recorded, since most buildings were designed primarily for gravity loads and did not possess adequate lateral stiffness, strength, or ductile detailing. Lifelines, especially roadways, were also severely damaged, with consequences for the rescue operations as the access to the affected areas became limited and alternative routes were not efficient. Furthermore, transportation systems are expected to possess high resilience in the aftermath of extreme events, such as earthquakes and floods, to allow easy access to local communities. However, it has been found that the existing bridge infrastructures, especially in South of Europe, exhibit high vulnerability [3, 4, 5, 6] and risk mitigation policies are deemed urgent. Additionally, recent studies have shown that current assessment methods for existing RC bridge structures need to be further investigated as they tend to provide unrealistic estimations for brittle failure modes [7, 8], especially for non-ductile systems under multiple earthquake records (e.g. [9], among others).

This paper illustrates the structural performance of existing masonry and RC bridges which were surveyed in the aftermath of the 2016 Central Italy seismic sequence. The paper provides an outline of the typical bridge vulnerabilities, as observed during past earthquakes, and focuses on the response of the bridges either damaged or partially collapsed after the 2016 earthquake swarm. Case studies are considered and preliminary numerical analyses are carried out to interpret the observed damage. It was found that structural damage was widespread in masonry structural systems, which in general were characterized by very low-quality materials and were also primarily affected by geotechnical induced effects. RC bridges showed acceptable performance: the limited damage occurrence, localized particularly in RC decks, was mostly attributed to the poor maintenance of the structural systems. Thus, poor quality of construction materials, aging phenomena, and scarce maintenance can significantly increase the vulnerability of existing structures subjected to seismic loads.


57 2.1 Masonry bridges

58 Masonry arch bridges are usually quite robust structural systems [10], as demonstrated by on-site
 59 surveys carried out during past seismic emergencies: in many circumstances they withstood major
 60 earthquakes with no or limited damage. This has been reported starting from the Irpinia, Italy
 61 earthquake of 1980 [11] up to the recent 2008 earthquakes of Wenchuan, China [12, 13]. After
 62 the L'Aquila, Italy earthquake of 2009, the one-track railway line from Rome to Sulmona, which
 63 includes several multi-span arch masonry bridges, was fully reopened 3 days after the main shock
 64 [14].


65 The main damage and collapse mechanisms reported from past earthquakes, validated on the basis
 66 of experimental and numerical analyses, consist of local and overall collapses in the longitudinal
 67 and transverse directions. These mechanisms develop in relation to the main geometrical features
 68 of the masonry arch bridges, such as number of spans, span length, arch rise, arch ring thickness,
 69 abutment (for single-span) or pier (for multi-span bridges) height, transverse bridge width, among
 70 the most relevant ones.

71 Single-span masonry arch bridges generally have massive abutments, which in most cases can be
 72 represented by infinitely rigid constraints. In this configuration, a local arch mechanism can be
 73 triggered in the longitudinal direction (mechanism A-L) under seismic action. This is an
 74 asymmetric collapse mechanism with the formation of three rigid voussoirs and four hinges (Fig.
 75 1a), located where the thrust line (red line in the figure) crosses the arch ring boundaries [15]; the
 76 input accelerations activating this local mechanism are lower for semi-circular arches than for
 77 segmental arches [16, 17]. In the case of single-span structures with more slender abutments an
 78 overall arch-abutment longitudinal mechanism may develop (mechanism AA-L), with hinges at
 79 the base of the abutments and in the arch (e.g. [18] among others) as shown in Figure 1b. This
 80 overall arch-abutment longitudinal mechanism is generally more vulnerable than the local arch
 81 mechanism typical of squat single-span bridges [16, 17].

82 In squat multi-span bridges, the spandrel walls at the arch springing provide fixed restraints for
 83 the arch, so that each span can be regarded as independent. The expected collapse mechanisms
 84 are the same as those for single-span bridges with squat abutments, i.e. mechanism A-L, for any
 85 individual arch in the longitudinal direction. Conversely, in multi-span structures with slender
 86 piers, the kinematic chain in the longitudinal direction may either involve the arches alone, or an
 87 overall arch-pier longitudinal mechanism may develop (mechanism AP-L, Figure 2a), with the
 88 formation of plastic hinges at the pier bases and in the arches. Local A-L and overall AP-L
 89 collapse mechanisms are both possible for multi-span arch bridges with piers of medium
 90 slenderness (pier height-to-depth ratio between 1 and 4). An example of damage due to large
 91 displacement of the bridge in the longitudinal direction can be found in the Guantong Bridge,
 92 China, an unreinforced sandstone masonry arch bridge hit by the 2008 Wenchuan earthquake
 93 (Figures 2b and 2c).



96 Figure 1 - Single-span bridges: (a) local longitudinal arch mechanism (A-L) and (b) overall longitudinal
 97 arch-abutment mechanism (AA-L).




99 Figure 2 - Multi-span bridges: (a) overall longitudinal arch-pier mechanism (AP-L); (b, c) damage to the
 100 Guantong Bridge, China, due to large displacements in the longitudinal direction in the 2008 Wenchuan
 101 earthquake (after [13]).
 102
 103
 104

105 Considering the response in the transverse direction, spandrel walls are often the most vulnerable
 106 elements and may easily rotate out-of-plane in a spandrel-wall transverse mechanism (mechanism
 107 SW-T, Figure 3a). Damage or overturning of these secondary elements does not generally
 108 jeopardize the overall structural safety of the bridge. However, subsequent loss of infill material
 109 may compromise road pavement support and hence bridge functionality. These local collapse
 110 mechanisms are usually related to the lowest limit accelerations and simple retrofit to prevent
 111 spandrel overturning can be very effective [16]. Other local out-of-plane failures involve
 112 abutment wing walls and parapets. Examples of overturning of spandrel walls (Figure 3b),
 113 spandrel walls and parapets (Figure 3c), and wing walls and parapets (Figure 3d) have been often
 114 reported in recent earthquakes.

115 In multi-span bridges with slender piers an overall collapse mechanism can occur in the transverse
 116 direction involving both arches and piers (AP-T): flexural hinges can form at the pier bases, due
 117 to bending in a vertical plane, and at the arch crowns, due to bending in a horizontal plane [22]
 118 (Figure 4a). A global collapse of this type was reported for the Yingchun Bridge (Figure 4b),
 119 which failed because the arch supports lost stability and the retaining walls at the supports toppled
 120 outward in the 2008 Wenchuan earthquake in China. Another example is the collapse of the
 121 slender multi-span bridge spanning the Río Claro in the 2010 Maule earthquake in Chile (Figures
 122 4c and 4d). Multi-span arch bridges with slender piers are generally more vulnerable to overall
 123 collapse mechanisms in both longitudinal and transverse directions (AP-L and AP-T), than to
 124 local longitudinal arch mechanisms (A-L). However, for common bridge geometries, the limit
 125 accelerations associated with these mechanisms are rather high [16, 17] compared to those
 126 triggering local spandrel mechanisms (SW-T).

127
 128
 129



(a)



(b)



(c)




(d)

130 Figure 3 - Local transverse mechanisms: (a) out-of-plane overturning of spandrel wall (SW-T); (b) out-of-
 131 plane collapse of a spandrel wall in the 1997 Umbria and Marche earthquake, Italy (after [19]); (c) damage
 132 to a railway masonry arch bridge in the 2001 Bhuj earthquake, India (after [20]); (d) collapse of wing wall
 133 and parapet of the Kahu Road East Bridge in the 2011 New Zealand earthquake (after [21]).
 134

135
 136

137 Most of the aforementioned mechanisms are based on the assumption of infinitely stiff and strong
 138 abutments and foundations. However, local failures of the abutments (flexural failure, AB_NM;
 139 and shear failure, AB_S) and of the abutment-foundation interface (sliding, AB_SL; and
 140 overturning, AB_OV), may also occur. Soil-structure interaction and foundation settlements can
 141 cause significant damage, as masonry arch bridges are extremely stiff structures: hence,
 142 widespread significant damage can be observed in case of differential settlements of the supports.
 143 Moreover, the load-bearing capacity of masonry bridges can be affected by the local attainment
 144 of strength, typically when poor materials such as low-quality mortar were used in construction.

145 In stone masonry bridge structures, with piers or abutments characterized by filling with
 146 discontinuities, cavities, and/or loose material, local effects of disaggregation of masonry units
 147 and loss of support can be observed also under low inertial forces.
 148 Aging and deterioration of material strength may also have an impact on the seismic behavior of
 149 masonry bridges. Most of these structures are part of the historical heritage of the 19th century,
 150 while some date back to the Renaissance or the Roman Era; nevertheless they are still in service.
 151 Due to their long life, the effects of natural weathering, aging, and increased traffic can be
 152 significant [24]. Deterioration conditions such as erosion of mortar joints, salt efflorescence in
 153 bricks, arch barrel deformations with cracking, separation between masonry rings in multi-barrel
 154 vaults, sliding, and bulging or detachment of spandrel walls, are often observed in in-service
 155 masonry bridges, with the potential of reducing the seismic capacity of the structure.
 156



(a)



(b)



(c)



(d)


157 Figure 4 - Overall transverse mechanisms: (a) overall AP-T mechanism of multi-span bridges; (b) collapse
 158 of the Yingchun Bridge in the 2008 Wenchuan earthquake, China (after [13]); (c, d): collapse of the Río
 159 Claro Bridge in the 2010 Maule earthquake, Chile (after [23]).
 160
 161
 162

163 2.2 Reinforced concrete bridges

164 The causes of failure in RC bridges are many and difficult to categorize. However, most damage
 165 and collapse cases in recent worldwide earthquakes fall into the following categories:
 166 substructure, superstructure, soil-structure interaction, and nonstructural damage.

167 As primary components of the gravity and lateral force-resisting system of bridges, piers are
 168 subjected to intense forces during earthquakes. Damage to piers depends largely on bridge
 169 geometry, structural design and seismic details, if any. Short, stout piers are more susceptible to
 170 shear failure. Lack of specific design details, such as insufficient reinforcement lap length or
 171 inadequate transverse reinforcement, can lead to premature failure, as surveyed for example in
 172 the aftermath of the 1994 Northridge (California) and 1995 Kobe (Japan) earthquakes (Figure 5).
 173 Additionally, because of flexure-torsion interaction, many RC bridge piers of curved and skewed
 174 bridges suffered severe damages during the 2008 Wenchuan earthquake in China [12, 25].

175 High shear demands typically develop within joints between piers and superstructure. The heavy
 176 damage observed on several RC bridges in the San Francisco Bay Area during the 1989 Loma
 177 Prieta earthquake dramatically highlighted this problem (Figure 6). Current design philosophies
 178 aim at capacity designing these connections in order to force inelastic actions to occur in beams
 179 and columns. Without adequate transverse reinforcement, concrete diagonal cracks occur in the
 180 joint regions, because of excessive shear-induced tensile stresses (Figure 6). Moreover, beam
 181 longitudinal bars do not anchor properly if bent within poorly confined joints, with the risk of
 182 bond failure.
 183



184 Figure 5 - Typical failure of bridge piers: (a) confinement failure at a bridge pier top during the 1994
 185 Northridge earthquake (courtesy of NISEE) and (b) flexural failure above base of columns of the Hanshin
 186 expressway, due to premature termination of longitudinal reinforcement and inadequate confinement in the
 187 1995 Kobe earthquake: overall collapse (top) and close-up view of the failure mechanism (courtesy of
 188 Kawashima).
 189



190 Figure 6 - Shear failure of pier-bent cap joints, and anchorage failure of beam longitudinal bars of the
 191 Cypress viaduct in Oakland, California, during the 1989 Loma Prieta earthquake (courtesy of NISEE).
 192
 193

194 Bearings are designed to transfer forces and allow relative motion between superstructure and
 195 substructure elements. Damage to bearings during earthquakes varies by bearing type: some
 196 examples include sliding of elastomeric bearings and pull-out or shearing of anchor bolts. Failure
 197 of bearings can contribute to unseating of spans, which occurs when the bridge superstructure is
 198 permanently displaced from its position atop the substructure. Some older bridges have very short
 199 bearing seat lengths, which makes unseating far more likely. Unseating can involve girders
 200 displacing from their bearings and coming to rest on the pier cap, but can also result in the
 201 complete collapse of one or more spans.

202 Expansion joints are designed to allow relative motion between superstructure segments due to
 203 temperature fluctuations, creep, shrinkage, and traffic loads. However, earthquakes can cause
 204 sudden closing or opening of expansion joints, which may cause concrete crushing or span
 205 discontinuities, respectively. Pounding between adjacent girders is also often observed when the
 206 ground motion imposes large relative displacements to the piers or to the portal frames supporting
 207 the bridge deck.

208 Abutment behavior is affected not only by the response of its structural components, but also by
209 the interaction with the surrounding soil. Abutments typically consist of bearings, wing walls,
210 back walls, and foundation elements. Abutments often include shear keys, which aid in restraining
211 the relative motion between the superstructure and the abutment itself, and can act as structural
212 fuses whose failure limits damage to other elements of the structure. Pounding may also occur
213 between the bridge deck and the abutments.

214 Nonstructural elements include railings, barriers, signage, and utility conduits. Damage to these
215 elements does not affect the structural integrity of the bridge, but secondary effects such as
216 injuries can occur as a result of their failure. Examples include impact damage from falling
217 overhead signs, risk of electrocution of passersby by severed electrical wires, and damaged
218 barriers failing to prevent roadway departures.

219 In recent Italian earthquakes such as the 2009 L'Aquila earthquake and the 2012 Emilia
220 earthquake, damage to reinforced concrete bridges was limited, even for those not specifically
221 designed for earthquake resistance (e.g. [26, 27], among many others). In most instances, the
222 observed minor damage was mainly the result of poor maintenance. To this end, the most affected
223 elements were drainage systems and deck bearings. However, movement of the bearings and
224 pounding of bridge deck segments were sometimes reported.

225 Highways A24 and A25 are two major infrastructures that connect the East coast with the West
226 coast of Italy, and run through the area affected by the 2009 L'Aquila earthquake. The double
227 carriageway bridge decks consist mostly of simply supported, single-span, precast pre-stressed
228 elements, resting on bearings on top of RC piers, as shown in Figure 7 for the "Della Valle" bridge
229 along A24. Bearings and gaps were designed to allow deck thermal deformations and were not
230 conceived to resist horizontal and vertical seismic loads or displacements: many of these supports
231 were unbolted and they could resist lateral loads relying solely on friction. These highways were
232 closed for inspection in the aftermath of the 2009 L'Aquila earthquake and reopened a few days
233 later: no structural damage to the bridges was generally observed, but some interventions were
234 needed to repair the damage induced by pounding, movement or failure of the bearings. Due to
235 lack of internal connections, each segment and each pier behaved independently during the
236 seismic event, causing relative displacements between the deck segments and their supports.

237 Only a 35-m-long multi-span RC bridge collapsed along a secondary road near the town of Fossa
238 (Figure 8a). The collapse was probably caused by pier failure due to lack of maintenance [26]:
239 the steel reinforcing bars were protected by a thin concrete cover and appeared to be severely
240 corroded. Another 3-span RC bridge, close to the town of Onna (Figure 8b), suffered some
241 damage at the top of the piers: again, damage was mainly due to poor maintenance.

242
243
244



245
246
247
248
249

Figure 7 - "Della Valle" bridge along Highway A24, Italy: (a) bridge configuration; (b) typical damage due to lack of maintenance.



250
251
252 Figure 8 - Bridge damage in the 209 L'Aquila earthquake, Italy: (a) bridge collapse near Fossa; (b) deck
253 failure near Onna (after [26]).
254

255 In the 2012 Emilia earthquake, Italy, RC bridges sustained only minimal damage [27].
256 Immediately after the event, inspections indicated some damage located near the expansion joints
257 (mainly cracking) and highlighted maintenance issues, in particular corrosion and drainage
258 deficiencies.
259

260 261 3 BRIDGE PERFORMANCE IN THE AFTERMATH OF THE 2016 CENTRAL ITALY 262 EARTHQUAKES

263 264 3.1 Earthquake sequence and inspected bridges

265 Visual inspections in the area struck by the 2016 Central Italy earthquakes included several
266 bridges and viaducts, in particular:
267

- 268 • “Tre Occhi” bridge, a three-span masonry arch bridge located along the SR260 route in
269 Amatrice (Figure 10);
- 270 • “Cinque Occhi” bridge, a five-span masonry arch bridge located along the local road
271 connecting SS4 (Casale Nibbi exit) and SR260 routes, towards Amatrice (Figure 11);
- 272 • Two masonry arch bridges along the SP129 “Trisungo-Tufo” route, located near the town
273 of Tufo (Figures 12 and 13);
- 274 • “Rosa” bridge, a five-span reinforced concrete deck and girder bridge with masonry piers
275 and abutments (Figure 14);
- 276 • Some reinforced concrete viaducts along the SS685 and SS4 state routes, including the
277 “Scandarello” viaduct (Figure 16).
278

279 Figure 9 shows the geographic location of the bridges along with the nearest seismic stations
280 belonging to the Italian Accelerometric Network (RAN), managed by the Department of Civil
281 Protection (DPC), and to the Italian Seismic Network, managed by the National Institute of
282 Geology and Volcanology (INGV), which were used to derive the input ground motions for the
283 bridges under examination. A data search was carried out on the closest strong-motion stations
284 for the events of 24/08/2016 and 30/10/2016. The data have been obtained through the ESM portal
285 (Engineering Strong Motion Database, version 1.0; [28]) and are reported in Table 1. The highest
286 values of peak ground acceleration (PGA) were recorded along the East-West direction at all
287 considered stations during both the 24/08/2016 Amatrice earthquake and the 30/10/2016 Norcia
288 earthquake. The vertical component of the seismic action was also significant, with accelerations
289 of the order of 25% to 50% of the horizontal PGA during the first event, and even up to 130% of
290 the horizontal PGA during the second event. It should be noted that the T1214 and T1244
291 recording stations were installed only after the 24/08/2016 mainshock and that the ACC records
292 of that event were of dubious quality: as a consequence there are no records of the 24/08/2016
293 earthquake from these stations.




Figure 9 - Location of the inspected bridges and of the nearest seismic stations.

294
295
296
297
298
299

Table 1 - Case-study bridge orientations and seismic data from the closest recording stations.

Bridge	Deck orientation	Recording station	Coordinates	PGA 24/08/2016 [g]			PGA 30/10/2016 [g]		
				N-S	E-W	Vert.	N-S	E-W	Vert.
Tre Occhi	E-W	AMT (Amatrice - RI)	42.63246 N 13.28618 E	0.380	0.870	0.400	0.401	0.532	0.324
Cinque Occhi	NWW-SEE	PCB (Poggio Cancelli Base Diga - AQ)	42.55861 N 13.33799 E	0.189	0.308	0.081	0.244	0.142	0.070
Rosa	NNE-SSW	ACC (Accumoli - AP)	42.69599 N 13.24200 E	-	-	-	0.392	0.434	0.558
Scandarello	NEE-SWW	T1214 (Forca Canapine - AP)	42.75954 N 13.20870 E	-	-	-	0.421	0.604	0.645
Trisungo-Tufo, single span	NEE-SWW	T1244 (Spelonga - AP)	42.75697 N 13.29779 E	-	-	-	0.193	0.285	0.354
Trisungo-Tufo, three spans	Curved								

300

301 3.2 Masonry bridges

302 Figure 10 shows the three-span arch masonry bridge referred to as the “Tre Occhi” bridge in
303 Amatrice, a critical lifeline for access to the town. In the aftermath of the August 24 event it was
304 closed to traffic, and a temporary by-pass road was promptly constructed to re-establish
305 connections to Amatrice from the South. The “Tre Occhi” bridge longitudinal axis is oriented
306 along the East-West direction, which was subjected to the maximum PGA of 0.87 g, during the
307 main event on August 24. The transverse direction was subjected to PGA values equal of 0.38 g
308 and 0.40 g, during the events of August 24 and October 30, respectively.

309 The semi-circular arch barrels are approximately 5-m-wide, with spans of 12 m. The total width
310 of the deck is about 10 m, as a result of a quite recent widening intervention, with two RC
311 cantilever slabs spanning more than 2.0 m on each side of the barrel vaults. The arches are made
312 of solid bricks, whereas spandrels, abutments and central piers are made of stone masonry. The
313 spandrel walls and abutment wing walls are made of 15- to 300-mm size stones with mortar layers.
314 The piers and the abutments have an external leaf consisting of 450- to 550-mm size, regular-
315 shaped stones with mortar joints; the internal core is made of relatively irregular smaller stones
316 and cobbles, bound with very poor earthen mortar stabilized with a low amount of lime.

317 Steel ties are provided through the spandrel walls and a few portions of the wing walls (Figures
318 10a and 10b), as a measure to prevent out-of-plane collapse. Three plain concrete buttresses are
319 built along the North-East wing wall (Figure 10c), while the pier and the abutment toes on the
320 river bed are capped by reinforced concrete walls (Figures 10f and 10g), unlikely part of the
321 original structure.

322 During the earthquakes, several sections of the external stone masonry layers collapsed out of
323 plane. This occurred particularly in some areas of the abutment walls (Figures 10b and 10c),
324 where ties were not placed. Moreover, wide horizontal cracks opened across the construction cold
325 joints in the buttresses retaining the North-East wing wall (Figure 10c), with residual widths of
326 the order of 10 mm. In addition, sliding occurred along these cracks, with permanent
327 displacements ranging from 10 to 50 mm.

328 This resulted in a lack of confinement of the interior uncemented cobbles and infill material,
329 causing lateral relaxation and settlement that was visible on the roadway surface above the
330 abutment (Figure 10d): major longitudinal and transverse cracks were observed along the road
331 surface, with maximum widths of about 60 mm vertically and 30 mm horizontally. A widespread
332 deformation pattern had already developed before the earthquake sequence, due to slope
333 instability in the eastern approach embankment: this was the cause of pre-existing cracks on the
334 road pavement mainly above the embankment and at the embankment-abutment joint, but only
335 marginally above the abutment.

336 Cracks were observed on the intrados of all the arches of the bridge, originating from the pier and
337 propagating diagonally along the arch intrados. The widest cracks were found on the East arch,
338 forming an X-shape pattern between the East abutment and mid-span (Figure 10e). This probably
339 occurred due to the restraining effect of the East abutment against transverse displacement of the
340 deck, which also caused horizontal cracking at the East arch springings at abutment and pier
341 (Figure 10f and 10g).

342 The “Cinque Occhi” bridge (Figure 11) is located along the internal road connecting SS4 and
343 SR260 routes, leading to Amatrice from the West. The bridge, which crosses over the Scandarello
344 lake, consists of five arches (Figure 11a) for a total length of 60 m, supported by four tapered
345 piers with rectangular cross-section and different heights. The bridge longitudinal axis is oriented
346 along the NWW-SEE direction, which was subjected to higher PGA values during the August 24
347 event.

348
349
350
351
352
353



(a)



(b)



(c)



(d)



(e)




(f)



(g)

354 Figure 10 - “Tre Occhi” masonry bridge (42.620668 N, 13.290176 E): (a) partial collapse of the South-East
 355 wing wall; (b) buttresses and partial collapse of the North-East wing wall; (c) roadway settlement and cracks
 356 above the East abutment; (d) pre-existing cracks on the roadway at the East embankment-abutment joint
 357 (from Google Maps); (e) cracks on the East arch intrados; (f) cracks on the East arch springing at the
 358 abutment; (g) cracks on the East arch springing at the pier.

359
 360



361 Figure 11 - “Cinque Occhi” masonry bridge (42.623178 N, 13.250428 E): (a) elevation view of the bridge;
 362 (b, c) partial collapse of masonry spandrel walls and loss of material at the arch springings, with evidence
 363 of previous retrofit and pre-existing damage; (d) collapse of a spandrel wall in proximity of the South
 364 abutment, with evidence of pre-existing damage to the reinforced concrete structure.
 365

366
 367 The masonry arrangement is similar to that of the “Tre Occhi” bridge, with original construction
 368 probably dating back to the beginning of the 20th century. The bridge was retrofitted with concrete
 369 jacketing of piers and arches intrados, while the original abutments were encased within
 370 reinforced concrete walls. Bridge maintenance was poor, leading to widespread pre-existing
 371 conditions (Figures 11b through 11d). In particular, a combination of damaged plaster and
 372 masonry with vegetation growth could be observed on the spandrels, while loss of material and
 373 exposure of steel reinforcement affected arches and abutments. The deck parapet appeared to be
 374 inadequate compared to current vehicle traffic.

375 The August 24 earthquake worsened the pre-existing damage pattern of the bridge, causing
 376 diffused out-of-plane failure of the spandrel walls (Figures 11a through 11d), due to low quality
 377 of the masonry and lack of ties. Localized losses of concrete cover and masonry units can be
 378 observed at the pier springing (Figures 9b and 11c): this can be associated with the development
 379 of horizontal hinges, as part of a longitudinal global mechanism facilitated by the pier slenderness
 380 and by the limited arch thickness-to-span ratio. Some damage was also observed on the spandrels
 381 close to the South abutment (Figure 11d). The bridge deck was not cracked along the roadway
 382 surface nor at the abutments: thus, structural safety was judged as not compromised by the
 383 earthquake and no traffic restrictions were applied.

384 Two arch bridges have been inspected along the “Trisungo-Tufo” road, in the locality of Tufo.
 385 The first one is a single-span arch stone masonry bridge (Figure 12), made with stone voussoirs
 386 of variable thickness. The bridge is oriented along the NEE-SWW direction, so it was subjected
 387 to higher PGA values along its longitudinal (partially inclined) direction. Cracks on the road
 388 surface over the abutments (Figure 12b) were caused by seismically induced infill settlements,
 389 related to displacements of the earth-retaining wing walls. Local cracking within load-bearing

390 masonry elements, and spalling of the external leaf of the abutments and of the vault intrados
391 (Figure 12c and 12d) were also observed.

392 Similar effects were observed for the second arch bridge along the “Trisungo-Tufo” route (Figure
393 13), a three-span arch structure made of stone masonry. The abutments and the piers are made of
394 stone masonry, with an external leaf made of larger blocks, and an internal infill made of smaller
395 stones, laid with mortar of poor characteristics and some loose material. This bridge has a curved
396 longitudinal axis, with the mid-span radius oriented along the East-West direction, which was
397 subjected to the highest PGA during all the main events.

398 In this case, out-of-plane overturning of the masonry parapets above the central span of the bridge
399 occurred (Figure 13a and 13b). Moreover, the bridge comprises an older part and an adjacent
400 relatively recent parallel extension; the latter behaved poorly during the earthquake, and
401 experienced spalling of the external masonry leaf in the North abutment (Figure 13c) and cracks
402 of one masonry pier (Figure 13d). These local effects were primarily due to the poor connection
403 between the stone blocks, which led to loss not only of single units, but also of entire portions of
404 the abutment walls. Horizontal cracks at the haunches can be compatible with an initial formation
405 of plastic hinges.

406 Both the bridges in the locality of Tufo showed evidence of damage on the road surface (Figure
407 12b), as a result of abutment infill settlements. These effects induced local officials to limit traffic
408 on the SP129 bridges.
409
410



411 Figure 12 - Single-span masonry bridge along the “Trisungo-Tufo” route (42.735981 N, 13.254862 E): (a)
412 view of the bridge; (b) damage on the road pavement; (c) spalling of the outer leaf of the abutment; (d)
413 spalling of the intrados of the vault.



414 Figure 13 - Three-span masonry bridge along the “Trisungo-Tufo” route (42.73538 N, 13.253655 E): (a, b)
 415 out-of-plane collapse of the parapet over the central arch; (c) spalling and (d) cracking of some masonry
 416 elements.

417

418

419 3.3 Reinforced concrete bridges

420 A number of RC bridges and viaducts were inspected in the aftermath of the earthquake. The
 421 structures inspected in the Amatrice area include the mixed RC/masonry “Rosa” bridge, in the
 422 town of Retrosi, and some viaducts of the SS685 and SS4 routes, with focus on the “Scandarello”
 423 viaduct. Overall, the outcome of this reconnaissance was satisfactory in that damage to the RC
 424 infrastructure network was found to be limited, confirming the impression that stiff (i.e. short
 425 period) rather than flexible bridges, were more heavily damaged during this event.

426 In general, although the extent of damage seen can vary from earthquake to earthquake, and even
 427 bridge to bridge, recurring damage patterns emerge when performing reconnaissance. While none
 428 of the bridges inspected raised major concerns, some of these types of damage were documented
 429 over the course of the inspection. Some examples are reported below, with reference to the
 430 structures assessed.

431 The “Rosa” bridge (Figure 14) is part of the local road that connects the SR577 route with the
 432 village of Retrosi, near Amatrice. The bridge consists of three tapered RC girders over five spans,
 433 with Gerber joints in the middle of the second and fourth spans. Four masonry piers with
 434 rectangular cross-section and rounded ends support the girders; the inner core of the piers is made
 435 of irregular cobbles and mortar, while the external leaf consists of clay brick masonry. The
 436 abutments also present an exterior clay brickwork. The girders are connected only by friction to
 437 piers and abutments, without any supporting or restraining device. The bridge longitudinal axis is
 438 oriented along the NNE-SSW direction, so the bridge was subjected to higher PGA values along
 439 its transverse direction.

440 As shown in Figure 14, the bridge was poorly maintained, with severe signs of degradation and
 441 pre-existing damage. In particular, the concrete girders showed widespread loss of concrete cover,
 442 steel reinforcement exposure and advanced corrosion (Figure 14a), especially at the Gerber beam
 443 joints (Figure 14b). Masonry piers showed degradation mainly related to erosion, loss of mortar
 444 joints, and vegetation growth (Figure 14c). In addition, the connections between parapets and
 445 deck were poorly designed: at some locations the parapet posts were torn from the deck (Figure
 446 14d), probably after vehicle collision, and were precariously suspended.
 447
 448
 449



450 Figure 14 - “Rosa” reinforced concrete and masonry bridge (42.623178 N, 13.250428 E): (a) elevation view
 451 of the North-East bay; (b) degradation of the reinforced concrete Gerber girders; (c) degradation of the
 452 masonry piers; (d) pre-existing damage of a parapet connection to the deck; (e, f) cracking and partial
 453 collapse of the exterior brick leaf of the piers.
 454
 455

456 After the August 24 event traffic restrictions were imposed on the “Rosa” bridge, with maximum
457 vehicle weight limited to 3.5 t; a Bailey bridge bypass was built for heavier traffic. The earthquake
458 caused local damage to the substructures (Figures 14e and 14f), with vertical cracks at the top of
459 the masonry piers starting from the external girder support and local collapse of the exterior brick
460 leaf. The poor quality of the masonry, combined with the weakening of the shear-friction transfer
461 between girders and piers due to material degradation and significant vertical earthquake
462 accelerations, appear to be the main causes of the observed damage.
463 The SS685 and the SS4 are two important state roads. These roads run predominantly East-West
464 and represent major connections between the two Italian coasts. In the surroundings of Amatrice,
465 a number of RC viaducts are part of this network, and were therefore inspected during the
466 reconnaissance trip. These viaducts were built in the 1970s and 1980s and were designed with
467 little to no attention for seismic details. The typical configuration of the viaducts assessed is
468 shown in Figure 15, with reference to SS685. These systems represent an interesting case study,
469 in that they are potentially susceptible to several of the structural issues discussed earlier.
470 However, little or no earthquake-induced damage was found in all inspected structures, as in the
471 case of the “Scandarello” viaduct along SS4 (Figure 16) between Amatrice and Accumoli.
472
473



(a)



(b)

474 Figure 15 - Typical configuration of the viaducts investigated along SS685: (a) location 42.752002 N,
475 13.267902 E; (b) location 42.756556 N, 13.277111 E.



Figure 16 - "Scandarello" reinforced concrete viaduct (42.643309 N, 13.266802 E; adapted from [29]).

476
 477
 478
 479
 480
 481
 482
 483
 484
 485
 486
 487
 488
 489
 490
 491
 492
 493
 494
 495
 496
 497
 498
 499
 500
 501
 502
 503
 504
 505

The structural systems are made of pre-cast (usually pre-stressed) concrete beams, connected to each other by a cast in place slab. The beams are simply supported atop unbolted laminated rubber bearings resting above large pier crossheads. It should be noted that these elements were not designed as seismic protection devices, but rather to resist gravity loads only and to accommodate small rotations and small displacements induced by thermal effects. Additionally, unbolted bearings rely on the friction between rubber pads and adjacent concrete to resist lateral loads: as discussed earlier, they tend to slide as soon as the applied lateral forces overcome their frictional strength.

It is evident that, in this configuration, the bridge deck is poorly restrained against differential movements with respect to the substructure (although shear keys are sometimes present at the bent caps, to prevent excessive transverse displacements). However, bearings appeared to be in good state in all inspected bridges and not to have displaced from their original position, as shown in Figure 17.

No relevant damage to the piers was observed in any of the inspected structures. Considering the average geometric properties of piers and superstructures of these viaducts, the period of vibration of the bridges can be estimated around 1.0 s. This can partially explain the limited damage observed, in that the peak horizontal acceleration demand induced by the seismic event was recorded for structural periods of about 0.25 s.

Even though no unseating was documented, some damage was observed due to excessive longitudinal displacements of the superstructure. These uncontrolled displacements often induced pounding effects which, in turn, caused damage (i.e. visible cracking and spalling) to elements such as bent-caps, transverse diaphragms, and abutments, as shown in Figure 18, sometimes worsening pre-existing damage due to material deterioration.



Figure 17 - Bearing pads of a viaduct investigated along SS685 (courtesy of Totaro).

506
 507
 508



(a)



(b)

Figure 18 - (a) Damage to bent cap and transverse diaphragms along SS685 (42.756556 N, 13.277111 E);
 (b) Damage to an abutment along SS4 (42.699565 N, 13.251978 E; courtesy of Totaro).

4 CASE STUDIES OF DAMAGED BRIDGES

4.1 Masonry bridges: simplified analysis of arch bridges

Among several possible analysis methods [30, 31, 32, 33], a simplified approach based on limit analysis was chosen in order to assess the values of spectral acceleration, a^*_0 , that trigger the longitudinal and transverse failure mechanisms discussed in Section 2.1. The procedure consists of an iterative application of the principle of virtual work (PVW) to estimate a load multiplier α_0 for the horizontal seismic load. The collapse-triggering acceleration, a^*_0 , can then be obtained by multiplying the seismic load multiplier, α_0 , by the gravity acceleration, g , and dividing it by the fraction of the structural mass participating in the kinematic mechanism, e^* , following the verification method proposed by the Italian Technical Standards for Constructions [34]:

$$a^*_0 = \frac{\alpha_0 \sum_1^n P_i}{M^*} = \frac{\alpha_0 g}{e^*} \quad (1)$$

$$e^* = \frac{g M^*}{\sum_1^n P_i} \quad (2)$$

The participating mass M^* can be calculated as:

$$M^* = \frac{\left(\sum_1^n \Delta x_{G_i} P_i \right)^2}{g \sum_1^n \Delta x_{G_i}^2 P_i} \quad (3)$$

where:

P_i is the weight of the generic i^{th} block and/or infill section of the kinematic mechanism;

n is the number of blocks and infill sections;

Δx_{G_i} is the virtual horizontal displacements of the application point G_i of each weight P_i .

Taking into account the main geometrical features of the arch bridges only, it is possible to obtain directly the collapse-triggering acceleration a^*_0 , as discussed by [16].

To carry out local strength verifications on the abutments (flexural collapse, AB_NM; and shear collapse, AB_S) and at the abutment-foundation interface (sliding, AB_SL; and overturning, AB_OV), linear static approaches were adopted for the analysis. The bending moment capacity of the abutment at the ultimate limit state, M_{Rd} , is calculated assuming a stress-block diagram in compression, neglecting the tensile strength of the masonry:

542
$$M_{Rd} = \left(\frac{l^2 t \sigma_0}{2} \right) \left(\frac{1 - \sigma_0}{0.85 f_d} \right) \quad (4)$$

543 where:

544 l is the length of the wall;

545 t is the thickness of the wall;

546 σ_0 is the mean compressive stress, referred to the gross cross-sectional area;

547 $f_d = f_k / \gamma_M$ is the design compressive strength of the masonry;

548 γ_M is taken as 1.0 in the assessment procedure.

549 The abutment shear strength, V_{Rd} , is evaluated as follows:

550
$$V_{Rd} = l' f_{vd} \quad (5)$$

551 where:

552 l' is the length of the portion of the wall subjected to compression

553 $f_{vd} = f_{vk} / \gamma_M$ is the design shear strength of the masonry;

554 γ_M is taken as 1.0 in the assessment procedure.

555 The structural safety checks for sliding and overturning at the abutment-foundation interface are

556 based on simple equilibrium. They take into account the unfavorable effects due to static and

557 dynamic actions of the soil acting on the abutment wall, the horizontal inertia due to the seismic

558 acceleration on the abutment/pier, and the horizontal component of the arch action. On the other

559 hand, the favorable effects of the structural dead loads and of the weight of the soil are accounted

560 for. For the sliding verification, the frictional strength, F_{Rd} , shall be evaluated as follows:

561
$$F_{Rd} = N_{sd} \tan \delta \quad (6)$$

562 where:

563 N_{sd} is the sum of the design values of the vertical actions;

564 δ is the friction angle on the foundation interface.

565 The strength values obtained from these capacity models can then be converted in terms of limit

566 spectral accelerations, for easier comparison to the values of collapse-triggering accelerations of

567 the main local and global mechanisms. Tables 2 through 5 list the limit acceleration values for

568 the examined masonry arch bridges, for the various possible mechanisms. The assumptions on

569 each bridge geometry and material properties are directly specified in the tables, where L

570 represents the arch span, H its rise, and s its structural thickness. The acceleration demand is given

571 by the PGA of the closer recording station, $a_g S$, divided by an assumed behavior factor $q = 2$.

572 The actual collapse mechanism of the “Tre Occhi” bridge was not correctly predicted with this

573 method, considering simple in plane or out-of-plane collapse mechanisms. The mechanism

574 predicted by the kinematic approach would be the transverse spandrel-wall overturning followed

575 by an arch-pier longitudinal failure. In reality, however, the SW-T mechanism was prevented by

576 transverse ties. Also the AP-L mechanism did not occur because a global transverse mechanism

577 (AP-T) was triggered earlier, including overturning of the abutment retaining buttresses,

578 transverse displacements of the East abutment and pier, and lateral shear deformations of the East

579 arch, with diagonal cracks in the barrel vault. Possible causes of this behavior can be attributed to

580 the quality of the masonry wing walls, to the curved geometry of the East abutment, and to pre-

581 existing damage to the abutment structure, which cannot be easily included in a kinematic

582 analysis. A more detailed FEM macro-model is presented in Section 4.2 to further investigate the

583 behavior of this structure, which cannot be effectively captured by the simplified approach.

584 The damage observed on the “Cinque Occhi” bridge included the collapse of the spandrel external

585 leaf, which is the most likely mechanism (SW-T) according to the simplified approach. In

586 addition, the formation of hinges, with horizontal cracks at the arch springings, can be related to

587 a longitudinal arch-pier mechanism (AP-L) that is also a possible mechanism according to the

588 simplified analysis.

589

590

591

592

593 Table 2 – Simplified analysis of “Tre Occhi” bridge.

Br1_Tre Occhi Bridge		
<i>Acceleration demand, $a_g S / q$</i>	<i>Long. [g]</i>	<i>Transv. [g]</i>
AMT (24/08/2016)	0.435	0.190
AMT (30/10/2016)	0.133	0.100
<i>Mechanism</i>	<i>Estimated limit acceleration [g]</i>	
AP-L	a^*_{01}	0.278
AP-T	a^*_{02}	0.382
SW-T	a^*_{03}	0.025
A_L	a^*_{04}	0.427
AB_SL	a^*_{06}	1.559
AB_OV	a^*_{07}	0.248
AB_NM	a^*_{08}	0.108
AB_S	a^*_{09}	0.511

Note: $q = 2$; modeling assumptions: $L = 12.00$ m, $H = 4.47$ m, $s/L = 0.08$, $f_d = 5.00$ MPa.



594
595
596

Table 3 – Simplified analysis of “Cinque Occhi” Bridge.

Br2_Cinque Occhi Bridge		
<i>Acceleration demand, $a_g S / q$</i>	<i>Long. [g]</i>	<i>Transv. [g]</i>
AMT (24/08/2016)	0.435	0.190
AMT (30/10/2016)	0.133	0.100
<i>Mechanism</i>	<i>Estimated limit acceleration [g]</i>	
AP-L	a^*_{01}	0.149
AP-T	a^*_{02}	0.444
SW-T	a^*_{03}	0.025
A-L	a^*_{04}	-
AB_SL	a^*_{06}	1.529
AB_OV	a^*_{07}	0.195
AB_NM	a^*_{08}	0.112
AB_S	a^*_{09}	0.4

Note: $q = 2$; modeling assumptions: $L = 9.50$ m, $H = 4.60$ m, $s/L = 0.07$, $f_d = 5.00$ MPa.



597
598
599
600
601
602
603
604
605
606
607
608
609
610

For the single-span “Trisungo-Tufo” bridge, the weaker mechanism according to the simplified approach would be the spandrel wall transverse failure (SW-T). The local masonry spalling at various heights on the vault intrados, although not clearly related to the formation of hinges, may be compatible with an initial triggering of a local arch mechanism in the longitudinal direction (A-L), which the second possible mechanism according to this procedure.

For the three-span “Trisungo-Tufo” bridge, the first expected mechanism, according to the simplified approach, is the spandrel wall transverse failure (SW-T): consistently, the actual and most severe damage was the out-of-plane overturning of the masonry parapets. Horizontal cracks at the southern haunches are also visible: this damage is compatible with the initial formation of hinges and the triggering of a global longitudinal mechanism (AP-L), which is the second most likely mechanism identified by the simplified analysis.

611 Table 4 – Simplified analysis of “Trisungo-Tufo” single-span Bridge.

Br4_Trisungo-Tufo Bridge, single span		
<i>Acceleration demand, $a_g S / q$</i>	<i>Long. [g]</i>	<i>Transv. [g]</i>
AMT (24/08/2016)	0.435	0.190
T1214 (30/10/2016)	0.302	0.211
<i>Mechanism</i>	<i>Estimated limit acceleration [g]</i>	
AP-L	a^{*01}	-
AP-T	a^{*02}	-
SW-T	a^{*03}	0.025
A-L	a^{*04}	0.367
AB_SL	a^{*06}	1.560
AB_OV	a^{*07}	1.560
AB_NM	a^{*08}	1.214
AB_S	a^{*09}	1.530

Note: $q = 2$; modeling assumptions: $L = 6.00$ m, $H = 3.00$ m, $s/L = 0.13$, $f_d = 5.00$ MPa.



612
613
614

Table 5 – Simplified analysis of “Trisungo-Tufo” three span bridge.

Br5_Trisungo-Tufo Bridge, three spans		
<i>Acceleration demand, $a_g S / q$</i>	<i>Long. [g]</i>	<i>Transv. [g]</i>
AMT (24/08/2016)	0.190	0.435
T1214 (30/10/2016)	0.211	0.302
<i>Mechanism</i>	<i>Estimated limit acceleration [g]</i>	
AP-L	a^{*01}	0.287
AP-T	a^{*02}	0.611
SW-T	a^{*03}	0.050
A-L	a^{*04}	-
AB_SL	a^{*06}	1.560
AB_OV	a^{*07}	1.211
AB_NM	a^{*08}	0.362
AB_S	a^{*09}	1.200


Note: $q = 2$; modeling assumptions: $L = 7.00$ m, $H = 2.50$ m, $s/L = 0.36$, $f_d = 5.00$ MPa.




615
616
617
618
619
620
621
622
623
624

4.2 Masonry bridges: non-linear static finite element analysis

Further analyses have been carried out on a model of the “Tre Occhi” bridge to understand the actual transverse collapse mechanism, with the overturning of the abutment retaining buttresses, and diffused cracking of the East abutment, pier and span, as represented in Figure 19.



(a)



(b)

625 Figure 19 - Actual crack pattern of “Tre Occhi” bridge: views from (a) North and (b) South.

626

627

628 A macro-model consisting of 3D finite elements was developed using the FEM software TNO
 629 DIANA (Figure 20). The fill is included in the model employing elements with very low stiffness,
 630 in order to consider their contribution only to the translational mass, with a unit weight $\gamma = 18$
 631 kN/m^3 . Adequate boundary conditions are introduced to reproduce pier and abutment foundations.
 632 The “total strain crack” model is adopted to simulate the material behavior including softening,
 633 with parabolic behavior in compression and linear in tension. Masonry mechanical properties
 634 (elastic modulus E , Poisson’s ratio ν , compressive and tensile strengths f_c and f_t , and fracture
 635 energy parameters G_c and G_t) are summarized in Table 6.

636 On the basis of this preliminary model, non-linear static analyses were carried out considering
 637 separately the longitudinal and transverse direction. Capacity curves obtained in both cases are
 638 shown in Figure 21. The control point was chosen at the top of the central arch. The idealized
 639 elastic-perfectly plastic force-displacement relationship was determined according to the latest
 640 version of the Italian Technical Standards for Constructions [34].

641


642

643


Table 6 - Masonry properties.

γ [kN/m ³]	E [MPa]	ν [-]	f_c [MPa]	f_t [MPa]	G_c [N/mm]	G_t [N/mm]
18.00	900.00	0.20	5.00	0.20	5.00	0.0025

644




645
646 Figure 20 - "Tre Occhi" bridge 3D finite element macro-model.
647
648



649 Figure 21 - Capacity curve for (a) longitudinal and (b) transverse action.
650

651
652 The yielding acceleration of the bilinear relationship in the longitudinal direction is 0.275 g, which
653 is consistent with the value of 0.278 g calculated according to the simplified method in Section
654 4.1, for the AP-L mechanism. In the transversal direction, however, the yielding acceleration is
655 only 0.121 g, which is less than one third of the simplified result. This is consistent with what
656 happened in reality, as a global transverse mechanism occurred and cracks related to longitudinal
657 mechanisms have not been observed. Figure 22 shows the crack pattern obtained with non-linear
658 static analysis in the transverse direction. It can be seen that the numerical crack pattern is fully
659 compatible with the one observed after the earthquake, as shown in Figure 19.
660

661



662 Figure 22 - Crack pattern predicted by the pushover analysis in the transverse direction.
663

664
665
666

4.3 Reinforced concrete bridges: linear static finite element analysis

667 The “Scandarello” viaduct along SS4 (Figure 16) was chosen as a case study and analyzed in
668 more depth in this section, to provide deeper insight into the performance of the inspected RC
669 bridges. More specifically, a linear 3D finite element model was used to obtain the dynamic
670 properties of the bridge, and a response spectrum analysis was performed to obtain the seismic
671 demand on the various structural elements, based on the spectrum from the August 24, 2016 event
672 recorded in Amatrice.

673 The viaduct, presumably constructed in the late 1980s, is located in the municipality of Amatrice,
674 in the Lazio region. It has a total length of 109 m, with five spans approximately 22-m long. Each
675 span comprises nine precast, pre-stressed concrete beams, connected transversally via four RC
676 diaphragms. The longitudinal beams are simply supported atop unbolted laminated rubber
677 bearings, which sit on four large RC cap beams and two abutments. The cast in place RC deck is
678 11.5-m wide and is separated into five segments by means of six expansion joints.

679 Each of the four bents consists of two cast-in-place RC circular hollow-core columns, connected
680 transversally at their top by a RC cap beam. The external diameter of all columns is 2.0 m at their
681 base, while the columns height varies from 12 m to 13.7 m. Limited information is available on
682 the cast-in-place RC abutments and on the pier foundations.

683 Except for this general information, some relevant data pertinent to the various structural elements
684 are missing. Therefore, a number of geometric and material assumptions were necessary before
685 the numerical model could be built:

686

687 • Columns: both external and internal diameter of all columns were assumed to be constant
688 and equal to 2.0 m and 1.4 m, respectively;

689 • Cap beams: the RC cap beams were assumed to be 11.5-m long, with a 2.2-m x 1.5-m
690 cross-section;

691 • Transverse diaphragms: the RC transverse diaphragms were assumed to be 10.5-m long,
692 with a 0.25-m x 0.8-m cross section;

693 • Longitudinal beams: the 22-m long longitudinal beams were assigned the cross section
694 properties of a “Type 60” State of Washington Bridge Girder (similar to a “Type III”
695 AASHTO Bridge Girder), which is ideal for simply supported spans of about 20 m and
696 is consistent with the cross section shape and dimensions that could be obtained from the
697 available photographs of the case study bridge;

698 • Rubber bearings: the rubber bearings were assumed to be 0.46-m x 0.15-m pads, with a
699 thickness of 0.04 m;

700 • Deck slab: the deck slab was assumed to be 0.25-m thick;


701 • Materials: (i) concrete was assigned an elastic modulus of 30,000 MPa, a shear modulus
702 of 12,500 MPa and a unit weight of 25 kN/m³; (ii) rubber was assigned an elastic modulus
703 of 2.3 MPa and a shear modulus of 1.0 MPa.

704


705 The 3D linear elastic model of the viaduct, shown in Figure 23a, was built using the commercial
706 software SAP2000 [35]. All beams and columns were modeled using elastic frame elements.
707 These elements account for axial deformation, torsion, biaxial bending, and biaxial shear, as
708 discussed by [36]. The pier foundations were assumed to provide full fixity at the base of the
709 columns and were modeled accordingly. The abutments were modeled as simple supports instead.
710 The deck slab provides in-plane diaphragm action with respect to longitudinal and transverse
711 lateral loads, while offering limited contribution to resisting out-of-plane actions; for this reason,
712 membrane elements were used to model the slab, as they transfer only in-plane forces. Each span
713 was assigned an individual rigid diaphragm membrane [37], allowing relative motion between
714 adjacent spans through expansion joints, especially in the transverse direction.

715

716



(a)



(b)

Figure 23 - “Scandarello” viaduct analysis: (a) 3D finite element model; (b) input response spectrum.

717
718

719
720

721
722
723

724 Bearings were introduced in the model by releasing the rotational degrees of freedom and by
725 assigning partial fixity springs in the x, y and z directions, at the end of each longitudinal beam.
726 The lateral stiffness (x and y direction) provided by the bearings was computed as GA/h , while
727 the vertical stiffness (z direction) was computed as EA/h , where G and E are the shear modulus
728 and the modulus of elasticity of rubber, A is the cross section of the bearing pads and h is the
729 thickness of the bearings.

730 A weight per unit volume was assigned to the material specified for each element. Therefore,
731 masses and weights were automatically accounted for in the model by the software.

732 The most relevant information extracted from the modal analysis of the bridge are its fundamental
733 periods in the two major directions. The longitudinal fundamental period was estimated at 0.755
734 s, while the transverse fundamental period at 0.683 s. The seismic input employed to perform the
735 response spectrum analysis was the acceleration response spectrum associated with the
736 accelerograms recorded at the Amatrice Station (42.6325 N, 13.2866 E) on August 24, 2016,
737 shown in Figure 23b. The two fundamental periods correspond to spectral accelerations of 0.363g
738 and 0.403g in the longitudinal and transverse directions, respectively.

739 Previous earthquakes and simulations have shown that the seismic vulnerability of this kind of
740 bridges is mainly related to the behavior of piers, bearings, and joints, while the response of the
741 superstructure is of minor concern [37]. More specifically, columns may develop a ductile
742 mechanism due to the formation of flexural plastic hinges, or a brittle flexural or shear failure,
743 depending on the detailing quality. Thin unbolted rubber bearings may experience a slipping
744 failure at the concrete-neoprene interface, which may result in large residual displacements,
745 damage to bearings through tearing of rubber, unseating problems, and damage to beams and
746 abutments due to pounding. Therefore, processing of the results of the response spectrum analysis
747 was focused on the force and/or displacement demand on these elements.

748

749 Table 7 - Response spectrum analysis key results for the “Scandarello” viaduct.

Structural Element	Transverse direction			Longitudinal direction			
	<i>M</i> [kNm]	<i>V</i> [kN]	δ [m]	<i>M</i> [kNm]	<i>V</i> [kN]	δ [m]	
Column	Base	4649	1357	-	8375	1223	-
	Top	4649	1357	-	0	1223	-
Bearing	-	75	0.043	-	68	0.039	-

750

751

752

753

754

755

756

757

758

A single bent was analyzed under the longitudinal and lateral forces calculated from the spectral accelerations determined above. The entire translational mass tributary to the bent was considered effective as a first-mode mass in each direction. The columns were assumed to act as cantilevers in the longitudinal direction, while an inflection point was located at mid-height for response in the transverse direction. The key results of the analysis, for the most critical elements, are summarized in Table 7.

759

760

761

762

763

764

765

It is observed that the ground motion induces a shear force demand on columns and bearings about 10% higher when it acts in the transverse direction. This is due to the stiffer transverse response of the system, which attracts higher acceleration resulting in higher base-shear demand. However, it can be seen that the highest flexural demand is recorded at the base of the columns when the earthquake acts in the longitudinal direction. This is consistent with the boundary conditions of the piers, which rely on a frame mechanism in the transverse direction, and work as simple cantilevers with respect to longitudinal actions.

766

767

768

769

770

771

772

773

Because of the columns high slenderness, with an aspect ratio of about 6 when acting as cantilevers, it is reasonable to expect that a shear failure would be preceded by a flexural mechanism under longitudinal excitation. However, when the earthquake acts in the transverse direction, the column shear span is nearly halved, resulting in an aspect ratio of about 3 and in higher sensitivity to shear failure. To this end, the main concerns related to the performance of the columns of this bridge may be associated with their ability to sustain inelastic flexural deformations and to develop ductile plastic hinges in any direction, but also to resist high shear demands when subjected to transverse earthquake action.

774

775

776

777

778

779

780

Geometric data and material properties to evaluate precisely the strength and deformation capacity of the columns are not available. However, it is possible to estimate their flexural strength assuming an effective moment of inertia equal to half the gross-concrete section one, $I_{eff} = 0.5 \cdot I_g = 0.298 \text{ m}^4$, a reinforcement yield strain $\varepsilon_y = 0.001$ (corresponding to a lower-bound yield stress of 215 MPa [38] and an elastic modulus of 210000 MPa), and a concrete elastic modulus $E_c = 30000 \text{ MPa}$. Given the column outer diameter $D = 2 \text{ m}$, the nominal yield curvature can be approximated as [39]:

781

$$\phi_y \approx 2.25 \frac{\varepsilon_y}{D} = 1.125 \cdot 10^{-3} \text{ rad/m} \quad (7)$$

782

The flexural strength is then estimated as:

783

$$M_{Rd} \approx E_c I_{eff} \phi_y = 10100 \text{ kNm} \quad (8)$$

784

785

786

787

which is larger than the elastic moment demands in both directions presented in Table 7. Similarly, the column shear strength can be roughly approximated assuming an effective shear area $A_{v,eff} = 0.8 \cdot A_g = 1.28 \text{ m}^2$ [37], a concrete compressive strength $f_{ck} = 30 \text{ MPa}$, and a reinforced concrete shear strength (including concrete and stirrup contributions):

788

$$f_{vd} \approx 0.33 \sqrt{f_{ck}} / \gamma_M = 1.81 \text{ MPa} \quad (9)$$

789

790

where the partial coefficient $\gamma_M = 1.0$ for assessment. This results in the estimated shear strength:

$$V_{Rd} \approx f_{vd} A_{v,eff} = 2310 \text{ kN} \quad (10)$$

791

792

which also exceeds the computed shear demands. These approximate strength verifications are supported by the fact that no damage to the columns was documented.

793 At the bearing level, while unseating problems are most likely not to be expected, excessive
794 displacements may result in pounding issues and in consequent damage of elements such as
795 beams, diaphragms, deck slab, and abutments. At the same time, the displacement of the bearings
796 may be of permanent nature, if the frictional strength of the elements is overcome by the lateral
797 forces experienced during the seismic event and a slipping failure mode occurs. It is estimated
798 that each bearing of the “Scandarello” viaduct carries an average weight of 187 kN. Assuming a
799 rubber-to-concrete friction coefficient equal to 0.7 [40], the frictional strength of each bearing can
800 be estimated as 131 kN, which is clearly higher than the demand from the analysis (75 kN). The
801 maximum estimated bearing displacement was 0.043 m (Table 7), which corresponds to a shear
802 strain of roughly 100%; this is lower than the deformation capacity of such bearings, since they
803 can tolerate a shear strain of 150% without any sign of distress, while failure is typically
804 associated to a shear strain of 300% [41]. Moreover, expansion joints allowed longitudinal
805 displacements of at least 0.05 m before pounding, which are also larger than the calculated
806 demand. These results provide numerical evidence in support of the reconnaissance observations,
807 as no bearing slipping or pounding was observed.
808 It should be noted that the “Scandarello” viaduct did not experience any observable damage
809 during the Central Italy Earthquake sequence and that the verifiable results of the analysis
810 conducted are reasonably consistent with this field observation. However the results of this
811 analysis can be considered of qualitative nature only, since accurate information about geometry
812 and materials was missing and several assumptions were made to create the numerical model.
813 Future studies supported by specific data may allow to estimate the capacity curves of the
814 reinforced concrete elements and to perform a detailed non-linear analysis of the viaduct.

815
816

817 5 CONCLUSIVE REMARKS ABOUT LESSONS LEARNED FROM THE 2016 CENTRAL 818 ITALY EARTHQUAKE FOR BRIDGES

819
820

820 *5.1 Masonry bridges*

821 The local road network in the surroundings of Amatrice was severely affected by damage to
822 masonry bridges after the August 24, 2016 earthquake, causing traffic disruptions and requiring
823 temporary replacements in two cases to restore emergency services. Considering the overall
824 performance of masonry bridges in the aftermath of the 2016 Central Italy earthquake sequence,
825 some general conclusions can be drawn:

826

- 827 • Masonry bridges in the area confirmed to possess a robust structural behavior, as overall
828 structural safety was maintained by all examined structures.
- 829 • Local damage, disaggregation, and loss of masonry portions were observed in almost all
830 of the structures, especially in spandrels, abutments, and piers. This damage was mainly
831 due to the poor quality of materials and stone masonry arrangement, to the lack of
832 maintenance, and to the deterioration of the structural elements.
- 833 • Out-of-plane overturning of the spandrel walls (SW-T) represents one of the most
834 common collapse mechanism in all the analyzed bridges. This did not generally impair
835 the bridge structural safety, but in certain cases compromised its functionality and
836 required traffic limitations. The addition of transverse steel tie-rods connecting the lateral
837 spandrels proved its effectiveness in preventing this mechanism, as observed in the “Tre
838 Occhi” bridge.
- 839 • The three bridges that were closed to traffic (“Tre Occhi” and both “Trisungo-Tufo”
840 bridges) suffered damage to the abutment earth-retaining wing walls. Infill pressure and
841 buttress ineffectiveness led to loss of support, that in the case of the “Tre Occhi” bridge
842 triggered a global transverse mechanism (AP-T). Failure of these elements, which are
843 often considered secondary for assessment purposes, can compromise not only the
844 functionality, but also the overall stability of a bridge.

845 • Despite the lack of certain geometrical and mechanical data, the proposed simplified
846 analyses could in general correctly predict the main failure mechanisms of the examined
847 bridges. More refined analyses or a refinement of the proposed method are required to
848 investigate the behavior of bridges characterized by special geometries or by the
849 activation of mechanisms related to soil-structure interaction, as in the case of the “Tre
850 Occhi” bridge.

851

852 *5.2 Reinforced concrete bridges*

853 Earthquake-induced damage to the RC infrastructure network was found to be limited, while
854 extensive pre-existing conditions due to lack of maintenance and aging effects were reported. The
855 reconnaissance activity can be summarized in the following conclusions:

856

857 • No serious damage to structural elements could be detected. Footings, columns,
858 abutments, bearings, and superstructure generally appeared sound, except for pre-existing
859 conditions related to poor maintenance.

860 • In some instances, minor damage caused by differential movements and excessive
861 displacements of the superstructure was observed. These movements may have worsened
862 the pre-existing conditions of some elements, for example causing spalling of previously
863 deteriorated concrete.

864 • Some non-structural damage, for example to the bridge barriers, was also observed. In
865 some cases, as for the barriers of the “Rosa” bridge near Amatrice, pre-existing non-
866 structural damage may have been amplified by the earthquake shocks.

867 • A linear-elastic analysis was carried out on the “Scandarello” viaduct, a case-study
868 representative of local reinforced concrete infrastructures. Despite the lack of information
869 about geometric and mechanical properties, these preliminary results were aligned with
870 the observed behavior, in that column and bearing capacities resulted larger than the
871 estimated demands.

872

873

874

875 REFERENCES

876

877 [1] ReLUIIS-INGV Workgroup (2016). Preliminary study on strong motion data of the 2016 central Italy
878 seismic sequence V6. Available at <http://www.reluis.it>. Accessed on 12/07/2018.

879

880 [2] Stewart, J.P., Lanzo, G., Aversa, S., Bozzoni, F., Chiabrande, F., Grasso, N., Di Pietra, V., Dashti, S.,
881 Di Sarno, L., Durante, M.G., Foti, S., Franke, K., Reimschiessel, B., Galadini, F., Falcucci, E., Gori, S.,
882 Kayen, R.E., Mylonakis, G., Katsiveli, E., Pagliaroli, A., Giallini, S., Scasserra, G., Santucci de Magistris,
883 F., Castiglia, M., Sica, S., Simonelli, A.L., Penna, A., Mucciacciaro, M., Silvestri, F., D'Onofrio, A.,
884 Chiaradonna, A., De Silva, F., Tommasi, P., Zimmaro, P. (2016). Engineering Reconnaissance Following
885 the 2016 M6.0 Central Italy Earthquake: Ver 1. Report No. GEER-050A. Geotechnical Extreme Event
886 Reconnaissance Association, University of California, Berkeley, CA, USA. DOI: 10.18118/G65K5W.

887

888 [3] Pinto, P.E., Mancini, G. (2009). Seismic assessment and retrofit of existing bridges. In: Manfredi, G.,
889 Dolce, M. (eds), The State of Earthquake Engineering Research in Italy: the ReLUIIS-DPC 2005-2008
890 Project, pp. 111-140. Doppiavoce, Napoli, Italy. ISBN-13: 9788889972427.

891

892 [4] De Risi, R., Di Sarno, L. and Paolacci, F. (2017). Probabilistic seismic performance assessment of an
893 existing RC bridge with portal-frame piers designed for gravity loads only. *Engineering Structures*,
894 145:348-367. DOI: 10.1016/j.engstruct.2017.04.053.

895

896 [5] Abbiati, G., Bursi, O.S., Caperan, P., Di Sarno, L., Molina, F.J., Paolacci, F., Pegon, P. (2015). Hybrid
897 simulation of a multi-span RC viaduct with plain bars and sliding bearings. *Earthquake Engineering and*
898 *Structural Dynamics*, 44(13):2221-2240. DOI: 10.1002/eqe.2580.

899

900 [6] Di Sarno, L., Del Vecchio, C., Maddaloni, G., Prota, A. (2017). Experimental response of an existing
901 RC bridge with smooth bars and preliminary numerical simulations. *Engineering Structures*, 136:355-368.
902 DOI: 10.1016/j.engstruct.2017.01.052.

903

904 [7] Kappos, A.J., Saiidi, M.S., Aydinoglu, M.N., Isaković, T. (Eds.) (2012). *Seismic Design and*
905 *Assessment of Bridges - Inelastic Methods of Analysis and Case Studies*. Springer, Netherlands. ISBN-13:
906 978-94-007-3943-7. DOI: 10.1007/978-94-007-3943-7.

907

908 [8] Del Vecchio, C., Kwon, O.S., Di Sarno, L., Prota, A. (2015). Accuracy of nonlinear static procedures
909 for the seismic assessment of shear critical structures. *Earthquake Engineering and Structural Dynamics*,
910 44(10):1581-1600. DOI: 10.1002/eqe.2540.

911

912 [9] Di Sarno, L. (2013). Effects of multiple earthquakes on inelastic structural response. *Engineering*
913 *Structures*, 56:673-681. DOI: 10.1016/j.engstruct.2013.05.041.

914

915 [10] Heyman, J. (1966). The stone skeleton. *International Journal of Solids and Structures*, 2(2):249-279.
916 DOI: 10.1016/0020-7683(66)90018-7.

917

918 [11] Berger, E., Studer, J. (1981). Southern Italy Earthquake, November 23, 1980. Reconnaissance
919 Summary. Earthquake Engineering Research Institute, Oakland, CA, USA.

920

921 [12] Han, Q., Du, X.L., Liu, J.B., Li, Z.X., Li, L.Y., Zhao J.F. (2009). Seismic damage of highway bridges
922 during the 2008 Wenchuan earthquake. *Earthquake Engineering and Engineering Vibration*, 8(2):263-273.
923 DOI: 10.1007/s11803-009-8162-0.

924

925 [13] Kawashima, K., Takahashi, Y., Ge, H., Wu, Z., Zhang, J. (2009). Reconnaissance report on damage
926 of bridges in 2008 Wenchuan, China, earthquake. *Journal of Earthquake Engineering*, 13(7):965-996. DOI:
927 10.1080/13632460902859169.

928

929 [14] Earthquake Engineering Research Institute (2009). The Mw 6.3 Abruzzo, Italy, Earthquake of April
930 6, 2009. Available at https://www.eeri.org/site/images/eeri_newsletter/2009_pdf/LAquila-eq-report.pdf.
931 Accessed on 12/07/2018.

932

- 933 [15] Clemente, P. (1998). Introduction to dynamics of stone arches. *Earthquake Engineering and Structural*
934 *Dynamics*, 27(5):513-522. DOI: 10.1002/(SICI)1096-9845(199805)27:5<513::AID-EQE740>3.0.CO;2-O.
935
- 936 [16] da Porto F., Tecchio G., Zampieri P., Modena C., Prota A. (2016). Simplified seismic assessment of
937 railway masonry arch bridges by limit analysis. *Structure and Infrastructure Engineering*, 12(5):567-591.
938 DOI: 10.1080/15732479.2015.1031141.
939
- 940 [17] Tecchio, G., Donà, M., da Porto, F., (2016). Seismic fragility curves of as-built single-span masonry
941 arch bridges. *Bulletin of Earthquake Engineering*, 14(11):3099-3124. DOI: 10.1007/s10518-016-9931-6.
942
- 943 [18] De Luca, A., Giordano, A., Mele, E. (2004). A simplified procedure for assessing the seismic capacity
944 of masonry arches. *Engineering Structures*, 26(13):1915-1929. DOI: 10.1016/j.engstruct.2004.07.003.
945
- 946 [19] Resemini, S., Lagomarsino, S. (2004). Vulnerabilità sismica dei ponti ferroviari ad arco in muratura.
947 Proc. of the 11th ANIDIS Conference “L’Ingegneria Sismica in Italia”, pp. 25-29, Genova, Italy (in Italian).
948
- 949 [20] Singh, M.P., Khaleghi, B., Saraf, V.K., Jain, S.K., Norris, G (2002). Roads and Bridges. In: Jain, S.K.,
950 Lettis, W.R., Murty, C.V.R., Bardet, J.P. (eds), Bhuj, India Earthquake of January 26, 2001,
951 Reconnaissance Report, pp. 363-379. *Earthquake Spectra*, supplement A to vol. 18. Earthquake
952 Engineering Research Institute, Oakland, CA, USA.
953
- 954 [21] Cowan, M. (2011). R132 Kahu Road East-Bridge Status Summary Report. Available at
955 <http://resources.ccc.govt.nz/files/R132KahuRdEastBridge.pdf>. Accessed on 12/01/2014.
956
- 957 [22] Zampieri, P., Tecchio, G., da Porto, F., Modena, C. (2015). Limit analysis of transverse seismic
958 capacity of multi-span masonry arch bridges. *Bulletin of Earthquake Engineering*, 13(5):1557-1579. DOI:
959 10.1007/s10518-014-9664-3.
960
- 961 [23] Grossi, P., Williams, C., Cabrera, C., Tabucchi, T., Sarabandi, P., Rodriguez, A., Aslani H., Rahnama,
962 M. (2011). The 2010 Maule, Chile earthquake: lessons and future challenges. *Risk Management Solutions*,
963 Inc., Newark, CA, USA.
964
- 965 [24] Modena, C., Tecchio, G., Pellegrino, C., da Porto, F., Donà, M., Zampieri, P., Zanini, M. A. (2015).
966 Reinforced concrete and masonry arch bridges in seismic areas: typical deficiencies and retrofitting
967 strategies. *Structure and Infrastructure Engineering*, 11(4):415-442. DOI: 10.1080/15732479.2014.951859.
968
- 969 [25] Wang, P., Han, Q., Du, X. (2014). Seismic performance of circular RC bridge columns with flexure-
970 torsion interaction. *Soil Dynamics and Earthquake Engineering*, 66:13-30. DOI:
971 10.1016/j.soildyn.2014.06.028.
972
- 973 [26] Kawashima, K., Aydan, O., Aoki, T., Kisimoto, I., Konagai, K., Matsui, T., Sakuta, J., Takahashi, N.,
974 Teodori, S., Yashima, A. (2010). Reconnaissance investigation on the damage of the 2009 L’Aquila,
975 Central Italy earthquake. *Journal of Earthquake Engineering*, 14(6):817-841. DOI:
976 10.1080/13632460903584055.
977
- 978 [27] Ioannou, I., Borg, R., Novelli, V., Melo, J., Alexander, D., Kongar, I., Verrucci, E., Cahill, B., Rossetto,
979 T. (2012). The 29th May 2012 Emilia Romagna Earthquake. EPICentre Field Observation Report No.EPI-
980 FO-290512. UCL EPICentre, University College London, London, UK.
981
- 982 [28] Luzi, L., Puglia, R., Russo, E. & ORFEUS WG5 (2016). Engineering Strong Motion Database, version
983 1.0. National Institute for Geophysics and Volcanology, Observatories & Research Facilities for European
984 Seismology, Italy. DOI: 10.13127/ESM".
985
- 986 [29] ANAS S.p.A., Condirezione Generale Tecnica Unità Ricerca e Innovazione (2010). Executive
987 Technical Report, 04.11.2010 (in Italian).
988
- 989 [30] Brencich, A., De Francesco, U. (2004a). Assessment of multispan masonry arch bridges. I: Simplified
990 approach. *Journal of Bridge Engineering*, 9(6):582-590. DOI: 10.1061/(ASCE)1084-0702(2004)9:6(582).
991

- 992 [31] Brencich, A., De Francesco, U. (2004b). Assessment of multispan masonry arch bridges. II: Examples
993 and applications. *Journal of Bridge Engineering*, 9(6):591-598. DOI: 10.1061/(ASCE)1084-
994 0702(2004)9:6(591).
995
- 996 [32] Galasco, A., Lagomarsino, S., Penna, A., Resemini, S. (2004). Non-linear seismic analysis of masonry
997 structures. *Proc. of the 13th World Conference on Earthquake Engineering*, Vancouver, Canada.
998
- 999 [33] Rota, M., Pecker, A., Bolognini, D., Pinho, R. (2005). A methodology for seismic vulnerability of
1000 masonry arch bridge walls. *Journal of Earthquake Engineering*, 9(sup2):331-353. DOI:
1001 10.1142/S1363246905002432.
1002
- 1003 [34] Ministry of Infrastructure (2008). *Technical Standards for Constructions (DM 14.01.2008)*. Rome,
1004 Italy (in Italian).
1005
- 1006 [35] Computers and Structures, Inc. (2016). *CSI Analysis Reference Manual For SAP2000, ETABS, SAFE*
1007 *and CSiBridge*. ISO# GEN062708M1 Rev. 15. Berkeley, CA, USA.
1008
- 1009 [36] Bathe, K.J., Wilson, E.L. (1976). *Numerical Methods in Finite Element Analysis*. Prentice-Hall,
1010 Englewood Cliff, NJ, USA. ISBN-10: 0136271901 / ISBN-13: 9780136271901.
1011
- 1012 [37] Priestley, M.J.N., Seible, F., Calvi, G.M. (1996). *Seismic Design and Retrofit of Bridges*. John Wiley
1013 and Sons, New York, NY, USA. ISBN-10: 047157998X / ISBN-13: 9780471579984.
1014
- 1015 [38] Ministry of Public Works (1992). *Technical Standards for the Construction of Reinforced and*
1016 *Prestressed Concrete and Steel Structures (DM 14.02.1992)*. Rome, Italy (in Italian).
1017
- 1018 [39] Priestley, M.J.N., Calvi, G.M., Kowalsky, M.J. (2007). *Displacement-Based Seismic Design of*
1019 *Structures*. IUSS Press, Pavia, Italy. ISBN-10: 8861980007 / ISBN-13: 9788861980006.
1020
- 1021 [40] Cardone, D., Perrone, G., Sofia, S. (2011). A performance-based adaptive methodology for the seismic
1022 evaluation of multi-span simply supported deck bridges. *Bulletin Earthquake Engineering*, 9(5):1463-1498.
1023 DOI: 10.1007/s10518-011-9260-8.
1024
- 1025 [41] Cardone, D. (2014). Displacement limits and performance displacement profiles in support of direct
1026 displacement-based seismic assessment of bridges. *Earthquake Engineering and Structural Dynamics*,
1027 43(8):1239-1263. DOI: 10.1002/eqe.2396.
1028