The HKU Scholars Hub The University of Hong Kong 香港大學學術庫



Title	A review of landslide problems and mitigation measures in Chongqing and Hong Kong: Similarities and differences
Author(s)	Kwong, AKL; Wang, M; Lee, CF; Law, KT
Citation	Engineering Geology, 2004, v. 76 n. 1-2, p. 27-39
Issued Date	2004
URL	http://hdl.handle.net/10722/48527
Rights	Creative Commons: Attribution 3.0 Hong Kong License

1

 $\mathbf{2}$ 

3

4

 $\frac{5}{6}$ 

7

 $\frac{8}{9}$ 

10 11 Available online at www.sciencedirect.com



Engineering Geology xx (2004) xxx-xxx



version

www.elsevier.com/locate/enggeo

### A review of landslide problem and mitigation measures in Chongqing (IRF) and Hong Kong (TRF) Similarities and differences

A.K.L. Kwong<sup>a,\*</sup>, M. Wang<sup>b</sup>, C.F. Lee<sup>a</sup>, K.T. Law<sup>c</sup>

<sup>a</sup>Department of Civil Engineering, University of Hong Kong, Pokfulam Road, Hong Kong, PR China <sup>b</sup>Chongqing Jianzhu University (重庆建筑大学), Chongqing, PR China <sup>c</sup>Department of Civil and Environmental Engineering, Carleton University, Ottawa, Canada

Received 9 October 2002; accepted 7 June 2004

#### 12 Abstract

The cities of Chongqing and Hong Kong are both located at hilly areas which are highly populated, with buildings and major highways located very close to slopes and earth-retaining structures. Landslides and rockfalls are very common in both cities, and large expenditures are being incurred by both Governments on the investigation, design and implementation of mitigation and preventive measures to reduce the likelihood of the loss of life and economic losses due to landslides.

As a result of the collaborative studies and technical exchange programs between the University of Hong Kong and the Chongqing Jianzhu University (重庆建筑大学), a more in-depth understanding of the landslide problem, methodology and mitigation measures in Chongqing and Hong Kong was achieved. The objective of this paper is therefore to: (1) highlight the similarities and differences of the slope safety problems which these cities have been facing and (2) present and compare the key technical approaches these two cities have been undertaken to reduce the risk of landslide and rockfalls, so that both cities could benefit from the experience and lesson learnt.

Based on the review of literature and published case records, it is concluded that the city of Chongqing has to deal with natural hazards such as earthquake, river erosion and flooding more than that in Hong Kong, but both cities have been applying practical and latest technology to mitigating the landslide problem.

It is recommended that the city of Chongqing should consider establishing a sustainable long-term landslide management
 plan and that the landslide prevention system being used in Hong Kong could be a good reference starting point.
 © 2004 Elsevier B.V. All rights reserved.

29

30 Keywords: Landslides; Natural hazard; Risk, mitigation measures; Monitoring; Management plan; Chongqing; Hong Kong

#### 31

\* Corresponding author. Tel.: +852-2859-2673; fax: +852-2559-5337.

*E-mail addresses:* kwongakl@hkucc.hku.hk (A.K.L. Kwong), wangmin@sohu.com (M. Wang), leecf@hkucc.hku.hk (C.F. Lee), tlaw@ccs.carleton.ca (K.T. Law).

#### 1. Introduction

<u>33</u>

The cities of Chongqing and Hong Kong are both 34 located at hilly areas that are highly populated, with 35 buildings and major highways located very close to 36 slopes and earth-retaining structures. Landslides and 37

A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx

rockfalls are very common in both cities, and large expenditures are being incurred by both Governments on the investigation, design and implementation of mitigation and preventive measures to reduce the likelihood of the loss of life and economic losses due to landslides.

For example, Chongqing was listed the top 1 among
70 cities in China in the National Planning Scheme
between 1999 and 2000 (Shu and Hu, 1998) where the
reduction of hazard due to landslides and implementation of mitigation measures had been given the highest
priority among other natural disaster hazards.

50 Similarly, since 1976, the Government of the Hong 51 Kong Special Administrative Region (HKSAR) has 52 spent over HK\$3.6 billion on studies and upgrading 53 works on both public and private man-made slopes and 54 retaining walls which were formed before the Geotech-55 nical Engineering Office (GEO) was established and which could pose a risk to life or property (HKSAR 56Internet webpage: www.info.gov.hk). These studies 57and upgrading works are being carried out under a 58long-term Landslip Preventive Measures (LPM) 59Programme where the long-term strategy is to complete 60 the upgrading works for another 2500 substandard 61 Government slopes and to complete the detailed studies 62 for another 3000 private slopes by the year 2010. 63

The Jockey Club Research and Information Centre 64 for Landslip Prevention and Land Development was 65 established in October 1998 in the Department of Civil 66 Engineering of the University of Hong Kong. The 67 Jockey Club Research and Information Centre has 68 jointly carried out a number of slope safety research 69 projects with some Mainland China's prominent univer-70sities through a collaborative research program and one 71of the on-going topics is on the application of soil nailing 72technology to stabilization of unstable slopes in 73



Fig. 1. Geographical location of Chongqing and Hong Kong.

A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx

74Chongqing. As a result of the collaborative studies and technical exchange programs among these universities 7576viz. the Chongqing Jianzhu University (重庆建筑大学), a more in-depth understanding of the landslide problem, 77methodology and mitigation measures in Chongqing 7879 and Hong Kong was achieved. The objective of this paper is therefore to: (1) highlight the similarities and 80 differences of the slope safety problems which these 81 cities have been facing and (2) present and compare the 82 key technical approaches these two cities have been 83 84 undertaken to reduce the risk of landslides and rockfalls, 85 so that both cities could benefit from the experience and lesson learnt. 86

#### 87 2. Factors causing landslides

88 The city of Chongqing is located at the Sichuan 89 Province (四川省), whereas Hong Kong is located at the 90 southeast coast of China. Fig. 1 presents the geo-91 graphical location of these two cities.

92 The population in Chongqing is about 30 million, 93 whereas in Hong Kong, it is only about 7 million. The city of Chongqing covers an area of about 820,000 94 $km^2$ , whereas in Hong Kong, it is about 1100  $km^2$ , very 95much smaller than Chongqing. In terms of the risk of 96 life and economic losses as a consequence of slope 97 98 failure, the major factor to be considered in any slope study and mitigation measures is the proximity of the 99

slope or earth-retaining structures to populated areas, 100 traffic and building. The landform in Chongqing and 101 Hong Kong is hilly with occupied buildings con-102 structed very close to slopes or on elevated platforms 103supported by earth-retaining structures. Fig. 2 shows 104that it is common to have residential buildings con-105structed at steep slopes and highway located very close 106 to slopes in both cities, because of the scarcity of flat 107 land. A comparison of the percentage of land at 108 different groups of slope angles is presented on 109Fig. 3. Based on the local experience, the slope at 110 Chongqing is generally stable when the slope angle is 111 less than 20° or greater than 50° (Shu and Hu, 1998). A 112similar observation can also be found for the slope in 113 Hong Kong. The same observation is consistent to the 114fact that for a slope which has an angle greater than  $50^{\circ}$ , 115it is most likely that it is a rock slope with failure 116 occurrence much less than of a soil slope due to the 117higher shear strength of the rock mass (Fig. 3 in Hu, 118 1995). 119

Fig. 3 indicates the fact that for more than 50% of<br/>the available land in Chongqing and Hong Kong, it is<br/>on sloping ground where the slope angles range from<br/>20° to 50°, a condition which is most vulnerable to<br/>stability problem.120<br/>123

Factors affecting failure of slopes have been described by Kuang (1995) and 张梁 (1998) for Chongqing and Wong et al. (1998) for Hong Kong. A range of triggering and contributory factors leading to the 128



Fig. 2. Landslide in Chongqing and Hong Kong.

A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx



Fig. 3. Percentage of land.

129 event of a landslide could be broadly classified in130 Table 1.

131An examination of Table 1 suggests that the slopes in Chongqing have to face natural hazards (earthquake 132and river erosion/flooding) more than that of Hong 133134Kong. River erosion would undermine the toe of the 135slope, reducing the restoring moment of the sliding mass, whereas flooding would decrease the effective 136stresses in the slip surfaces particularly when the pore 137138pressures in the saturated sliding mass are not dissipated quick enough. Shu and Hu (1998) indicated that 139the river level in Chongqing could fluctuate by 5 m 140 daily and 30 m annually and could account for about 141

142 40% of the landslide cases.

t1.1 Table 1

Summary of landslide triggering and contributory factors for both

t1.3       Landslide triggering factors       Chongqing       Hong Kong         t1.4       Rain, rise in groundwater level, etc.       Image: Construction/human       Image: Construction/human         t1.5       Adverse construction/human       Image: Construction/human       Image: Construction/human         activities       Image: Construction/human       Image: Construction/human       Image: Construction/human         t1.6       Deterioration and erosion       Image: Construction       Image: Construction         t1.7       Bursting and leakage of       Image: Construction       Image: Construction         t1.8       Earthquake       Image: Construction       Image: Construction         t1.10       Contributory factors       Image: Construction       Image: Construction         t1.12       Inadequate design       Image: Construction       Image: Construction         t1.14       Adverse topography       Image: Construction       Image: Construction         t1.15       Inadequate maintenance       Image: Construction       Image: Construction	t1.2	cities		
t1.4       Rain, rise in groundwater level, etc.       Image: Construction and erosion of surface         t1.5       Adverse construction/human activities       Image: Construction and erosion of surface         t1.6       Deterioration and erosion of surface       Image: Construction and erosion of surface         t1.7       Bursting and leakage of buried water services       Image: Construction and flooding         t1.8       Earthquake       Image: Construction and flooding         t1.10       Contributory factors       Image: Construction and flooding         t1.12       Inadequate design       Image: Construction and flooding         t1.13       Poor construction       Image: Construction and flooding         t1.14       Adverse topography       Image: Construction and flooding         t1.15       Inadequate maintenance       Image: Construction and flooding	t1.3	Landslide triggering factors	Chongqing	Hong Kong
t1.5       Adverse construction/human activities         t1.6       Deterioration and erosion of surface         t1.7       Bursting and leakage of buried water services         t1.8       Earthquake         t1.9       River erosion and flooding         t1.10       Contributory factors         t1.12       Inadequate design         t1.13       Poor construction         t1.14       Adverse topography         t1.15       Inadequate maintenance	t1.4	Rain, rise in groundwater level, etc.		
t1.6       Deterioration and erosion of surface         t1.7       Bursting and leakage of buried water services         t1.8       Earthquake         t1.9       River erosion and flooding         t1.10       Contributory factors         t1.11       Adverse geological conditions         t1.12       Inadequate design         t1.13       Poor construction         t1.14       Adverse topography         t1.15       Inadequate maintenance	t1.5	Adverse construction/human activities	V	
t1.7       Bursting and leakage of buried water services         t1.8       Earthquake         t1.9       River erosion and flooding         t1.10       Contributory factors         t1.11       Adverse geological conditions         t1.12       Inadequate design         t1.13       Poor construction         t1.14       Adverse topography         t1.15       Inadequate maintenance	t1.6	Deterioration and erosion of surface	1 miles	
t1.8       Earthquake       I         t1.9       River erosion and flooding       I         t1.10       Contributory factors       I         t1.11       Adverse geological conditions       I         t1.12       Inadequate design       I         t1.13       Poor construction       I         t1.14       Adverse topography       I         t1.15       Inadequate maintenance       I	t1.7	Bursting and leakage of buried water services		
t1.9       River erosion and flooding         t1.10       Contributory factors         t1.11       Adverse geological conditions         t1.12       Inadequate design         t1.13       Poor construction         t1.14       Adverse topography         t1.15       Inadequate maintenance	t1.8	Earthquake		
t1.11       Adverse geological conditions       I         t1.12       Inadequate design       I         t1.13       Poor construction       I         t1.14       Adverse topography       I         t1.15       Inadequate maintenance       I	t1.9 t1.10	River erosion and flooding Contributory factors		
t1.12       Inadequate design       Image: Construction         t1.13       Poor construction       Image: Construction         t1.14       Adverse topography       Image: Construction         t1.15       Inadequate maintenance       Image: Construction	t1.11	Adverse geological conditions		<b>1</b>
t1.13       Poor construction       Image: Construction       Image: Construction         t1.14       Adverse topography       Image: Construction       Image: Construction         t1.15       Inadequate maintenance       Image: Construction       Image: Construction	t1.12	Inadequate design		
t1.14 Adverse topography t1.15 Inadequate maintenance	t1.13	Poor construction		1
t1.15 Inadequate maintenance	t1.14	Adverse topography		
	t1.15	Inadequate maintenance		

#### 3. Rainfall intensity

Rainfall is one of the main factors contributing to144landslides in Chongqing and Hong Kong. In Chongq-145ing, the average annual rainfall is about 1125 mm,146whereas it is about 2225 mm in Hong Kong (about14750% more rain than Chongqing).148

Based on the work of Li (1995), the following 149 guidelines are established for providing early landslide warning to the city of Chongqing: 151

Rainfall intensity	Apparent conditions of slope
$\geq$ 25 mm/day	Show signs of surface erosion
$\geq$ 50 mm/day	Surface erosion intensify
$\geq$ 100 mm/day	Stability deteriorate, marginally
	stable slope may deform and move
$\geq$ 150 mm/day	Marginally stable slope may
	deform or collapse
$\geq$ 200 mm/day	Marginally stable slope may
	deform or collapse
	Stable slope may also show signs
	of instability
$\geq$ 250 mm/day	Stable and well vegetated slope
	may also deform or collapse

Based on the early work of Brand et al. (1984) and 152recent updating work of Kay (1998), most of the 153landslides in Hong Kong occurred within 4 h after 154the peak hourly rainfall and less than 10% of landslides 155occurred 16 h after the peak hourly rainfall. For a peak 156hourly rainfall of 70 mm (the Landslip Warning would 157generally be issued if the 24-h rainfall was expected to 158exceed 175 mm, or the 60-min rainfall was expected to 159exceed 70 mm, over a substantial part of the urban 160

4

### **CLE IN**

area), the probability of having severe landslide 161 (dozens of landslides) is about 15%. For the same peak 162hourly rainfall, but when the associated 24-h rainfall is 163less than 100 mm, the probability of having minor 164165incident (none or few landslides) is negligible.

166 It can be observed from the statistics and experiences gained at Chongqing and Hong Kong that 167although the annual rainfall in Chongqing is only 16850% to that of Hong Kong, landslide would normally 169occur when the rainfall intensity is greater than 250 170mm/day. This threshold level is much smaller than 171that of Hong Kong and generally indicates that the 172landslide problem in Chongqing could be more wide-173spread than Hong Kong and more resources should be 174directed towards minimizing the occurrence and im-175pact of landslides. It is suggested that the peak hourly 176rainfall intensity in Chongqing should also be consid-177ered in the future correlation and observation.

#### 4. Scale of landslides 170

178

The volume of landslide material reported in 180 181 Chongqing is much larger than that in Hong Kong. 182Fig. 4 summarizes the reported landslide cases in 183Chongqing, and it can be seen that most of the reported landslides have volume exceeding 100,000 m<sup>3</sup> (张梁, 184 1998). According to the classification of natural haz-185ards (including debris flow, ground subsidence/crack-186187 ing, collapse of cavity in karst, etc.) in Chongqing, the

following grades are used for prioritization of funding 188 for mitigation works: 189

Grading	Landslide volume, m <sup>3</sup>	T2.1
Small	<10,000	T2.2
Medium	10,000-100,000	T2.3
Large	100,000-500,000	T2.4
Very large	>500,000	T2.5

In Hong Kong, the following scales are generally 190used to describe the landslide volume: 191

Grading	Landslide volume, m <sup>3</sup>	Т3.
Small	< 50	ТЗ.
Medium	50-500	ТЗ.
Large	>500	ТЗ

Based on the record from GEO, the majority of the 192landslides in Hong Kong have a volume less than 500 193m<sup>3</sup>. The landslide volume involved in the Fei Tsui 194Road slope failure was 14,000 m<sup>3</sup>, and it was already 195considered as one of the largest and fast-moving 196landslides in Hong Kong history (Kwong et al., 1971998; Wong et al., 1997). 198

It could be postulated that many small landslides 199occurred in Chongqing were either not reported or not 200recorded into the database, perhaps due to a deficien-201cy in public funding or insufficient awareness from 202the local residents. 203



Fig. 4. Landslide volume in Chongqing.

A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx

### 204 5. Geological conditions

205Based on the geological information in Chongqing, the city is underlain by sedimentary rocks of Jurassic 206 Age. The sedimentary rocks are mainly mudstone and 207208sandstone. They are present in the forms of a series of narrow stretching non-symmetric folds. The dip angle 209of the bedding planes exhibits large variations from 210gentle to steep and even to vertical within a short 211distance (Yue et al., 2001). Above the sedimentary 212213rocks are Quaternary deposits and soils including landslide debris, colluvium and alluvium of variable 214 thickness. 215

The mudstone contains abundant illite and askanite and is therefore sensitive to weathering and would quickly swell (20–110% by volume) and break once in contact with water.

The groundwater table is usually low but could also 220quickly rise to the ground surface during heavy rainfall 221 in local areas. Local groundwater table usually exists 222in the fissure of the sandstone and mudstone. Fig. 5 223illustrates schematically the complexity of groundwa-224ter flow path in sandstone and mudstone. In this figure, 225due to the interbedded nature of sandstone and mud-226stone, the groundwater flow path is greatly influenced 227by the network of joints, faults and other discontinu-228



Geological Profile Showing Interbedding of Mudstone and Sandstone

Fig. 5. Schematic view of groundwater effect to slope stability.

A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx

ities, which divide the rock mass into an assemblage of
closely interlocking blocks. For all practical purposes,
the blocks themselves are effectively impermeable.
The degree of transmissivity of the rock mass is
therefore dependent on the frequency, connectivity
and effective aperture of the discontinuities. The

effective aperture of the discontinuities is, to a large235extent, controlled by the degree of infilling, tectonic236history and stress-relief effects of erosion and excava-237tion. The transmissivity of the rock mass can also be238affected by the presence of highly fractured zones239associated with sub-vertical faulting. It is very difficult240



Fig. 6. Contribution of groundwater to slope stability.

to predict with high certainty the phreatic surface for 241slope stability assessment. 242

243The geology in Hong Kong mainly consists of 244volcanic and granitic rock of igneous origin of Jurassic 245Age. Sedimentary rocks, some of which are metamor-246phosed, cover only a small area. Above the rock formation is Quaternary deposits including colluvium, 247alluvium, debris flow deposit and marine deposit. 248Deep weathering of rock is not uncommon and vari-249250able decomposition grades, from fresh rock to residual 251soils, are widely used in Hong Kong (GEO, 1984).

252The groundwater table in Hong Kong is quite 253variable within a short distance and very much influ-254enced by the storage capacity of the soil, infiltration of rain, runoff and subsurface flow. Perched water table, 255sometimes transient in nature, may exist in the residual 256257soil governing the local stability of a slope.

258Groundwater movement takes place from areas of high total pressure head to areas of low total pressure 259head. Fig. 6 shows that this movement will generally 260261occur along preferential flow paths where permeability 262values are high and the resistance to movement is therefore less. Potential zones of high permeability 263include the layers of sand, gravel and cobbles within 264265the alluvium, internal piping in the completely decom-266posed materials and highly fractured, open jointed zones within the rock mass. The assessment of ground-267water table in the urban area could become very 268complicated if ponding or leakage of water in buried 269270services is present.

#### 2716. Mechanisms of landslides

272Five major landslides in the city of Chongqing 273have been described in details by Rao et al. (1995), 274whereas six landslide case histories along a national expressway in Chongqing have been documented by 275(Yue et al., 2001). The following summarises the 276movement history and mechanisms described by 277Rao et al. (1995). Interested readers should refer to 278the geological cross sections presented in their paper. 279280(1) Zhen Jiang Si (镇江寺滑坡) Landslide

281Flooding had created a high water table in the slope and generated excess pore pressure which could not 282be dissipated fast enough when the river level was 283284lowered. Landslide was initiated by downward move-285ment at the slope toe and propagated to the middle height, thereafter, masonry wall was cracked and 286several houses tilted. The volume of this landslide 287was estimated to be about  $300,000 \text{ m}^3$ .

(2) Li Zi Ba (李子坝重庆仪表厂滑坡) Instrument and 289Meter Plant Landslide 290

Excessive man-made fill was placed on top of 291alluvium making a total thickness of 25 m above 292the underlying interbedded mudstone and sandstone 293bedrock. Slip surfaces follow the interface between 294the alluvium and the bedrock. Cracks (25 m long and 295100 mm wide) were formed and displaced by more 296than 1 m, causing factory and retaining wall to crack. 297Every year when the flood returns, the movement of 298this slope reactivates. The volume of this landslide 299was estimated to be about  $500,000 \text{ m}^3$ . 300

(3) Li Zi Ba (李子坝小学滑坡) Primary School Landslide 301 This is a 9-m-thick fill slope which has been 302 subjected to river erosion and undermining since 303 1950. In 1981, when the river flood level was quickly 304 reduced, creep movement was observed in the fill body 305 and the road above subsided and retaining wall 306 cracked. In 1989, the road above the slope suddenly 307 cracked (30-40 m long, 150-350 mm wide) and 308 subsided by 1 m. Minor urgent stabilization work 309 was carried out but up to this moment, detailed ground 310 investigation work and mitigation measures had not 311 been carried out. The volume of this landslide was 312estimated to be about 120,000 m<sup>3</sup>. 313

(4) Wang Jia Po (王家坡滑坡) Landslide

This slope is 120 m long, 80 m wide and has a 315volume of about 60,000 m<sup>3</sup>. It is a fill slope overlying 316 the mudstone/sandstone bedrock. The fill body is 317 composed of clayey sand with a mixture of gravel, 318 boulder and construction debris. It was formed in 1957 319from uncontrolled dumping during the construction of 320 the nearby highway. Every year, during heavy rainy 321 season, the fill saturates with water and moves. The 322 last 30-year record shows that it has moved by 6-8 m 323and settled at 3 m. In July 1985, it had moved by 20-324 30 mm and cracks were developed inside the fill body 325 and extended upward. Several houses on top of the 326 slope developed cracks, threatening the lives of more 327 than 100 people. Remedial works were carried out in 328 1981 and 1987, but new cracks continue to develop. 329

(5) Gao Jiao Stove (重钢高焦炉滑坡) Landslide

The slope is composed of soft clay overlain highly 331 fractured rock mass. It was estimated that the internal 332 friction angle of the sliding surface was about 8.5° and 333

8

288

314

A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx

the sliding plane had an angle of about  $2-5^{\circ}$ . In 1958 334 when the river flooding level increase, 50 mm differ-335 336 ential settlement was recorded. Several water holding tanks were cracked and some moved by 14.6 m and 337 settled at 100-900 mm. The major cause of the 338339 landslide is due to river erosion undermining the toe, exacerbated by uncontrolled industrial water leakage 340 into the ground. The area of the landslide was about 3411,020,000 m<sup>2</sup>, whereas the volume of this landslide 342 was estimated to be about 14,200,000 m<sup>3</sup>. 343

In Hong Kong, the most common slope failure
mechanism involved shallow sliding of less than 3 m
deep (Brand, 1985), most of which are caused by
surface infiltration and erosion due to surface runoff.
Other common modes of failure and mechanisms
illustrated with reference to case histories can be found
in Wong et al. (1998).

### 7. Mitigation measures

In Chongqing, typical stabilization measures, 352 adopted to suit local ground conditions and local 353 construction practice, may consist of the following: 354

- 1. trimming back to follow the sedimentary rock bedding; 355
- hand-dug lateral resistance piles with or without prestressed ground anchors (see Fig. 7 for conceptual illustration);
   358
- reinforced concrete wall between lateral resistance 359 piles (see Fig. 8 and Liu and Li, 1995 for conceptual 360 illustration); 361
- 4. pre-stressed or passive ground anchors; 362
- 5. gravity masonry retaining wall and 363
- slope surface protection including hydroseeding, sprayed concrete and reinforced concrete grids.
   364 365

366



Fig. 7. Slide resisting piles.

9

A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx



Fig. 8. Slide resisting piles integrated with concrete wall.

In Hong Kong, common stabilization measures
may include a number of combinations as follows:
For soil slopes:

- 370 1. trimming and cutting;
- 371 2. retaining wall with or without tie-back;
- 372 3. re-compaction of fill slopes;
- 373 4. soil nailing;
- 374 5. mini-piles and
- 375 6. slope surface protection including hydroseeding,
- 376 sprayed concrete and reinforced concrete grids.
- 377
- 378 For rock slopes:
- 379 1. scaling and trimming;
- 380 2. bolting and dowelling;
- 381 3. meshing and shotcreting;
- 382 4. buttressing and
- 383 5. anchoring (occasional).
- 384

Typical details of these stabilization measures can be found in CED (2002).

387 A review of the publications suggests that the use 388 of piles to stabilize slopes in Chongqing is very 389 common, whereas it is not commonly adopted in 390 Hong Kong. The use of soil nails to stabilize slopes in Hong Kong is very common but not widely used in 391 Chongqing. The rational being that the critical slip 392 surface of the slope in Chongqing is usually deep and 393 significant lateral resistance is required to stabilize the 394 slope. In Hong Kong, the critical slip surface is 395 usually very shallow, in the order of 3 m deep, and 396 therefore, the use of soil nails is economical and 397 feasible. 398

Ground anchors (whether active or passive) are 399commonly used in Chongqing because of deep critical 400 slip surface and significant restoring force and 401 moments are required. The use of active anchor is 402 not encouraged in the industry in Hong Kong simply 403 because of poor performance record (stress relaxation, 404 poor workmanship and insufficient corrosion protec-405tion) and long-term monitoring requirement. The 406 party responsible for long-term maintenance would 407 normally select mitigation options that are monitor-408 ing-free and the use of active ground anchors would 409 normally be discouraged unless technically it can be 410 justified that there are no other alternative solutions. 411

The use of soil nails integrated with reinforced 412 concrete tie beams or panels is gaining popularity in 413 Hong Kong. The system would allow better distribution of resisting force, and confinement provided by 415 the system would prevent surface erosion between the 416





A.K.L. Kwong et al. / Engineering Geology xx (2004) xxx-xxx

417 soil nail's head. An example used by the author in418 Hong Kong is presented in Fig. 9.

### 419 8. Management and monitoring programs

The use of monitoring and observational approach 420 (Li and Liu, 1995) is widely adopted in Chongqing to 421reduce the initial capital expenditure on mitigation 422 measures. It also provides very useful data for back 423 424 analysis of engineering parameters and failure mech-425anisms developed. In Chongqing, huge expenditure has been committed yearly to reduce the likelihood of 426 427 landslide and managed under different level of governments. The Office for Landslip Prevention in Chongq-428ing, similar to the Geotechnical Engineering Office in 429Hong Kong, is responsible for the design, mitigation, 430prevention, monitoring of landslide and rockfall and 431allocation of funding for emergency works. 432

In Hong Kong, the control and management of
landslides is well established, and they are summarized in the following, which would serve as a good
reference for Chongqing to develop their own management plan, taking into consideration their own
financial budget and constraints.

- 439 1. Registration of all slope details so that a prioriti-440 zation of mitigation measures can be given to441 slopes which deserve greater and early treatment.
- 442 2. Provision of a slope information system to the
  public so that they would be aware of the potential
  hazards of their surroundings and be responsible
  for maintaining and keeping the slope safe under
  their own property boundary.
- 447 3. Establishment of consultancy contract so that wider
  448 professional resources can be gathered to mitigate
  449 the slopes in a shorter period of time.
- 450 4. Establishment of external review board so that451 there could be a channel for technical exchange of452 latest development of technology and research.
- 453 5. Establishment of landslip warning system for early
  454 notification of potential hazards to the public so that
  455 people can stay away from slopes during heavy rain.
- 456 6. Establishment of emergency team so that profes-457 sional staff can arrive at the landslide location in the
- 458 earliest possible time to provide advice to evacua-
- 459 tion and repair works and gather first-hand geolog-
- 460 ical information for detailed engineering studies.

- 7. Identification of maintenance party of all slopes
   461
   and enforcement of regular inspection, review and
   462
   463
   463
- 8. Provision of education to the public regarding 464 proper registration, maintenance of slopes and 465 reporting of landslides. 466

467

496

9. Conclusions

A review of the current geotechnical engineering 468 practice in Chongqing and Hong Kong has been 469 undertaken in this study. It is found that the city of 470 Chongqing has a relatively larger landslide problem 471 than Hong Kong due to the following elements: 472

- 1. The volume of landslide material is larger in<br/>Chongqing because it normally involves a deep-<br/>seated failure mechanism. The cost of mitigation<br/>measures is therefore higher because it requires<br/>the eavy retaining structures or piles to resist the<br/>sliding mass.473<br/>475
- 2. Chongqing has to deal with landslides triggered by<br/>earthquake, river erosion and flooding.479480
- The landslides in Chongqing would initiate at a much lower rainfall intensity than that in Hong Kong.
   481
   482
- 4. The prediction and monitoring of phreatic surface
  483
  in Chongqing is more difficult than in Hong Kong
  484
  because it is controlled by the network of joints and
  fissures in the discontinuities.
  486
- 5. Observational and monitoring approach is widely 487 adopted in Chongqing to reduce the initial capital 488 investment on mitigation measures, whereas in Hong 489 Kong, active prevention and stabilization measures 490 are usually carried out to reduce the potential risk and long-term deterioration of the slopes. 492
- 6. The control and management of landslide in the 493 city of Chongqing is in an immature stage largely 494 due to financial constraints. 495

In terms of technical capability and achievement, it 497 is conceived that both cities have been applying the 498 practical and latest technology in mitigating the landslide problem. 500

It is recommended to the city of Chongqing that 501 comprehensive long-term landslide management plan 502 be established and in this respect, the system being 503 used by the Geotechnical Engineering Office of the 504

505 Hong Kong SAR Government could be a good refer-506 ence starting point.

### 507 10. Uncited reference

508 Liu, 1992509 Yue and Lee, 2002

#### 510 Acknowledgements

511 The authors would like to acknowledge the Hong 512 Kong Jockey Club Charities Trust for their financial 513 supports of the study reported herein. The authors 514 would also like to thank Dr. Z.Q. Yue for his valuable 515 advice throughout the study.

#### 516 References

- 517 Brand, E.W., Premchitt, J., Phillipson, H.B., 1984. Relationship
  518 between rainfall and landslide in Hong Kong. Proceedings of
  519 the 4th Symposium on Landslide, Toronto, 377–384.
- Brand, E.W., 1985. Geotechnical engineering in tropical residual
   soils (Special Lecture/Discussion). Proceedings of the First In ternational Conference on Geomechanics in Tropical Lateritic
- 522ternational Conference on Geomechanics in Tropical Lateritic523and Saprolitic Soils, Brasilia, vol. 3, pp. 23–91, 92–99.
- 524 CED, 2002. Civil Engineering Department Standard Drawings Civil
   525 Engineering Department, Hong Kong SAR Government (available in webpage: www.magicaldesk.com).
- 527 张梁,张业成 及 罗元华, 1998. 地质灾害灾情评估理论与实践 地质出版社 北京.
- GEO, 1984. Geotechnical Manual for Slopes Geotechnical Control
   Office, Engineering Development Department, Hong Kong
   295 pp.
- 531 Hu, K.D., 1995. Superficial discussion on distribution laws of
- 532 landslides in Chongqing region. The Chinese Journal of Geo-
- 533 logical Hazard and Control 6 (3), 20-22 (September;
   534 胡克定 浅论重庆地区滑坡的分布規律 中国地质灾害与防治学報).
- 535 Kay, J.N., 1998. Rainfall-landslide relationship update. Slope En-536 gineering in Hong Kong, Balkema, 83-85.
- Kuang, Z., 1995. Study on characteristics, deformation mechanisms and control of dangerous rock and rock fall in central area of Chongqing city. The Chinese Journal of Geological

```
Hazard and Control 6 (3), 51-56 (September; 旷镇国 重 540 
庆市中区危岩崩塌特征 形成机制及防治研究 中国地质灾害与防治学報). 541
```

- Kwong, A., Monaghan, B., Wong, H.N., 1998. Investigation and design of stabilization measures for the 1995 Fei Tsui Road land-slide. Slope Engineering in Hong Kong, Balkema, pp. 43–50.
- Li, X., 1995. Analysis of the relationship between heavy rainfall and geological hazard in Chongqing. The Chinese Journal of Geological Hazard and Control 6 (3), 39-41 547 (李晓 重庆地区的强降雨过程与地质灾害的相关分析 中国地质灾害与防治学報). 548
- Li, T., Liu, J., 1995. An example on emergency monitoring of Jian Xian Po Landslide and slide-resistance pile in Cai Yuan Ba. The Chinese Journal of Geological Hazard and Control 6 (3), 92-97 (李同明 及 刘军 应急监测菜元坝建兴坡滑 坡及抗滑桩实录 中国地质灾害与防治学報). 553
- Liu, Z.X., 1992. Chongqing Landform and Economic Construction. The Science and Technology Press of China June. 刘喜忠主編 重庆地貌与經济建设 北京 中国科学技术出版社.
- Liu, Z., Li, J., 1995. Application of circular hollow slide-resistance pile on regulation of the landslide and its effect. 558
   The Chinese Journal of Geological Hazard and Control 6 (3), 63-66 (September; 刘志貴及李俊雄 圆形空心抗滑桩在滑坡治 560
   理中的運用及成效 中国地质灾害与防治学報). 561
- Rao, H., Li, Y., Ma, Y., 1995. The distribution and characteristics of landslide, rock fall and mud flow in the plane region of Chongqing city. The Chinese Journal of Geological Hazard and Control 6 (3), 9–19 (September; 浇紅庆 李玉生 565 及馬映清 重庆市規划区滑坡崩塌及泥流的分布与特征 中国地质灾害与防治 566 学報).
- Shu, W.Y., Hu, S.Q., 1998. General situation of landslide hazard mitigation in Chongqing. The Journal 569 of Chongqing Geological Hazard Study (1), 5-8 570 (舒 文寬 胡善铨及 汪予生 重庆市城市危岩滑坡灾害防治概况 重庆地质灾害研究 571 与防治). 572
- Wong, H.N., Ho, K.K.S., Chan, Y.C., 1997. Assessment of consequence of landslides. Landslide Risk Assessment, Balkema, 111–149. 575
- Wong, H.N., Ho, K.K.S., Pun, W.K., Pang, P.L.R., 1998. Observations from some landslide studies in Hong Kong. Slope Engineering in Hong Kong, Balkema, pp. 277–285.
- Yue, Z.Q., Lee, C.F., 2002. A plane slide that occurred during construction of a national expressway in Chongqing, SW China. Quarterly Journal of Engineering Geology and Hydrogeology (in press). 582
- Yue, Z.Q., Lee, C.F., Pan, X.D., 2001. Landslides and stabilization measures during construction of a national expressway in Chongqing, Southwestern China. Proceedings of International Conference on Landslides: Causes, Impacts and Countermeasures, Davos, Switzerland, June 17–21, pp. 625–633.
  587

554

555

556

576

577