

1 **The Saint-Jude landslide of May 10th, 2010, Quebec, Canada:**
2 **Investigation and characterisation of the landslide and**
3 **its failure mechanism**

4 **Ariane LOCAT ing. Ph.D.** – Auteure principale

5 Département de génie civil et de génie des eaux, Université Laval
6 Pavillon Adrien-Pouliot, 1065 av. de la Médecine
7 Québec, Qc, Canada G1V 0A6
8 Tel : 1 418 656 2992
9 ariane.locat@gci.ulaval.ca

10 **Pascal LOCAT ing. M.Sc.**

11 Section des Mouvements de Terrain, Service de la géotechnique et de la géologie
12 Ministère des Transports, de la Mobilité durable et de l'électrification des transports
13 880 Ch. Sainte-Foy, 3^{ème} étage
14 Québec, Qc, Canada G1S 2L2
15 Pascal.Locat@transportsgouv.qc.ca

16 **Denis DEMERS ing. Ph.D.**

17 Section des Mouvements de Terrain, Service de la géotechnique et de la géologie
18 Ministère des Transports, de la Mobilité durable et de l'électrification des transports
19 880 Ch. Sainte-Foy, 3^{ème} étage
20 Québec, Qc, Canada G1S 2L2
21 Denis.Demers@transportsgouv.qc.ca

22 **Serge LEROUEIL Ph.D.**

23 Département de génie civil et de génie des eaux, Université Laval
24 Pavillon Adrien-Pouliot, 1065 av. de la Médecine
25 Québec, Qc, Canada G1V 0A6
26 serge.leroueil.@gci.ulaval.ca

27 **Denis ROBITAILLE ing.**

28 Section des Mouvements de Terrain, Service de la géotechnique et de la géologie
29 Ministère des Transports, de la Mobilité durable et de l'électrification des transports
30 880 Ch. Sainte-Foy, 3^{ème} étage
31 Québec, Qc, Canada G1S 2L2
32 Denis.Robitaille@transportsgouv.qc.ca

33 **Guy LEFEBVRE Ph.D.**

34 Département de génie civil, Université de Sherbrooke
35 2500, boul. de l'Université, Sherbrooke
36 Québec, Qc, Canada J1K 2R1
37 Guy.Lefebvre@USherbrooke.ca

38 Abstract

39 A landslide occurred on May 10, 2010, along the Salvail River, in the municipality of Saint-
40 Jude, Quebec. Debris of the landslide was formed of blocks clay having horst and graben
41 shapes, typical of spreads in sensitive clays. A detailed investigation was carried out by the
42 Ministère des Transports, de la Mobilité durable et de l'électrification des transports du
43 Québec in collaboration with Université Laval, with the objective of characterizing this
44 landslide, determining the causes and learning about its failure mechanism. The soil
45 involved is a firm, grey, sensitive lightly overconsolidated clay with some silt. Data from
46 piezometers installed near the landslide indicated artesian conditions underneath the
47 Salvail River. Cone penetration tests allowed to location of two failure surface levels. The
48 first one starting 2.5 m below the initial river bed and extending horizontally up to 125 m
49 and a second one 10 m higher reaching the backscarp. Investigation of the debris with
50 onsite measurements, light detector and ranging surveys, cone penetration tests, and
51 boreholes allowed a detailed geotechnical and morphological analysis of the debris and
52 reconstitution of the dislocation mechanism of this complex spread.

53 Key words: landslide, spread, sensitive clay, geotechnical investigation, horst, graben.

54 **Résumé**

55 Un glissement est survenu le 10 mai 2010 le long de la rivière Salvail, dans la municipalité
56 de Saint-Jude au Québec. Les débris de ce glissement étaient formés de blocs d'argile ayant
57 la forme d'horst et de grabens, typique des étalements dans les argiles sensibles. Le
58 Ministère des Transports, de la Mobilité durable et de l'électrification des transports du
59 Québec et l'Université Laval ont réalisé l'investigation détaillée de ce glissement de
60 terrain, dans le but de le caractériser, d'en déterminer les causes et d'en apprendre
61 d'avantage sur le mécanisme de rupture. Le sol impliqué est une argile sensible grise avec
62 un peu de silt, de consistance ferme, légèrement surconsolidée. Les piézomètres installés à
63 proximité du glissement indiquent des conditions artésiennes sous la rivière Salvail.
64 L'utilisation du piézocône a permis de localisée deux niveaux de surfaces de ruptures. L'un
65 a 2.5 m sous la position initiale de la rivière, s'entendant horizontalement sur 125 m, et
66 l'autre 10 m plus haut, allant jusqu'à l'escarpement arrière. L'investigation des débris par
67 mesures prises sur le terrain, levées de télédétection par laser, piézocônes et forages a
68 permis une analyse géotechnique et morphologique détaillée de ces derniers et la
69 reconstitution du mécanisme de dislocation de ce glissement complexe.

70 Mots-clés: glissement de terrain, étalement, argile sensible, investigation géotechnique,
71 horst, graben.

72 **Introduction**

73 On the 10th of May 2010, at 08:25 pm, a large landslide occurred in the municipality of
74 Saint-Jude, Québec, about 50 km north-east of Montréal (Figure 1). Four people were killed
75 as their house was destroyed by the movement and one man was injured falling with his
76 truck in the crater of the landslide while driving on the North Salvail road. The landslide
77 occurred in a sensitive Champlain Sea clay deposit along the Salvail River. The original
78 slope had a height of about 22 m and an inclination varying between 12 and 20°. A section
79 of about 275 m long, parallel to the river, was affected by the landslide. The retrogression
80 of the landslide, from the initial crest of the slope to the backscarp of the landslide, was 80
81 m. The total volume of debris was about 520 000 m³. The soil mass dislocated in blocks of
82 more or less intact material having horst and graben shapes. These structures present in the
83 debris of the landslide are typical of spreads (Cruden and Varnes 1996; Locat et al. 2011a;
84 and Hungr et al. 2014). This type of landslide can be hazardous to affected people and
85 infrastructures as it occurs suddenly, without any warning and can cover large areas.

86 The Ministère des Transports, de la Mobilité durable et de l'électrification des transports
87 (MTMDET) in collaboration with Université Laval carried out a detailed investigation in
88 order to characterise this landslide and to specify its failure mechanism. The investigation
89 included field observations and in situ testing as well as laboratory tests that enabled the
90 investigators to obtain information on the morphology of the landslide, the stratigraphy of
91 the deposit and the properties of the soil involved in the landslide.

92 This paper begins by describing the regional context of the area where the landslide
93 occurred. The detailed investigation performed is also presented. A discussion on the

94 failure mechanisms, the possible aggravating and triggering factors, and the consequences
95 of the landslide is presented followed by a conclusion to this paper.

96 **The landslide and its regional context**

97 The 2010 landslide involved post-glacial Champlain sea clays that were deposited between
98 approximately 12 000 and 10 000 years ago (Ochietti 1989). In the region of Saint-Jude,
99 the sediments filled a shallow preglacial valley, located below the modern Salvail River
100 and extending up about 15 km in the north-east direction, below the Yamaska River
101 (Rissmann et al. 1985). Near the landslide, sediment deposits reach a thickness up to 45 m
102 tapering to only a 20 to 25 m thickness on both sides of this preglacial valley (Rissmann et
103 al. 1985).

104 Figure 2 presents a Digital Elevation Model (DEM) of the region where the 2010 landslide
105 occurred. The data were obtained from aerial Light Detection and Ranging (LIDAR)
106 surveys performed after the landslide. The figure shows location of the 2010 landslide and
107 other large retrogressive landslides that previously occurred along the Salvail River and its
108 tributaries. 16 similar landslides can be identified in the area of the 2010 landslide.

109 Analysis of aerial photographs, dating back as far as 1931, indicated that seven large
110 landslides (> 1 ha) occurred along the Salvail River between the Yamaska River and the
111 municipality of Saint-Jude, between 1931 and present, while the rest of the landslides
112 inferred from LIDAR occurred prior 1931, at unknown dates. When observing these aerial
113 photographs and LIDAR data of the site of the 2010 event, it was observed that the south
114 part of the 2010 event involved debris of a landslide that occurred at an unknown date. In

115 addition, observation of aerial photographs of the site since 1950 indicated that two slides
116 recently occurred (present on the 2009 aerial photographs). These two slides had a width
117 of 75 m and 20 m respectively. It points out that erosion may have been active near the foot
118 of the slope. The debris of these slides were gradually eroded by the river and vanished
119 with time.

120 Figure 3 presents an aerial photograph taken on May 11th 2010, the day after the landslide.
121 It can be seen that the debris completely blocked the Salvail River, creating flooding
122 upstream and leaving downstream completely dry. Observations on site showed that ridges
123 created by horsts and grabens covered with grass, trees and pieces of road were forming
124 the debris. Figure 4 presents a general view of the south part of the landslide showing this
125 complex debris. Horsts are blocks that form triangular ridges of relatively intact material
126 in the debris and have sharp tips pointing upward. Grabens are blocks having flat tops
127 generally covered with grass and trees. These structures show a “thumbprint microrelief
128 pattern” when viewed on aerial photographs. Figures 5 and 6 present a closer look of such
129 blocks, showing horsts, with horizontal stratifications, and grabens covered by pieces of
130 road or grass. Note the electric pole still standing on the right of the photograph on Figure
131 5 and trees standing in the debris after the landslide on Figure 6. Horsts and grabens are
132 typical of spreads (Cruden and Varnes 1996; Hungr et al. 2014) occurring in sensitive clays
133 and were described by Odenstad (1951), Carson (1979a, b), Tavenas (1984), Grondin and
134 Demers (1996), Demers et al. (2000), Locat et al. (2008), and Locat et al. (2011a). In
135 addition to horsts and grabens, inclined slices were observed in the debris. Figure 7 presents
136 a photograph of these inclined sliced located in the south part of the landslide.

137 **Investigation methods**

138 Investigation of the site started the day after the event, on May 11th 2010, and included
139 detailed field observations, analysis of aerial photographs and LIDAR surveys. The
140 investigation also included 4 boreholes, 35 piezocone tests with pore water pressure
141 measurement (CPTU), 2 field vane shear test profiles, 3 piezometer nests and 4 trenches
142 located on Figure 3.

143 Aerial photographs of the site were taken on May 11th 2010, a few hours after the event
144 while excavation works were ongoing near the house (Figure 3). Comparing these aerial
145 photographs to previous ones allowed the identification several targets and the
146 measurement of their displacement due to ground movement. This gives valuable
147 information on the kinematic of failure.

148 Detailed topographic data of the area where the 2010 landslide occurred was obtained from
149 LIDAR surveys. Two types of surveys were performed: aerial LIDAR survey, performed
150 on May 13th 2010, and terrestrial LIDAR survey taken on May 19th and 20th 2010. The first
151 survey covered the entire landslide and its surroundings. The second one covered only the
152 south-east part of the debris, near the backscarp of the landslide (about zone 4 on Figure
153 3).

154 The intact soil, outside the 2010 landslide, was characterized by 9 CPTUs, 2 boreholes and
155 2 field vane shear test profiles near the borehole locations. The locations of 6 of these
156 CPTUs are shown on Figure 3. One of them, at location 32060, was done by the MTMDET
157 in 2004, six years before the landslide. It is now located inside the landslide and gives

158 information on soil conditions before the event. These CPTUs give detailed and continuous
159 strength profiles (corrected tip resistance, q_t , water pressure, u_{base} , and sleeve friction
160 resistance), and thus give information on the stratigraphy of the deposit. This information,
161 combined with samplings from the boreholes and shear strength profiles from the field
162 vane shear tests ($S_{u \text{ vane}}$), enables the determination of the geotechnical properties of the
163 material involved in the landslide. It is worth noting that no feature such as a weak layer or
164 a softened zone was observed on the 2004 CPTU that could explain the 2010 landslide (see
165 section Location of the failure surface and figure 14).

166 The debris were studied with 26 CPTUs and 2 boreholes (32140 and 32141). Their
167 locations are shown on Figure 3. These CPTUs enabled the precise location of the failure
168 surface and to observe the stratigraphy and the characteristics of the disturbed debris and
169 the soil below.

170 Four trenches were dug in the debris to observe the stratigraphy of intriguing
171 morphological structures and to get a better understanding of the dislocation mechanism of
172 the soil mass. Their locations are shown on Figure 3 by white rectangles with their longer
173 side oriented parallel to the trench.

174 Pneumatic and Casagrande types piezometers were installed at different locations south of
175 the landslide. Piezometers nests were installed at location 32146, on the plateau far behind
176 the top of the slope, at location 32100, near the crest of the slope, as well as at location
177 32145, near the base of the slope.

178 Samples of soft clayey materials near the landslide and in the debris were taken with thin
179 wall tubes ~70 mm in diameter obtained using a piston sampler. In stiff and coarse
180 materials, a split-spoon sampler was used. Several of the thin wall tubes were examined
181 with computerized axial tomography scans (CAT scan) to obtain images of the stratigraphy
182 of the samples.

183 The geotechnical properties of the soil specimens were studied in the laboratory with the
184 following tests: particle size distribution, water content (w), consistency limits, pore water
185 salinity estimated by electric resistivity, intact ($S_{u \text{ cone}}$) and remoulded (S_{ur}) shear strengths
186 with the Swedish fall cone, oedometer tests and falling-head hydraulic permeability tests.
187 In addition, the shear behaviour of the soil involved in the landslide was studied with
188 triaxial compression tests in undrained conditions (CIU) and constant volume (undrained)
189 direct simple shear tests (DSS) on intact specimens.

190 **Geotechnical characterization of intact soil**

191 *Morphology of the slope before failure*

192 Cross-sections of the slope before and after the landslide are presented on Figures 8 and 9
193 (see Figure 3 for location). The topography before failure is from the DEM built from aerial
194 photographs taken in 2004. The plateau at the top of the natural slope is at an elevation of
195 about 28 m above sea level and the Salvail River bed is located at an elevation of about 6
196 m. The total height of the slope at the site of the landslide was 22 m. The angle of the slope
197 before failure ranged from 12° to 16° for the upper 12 m and was about 20° for the lower
198 10 m.

199 *Stratigraphy and geotechnical properties of the intact soil*

200 Investigations carried out in intact material at locations 32092 and 32100 (boreholes,
201 CPTUs, field vane shear tests and piezometers, located on Figure 3), made it possible to
202 obtain information on the stratigraphy and geotechnical properties of the intact soil outside
203 the footprint of the landslide. The 2 boreholes and 9 CPTUs carried out in the intact deposit
204 show the remarkable uniformity of the soil properties. The results from the CPTUs done in
205 2010 were also comparable to results from the CPTU carried out in 2004 at location 32060
206 inside the footprint of the landslide. Borehole at location 32100 gave similar results to the
207 one at location 32092, located at an elevation 0.06 m lower, only the geotechnical profile
208 obtained at location 32100 near the crest of the slope, south of the landslide (white star on
209 Figure 3), is presented in this paper (Figure 10). Five distinct units can be identified in the
210 intact soil overlying the bedrock. The bedrock was sampled at location 32092, data are
211 therefore not shown on Figure 10. Readers are referred to Locat et al. (2011b) for further
212 details.

213 The top unit, unit A, is a 3.8 m thick, (from elevation 28 to 24.2 m) dense, grey brown,
214 sandy crust. Samples from this unit were taken at location 32092 and are not presented
215 here. Readers are referred to Locat et al. (2011b) for further details. The water content
216 varies between 24 and 78% and the intact shear strength from CPTU ($S_{u\text{CPTU}}$), between 50
217 and 165 kPa (calculated with a dimensionless parameter for CPTU shear strength, N_{kt} ,
218 estimated to 13.5). Based on the average water content, unit weight is approximately 18.6
219 kN/m³.

220 Unit B is a 22.2 m thick (from elevation 24.2 to 2 m), firm, grey, sensitive clay deposit
221 very uniform with some silt. The clay is characterized by light and dark grey beds having
222 thickness of about 5 cm, near the top of the unit, getting thinner than 2.5 cm near the
223 bottom. Clay fraction is between 50 and 80%. The water content is about 65% over the
224 entire unit. The plastic limit (w_P) has a mean value of 26% and is generally constant
225 throughout the depth of the unit. The liquid limit (w_L) increases from 45 to 65% with depth.
226 The liquidity index (I_L) thus decreases with depth from about 2.0 to 1.0, corresponding to
227 remoulded shear strength varying respectively from 0.3 to 1.6 kPa, according to Leroueil
228 et al. (1983) relationship. The salinity of the pore water, determined through electrical
229 resistivity on samples taken at location 32092, varies from 1 g/L, at a depth of 8 m, to 7
230 g/L at a depth of 28 m. These values correlate well with the increase in liquidity limit with
231 depth. The intact field vane shear strength increases almost linearly with depth from 25 to
232 65 kPa from the top to the bottom of the unit. Given the intact and remoulded shear
233 strengths of this unit, its sensitivity varies from 80 to 40 from the top to the bottom of the
234 unit. The preconsolidation pressure (σ'_p) increases from 120 kPa, at a depth of 8 m, to 220
235 kPa, at a depth of 23 m. The overconsolidation ratio ($OCR = \sigma'_p / \sigma'_v$, where σ'_v is the
236 vertical effective stress) decreases from 1.9 to 1.2 over the same depths. The clay is
237 therefore lightly overconsolidated. A hydraulic conductivity of 9×10^{-10} m/s was measured
238 on a sample from a depth of 16.8 m with varying head permeability tests during an
239 oedometer test. Unit B corresponds to a typical Champlain Sea clay deposit and was the
240 main unit involved in the 2010 landslide.

241 Unit C is a 5 m thick (from elevation 2 to -3 m), stiff, silty clay of low sensitivity.
242 Observation of samples from this unit showed that it is made of four layers. From a depth

243 of 26.5 m to 28 m a grey silty clay with darker grey clay nodules and a few sea shells was
244 identified. In this layer, two pinkish silty clay sub-layers (pink layer on Figure 10), having
245 thickness of about 8 and 19 cm each and darker grey nodules, were also found at depths of
246 26.9 and 27.1 m. A grey silty clay layer with dark black spots has been observed from a
247 depth of 28 m to a depth of 28.7 m (dark grey layer on Figure 10). Unit C ends with a grey
248 silt and clay layer having thin sand and silt beds with a few sea shells. Clay fraction is
249 around 54% through unit C. The water content decreases from 70 to 40% with depth. The
250 plastic limit decreases from 30 to 19% and the liquid limit from 64 to 46%. The liquidity
251 index decreases from 1 to 0.7. The shear strength throughout unit C is variable. It increases
252 rapidly from 65 kPa to about 107 kPa between depths of 26 m to 27 m, decreases to 50 kPa
253 at a depth of 28 m and increases again to 77 kPa at a depth of 29.5 m, to finally decrease
254 down to 50 kPa at a depth of 31 m. This variation of shear strength defines a peak in unit
255 C shear strength profile at a depth of 27 m.

256 Unit D is a 6 m thick (from elevation -3 to -9 m) very stiff, grey-brown clayey silt. Clay
257 fraction is around 33%. The water content is around 23%. The plastic and liquid limits are
258 13 and 27% respectively. The liquidity index is about 0.7. The shear strength from CPTU
259 (N_{kt} of 13.5) varies between 50 and 150 kPa. The hydraulic permeability measured with
260 varying head permeability tests during an oedometer test is 5.5×10^{-10} m/s on a sample
261 taken at a depth of 33.3 m. This unit is therefore less permeable than unit B although its
262 grain size is coarser. Unit E is a 5 m thick (from elevation -9 to -14.6 m) deposit of hard,
263 grey-brown, sandy silt with some clay and traces of gravel and silt. Clay fraction varies
264 between 4 and 20%. This unit is interpreted as a till overlying the bedrock.

265 Unit R (lower than elevation -14.6 m) is comprised of grey sandstone and red shale
266 bedrock.

267 Triaxial compression tests were performed on samples from depths of 20.5, 20.9, and 22.2
268 m in unit B, slightly above the river bed elevation, taken from the borehole at location
269 32092. Samples from depths of 20.5 and 20.9 m were isotropically consolidated in the
270 normally consolidated range under effective stresses of 192 and 293 kPa respectively, and
271 compressed in undrained conditions. These tests showed that the soil in unit B has a friction
272 angle in the normally-consolidated range of 30° and a cohesion of 10 kPa. Figure 11
273 presents the deviatoric stress (q) and water pressure (u) vs. axial strain (ϵ_1) curves for tests
274 performed on samples from depths of 22.2. The sample was isotropically consolidated in
275 the overconsolidated domain at a vertical stress of 87 kPa ($0.4 \sigma'_p$) and sheared in
276 undrained conditions (CIU_{oc}). The results indicate that the soil has a strain-softening
277 behaviour in undrained conditions with peak shear strength of 65.6 kPa reached at an axial
278 strain of 1.4% and a strength of 41.9 kPa reached at an axial strain of 14.6% (end of test,
279 see Figure 11). The soil has therefore a strain-softening behaviour in undrained conditions
280 when tested in overconsolidated conditions.

281 DSS tests were performed on samples from depths of 22.1 and 22.7 m in unit B at location
282 32092, slightly above the river elevation. Figure 12 shows the stress-strain behaviour in a
283 shear stress (τ) vs. shear strain (γ) diagram obtained from these tests. Samples from depths
284 of 22.1 and 22.7 m were consolidated under a vertical effective stress of 91 ($0.4 \sigma'_p$) and
285 170 kPa (close to in situ σ'_v at the sample depth) respectively, and sheared while keeping
286 their height constant (constant volume) to prevent drainage and simulate an undrained

287 conditions. The test consolidated at 91 kPa reached a peak shear strength of 47.9 kPa at a
288 shear strain of 4.3% and at 26.8%, the shear strength had decreased to 31.9 kPa. It shows
289 a dilatant behaviour from shear strain of 0 to 5% and then became contractant for the rest
290 of the test. The sample consolidated at 170 kPa shows a peak shear strength of 55.6 kPa at
291 a shear strain of 3.2% and a shear strength of 28.2 kPa at a shear strain of 31%. Both tests
292 show strain-softening behaviours in DSS constant volume when tested at slightly to
293 moderately overconsolidated conditions. Such large deformation shear strengths are much
294 larger than shear strength of the remoulded soil (~1.6 kPa, near the bottom of unit B).

295 *Ground water regime*

296 Piezometers were installed at location 32146 on the plateau, location 32100 close to the
297 crest of the slope, and at location 32145, near the toe of the slope (see location on Figure
298 3). Figure 13 presents the different piezometers installed at these locations (circles) and the
299 measured water levels (open triangles) along cross-section D-D' (located on Figure 3). This
300 cross-section has been drawn perpendicular to the slope at locations 32100 and 32145. It
301 has to be noted that piezometers at locations 32100 and 32146 are located a few meters
302 from the cross-section D-D' (see Figure 3). It can be observed that water levels measured
303 at location 32146, indicate a slight downward flow with a groundwater table close to the
304 ground surface. Similar observations are made for piezometers at location 32100 located
305 behind the crest of the slope. On the other hand, near to the toe of the slope, at location
306 32145, the measured water elevations increase with the depth of piezometers. The water
307 levels in piezometers in unit E at location 32145 are above the ground elevation (Figure

308 13). Therefore, upward seepage is present at the toe of the slope with high artesian water
309 pressure conditions.

310 **Location of the failure surface**

311 Figures 8 and 9 show cross-sections B-B' and C-C' of the topography before and after the
312 landslide (dashed and full black lines, respectively), location of the interpreted failure
313 surface (black dots), and displacement vectors of some debris (red arrows). Locations of
314 these cross-sections is shown on Figure 3. In this section, only cross-sections B-B' and C-
315 C' are presented. Cross-section A-A' will be discussed later in section Discussion on the
316 landslide failure mechanism. On Figures 8 and 9, the topography after the landslide was
317 obtained from a DEM made by combining aerial and terrestrial LIDAR surveys performed
318 a few days after the landslide. The failure surface was defined using the difference in shear
319 strength of the intact soil and the above remoulded debris from the 26 CPTUs performed
320 inside the scar and located on Figure 3. An example is shown on Figure 14 where, the
321 CPTU carried out at location 32060 in 2004, before the landslide, shows the intact strength
322 profile of the soil and the CPTU at location 32103 shows the strength profile of the debris
323 following landslide deformation. The difference between both profiles delimits the debris
324 thickness having lower strength than the intact soil. The point where the strength of the soil
325 in the debris becomes equal to the intact strength defines the elevation of the failure surface
326 (Figure 14).

327 Figures 8 and 9 show that the failure surface is located at an elevation of about 3.5 m near
328 the toe of the initial slope. This is about 2.5 m below the elevation of the Salvail River bed
329 observed on the north of the 2010 landslide, when its course was blocked by debris. At the

330 locations of cross-section B-B' (Figure 8), the failure surface is horizontal over a length of
331 about 115 m, away from the initial river location, and then rises up suddenly to an elevation
332 of around 14 m before reaching the backscarp of the landslide. Along cross-section C-C'
333 (Figure 9) the failure surface is at about elevation 3.5 m for about 125 m inside the deposit
334 and comes up to an elevation of about 14 m. Along cross-section A-A', the main failure
335 surface has a length of about 80 m before jumping to about an elevation of 14 m (see section
336 Discussion on the landslide failure mechanism).

337 **Modeling of the ground water seepage and stability of the initial slope**

338 *Seepage modeling*

339 In order to evaluate the pore water pressures present before the landslide, a steady-state
340 seepage model of groundwater conditions was performed using Seep/W (Krahn 2004a). A
341 simplified geometry of the slope before the landslide was estimated according to cross-
342 section B-B' shown in Figure 8. The stratigraphy of the slope was estimated according to
343 the data obtained from CPTU at location 32060 and from boreholes and CPTUs performed
344 around the landslide (Figures 3 and 10). Hydraulic conductivity values used for each soil
345 unit are presented in Table 1. They are based on values measured in the laboratory and also
346 on vertical hydraulic gradient, observed in situ at some distance from the crest of the slope
347 at location 32146 (Figure 13), larger in units C and D than in unit B. Modeling was
348 performed using triangular elements having an average width of 1 m. The right, left, and
349 bottom boundaries were considered impervious and the slope itself was considered to be a
350 potential seepage face. The water elevation in the river was fixed at an elevation of 7 m (1
351 m above the bottom of the river bed). An infiltration rate of 4×10^{-10} m/s (1% of the normal

352 annual precipitation observed in the area) was imposed on the top flat part of the slope.
353 This infiltration rate was chosen so the modeled pore pressures would be similar to the
354 measured piezometer pore pressures at locations 32100, 32145, and 32146.

355 The seepage model shows that the hydraulic head in the till under the clay deposit reaches
356 an elevation of about 18.5 m at the level of the river, similar to the one observed in unit E
357 at location 32145 (see Figure 13). This represents water column of about 12.5 m above the
358 bottom of the river. Considering a water level in the river at an elevation of 7 m, this
359 represents an upward average gradient of around 0.7 over the clay deposit between the till
360 unit and the river bed. This results in very low effective stresses and shear strength values
361 near the foot of the slope. The long-term stability of the initial slope was analysed using
362 these modeled pore water pressures and SLOPE/W.

363 *Stability analysis*

364 Stability analyses were performed with SLOPE/W (Krahn 2004b) coupled with SEEP/W
365 in drained conditions in order to evaluate the long-term stability of the slope and in
366 undrained conditions as well to evaluate the safety factor for the observed failure surface.

367 The shear strength parameters used in the drained stability analysis are based on
368 preconsolidation pressure, as suggested by Lefebvre (1981). Cohesion and friction angle
369 values used for each unit are presented on Table 1. The grid and radius method was used
370 in SLOPE/W to determine the critical failure surface in drained conditions that gives an
371 indication of the long term stability of the slope. The critical failure surface and its
372 corresponding safety factor are presented on Figure 15. It can be seen that the critical failure

373 surface involved the bottom half of the slope (up to elevation 17.5 m), almost reaching the
374 top of unit C, and has a safety factor of 0.99 with Bishop method (1.03 with Morgenstern-
375 Price method). It also goes below the river bed. This analysis shows the precarious stability
376 of the slope before the event of 2010.

377 It is believed that the spread itself occurred in a matter of a few minutes (Locat et al. 2016).
378 It can therefore be assumed that the observed failure occurred in undrained conditions. An
379 undrained analysis was therefore performed to evaluate the safety factor for the entire
380 failure surface observed on site. The strength profile obtained from the field vane shear
381 tests at location 32100 (see Figure 10) was used for this undrained analysis in SLOPE/W
382 and the fully specified SLOPE/W option used to define the failure surface observed on site.
383 The resulting safety factor obtained from this analysis is 2.16, with the Bishop method
384 (2.26 with Morgenstern-Price method). Therefore, this analysis cannot explain the entire
385 event that occurred in 2010 at Saint-Jude. It shows the limits of the usual limit equilibrium
386 method and indicates that another calculation method is needed to explain the observed
387 landslide and its failure mechanism.

388 **Landslide detailed description**

389 *Morphology of the landslide*

390 Analysis of the aerial photographs presented on Figure 3 enabled to determine the size of
391 the landslide. Using definitions from Cruden and Varnes (1996), the width of the displaced
392 mass is about 275 m, the length of the zone of depletion is about 150 m and the total length
393 of the landslide is about 210 m (Figure 3). The surface of the scar itself is about 42 000 m²

394 and the total area affected by the landslide (delimited by the full black line) is about 53 500
395 m². The maximum retrogression of the landslide, taken from the crest of the initial slope to
396 its backscarp, is approximately 80 m. The position of the failure surface, as described
397 above, made it possible to calculate a total volume of displaced material of about 520 000
398 m³. The debris blocked the Salvail River and moved onto the opposite bank over a distance
399 of about 60 m. There was no significant movement of the debris up-stream or down-stream
400 of the Salvail River.

401 Traces of the initial river bed, including fresh water mussels' shells and recent river deposit,
402 were found 50 m from their original position near the toe of the landslide (at its north-west
403 boundary). In addition, CPTUs performed along cross-section B-B' (Figure 8) near the
404 initial Salvail River location show that the failure surface passed below the Salvail River.
405 These observations indicate that the failure surface came up at the ground surface on the
406 west side of the Salvail River. Soil located near the north-west limit of the landslide
407 therefore corresponds to soil from the initial river bed that was pushed and uplifted from
408 elevation 6 m to elevation 15 m onto the opposite side of the Salvail River during the
409 landslide.

410 The debris of the landslide can be divided into four different zones based on the observed
411 morphology. Delimitation of these zones is shown on Figures 3, 8 and 9 by dashed lines.
412 Zone 1 is a highly fissured area in which parts of the initial river bed were observed, mainly
413 at its north-west border. Zone 1 is approximately 22% of the total landslide area. As
414 explained above, soil in this zone corresponds to the initial Salvail River bed and banks
415 that were pushed above the opposite side of Salvail River.

416 Zone 2 is an area with a few fissures and vegetation that was generally intact. The ground
417 surface is roughly horizontal and trees were still standing, slightly inclined toward the
418 backs carp of the landslide. As shown on to Figures 3, 8 and 9, zone 2 is about 20% of the
419 total landslide area and lies on top of the Salvail River initial location and bottom of the
420 initial slope. Observations of displacement vectors of some debris located on aerial
421 photographs before and after the landslide indicates that the soil in this zone was initially
422 from the upper two thirds of the initial slope that was pushed above the Salvail River's
423 initial location in a continuous movement that kept the soil relatively intact.

424 Zone 3 is a highly fissured area where the ground dislocated in several blocks. A part of
425 this zone can be observed on the upper left of Figure 4. Some of the blocks in this zone
426 have flat tops covered with intact vegetation and other blocks are prisms with tips pointing
427 upward. As explained above, these blocks are respectively called grabens and horsts.
428 Figure 6 presents a photograph of a horst and a graben at the boundary between zones 3
429 and 4, near the house. As can be observed on Figures 8 and 9, spacing and inclination of
430 fissured as well as the presence of vegetation on top of some horsts in zone 3 make it
431 difficult to distinguish horsts from grabens in this zone. Stratigraphy in these blocks is
432 generally close to the horizontal, indicating that they did not rotate during the landslide.
433 These blocks moved over a distance of 20 to 40 m towards the Salvail River and subsided
434 by about 8 m. This zone forms approximately 24% of the landslide area. From displacement
435 vectors, it can be assumed that soil in zone 3 is was near the crest and the first 20 m of the
436 top of the initial slope (see Figure 8b).

437 Zone 4 is an area formed of soil that was dislocated into horsts and grabens forming sub-
438 parallel stripes oriented perpendicular to the direction of the landslide movement. Part of
439 this zone located in the south part of the landslide is presented on the left of Figure 4. In
440 this zone, grabens are well defined by their flat tops covered with vegetation or pieces of
441 the road. Horsts form ridges of clay with sides inclined at around 60° (varying between 45
442 and 80°). Figure 5 shows a good example of a horst and a graben from zone 4. As can be
443 observed on the horst on Figure 5, stratifications inside horsts were inclined between 0 and
444 17° with the horizontal (see also Figures 8a and 9a), indicating that these blocks did not
445 rotate much during the movement. It was also observed that the downstream side of some
446 horsts was covered with brown soil, thus coming from the sandy crust and contrasting with
447 the grey clay (unit B) forming them. This last observation was also noted by Carson
448 (1979a), on the 1978 landslide at Rigaud, and by Geertsema et al. (2006), on the Mink
449 Creek landslide. In addition to horsts and grabens, slices of soil, originally horizontal, were
450 found inclined after the movement at an angle of 25 to 50° with respect to the horizontal
451 (see Figures 8a and 9a). These slices were observed directly behind some horsts. At some
452 other places, inclined slices had slid over grabens in front of them, as seen on Figure 7.
453 These slices were also observed at the base of grabens located near the backscarp of the
454 landslide. Such slices have rarely been observed or at least reported for this type of
455 landslide, except in the case of the 1978 Sainte-Madeleine-de-Rigaud spread described by
456 Carson (1979a) and at Mink Creek in British Columbia (Geerstema 2004). Soil in zone 4
457 is soil that was initially between the initial location of the house and the backscarp of the
458 landslide. Zone 4 covers about 34% of the total landslide area.

459 *Characteristics of the debris*

460 Four trenches were dug into horsts and inclined slices in order to observe their
461 stratifications and understand their formation (see Figure 3 for location). Figure 16 shows
462 a photograph of the trench at location 32152, close to cross-section C-C' (see Figures 3 and
463 9a for location) and inclined slices shown on Figure 7, that has been observed in details. It
464 can be seen that the trench has exposed close 3 m of the top of these inclined slices (on the
465 left side of Figure 16) and a horst (on the right side of Figure 16) in the direction
466 perpendicular to the general ground movement. The two types of structure are easily
467 differentiated by the inclination of their stratifications. The stratifications of the horst are
468 inclined of about 10° to the horizontal whereas the stratifications of the slices are inclined
469 close to 50° to the horizontal. The contact between the horst and the slices has an angle of
470 about 70° to the horizontal. This angle as well as the inclination of the stratification
471 indicates that this horst has been rotated by about 10° . The different slices have a thickness
472 of about 60 cm each with several of them outcropping side by side immediately behind the
473 horst. They were separated by shear zones made up of silty soil, having a thickness close
474 to 2 mm, and following stratification.

475 CPTUs and boreholes at locations 32140 and 32141 (see figures 17 and 18 respectively)
476 were performed through the inclined slices near the trench at location 32152, shown on
477 Figure 16. Water content was also measured on soil samples at various depths from these
478 boreholes. In addition, these samples were passed through CAT scan to obtain images of
479 the stratifications of the intact soil. Each profile also presents the description of soil units,
480 the water content profile, the undrained shear strength interpreted from CPTU, and the
481 location of the failure surface. Readers should refer to Locat et al. (2011b) for further detail
482 about these boreholes.

483 Results from location 32140 (Figure 17) show that the failure surface is located at a depth
484 of 17.3 m (elevation 3.5 m). Debris at this location are represented by unit F subdivided
485 into 5 subunits: F1, F2, F3, F4, and F5. Subunit F1 (from the ground surface down to a
486 depth of 5.1 m) is a soft silty clay with stratifications inclined at about 45° to the horizontal.
487 The average water content of this subunit is about 65%, typical of unit B on Figure 10, and
488 the shear strength varies from 16 to 27 kPa with depth. This subunit corresponds to the
489 inclined slices observed from the ground surface (see figure 13). From a depth of 5.1 m
490 down to a depth of 8.6 m, a stiff grey-brown sandy and silty layer is observed (subunit F2).
491 CAT scan shows that stratification in this subunit is slightly inclined. The average water
492 content is 29% and shear strength has values between 50 to 200 kPa. These characteristics
493 are typical of the sandy crust observed in intact soil (unit A on Figure 10). Underneath, lays
494 a very soft grey clayey silt having inclined stratifications from depths 8.6 to 11.6 m,
495 becoming more clayey at a depth of 11 m (subunit F3). The water content of this subunit
496 varies from 24 to 70% and the shear strength is around 3 kPa. A soft grey silty clay with
497 inclined and folded stratification was found from depths of 11.6 to 12.8 m (subunit F4).
498 The average water content is 62% and shear strength varies from 24 to 30 kPa with depth.
499 Geotechnical properties of this subunit indicate that it is soil from unit B that was sheared
500 during the landslide. Stiff grey silty clay with horizontal stratifications (subunit F5) is found
501 below a depth of 12.8 m down to the failure surface observed at a depth of 17.3 m. The
502 water content in this subunit is generally constant with an average value of 65%. The shear
503 strength varies from 45 to 65 kPa with depth. These characteristics are typical of the soil
504 from unit B on Figure 10 that was involved in the landslide. Below the failure surface units
505 B, C, and D, also detected in the intact deposit (Figure 10), are observed. They exhibit

506 properties similar to those observed at locations 32092 and 32100, indicating continuity in
507 the stratigraphy of the deposit.

508 Results from location 32141 (Figure 18) show that the failure surface is located at a depth
509 of 16.9 m (elevation 3.7 m). Debris (unit F) at this location can be divided in three subunits:
510 F1, F4 and F5 (Figure 18). A soft grey silty clay with stratification inclined at about 45° to
511 the horizontal is observed from the ground surface down to a depth of 9.8 m. Its water
512 content is 62% in average and the shear strength varies from 17 to 39 kPa. Around a depth
513 of 9 m, the shear strength decreases down to about 3 kPa. This subunit presents similar
514 properties with subunit F1 at location 32140 (Figure 17) and originates from unit B. It
515 corresponds to inclined slices observed at the ground surface. Grey stiff soft silty clay with
516 folded and disturbed stratifications is observed from a depth of 9.8 m to a depth of 10.6 m.
517 A sample from this subunit shows almost vertical stratifications. The average water content
518 is 65% and the shear strength of the soil varies from 40 to 50 kPa. The properties of this
519 subunit correspond to soil from unit B (Figure 10) that was sheared during the landslide
520 and are comparable with subunit F4 from location 32140 (Figure 17). From 10.6 m down
521 to the failure surface, at a depth of 16.9 m, a stiff grey silty clay with horizontal
522 stratifications is observed. The average water content of this subunit is 65% and its shear
523 strength varies from 50 to 70 kPa with depth. The properties of this subunit are similar to
524 those observed for unit B (Figure 10), involved in the landslide and are similar to those of
525 subunit F5 (Figure 17). Below the failure surface Units B, C and D have been observed and
526 represent the intact soil under the landslide body.

527 CPTU 32120 was performed through the horst exposed by trench at location 32152 and
528 shown on Figure 16, near location 32140 (see Figure 3). Figure 19 shows the results of this
529 in situ test. At this location, the failure surface is at a depth of 16.8 m (elevation 3.8 m) and
530 the debris (unit F) can be divided in three subunits: F6, F2 and F3. It can be seen that for
531 the first 3 m, the corrected tip resistance and the pore pressure are about 400 kPa and 200
532 kPa respectively, indicating a clayey soft layer. This indicates that this subunit F6
533 corresponds to the horst observed at the ground surface (Figure 16). From a depth of 3 m
534 to a depth of 8 m, the corrected tip resistance varies from 550 kPa to more than 3000 kPa
535 and the pore pressure is closed to 0 kPa. This indicates a stiff coarse layer very similar to
536 the sandy crust observed at location 32140 (subunit F3 on Figure 17). From a depth of 8 m
537 down to a depth of 16.8 m (depth of the failure surface), the soil is a grey silty clay and the
538 corrected tip resistance varies between 300 to 600 kPa. Under the failure surface the intact
539 soil, observed at location 32100 (Figure 10) is also detected and corresponds to units B, C
540 and D as observed at location 32100.

541 Figure 20 shows location of profiles 32120, 32140 and 32141 (Figures 17 to 19) on part of
542 cross-section C-C' (see Figure 9), and examples of CPTU and CAT scan images obtained
543 at location 32140. A schematic cross-section of the trench and location of these soundings
544 is also shown in figure 20. Extrapolating the subunits observed at locations 32120, 32140
545 and 32141 it is possible to get an approximate interpretation of the stratigraphy near these
546 three soundings. The top soft silty clay layer (subunit F1 on Figures 17 and 18) represents
547 inclined slices observed at trench 32152, on Figure 16 and is originating from unit B
548 (Figure 7). Unfortunately, this latter unit is so homogeneous in terms of water content that
549 it is not possible to specify the original elevation of that subunit. The stiff sandy layer

550 (subunit F2 on Figures 17 and 19) seen on profiles 32140 and 32120 represents the sandy
551 crust of a graben (graben on the right on figure 20a). Subunit F3, observed at locations
552 32140 and 32120 (Figures 17 and 19), would correspond to soil below this sandy crust
553 forming the bottom of this graben. Units F5 (Figures 17 and 18) show horizontal
554 stratification above the failure surface that seems to correspond to the lower base of the
555 horst. Subunit F4 (Figures 17 and 18) would correspond to a shear zone forming between
556 the base of the inclined slices and the horst sides during the movement. The tip of that horst
557 (observed on Figure 16 and corresponding to subunit F6 on Figure 19) could have been
558 swept away on top of the graben by the inclined slices, creating the observed morphology.

559 Another CPTU, performed at location 32118 in the debris (see figure 3 for location) shown
560 on Figure 21, presents a sandy crust (unit A as presented on figure 7) located a depth of 10
561 m in the debris and covered by what can be identified as a silty clay layer. This indicates
562 that, at this location, the sandy crust, originally located at the ground surface, subsided from
563 an elevation of 28 m down to an elevation of 10 m and was covered by other debris. This
564 is considered to be the lowest elevation where the sandy crust is found in the debris. This
565 detailed study shows the complexity of soil movements that occurred during the 2010
566 Saint-Jude spread.

567 **Discussion on the landslide failure mechanism**

568 Based on the 2010 Saint-Jude landslide investigation presented above, and as shown in
569 Figure 15, the bottom half of the slope was marginally stable, which is in accordance with
570 the observed ground movements on aerial photograph of the site taken in august 2009 (see
571 section The landslide and its regional context). Debris of these movements were probably

572 eroded during the 2010 spring, unloading the toe of the slope and further decreasing the
573 overburden pressure under the river. It has to be noted that there was no witness, nor any
574 indication that an initial slide large enough to be noted by the residents of the house could
575 have occurred just before the main landslide. The family living on the site did not mention
576 anything about such an event to a visitor who talked to them half an hour before the main
577 event. It is therefore difficult to know the exact trigger of the 2010 landslide, but it can be
578 taught that an initial instability could have developed, with time, near the toe of the slope
579 and, given the high artesian pore pressures, reduced the vertical and horizontal stresses
580 under the river, and initiated the main failure surface 2.5 m below the river bed elevation.
581 From that point, the failure progressed horizontally for about 125 m in the intact deposit,
582 as seen on Figures 8 and 9. The presence of high artesian pressure could have influenced
583 the location of the failure surface, located 2.5 m below the river bed. However, the exact
584 influence of such hydraulic conditions on the failure mechanism is still not clear and should
585 be studied further in relation to spreads. These observations indicate that, most probably,
586 the 2010 landslide seems to be of natural origin and triggered by erosion near the toe of the
587 slope with high artesian pressures under the river, and deepening of the river with time with
588 a process similar to that described by Lefebvre (1986).

589 As explained by Bjerrum (1967), Quinn et al. (2011), Locat et al. (2011a, 2013 and 2015)
590 and Leroueil et al. (2012), progressive failure can explain how a failure surface can
591 progress horizontally into an intact soil mass creating a spread. Locat et al. (2011a, 2013
592 and 2015) associated the development of spreads in sensitive clays with progressive failure
593 by two distinct processes: (i) propagation of the failure surface horizontally into an intact
594 soil mass and (ii) dislocation of the soil mass above the failure surface into horsts and

595 grabens. As explained by Leroueil (2012), development of progressive failure requires: (i)
596 a geomaterial with strain softening behaviour; (ii) non-uniformity of stresses; (iii) boundary
597 conditions enabling the slope to deform; and (iv) stresses exceeding the peak shear strength
598 of the soil. The present study demonstrates that the Saint-Jude landslide corresponds to all
599 of these criteria: (i) the clay involved in the landslides presents a strain-softening behaviour
600 during shear (see Figures 11 and 12); (ii) shear stresses were present in the slope, giving
601 the initial slope inclination; (iii) the soil mass involved in the landslide was free to move
602 towards the opposite river bank; and (iv) the initial slope was unstable, as demonstrated by
603 the stability analysis taking into account the high hydraulic gradient under the river. It is
604 also probable that the shear stresses were larger than or closer to the peak shear strength of
605 the soil near the toe of the slope (Figure 15). Conditions for progressive failure seem
606 therefore to have been present and progressive failure could have taken an important role
607 in the initiation and propagation of the main failure surface. In addition, Locat et al. (2011a,
608 2013 and 2015) explained and demonstrated that when progressive failure is taken into
609 account to understand spreads in sensitive clays, only a small unloading near the toe of the
610 slope can initiate a failure surface resulting in a spread. As mentioned above, it is not clear
611 what was the importance of the trigger necessary to initiate the 2010 Saint-Jude landslide.
612 It can be said that, as the safety factor of the initial slope was low, the magnitude of the
613 trigger did not need to be large in order to initiate the main failure surface under the river
614 bed.

615 Giving the detailed study of the morphology of this landslide, it was possible to reconstruct
616 the initial and final conditions of the debris and understand better the dislocation
617 mechanism that occurred during this spreads. Figure 22 presents cross sections A-A', B-

618 B' and C-C' before and after the landslide, showing the probable initial and final position
619 of the debris. The final positions of horsts presented in Figures 22b, d and f were
620 determined from field observations and correspond to horsts presented on Figures 8 and 9.
621 Locations of sandy crust and parts of horsts B-2 and C-3 that are below the ground surface
622 after the landslide were determined by careful study of soundings performed inside the
623 landslide as described in section Characteristics of the debris. The initial probable positions
624 of horsts presented in Figures 22a, c and e were estimated with the help of the
625 displacements vectors of targets shown in Figures 8 and 9 (further details on displacement
626 vectors are given in Locat et al. 2011b) and by assuming that (i) horsts had tip angle of 60°
627 (see Locat et al. 2011a) and (ii) that they only translated during the movement with no
628 subsidence, keeping their initial shape.

629 From Figure 22, it can be interpreted, that once the main failure has been formed inside the
630 intact deposit, the entire soil above moved horizontally towards the river and the bottom of
631 the river was pushed over the opposite bank. This created morphological zones 1 and 2
632 (Figures 3, 8 and 9). As the failure surface continued its progression, the above soil mass
633 dislocated in horsts (A-1, A-2, B-1, B-2, C-1, C-2 and C-3 on Figure 22) and grabens
634 observed in zone 3 (Figures 3, 8 and 9). This first phase of the movement seems to have
635 stopped behind the house, as seen on Figures 8 and 22, where the failure surface gets at a
636 higher elevation of 14 m. Stratifications in horsts are inclined between 0 and 15° with the
637 horizontal, which corresponds to stratifications in intact soil. This indicates that horsts
638 moved mainly horizontally with only minor rotation during the landslide. The presence of
639 these horsts enables to classify this landslide as a spread. In addition, inclinations of horsts'
640 sides are inclined at about 60° to the horizontal. This inclination corresponds to the results

641 of an active failure, as seen in undrained triaxial tests on clay. Horsts seem therefore to be
642 formed by active failure occurring during the landslide as explained by Locat et al. (2011a,
643 2013 and 2015).

644 Looking at Figure 22, it can be seen that horsts A-1, A-2, B-1, C-1 and C-2 have moved
645 toward the initial position of the river and were compressed against the debris from zone 1
646 and 2 stopped on the opposite bank. It can also be seen that for each cross-section, sandy
647 crust on top of grabens behind horsts A-2, B-1 and C-2 were found deep in the debris at
648 level of soundings 32118 (Figure 21), 32119, 32120 (Figure 19) and 32140 (Figure 17) and
649 covered with debris from horsts A-3, B-2 and C-3 located behind them. This indicates that
650 grabens behind these horsts subsided, probably allowing overtopping when horsts B-2 and
651 C-3 moved toward the river and were stopped by the lower downstream debris. It seems
652 that the movement was fast enough for the tips of horsts B-2 and C-3 to be disconnected
653 from their base and move over the lower graben as presented in Figures 16, 20, 22d and f
654 and explained in section Characteristics of the debris, creating zone 3.

655 An unstable scarp, creating the appropriate conditions for the upper failure surface to form
656 10 m higher than the first one (see Figures 8, 9, 21, and 22), seems to have formed after the
657 first phase of the movement creating zones 1 to 3. It is not clear how this upper failure
658 surface was formed, but progressive failure was probably also involved in this failure. As
659 this upper failure propagated, horsts A-3, A-4, A-5, B-3 and C-4 (Figure 22) and grabens
660 were formed. This part of the debris was delimited as zone 4 in Figures 3, 8 and 9. From
661 Figure 22, it can be observed that inclined slices found in this zone were formed as a result
662 of overlapping movement of graben tops when this soil mass slid on top of downstream

663 debris. It is not exactly clear how the upper failure surface and inclined slices have formed,
664 but reconstitution of the movement in Figure 22 explains observations near trench 32152
665 showing how inclined slices and horst tips moved on top of grabens and, in doing so,
666 crushed the house basement and indicating that the kinetic energy of the landslide was very
667 high.

668 **Conclusion**

669 The 2010 landslide at Saint-Jude has been very well documented. The stratigraphy and the
670 geotechnical properties were found to be uniform around the landslide. The soil involved
671 in the landslide mainly consists of sensitive grey clay typical of Champlain Sea Clay, with
672 liquidity index varying from top to bottom between 2 to 1, intact shear strength increasing
673 linearly with depth from 25 to 65 kPa and an OCR decreasing over the same depths from
674 1.9 to 1.2. The important points resulting from the investigation of the landslide are:

- 675 • River erosion and high artesian pore pressures under the river seem to have been
676 aggravating factors decreasing the stability of the initial slope.
- 677 • It is believed that the Saint-Jude landslide could have been triggered by natural
678 causes. The magnitude of the triggering event that initiated this landslide is however
679 not known, but could have been small given the low stability of the initial slope.
- 680 • The failure surface was identified with CTPUs tests. It started 2.5 m under the river
681 elevation and propagated almost horizontally over 100 m in the intact deposit.
- 682 • The initial slope moved over the opposite side of the river with only a little
683 disturbance in the debris. Behind it, the soil mass dislocated in several blocks,
684 having horst and graben shapes.

- 685 • An upper failure surface, about 10 m higher than the main one was also located
686 with CPTUs. This seems to indicate that the movement has occurred in two
687 successive phases, along two failure surfaces at different elevations. This is one of
688 the first time that two failure surfaces are clearly observed in a spread.
- 689 • Stratifications in horsts indicate that the main movement of the debris was mostly
690 translational along the failure surface, with little or no rotation. This indicates that
691 the landslide did not occur as the result of a succession of rotational slides, which
692 would have induced more rotation of the debris and might not have led to the
693 formation of a continuous failure surface.
- 694 • Another rare particularity of this landslide is the presence of inclined slices
695 observed in the upper part of the debris. These inclined slices could result from the
696 rotation of the bottom part of some grabens sliding along the upper failure surface
697 onto the debris from the lower failure surface.
- 698 • Reconstitution of the initial position of the debris allowed the understanding of the
699 dislocation of the debris and showed the complexity of the 2010 Saint-Jude spread.

700 The investigation of the Saint-Jude landslide gives valuable information on the
701 mechanisms and kinematics of spreads occurring in sensitive clays, which are very
702 different from other types of retrogressive landslides such as flowslides. It also emphasizes
703 the need of detailed investigations in order to understand the conditions of initiation and
704 development of spreads.

705 **Acknowledgments**

706 The authors would like to acknowledge the precious collaboration of Saint-Jude municipal
707 authorities, particularly Mayor Yves de Bellefeuille and General Director Sylvie
708 Beaugard. Sincere thanks to the family of the people that lost their life in this tragic event
709 and also to the Saint-Jude citizens for their essential collaboration during this investigation.
710 Without their assistance, this work would not have been possible.

711 Many people at the MTMDET need to be acknowledged for their contribution to this work,
712 in particular: Martin D'Anjou, Thomas Fournier, Gilbert Grondin, Denis Hudon, Daniel
713 Ouellet and Mélissa Raymond. Finally, the authors would also like to recognize François
714 Noël for realizing, as an MTMDET intern, detailed cross-sections of the landslide
715 presented in this paper and Sandra Veillette, a master student, for the help with some figures
716 used in this paper. Dr. Pete Quinn and another anonymous reviewer are acknowledged for
717 their constructive comments.

718 **References**

- 719 Bjerrum, L. 1967. Progressive failure in slopes in overconsolidated plastic clay and clay
720 shales. Terzaghi Lecture. Journal of the Soil Mechanics and Foundations Division,
721 ASCE, **93**(5): 3-49.
- 722 Carson, M. A. 1979a. *Le glissement de Rigaud (Québec) du 3 Mai 1978: Une interprétation*
723 *du mode de rupture d'après la morphologie de la cicatrice*. Géographie physique
724 et Quaternaire, **33**(1): 63-92.
- 725 Carson, M. A. 1979b. *On the retrogression of landslides in sensitive muddy sediments:*
726 *Reply*. Canadian Geotechnical Journal, **16**(2): 431-444.

- 727 Cruden, D. M., and Varnes D. J. 1996. *Landslides types and processes*. In *Landslides*
728 *investigation and mitigation*, Special Report 247, Transportation, Research Board,
729 National Research Council, Edited by A. K. Turner, and R. L. Schuster, National
730 Academy press, Washington, D.C. pp. 37-75.
- 731 Demers, D., Robitaille, D., and Perret, D. 2000. *The St. Boniface Landslide of April 1996 :*
732 *a Large Retrogressive Landslide in Sensitive Clay with Little Flow component*. In
733 *Proceedings of the 8th International Symposium on Landslides*, Cardiff, 26-30 June
734 2000. Thomas Telford Publishing, London, Vol. 1, pp. 447-452.
- 735 Geertsema, M., Cruden, D. M., and Schwab, J. W. 2006. *A large landslide in sensitive*
736 *glaciomarine sediments at Mink Creek, northwestern British Columbia, Canada*.
737 *Engineering Geology*, **83**(1-3): 36-63.
- 738 Geertsema, M. 2004. *A composite earthflow-spread in sensitive glaciomarine sediments*
739 *near Terrace, British Columbia*. M.Sc. thesis, University of Alberta, 147 pp.
- 740 Grondin, G. and Demers, D. 1996. *The Saint-Liguori flakeslide: Characterisation and*
741 *remedial works*. In *Proceedings of the 7th International Symposium on Landslides*,
742 Trondheim, Norway, 17-21 June 1996. *Edited by K. Senneset*. Balkema, Rotterdam,
743 the Netherlands. Volume 2, pp. 743-748.
- 744 Hungr, O., Leroueil, S., and Picarelli L. 2014. *The Varnes Classification of landslide types,*
745 *an update*. *Landslides*, **11**(2): 167-194.
- 746 Krahn, J. 2004a. *Seepage modeling with SEEP/W, an engineering methodology*. GEO-
747 SLOPE International, Ltd., Calgary, Alta.
- 748 Krahn, J. 2004b. *Stability modeling with SLOPE/W, an engineering methodology*. GEO-
749 SLOPE/W International, Ltd., Calgary, Alta

- 750 Lefebvre, G. 1986. *Slope instability and valley formation in Canadian soft clay deposits*.
751 Canadian Geotechnical Journal, **23**(3): 261-270.
- 752 Lefebvre, G. 1981. *Fourth Canadian Geotechnical Colloquium: strength and slope*
753 *stability in Canadian soft clay deposits*. Canadian Geotechnical Journal, **18**(3): 420-
754 442.
- 755 Leroueil, S., Locat, A., Eberhardt, E., and Kovacevic, N. 2012. Keynote Lecture:
756 *Progressive failure in natural and engineering slopes*. In: EBERHARDT E. et al.
757 (eds) *Landslides and Engineered Slopes: Protecting Society through Improved*
758 *and Understanding*. Proceedings of the 11th International and 2nd North American
759 Symposium on Landslides, 3-8 June 2012, Banff, Alberta. Taylor & Francis
760 Group. pp. 31-46.
- 761 Leroueil, S., Tavenas, F., and Le Bihan, J.-P. 1983. *Propriétés caractéristiques des*
762 *argiles de l'est du Canada*. Canadian Geotechnical Journal, 20(4): 681–705.
- 763 Locat, A., Demers, D., and Leroueil, S. 2016. *Spreads in Canadian sensitive clays*. In:
764 AVERSA, S. et al. (eds.) *Landslides and Engineered Slopes – Experience, Theory*
765 *and Practice*. Proceedings of the 12th International Symposium On Landslides. 12-
766 19 June 2016, Napoli, Italy. Taylor & Francis Group. pp. 1295-1304.
- 767 Locat, A., Leroueil, S., Bernander, S., Demers, D., Jostad, H. P., and Ouehb, L. 2011a.
768 *Progressive failures in Eastern Canadian and Scandinavian sensitive clays*.
769 Canadian Geotechnical Journal, **48**(11): 1696-1712.
- 770 Locat, A., Leroueil, S., Bernander, S., Demers, D., Locat, J., and Ouehb, L. 2008. *Study of*
771 *a lateral spread failure in an eastern Canada clay deposit in relation with*
772 *progressive failure: The Saint-Barnabé-Nord Slide*. In Proceedings of the 4th

- 773 Canadian Conference on Geohazards: From Causes to Management. Québec, Que.,
774 20-24 May 2008. Edited by J. Locat, D. Perret, D. Turmel, D. Demers et S. Leroueil,
775 Presses de l'Université Laval, Québec, Que. pp. 89-96.
- 776 Locat, A., Leroueil S., Locat P., Demers D., Robitaille, D., et Lefebvre, G. 2012a. *In Situ*
777 *Characterisation of the Saint-Jude landslide, Québec, Canada*. In the Proceedings
778 of the 4th International Conference on Geotechnical and Geophysical Site
779 Characterisation, ISC'4, 18-21 September, 2012, Porto de Galinhas, Brazil. Vol.
780 1, pp. 507-514.
- 781 Locat P., Demers D., Robitaille D., Fournier T., Noël F., Leroueil S., Locat A., et
782 Lefebvre G. 2012b. *The Saint-Jude landslide of May 10, 2012, Québec, Canada*.
783 *Dans* Eberhardt, E. et al. (eds) *Landslides and Engineered Slopes: Protecting*
784 *Society through Improved and Understanding*. Proceedings of the 11th
785 International and 2nd North American Symposium on Landslides, 3-8 June 2012,
786 Banff, Alberta. Taylor & Francis Group. pp. 635-640.
- 787 Locat, P., Fournier, T., Robitaille, D., and Locat, A. 2011b. *Glissement de terrain du 10*
788 *mai 2010, Saint-Jude, Montérégie, Rapport sur les caractéristiques et les causes*.
789 Rapport MT11-01. Section des mouvements de terrain, Services de la géotechnique
790 et de la géologie, Ministère des transports du Québec. Bibliothèque et Archives
791 nationales du Québec, Gouvernement du Québec. 101 p.
- 792 Ochiatti, S. 1989. *Quaternary geology of St. Lawrence Valley and adjacent Appalachian*
793 *subregion*. In: Fulton, R.T. (ed.), *Quaternary Geology of Canada and Green-land*,
794 Geological Survey of Canada, Geology of Canada, 1 (also: Geological Society of
795 America, *The Geology of North America*, K-1), 350-379.

- 796 Odenstad, S. 1951. *The landslide at Sköttorp on the Lidan River, February 2, 1946*. Royal
797 Swedish Institute Proceedings, **4** :1-40.
- 798 Quinn, P.E., Diederichs, M.S., Rowe, R.K. and Hutchinson, D.J. 2011. A new model for
799 large landslides in sensitive clay using a fracture mechanism approach. *Canadian*
800 *Geotechnical Journal*, **48**(8)L 1151-1162.
- 801 Rissmann, P., Allard, J.-D., and Lebuis, J. 1985. *Zones exposées aux mouvements de*
802 *terrain le long de la rivière Yamaska, entre Yamaska et Saint-Hyacinthe*. Ministère
803 de l'Énergie et des Ressources, Rapport DV 83-04.
- 804 Tavenas, F. 1984. *Landslides in Canadian sensitive clays - a state-of-the-art*. In
805 Proceedings of the 4th International Symposium on Landslides, Toronto, Ont., 16-
806 21 September 1984. University of Toronto Press, Toronto, Ont. Volume 1, pp. 141-
807 153.

808 TABLE AND FIGURE CAPTIONS

809 Table 1: Input parameters for seepage modeling and stability analysis.

810 Figure 1 : Location of the 2010 landslide at Saint-Jude. Dark grey area shows the extent of
811 the Champlain Sea deposit in Quebec.

812 Figure 2 : Digital elevation model of the region obtained from LIDAR surveys, showing
813 the numerous scars of interpreted previous landslides (dashed line) and the 2010 event.
814 Water flow in the Salvail River is from south to north.

815 Figure 3 : Aerial view of the landslide at Saint-Jude taken on May 11th 2010, the day after
816 the landslide while excavation work were going on near the house (Courtesy of
817 MTMDET). Location of the soundings, delimitations of the landslide and its morphological
818 zones as well as the crest of the slope are shown. Note that the crest of the slope inside the
819 landslide footprint is the estimated crest of the slope location before the landslide.
820 Movement direction of the debris is toward the Salvail River, at the top of the photograph.

821 Figure 4: General photograph of the south part of the landslide taken on May 11th 2010,
822 the morning after the landslide. Movement direction is toward the top left of the photograph
823 (Courtesy of MTMDET).

824 Figure 5 : Photograph of a horst and a graben close to section B-B' (see Figure 3), taken
825 on May 18th 2010, eight days after the landslide (modified from Locat et al. 2012a).

826 Figure 6: View of a graben and a horst behind the house, close to section B-B' (see Figure
827 3) taken on May 11th 2010, the morning after the landslide (Courtesy of MTMDET).
828 Movement direction is toward the left of the photograph.

829 Figure 7: Closer view of the south part of the landslide, close to section C-C' (see Figure
830 3), showing inclined slices (Courtesy of MTMDET). Movement direction is toward the
831 right of the figure. Photograph taken on May 11th 2010, the morning after the landslide.

832 Figure 8 : Cross-section B-B'. (a) 3 times vertical exaggeration and (b) to scale (see Figure
833 3 for location of cross-section, modified from Locat et al. 2012b).

834 Figure 9 : Cross-section C-C'. (a) 3 times vertical exaggeration and (b) to scale (see Figure
835 3 for location of cross-section, modified from Locat et al. 2012a).

836 Figure 10 : Geotechnical profile at location 32100 outside the footprint of the 2010
837 landslide (see Figure 3 for location). Where w_{cone} is fall cone test water content used to
838 calculate I_L , w_{natural} is the natural water content, I_P the plasticity index, σ'_{pCPTU} the σ'_p
839 estimated with CPTU, N_{σ_t} a dimensionless parameter for σ'_{pCPTU} , and σ'_v the vertical
840 effective stress calculated with pore water pressure from piezocone at location 32100
841 (u_{z32100}).

842 Figure 11 : Results of a triaxial undrained compression tests consolidated under an effective
843 stress (σ'_c) of 87 kPa on a sample taken at a depth of 22.2 m from the borehole at location
844 32092.

845 Figure 12 : Results of constant volume DSS tests (a) consolidated under an effective stress
846 of 90 kPa on a sample taken at a depth of 22.1 m and (b) consolidated under an effective
847 stress of 170 kPa on a sample taken at a depth of 22.7 m, both at location 32092.

848 Figure 13 : Cross-section D-D', view toward the north, piezometers at location 32145,
849 32100 and 32146 (see Figure 3 for locations, modified from Locat et al. 2012a).

850 Figure 14 : Failure surface identified by CPTU (see Figure 3 for location of CPTUs).

851 Figure 15 : Result of the drained stability analysis showing the critical failure surface
852 (dashed line) and grey zone locating failure surfaces giving a safety factor lower than 1.05.

853 Figure 16 : View toward the south-west of the trench 32152 and approximate location of
854 sites 32120, 32140 and 32141 (see Figures 3 and 9 for location). The picture was taken on
855 June 16th 2010, about a month after the landslide (modified from Locat et al. 2012a).

856 Figure 17 : Geotechnical profile at location 32140 in the debris (see Figure 3 for location).

857 Figure 18 : Geotechnical profile at location 32141 in the debris (see Figure 3 for location).

858 Figure 19 : CPTU profile at location 32120 in the debris and corresponding units as
859 described on Figures 17 and 18 (see Figure 3 for location).

860 Figure 20 : a) Approximate interpretation of the stratigraphy near trench 32152 (Figures 9
861 and 16), view toward the south-west, including location of soundings and b) example of
862 CPTU and CAT scan results at location 32140 (see Figures 3 and 9 for location, modified
863 from Locat et al. 2012a).

864 Figure 21: CPTU profile at location 32118 in the debris showing the sandy crust,
865 introduced on figure 10, buried at a depth 10 m under a layer of silty clay (see Figure 3
866 for location).


867 Figure 22: Drawing showing suggested position of each horst and graben before (a, c and
868 e) and after (b, d and f) the landslides for cross-sections A-A', B-B' and C-C'.

869

870 Table 1: Input parameters for seepage modeling and stability analysis.


Soil unit	k (m/s)	c' (kPa)	ϕ' ($^{\circ}$)
A	2×10^{-7}	0	35
B	9×10^{-10}	7.7	35
C	5×10^{-10}	7.7	40
D	5×10^{-10}		
E	1.5×10^{-7}		

871




872

873 Figure 1 : Location of the 2010 landslide at Saint-Jude. Dark grey area shows the extent of
 874 the Champlain Sea deposit in Québec.



875

876 Figure 2 : Digital elevation model of the region obtained from LIDAR surveys, showing
877 the numerous scars of interpreted previous landslides (dashed line) and the 2010 event.
878 Water flow in the Salvail River is from south to north.



880 Figure 3 : Aerial view of the landslide at Saint-Jude taken on May 11th 2010, the day after
 881 the landslide while excavation work were going on near the house (Courtesy of
 882 MTMDET). Location of the soundings, delimitations of the landslide and its morphological
 883 zones as well as the crest of the slope are shown. Note that the crest of the slope inside the
 884 landslide footprint is the estimated crest of the slope location before the landslide.
 885 Movement direction of the debris is toward the Salvail River, at the top of the photograph.



886

887 Figure 4: General photograph of the south part of the landslide taken on May 11th 2010,
888 the morning after the landslide. Movement direction is toward the top left of the photograph
889 (Courtesy of MTMDET).



890

891 Figure 5 : Photograph of a horst and a graben close to section B-B' (see Figure 3), taken
 892 on May 18th 2010, eight days after the landslide (modified from Locat et al. 2012a).




893

894 Figure 6: View of a graben and a horst behind the house, close to section B-B' (see Figure
 895 3) taken on May 11th 2010, the morning after the landslide (Courtesy of MTMDET).
 896 Movement direction is toward the left of the photograph.




897

898 Figure 7: Closer view of the south part of the landslide, close to section C-C' (see Figure
899 3), showing inclined slices (Courtesy of MTMDET). Movement direction is toward the
900 right of the figure. Photograph taken on May 11th 2010, the morning after the landslide.




901

902 Figure 8 : Cross-section B-B'. (a) 3 times vertical exaggeration and (b) to scale (see Figure
 903 3 for location of cross-section, modified from Locat et al. 2012b).




904

905 Figure 9 : Cross-section C-C'. (a) 3 times vertical exaggeration and (b) to scale (see Figure
 906 3 for location of cross-section, modified from Locat et al. 2012a).




908 Figure 10 : Geotechnical profile at location 32100 outside the footprint of the 2010
 909 landslide (see Figure 3 for location). Where w_{cone} is fall cone test water content used to
 910 calculate I_L , w_{natural} is the natural water content, I_P the plasticity index, $\sigma'_{p\text{CPTU}}$ the σ'_p
 911 estimated with CPTU, N_{ot} a dimensionless parameter for $\sigma'_{p\text{CPTU}}$, and σ'_v the vertical
 912 effective stress calculated with pore water pressure from piezocone at location 32100
 913 (u_{z32100}).




914

915 Figure 11 : Results of a triaxial undrained compression tests consolidated under an effective
 916 stress (σ'_c) of 87 kPa on a sample taken at a depth of 22.2 m from the borehole at location
 917 32092.



918


919 Figure 12 : Results of constant volume DSS tests (a) consolidated under an effective stress
 920 of 90 kPa on a sample taken at a depth of 22.1 m and (b) consolidated under an effective
 921 stress of 170 kPa on a sample taken at a depth of 22.7 m, both at location 32092.



922


923 Figure 13 : Cross-section D-D', view toward the north, piezometers at location 32145,

924 32100 and 32146 (see Figure 3 for locations, modified from Locat et al. 2012a).



925

926 Figure 14 : Failure surface identified by CPTU (see Figure 3 for location of CPTUs).



927

928 Figure 15 : Result of the drained stability analysis showing the critical failure surface
 929 (dashed line) and grey zone locating failure surfaces giving a safety factor lower than 1.05.






Figure 16 : View toward the south-west of the trench 32152 and approximate location of sites 32120, 32140 and 32141 (see Figures 3 and 9 for location). The picture was taken on June 16th 2010, about a month after the landslide (modified from Locat et al. 2012a).




934

935 Figure 17 : Geotechnical profile at location 32140 in the debris (see Figure 3 for location).




936

937 Figure 18 : Geotechnical profile at location 32141 in the debris (see Figure 3 for location).




938

939 Figure 19 : CPTU profile at location 32120 in the debris and corresponding units as
 940 described on Figures 17 and 18 (see Figure 3 for location).




941

942 Figure 20 : a) Approximate interpretation of the stratigraphy near trench 32152 (Figures 9
 943 and 16), view toward the south-west, including location of soundings and b) example of
 944 CPTU and CAT scan results at location 32140 (see Figures 3 and 9 for location, modified
 945 from Locat et al. 2012a).



946

947 Figure 21: CPTU profile at location 32118 in the debris showing the sandy crust,
 948 introduced on figure 10, buried at a depth 10 m under a layer of silty clay (see Figure 3
 949 for location).



950

951 Figure 22: Drawing showing suggested position of each horst and graben before (a, c and
 952 e) and after (b, d and f) the landslides for cross-sections A-A', B-B' and C-C'.

953