

See discussions, stats, and author profiles for this publication at: <https://www.researchgate.net/publication/366645547>

# STIFFENER AS A SPECIAL DESIGN SOLUTION FOR PRESSURE VESSEL REPAIR UKRUTNI PRSTEN KAO POSEBNO KONSTRUKTIVNO REŠENJE ZA SANACIJU POSUDE

Article · December 2022

CITATIONS

0

READS

19

7 authors, including:



Lazar Jeremic

University of Belgrade

15 PUBLICATIONS 68 CITATIONS

SEE PROFILE



Nikola Milovanović

University of Belgrade

17 PUBLICATIONS 69 CITATIONS

SEE PROFILE



A. Sedmak

University of Belgrade

434 PUBLICATIONS 3,169 CITATIONS

SEE PROFILE



Nenad Milosevic

Faculty of Mechanical Engineering University of Belgrade

22 PUBLICATIONS 81 CITATIONS

SEE PROFILE

Some of the authors of this publication are also working on these related projects:



TR 35040 [View project](#)



Research of possibility for improvement of welding technology of microalloyed steels [View project](#)

## STIFFENER AS A SPECIAL DESIGN SOLUTION FOR PRESSURE VESSEL REPAIR

### UKRUTNI PRSTEN KAO POSEBNO KONSTRUKTIVNO REŠENJE ZA SANACIJU POSUDE

Originalni naučni rad / Original scientific paper  
UDK /UDC:

Rad primljen / Paper received: 30.07.2022

Adresa autora / Author's address:

- 1) Reversible Hydropower Plant 'Bajina Bašta'
- 2) University of Belgrade, Innovation Centre of the Faculty of Mechanical Engineering, Belgrade, Serbia
- 3) University of Belgrade, Faculty of Mechanical Engineering, Serbia email: [asedmak@mas.bg.ac.rs](mailto:asedmak@mas.bg.ac.rs)

#### Keywords

- pressure vessel
- stiffener
- welded joints
- repair
- defect

#### Abstract

*The reparation of vessel 970 is shown, since the risk is very high (close to the worst case of both probability and consequence, being the highest). Since the defect location was not suitable for digging out and repair welding, it was decided to make a circumferential stiffener, to reduce the stress acting on the welded joint, so that both the stress intensity factor and net stress are reduced significantly.*

#### INTRODUCTION

After long-term operation, defects are found in welded joints in pressure vessel 970, Fig. 1. Given the high price and often the inability to purchase new working parts, there is a need for repairs. As mentioned above, after a long exploitation of the parts, defects are noticed, that can compromise the integrity of the structure.



Figure 1. The pressure vessel 970, before repair.

#### Ključne reči

- posuda pod pritiskom
- ukrutni prsten
- zavareni spojevi
- reparatura
- greška

#### Izvod

*Prikazana je popravka posude 970, jer je rizik bio veoma visok, blizu najgoreg slučaja verovatnoće i posledica. Kako položaj greške nije bio pogodan za iskopavanje i reparaturno zavarivanje, odlučeno je da se napravi ukrutni prsten, kako bi se smanjio napon u zavarenom spoju, tako da se i faktor intenziteta napona i neto napon značajno smanjuju.*

Repairing the pressure equipment is an efficient solution to many problems, /1/, and requires both practical and theoretical knowledge, especially for pressurized equipment, /2-5/. Nowadays, these repairs are very accurate, thanks to modern non-destructive testing devices and the precise determination of the size and position of defects, /1-5/. Figure 2 shows the pressure vessel 970, with the stiffener as a special repair design solution.



Figure 2. The pressure vessel 970, after repair with stiffener.

## INSPECTION OF PRESSURE VESSEL 970

First inspection and testing of pressure vessel 970, as shown in Fig. 1, was performed by NDT methods before the repair with stiffener. Visual testing, magnetic particle testing and ultrasonic method were applied. It is known that ultrasonic testing is mostly used in the testing of pressure equipment, which proves to be the most reliable technique in detecting defects, /1-5/.

Vessels are made of microalloyed steel Nival 50, with pressure in vessel 970  $p = 81$  bar; thickness  $t = 50$  mm; and diameter  $D = 2150$  mm. The vessel 970 was inspected by 100 % ultrasonic testing of two vertical and three circular welded joints. Nine unacceptable indications (1.1-1.4, 5.1-5.4 and 5.6), as well as one with an echo height above the registration level (5.5) were detected.

After the final UT testing of the vessel 970, defects 1.4 and 5.6 were found out to be the most dangerous with the following geometry and location:

- defect 1.4; length 35 mm and width / depth 22 mm in the central circular seam, from 28 to 50 mm,
- defect 5.6; length 75 mm and width / depth 20 mm in the central circular seam, from 18 to 38 mm.

Welded joints tested before repair, are shown in Figs. 3 and 4. Figures 5 and 6 show results of NDT testing for indications 1.4 and 5.6.



Figure 3. Tested welded joints (marked by red arrows) on vessel 970, before repair.

## SPECIAL DESIGN SOLUTION FOR PRESSURE VESSEL 970

Risk-based analysis has been successfully used in recent years to evaluate possible effects on pressure vessel safety, /6-12/. As for the pressure vessel 970, since the risk was at a very high level, close to the worst case of the probabilities and consequences, and the position was not suitable for the repairer by welding, it was decided to make a stiff ring in order to reduce the stress on the welded joint, so that both the stress intensity factor and the stress acting on the defect 5.6 become significantly reduced.



Figure 4. Tested welded joint 5 on vessel 970, before repair.




Figure 5. Position and size of defect 1.4 in vessel 970.




Figure 6. Position and size of defect 5.6 in vessel 970.

The first thing that has been done is the calculation of stresses and strains in the zone of the stiffener, which we shall explain below.

Input data for pressure vessel 970:

- design diameter:  $\varnothing 2200$  mm,
- length (height): 4485 mm,
- volume: 13 m<sup>3</sup>,
- wall thickness: 50 mm,
- pressure: working 7.3-7.7 MPa, design 8.1 MPa.

Calculation of stress and strain of vessel 970 for pressure 8.1 MPa:

$$\sigma_t = pD/2s = 8.1 \cdot 2100 / 2 \cdot 50 = 170.1 \text{ MPa}, \quad (1)$$

$$\sigma_z = pD/4s = 8.1 \cdot 2100 / 4 \cdot 50 = 85.05 \text{ MPa}, \quad (2)$$

$$\sigma_r = p = 8.1 \text{ MPa}, \quad (3)$$

$$\sigma_i = \frac{1}{\sqrt{2}} \sqrt{(\sigma_z - \sigma_y)^2 + \sigma_z^2 + \sigma_y^2} = \frac{\sqrt{3}}{2} \frac{pR}{t} = 147 \text{ MPa}, \quad (4)$$

where:  $\sigma_t$ ,  $\sigma_z$ ,  $\sigma_r$  are stress components in the circumferential, longitudinal, and radial directions; and  $\sigma_i$  is total stress. Strains are defined by:

$$E\varepsilon_x = \sigma_x - \nu\sigma_z - \nu\sigma_y = -\frac{3}{2} \nu \frac{pR}{t}, \quad (5)$$

$$E\varepsilon_y = \sigma_y - \nu\sigma_z - \nu\sigma_x = \left(1 - \frac{\nu}{2}\right) \frac{pR}{t}, \quad (6)$$

$$E\varepsilon_z = \sigma_z - \nu\sigma_y - \nu\sigma_x = \left(1 - \frac{\nu}{2}\right) \frac{pR}{t}, \quad (7)$$

where:  $\varepsilon_t$ ,  $\varepsilon_z$ ,  $\varepsilon_r$  are strain components in circumferential, longitudinal and radial directions;  $E = 2.1 \cdot 10^5$  MPa is modulus of elasticity; and  $\nu = 0.3$  is Poisson's coefficient.

After the finished calculation, the scheme for installation and assembly of the stiffener on the vessel 970 are made, Figs. 7-9. The first stiffener had 16 plates, the second one 17, all of them are 5x50 mm.




Figure 7. Scheme of vessel 970 reinforcement with outer stiffeners.




Figure 8. Schematic solution of flange joint for tightening rings.




Figure 9. Schematic solution of connecting half of the rings.

After making the plan for the assembly and erection of the stiffener, it was successfully installed on vessel 970. Details are shown in Figs. 10-12.



Figure 10. Details of the two-ring reinforcement solution.



Figure 11. Flange joint details.



Figure 12. Stiffener bonding with 4 screws M30 (class 8.8).

## INSPECTION OF PRESURE VESSEL 970 AFTER REPAIR

Only some details of the NDT inspection of vessel 970 after the erection of stiffener is presented. Figure 13 shows details of NDT inspection of vessel 970. It should be noted that after placing the stiff ring, the NDT methods show that the defect on the vessel 970 has not changed.




Figure 13. Ultrasonic examination of vessel 970, after repair.

## CONCLUSIONS

Defect 5.6 in vessel 970 presents a high risk, but in this case removal by repair welding was not a practical solution, so a special design solution is successfully made in the form of a stiffener to reduce the stress.

## ACKNOWLEDGEMENTS

This work is supported by the Ministry of Education, Science and Technological Development of the Republic of Serbia (Contracts No. 451-03-68/2022-14/200135 and No. 451-03-68/2022-14/200213).

## REFERENCES

1. Jeremić, L., Sedmak, A., Milovanović, N., et al. (2021), *Assessment of integrity of pressure vessels for compressed air*, *Struct. Integ. Life*, 21(1): 3-6.
2. Jovičić, R., Jeremić, L., Milošević, N., et al. (2021), *Repair welding of pressure equipment with unacceptable defects*, *Struct. Integ. Life*, 21(2): 163-167.
3. Jeremić, L., Đorđević, B., Šapić, I., et al. (2020), *Manufacturing and integrity of ammonia storage tanks*, *Struct. Integ. Life*, 20(2): 123-129.

4. Jeremić, L., Sedmak, A., Petrovski, B., et al. (2020), *Structural integrity assessment of welded pipeline designed with reduced safety*, *Tech. Gazette*, 27(5): 1461-1466. doi: 10.17559/TV-20200413142538
5. Arandelović, M., Milovanović, N., Đorđević, B., et al. (2020), *Reparation, inspection and damage analysis of steam boiler*, *Weld. Mater. Test.*, XXIX(3): 9-12.
6. Martić, I., Sedmak, A., Mitrović, N., et al. (2019), *Effect of over-pressure on pipeline structural integrity*, *Tech. Gazette*, 26(3): 852-855. doi: 10.17559/TV20180708213323
7. Kirin, S., Jeremić, L., Sedmak, A., et al. (2020), *Risk based analysis of RHPP penstock structural integrity*, *Frattura ed Integrita Strutturale*, 14(53): 345-352. doi: 10.3221/IGF-ESIS.53.27
8. Sedmak, A., Kirin, A., Martić, I., et al. (2020), *Structural Integrity and Life Assessment of Pressure Vessels - Risk Based Approach*. In: Mitrović, N., Mladenović, G., Mitrović, A. (Eds) *Experimental and Computational Investigations in Engineering, CNNTech 2020. Lecture Notes in Networks and Systems*, vol.153. Springer, Cham. 274-293. doi: 10.1007/978-3-030-58362-0\_16
9. Jovičić, R., Algoal, M.M.A., Tatić, U., et al. (2014), *Storage tank integrity assessment after the removal of weld defects*, *Struct. Integ. Life*, 14(1): 35-38.
10. Golubović, T., Sedmak, A., Spasojević Brkić, V., et al. (2018), *Novel risk based assessment of pressure vessels integrity*, *Tech. Gazette*, 25(3): 803-807. doi: 10.17559/TV-20170829144636
11. Vučetić, I., Kirin, S., Sedmak, A., et al. (2019), *Risk management of a hydro power plant - fracture mechanics approach*, *Tech. Gazette*, 26(2): 428-432. doi: 10.17559/TV-20180618102041
12. Vučetić, I., Kirin, S., Vučetić, T., et al. (2018), *Risk analysis in the case of air storage tank failure at RHPP Bajina Bašta*, *Struct. Integ. Life*, 18(1): 3-6.
13. Sedmak, A., Jeremić, L., Milovanović, N., et al. (2021), *How to deal with cracked welded structure - Application of fracture mechanics parameters to structural integrity assessment*, *ASR International Conference 'Welding 2021'*, University Centre UBB Reșița, Romania

© 2022 The Author. Structural Integrity and Life, Published by DIVK (The Society for Structural Integrity and Life 'Prof. Dr Stojan Sedmak') (<http://divk.inovacionicentar.rs/ivk/home.html>). This is an open access article distributed under the terms and conditions of the [Creative Commons Attribution-NonCommercial-NoDerivatives 4.0 International License](https://creativecommons.org/licenses/by-nc-nd/4.0/)