

MSE Walls Retrofit

Design and Construction

110th Annual Road School 2024

3/12/2024

Aamir Turk, PE

Geotechnical Manager (In-House Design &
Asset Management)

Indiana Department of Transportation

Aturk@indot.in.gov

Malek Smadi, Ph.D., P.E.

Principal Engineer - GEOTILL - Fishers, IN
msmadi@geotill.com - www.geotill.com



GEOTILL


ENGINEERING, INC.




CONTENTS

1. What is an MSE
2. External Stability
3. Internal Stability
4. MSE Walls Failures Survey for 30 States
5. MSE Walls Retrofit
6. Contract B-43196 (40 MSE Wall Repair Statewide INDOT)
7. I-65 and I-80-I-94-Wall
8. I-69 over SR 57
9. SR-641 Over McDaniel Road
10. 82nd St Over I-465
11. INDOT Various Projects


Typical section & components of MSE structures



- Bearing resistance
- Settlement
- Sliding
- Overturning
- Overall Stability



(a) Assumed Bearing Failure Zone of Current Practice



(b) Possible Failure Zone

Bearing Capacity of Retaining Walls



Bearing Failure





External Stability



Settlement



TYPE OF FACING	LIMIT OF DIFFERENTIAL SETTLEMENT	
CIP Gravity Wall	1/500	2 In. in 100 Ft.
Welded Wire Facing	1/50	2 Ft. in 100 Ft.
5' x 5' Panels with $\frac{3}{4}$ " Joints	1/100	1 Ft. in 100 Ft.
5' x 10' Panels with $\frac{3}{4}$ " Joints	1/200	6 In. in 100 Ft.
Modular Block Walls	1/200	6 In. in 100 Ft.
Full Height Facing Panels	1/500	2 In. in 100 Ft.


Differential Settlement

Sliding Failure



Wall Embedment

Slope in Front of Wall	Minimum to Top of Leveling Pad
Horizontal (walls)	$H / 20$
Horizontal (abutments)	$H / 10$
3 Horiz : 1 Vert	$H / 10$
2 Horiz : 1 Vert	$H / 7$
3 Horiz : 2 Vert	$H / 5$



$H = 100$ ft
Embed.
10 ft

- For sloping ground provide a bench 4 ft bench in front of wall
- Embed at least 2 ft below anticipated scour depth
- Embed below frost depth, Indiana 3 ft



Overturning






Overall Stability



How do Reinforcements Hold Up the Wall ?



Internal Stability Reinforcement Failure Modes

- Pull out
- Reinforcement tensile strength
- Connection



Internal Failure



Survey done by Texas A&M in 2013 for TxDOT

• Massachusetts DOT. • Oregon DOT. • Nevada DOT. • Idaho DOT. • **Indiana DOT.** • Missouri DOT. • New Mexico DOT. • Alabama DOT. • Kansas DOT. • Connecticut DOT. • Illinois DOT. • Iowa DOT. • Maryland DOT. • New Hampshire DOT. • New York DOT. • South Carolina DOT. • Washington DOT. • Wisconsin DOT. • California DOT. • Minnesota DOT. • Missouri DOT. • Montana DOT. • North Carolina DOT. • Vermont DOT. • Wyoming DOT. • Nebraska DOT. • Louisiana DOT. Texas DOT.

- All the DOTs have indicated that the FHWA design methodology **has been followed** to design the MSE walls.
- The minimum reinforcement length used for design is **0.7H or 8 ft**, whichever is longer.
- In all, DOTs have **different backfill specifications** from FHWA guidelines. However, many of them have higher quality of material than the FHWA guidelines.



Survey Results

- According to the frequency of the failure modes being seen, the ranking of the failure modes with frequency **descending** is:
- **Bearing Capacity.**
- **Sliding.**
- **Global Stability.**
- **Compound Failure.**
- **Overturning.**

Retrofit that did not Work I-10



I-10 in Beaumont, Texas - Distressed Portion of the Roadway

Retrofit that did not Work I-10



The separation ran about 100 ft long and up to 3 inches wide. Cracking was also observed at the connection between the coping/barrier and the MSE wall panels. To prevent the propagation of the settlement and further separation, a retrofit measure was taken by **dowelling the shoulder to the adjacent travel lanes**. After the retrofit, **cracks appeared in the same travel lanes again, but were shifted toward the centerline of the roadway**

General Identified Failure Distress Modes in MSE Walls

- 1. Pavement cracking.
- 2. Pavement depression and separation.
- 3. MSE wall lateral movement.
- 4. MSE wall and bridge separation.
- 5. MSE wall longitudinal movement.
- 6. MSE wall panel dislocation.
- 7. MSE wall sliding.

Possible Causes of Failures in MSE Walls

- 1. Unsuitable backfill material.
- 2. Sizeable void within backfill.
- 3. Drainage and Erosion.
- 4. Foundation soil.
- 5. Tension failure of the reinforcements.
- 6. Failure of connection of the reinforcement

The sizeable void may be the result of poor construction, inappropriate gradation of backfill material or poor drainage.

When Visiting MSE Wall that has Issues (What to look for per minimum)

- 1. Check all drainage and erosions issues.
- 2. Check for any excessive settlements.
- 3. Check precast concrete panel facing do they need rejection or repair.
- 4. Check field modification limitations (e.g., cutting panels, resting panels, anchoring panels, use nails, etc.).
- 5. Check any backfill migration from facings.
- 6. Check backfill void mitigation and void-filling techniques.
- 7. Wall condition monitoring methods if needed.
- 8. Check distressed joint openings.
- 9. Check local facing repair or replacement strategies.
- 10. Check global repair or replacement strategies.
- 11. Check global wall stabilization.

Check List - Wall and Slope Distress Visual Indicators

Slopes or Slope / Paving Above Wall			
Observed		CHECKS (characteristics)	
Yes	No	NA	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	1. Cracks in slope/pavement (circle size: marble, golf ball, tennis ball, football, _____)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	2. For cracks, circle: new/previous, sealed/unsealed, previously treated Approximate distance from wall face: _____ ft.)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	3. Formation of shallow surface slides, depressions near top, bulging near bottom?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	4. New or increased dip in paving, curb, gutter line or slope?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	5. Landscape areas (Yes/No) – Working irrigation (Yes/No)
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	6. Ponding water?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	7. Joint separation in pavement and shoulder joint pavement?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	8. Erosion of soil on slope or around flatwork, flumes, guardrails, light fixture base, electrical communication bores?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9. Soft and / or wet soil (greener grass, ruts)?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Washout areas, silt buildup?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Signs, structures or rails next to wall (plumb, leaning to/away from wall face ___ inches over ___ ft.)
Wall Face			
Observed		CHECKS (characteristics)	
Yes	No	NA	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	12. Bulging of panels?
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. New or increased cracks in panels?

Retrofit Options

- 1. All **drainage and erosions** issues shall be resolved, such as **sealing** all opening, install **curbs & riprap channels** to divert water from the wall .
- 2. **Weep holes** to provide an outlet for water to drain and escape.
- 3. Near the **top of the wall** if the reinforcements overstressed, it may be feasible to **add additional reinforcements**.
- 4. If access to the backfill is a problem, **soil nails** drilled through the **existing wall face** may be used. (Needs deformation to activate soil nails).

Retrofit Options


- 5. **Bearing plates** may be used to distribute nail loads at the wall face.
- 6. If the increase in lateral thrust and the **potential for a sliding failure** is a problem, the front of the wall may be **buttressed**.
- 7. **Backfill may be modified** to reduce the driving forces, such as grouting, partial replacement with lightweight fill, flowable fill, or decreasing the slope angle of the backfill surface.
- 8. **Foundation soil treatment** to stop settlement or strengthen the soil.

Shotcrete Retrofit of MSE Wall



British Columbia, Canada, the MSE wall was 26 ft high and 230 ft long, the backfill is fine dredged river sand

Free Draining Seal (Foam pieces wrapped in a fabric cloth)





MSE Walls Retrofit





MSE Walls Retrofit



BEJS

Bridge Expansion Joint System



Install first length

Apply epoxy to joint faces

B-43196 (40 MSE Wall Repair Statewide INDOT) Project Development Process for IDIQ MSE Wall Rehabilitation Projects

- Phase 1: Project **Initiation** and Programming.
- Phase 2: Project **Letting** and Post Award.
- Phase 3: **Initiate Work** Order requests and Site Visit.
- Phase 4: **Process Work** Order and Schedule Construction Activities.
- **Finalize work** at site and provide district Asset Management Staff as-built of completed work.
- Contractor **submits as-built plans** to ERMS for final record keeping.

B-43196 (40 MSE Wall Repair Statewide INDOT) Projects List

- 01- 82nd St Over I465
- 02- Kenilworth Road over US31
- 03- SR168 Over I-69
- 04- SR 56-61 over I-69
- 05- SR 57 over I-69
- 06 US31 Over CR125
- 07 US31 & SR 32 Hamilton Co
- 08 US-24 at 154+89 Over Burick Rd
- 09 US-24 at 156+96-N Webster
- 10 US-24 at RP153+49 over Doyle Rd
- 11 I-69 over CR 710 S
- 12- Cline Ave under I-80 & I-94
- 13- US41 over Norfolk Southern
- 14- New Road US31 & US20
- 15- US-31 Over Main Street
- 16- US-31 Over Kern Road
- 17- US-6 Bridge over CSX R & Tracy Rd
- 18- US31 over 1st Road
- 19- US31 over 3A Road (LaPorte)
- 20- Ameriplex and I-70
- 21-10th St over I-465
- 22- US31 over 3A Rd
- 23- US31 over 1st Rd
- 24- Bridge over CSX RR & Tracy Rd US-6
- 25- Burr St over I-8094
- Lloyd Expressway & 9th Ave.
- 27- I-69 & CR1250S (Nobel Chapel Rd)
- 28- I-69 at N CR450 E
- 29-I-69 at MM77.5 over RR
- 30- 136th and 31 damage
- 31- US-31 over SR-931

B-43196 (40 MSE Wall Repair Statewide INDOT) Projects List

- 32- 80-94 EB near Cline Ave
- 33- I74-over-white-river
- 34- SR641 Over McDaniel Rd
- 35- SR641 Over Indiana R.R
- 36- I-65 and I-80-I-94-Wall #41
- 37- SBL of I-465 under NBL of Shadeland Avenue
- 38- US 31 over Creek close to 156th
- 39- SR 66 (Lloyd Expressway)
- 40-SR 46 & SR 11, SW of Columbus

Most Issues & Problems that have been Noticed

- Sand leaking from joints.
- Settlement and tilting of panels.
- Uncontrolled drainage.
- Deteriorating panels.
- Tilting.
- Differential movement.
- Voids, Erosion & Approach Slabs.
- Corrosion.




MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41



Going I-65 South to I-80 West

MSE Wall

MSE Wall






MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41

Going I-65 South to I-80 West



MSE Wall



Going I-65 South to I-80 West



MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41






MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41



MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41




Moved Panels

Broken Pavement

Manhole

Cracks

Gap



**Panel with
greatest
amount of
movement**

**Void extends 2.5 to 3.5 ft
deep behind wall at this
panel and 5 ft high under the
pavement**



MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41





MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41






MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41





MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41



MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41

Void

5 ft High

3.5 Wide







MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41

Void
5 ft High






Temporary Fix

Temporary Bracing System




Temporary Bracing System






MSE Walls Retrofit - I-65 and I-80-I-94-Wall #41





MSE Walls Retrofit - I-69 over SR 57

Going I-69 Northbound Near Southwest Wall





MSE Walls Retrofit - I-69 over SR 57



MSE Wall





MSE Walls Retrofit - I-69 over SR 57

Southbound


Northbound

Showing Northeast Wall
Looking Northeast






MSE Walls Retrofit - I-69 over SR 57



MSE Walls Retrofit - I-69 over SR 57





MSE Walls Retrofit - I-69 over SR 57



Southbound




Northbound





MSE Walls Retrofit - I-69 over SR 57



The Origin of the Problem is Hydraulic



Retrofit Recommendation





MSE Walls Retrofit - I-69 over SR 57



MSE Walls Retrofit - I-69 over SR 57



MSE Walls Retrofit - I-69 over SR 57






MSE Walls Retrofit - I-69 over SR 57




MSE Walls Retrofit - I-69 over SR 57



Since the origin of the problem is Hydraulic, permanent repair is scheduled to be done by the summer of 2024. The permanent repair will involve replacing the bridge approaches and installing a new drain system that can handle the amount of water that come on the top of the bridge.



MSE Walls Retrofit – SR-641 Over McDaniel Rd.





MSE Walls Retrofit – SR-641 Over McDaniel Rd.

6/2022

Many panels moved

Many panels moved





MSE Walls Retrofit – SR-641 Over McDaniel Rd.



Looking West



Looking East



MSE Walls Retrofit – SR-641 Over McDaniel Rd.



**Due to
Settlement
&
Connections**


A photograph of a concrete MSE wall panel. A yellow rectangular box highlights a section of the wall where the panels are misaligned, showing signs of settlement and poor connections between the panels.

**Due to
Settlement
&
Connections**

A photograph of a concrete MSE wall panel, similar to the one on the left. A yellow rectangular box highlights a section of the wall showing misalignment and signs of settlement and connection issues.




MSE Walls Retrofit – SR-641 Over McDaniel Rd.




25 nails for the South wall

Soil Nail Locations (25 Nails) for the South Wall by INDOT & Geotill





MSE Walls Retrofit – 82nd St Over I-465



Issues Observed

- **Backfill leak from Northwest side.**
- **Broken CIP copings.**
- **Some bulging panels.**
- **Pavement issues probably voids.**
- **Widen and tighten panel gaps, possibly because of settlement.**
- **Some blocked underdrain**

MSE Walls Retrofit – 82nd St Over I-465





MSE Walls Retrofit – 82nd St Over I-465



Short Pipe

MSE Walls Retrofit – 82nd St Over I-465






MSE Walls Retrofit – 82nd St Over I-465



The main problem for this location is that the **drainage** system is not able to drain all the water away from the MSE walls. The water seeps through the damaged expansion joints and some manholes and then seep on top of the MSE walls especially at the northwest wall. In addition, to the known **connections** problems that Tricon MSE Wall system has.



West Walls



Outlets

Manholes

Outlets

Moved panels

Settled & rotated
bridge railings


Defective joints

Manhole without
direct outlet



MSE Walls Retrofit – 82nd St Over I-465

East Walls



MSE Walls Retrofit – 82nd St Over I-465



MSE Walls Retrofit – 82nd St Over I-465



MSE Walls Retrofit – 82nd St Over I-465





Image showing the wing wall and panels with air gap GPR signatures (red).




MSE Walls Retrofit – 82nd St Over I-465

Drainage Extension

Proposed Retrofit

Extend and trench drainage to the nearest ditches to prevent ponding at abutments (see next page)



MIN. VERTICAL CLEARANCE – SOUTH COPING | MIN. VERTICAL CLEARANCE – NORTH COPING

* TRANSITION TO CONTINUOUS COMPOSITE PRESTRESSED



MSE Walls Retrofit – 82nd St Over I-465

Drainage Extension

Proposed Retrofit



Abutment 3: Northeast Corner



Abutment 1: Standing water due to inadequate drainage

Extend Drains to nearest ditch




Abutment 1: Northwest Corner




Abutment 1: Southwest Corner

Proposed Retrofit



MSE Walls Retrofit – 82nd St Over I-465



- Weep holes to be spaced a minimum from 1'-0" from the edge of a panel and 1'-0" from the ground line.



Hollow Bar Anchor System

Geo-Drill Injection Anchor System

The Williams Geo-Drill Injection Anchor System is today's solution for a fast and efficient anchoring system into virtually any type of soil. The system has historically been known as a "self-drilling anchoring" because the hollow fully-threaded bar serves as both the drill string and the grouted anchor, thus installation is performed in a single operation. The sacrificial drill bit is threaded onto the end of the Hollow Injection Bar and left in place following drilling. The drilling fluid (air, water, or grout) is introduced through the hollow bar and allows the spoils to flush from the borehole.

The Geo-Drill System is particularly suitable for soils that do not allow for open-hole drilling (i.e. granular soils that are collapsible in nature). In such cases, drilling with a grout fluid serves the purpose of flushing spoils from the borehole and prevents looser, surrounding material from collapsing due to the higher relative density of the grout. Williams Geo-Drill Injection Anchor System should be considered on any project requiring fast production that would otherwise need to involve a casing system in order to maintain borehole stability.



Advantages of the Williams Geo-Drill Injection Anchor System

- Fully domestic system available.
- Fast, single-step anchoring system with simple equipment.
- Eliminates the need for a cased borehole in collapsing soils.
- Efficient installation since drilling and grouting can be performed in a single operation, saving both time and money.
- Continuously drilling and grouting under high pressure causes the grout to permeate into looser soils and creates a bulb-effect for increased bond capacity.
- Suitable for working in limited space and areas of difficult access.
- Multiple ranges of drill bits suitable for most soil conditions.
- Installed with standard track drill (top hammer) or hand-held drilling equipment, eliminating the need for larger casing rigs.
- Continuously threaded bar pattern can be cut and coupled anywhere along its length.
- Domestic available in 10' or 20' lengths, non-domestic available in 3 meter lengths only.
- Corrosion protection systems available upon request.
- FHWA approved for use as a micro pile or soil nail (Domestic Hollow Injection Bar only)

B7X1 Domestic Hollow Injection Bar

Bar Diameter	Minimum Net Area Through Threads	Minimum Ultimate Strength	Minimum Yield Strength	Nominal Weight	Average Inner Diameter	Part Number
32 mm (1-1/4")	0.556 in ² (359 mm ²)	58.4 kips (260 kN)	47.2 kips (210 kN)	2.1 lbs/ft (3.1 Kg/M)	0.787" (20.0 mm)	B7X1-32
32X mm (1-1/4")	0.776 in ² (501 mm ²)	81.5 kips (363 kN)	66.0 kips (294 kN)	2.7 lbs/ft (4.0 Kg/M)	0.826" (15.9 mm)	B7X1-32X
38 mm (1-1/2")	1.087 in ² (688 mm ²)	112 kips (498 kN)	90.7 kips (404 kN)	3.76 lbs/ft (5.6 Kg/M)	0.930" (21.1 mm)	B7X1-38
51 mm (2")	1.795 in ² (1158 mm ²)	188 kips (837 kN)	152 kips (677 kN)	6.26 lbs/ft (9.3 Kg/M)	1.187" (30.1 mm)	B7X1-51
76 mm (3")	3.880 in ² (2503 mm ²)	407 kips (1811 kN)	329 kips (1466 kN)	13.79 lbs/ft (20.5 Kg/M)	1.890" (48.0 mm)	B7X1-76

Proposed Retrofit

Proposed Retrofit

B7XB Drill Bits



HC Hardened Bit
Hardened cross cut drill bit, suitable for the majority of applications including narrow bands of soft rock.
Soil Types: Fills and Medium Dense Gravels



CC Carbide Bit
Tungsten carbide cross-cut drill bit. Excellent choice for majority of granular soils with mixed hard formations.
Soil Types: Fills, Gravels, Shale & Seamy Rock Formations.



SB Sand/Clay Bit
Two stage cross cut drill bit, suitable for loose to medium dense ground and fills.
Soil Types: Sand, Clay and Light Gravels



BB Button Bit
Tungsten carbide hemispherical button drill bit for moderately strong to strong rock, boulders and rubble.
Rock Types: Mudstone, Limestone, and Granite



CB Cobble Bit
Offset face cross cut drill bit suitable for drilling in cobbles with silt and gravel as well as sedimentary bedrock material.

Nominal Bar Diameter	Available Drill Bit Diameters				
	HC	CC	SB	BB	CB
32 mm (1-1/4")	2" (51 mm)	2" (51 mm)	5" (127 mm)	2-1/2" (65 mm)	4" (102 mm)
	2-1/2" (65 mm)	2-1/2" (65 mm)		3"	
	3"	3"		3-1/2" (89 mm)	
	3-1/2" (89 mm)	3-1/2" (89 mm)		4" (102 mm)	
	4" (102 mm)	4" (102 mm)			
38 mm (1-1/2")	2-1/2" (65 mm)	2-1/2" (65 mm)	5" (127 mm)	2-1/2" (65 mm)	4" (102 mm)
	3"	3"		3"	
	3-1/2" (89 mm)	3-1/2" (89 mm)	5" (127 mm)	3-1/2" (89 mm)	
	4" (102 mm)	4-1/2" (114 mm)		4" (102 mm)	
51 mm (2")	-	3" (76 mm)	5" (127 mm)	3" (76 mm)	4-3/4" (121 mm)
	-	3-1/2" (90 mm)		3-1/2" (89 mm)	
	-	4" (102 mm)	8" (203 mm)	4" (102 mm)	5" (127 mm)
	-	4-1/2" (114 mm)		5" (127 mm)	
	-	5" (127 mm)		5" (127 mm)	
76 mm (3")	-	5" (125 mm)	7" (175 mm)	5" (125 mm)	-
	-	6" (152 mm)	10" (254 mm)	6" (152 mm)	-
	-	7" (175 mm)		5" (125 mm)	
T40	-	3" (76 mm)	5" (127 mm)	2-1/2" (65 mm)	-
	-	4" (102 mm)		3" (76 mm)	
T52	-	4" (102 mm)	7" (178 mm)	-	-

Northwest MSE Wall

- Seven panels were repaired by installing two nails in each panel. Two weepholes were installed at each bottom panel, a total of 8 weepholes.
- The damaged and spalling concrete in the MSE wall and abutment area, caused by expansion was repaired by removing the damaged and unsound concrete, followed by cast-in-place concrete panel to restore the structural integrity of the wall and prevent the backfill loss.

Southwest MSE Wall

- Three panels were repaired by installing two nails in each panel. Two weepholes were installed at each bottom panel, a total of 4 weepholes.
- The damaged and spalling concrete in the MSE wall and abutment area, caused by expansion was repaired by removing the damaged and unsound concrete, followed by cast-in-place concrete panel to restore the structural integrity of the wall and prevent the backfill loss.
- The chipped coping was patched with concrete. It has been difficult to verify if pins or rebar anchors were used to anchor the patched concrete.

Items that have been Repaired

Southeast MSE Wall

- The damaged and spalling concrete in the MSE wall and abutment area, caused by expansion was repaired by **removing the damaged and unsound concrete**, followed by **cast-in-place concrete panel** to restore the structural integrity of the wall and prevent the backfill loss.

Northeast MSE Wall

- **Vegetation and trees** grown between the coping and the bridge railing were **trimmed**.

East end bent:

- The **joint** between the phased walls **has been sealed** using a conventional sealant.

West end bent:

- The **joint** between the phased walls **has been sealed** using a conventional sealant.

Items that have been Repaired

MSE Walls Retrofit – 82nd St Over I-465



MSE Walls Retrofit – 82nd St Over I-465

Backfill behind
bottom core

Backfill behind
top core



**Coring for Soil
Nails and
Weep Holes**





MSE Walls Retrofit – 82nd St Over I-465

Installed Soil Nails

**After
Repair**

Installed Weep Holes





MSE Walls Retrofit – 82nd St Over I-465

Soil Nail Proof Test Report

Project: B-43196 82nd St over I-465
 Location: Indianapolis
 Client: INDOT
 Project #: 05-111

Tie Back #: SW1-R
 Date Installed: 3/4/2023
 Date Tested: 3/8/2023
 Design Load (Kips): 20.6
 Bonded Length (ft): 17.5
 Unbonded length (ft): 1
 Free Length (ft): 3
 32mm Hollow Bar: 0.776
 Modulus of Elasticity (ksi): 28700

Equipment

Pump: PE554 Jack No. S16993
 Gauge: 5405OVPJ 1 Kip= 83.77 PSI
 Tested By: ESB


Boring Information

Diameter _____ Inches
 Yards of cement _____ External
 Cubic feet of grout _____ Internal

Value of Design Load	Loading Kips	Gauge Pressure, PSI	Movement Reading, In	Delta, Min Inches	Delta, Max Inches	Ten Minute Hold Minutes	Ten Minute Hold Reading, In
Alignment	6.0	503	0.000	0.010	0.041	1	0.170
0.25	5.2	431	0.012	0.009	0.035	2	0.170
0.50	10.3	863	0.034	0.018	0.071	3	0.170
0.75	15.5	1294	0.088	0.027	0.106	4	0.170
1.00	20.6	1726	0.125	0.036	0.142	5	0.170
1.20	24.7	2071	0.145	0.043	0.170	6	0.170
1.33	27.4	2295	0.170	0.047	0.188	10	0.170

Lock Off at 21 Kips, Dial Reading = 0.132

Creep = 0.000
 Result = PASS





MSE Walls Retrofit – 82nd St Over I-465



Sealed joint



After
Repair

Sealed joint



MSE Walls Retrofit – INDOT Various Projects

Settlement of Panels





MSE Walls Retrofit – INDOT Various Projects

**Panels Damaged & Coping Tilting
Due to Abutment Movement**





MSE Walls Retrofit – INDOT Various Projects

Panels & Coping Tilting
Due to Uncontrolled Drainage



**Uncontrolled
Drainage
Weephole**



**Controlled
Drainage
Weephole**





MSE Walls Retrofit – INDOT Various Projects

MSE Wall Repair with Soil Nail




MSE Wall Repair with Soil Nail





MSE Walls Retrofit – INDOT Various Projects



MSE Wall Repair with Soil Nail





MSE Walls Retrofit – INDOT Various Projects

MSE Wall Repair with Soil Nail Soil Nail Pull Test





MSE Walls Retrofit – INDOT Various Projects

MSE Wall Repair Extending Curb to Control Drainage





MSE Walls Retrofit – INDOT Various Projects

MSE Wall Repair Sealing
Separation at the Concrete
Jersey Barrier to Control
Drainage



When Should We Evaluate Retaining Wall Assets?

- **During construction (QA/QC).**
- **Periodic (routine) performance inspections.**
- **Extreme events (seismic, flood, impact).**
- **Before widening, load changes, rehabilitation.**
- **As part of plan to extend useful life – as part of asset management.**

Questions ?

Aamir Turk, PE

Geotechnical Manager (In-House Design &
Asset Management)

Indiana Department of Transportation

Aturk@indot.in.gov

317-914-3747

Malek Smadi, Ph.D., P.E.

Principal Engineer - GEOTILL - Fishers, IN

msmadi@geotill.com - www.geotill.com

317-828-4098

