30/45 NB. (1)

7-1252-1

I- 22607

UCID--20436 DE85 017148

Metallurgical Analysis of a 304L Stainless Steel Canister from the Spent Fuel Test--Climax

H. Weiss
R. A. Van Konynenburg
R. D. McCright


April 1985

This is an informal report intended primarily for internal or limited external distribution. The opinions and conclusions stated are those of the author and may or may not be those of the Laboratory.

Work performed under the auspices of the U.S. Department of Energy by the Lawrence Livermore National Laboratory under Contract W-7405-Eng-48.



Nuclear Waste Management Projects



#### DISCLAIMER

This document was prepared as an execuse of work sponsored by an agency of the United States Government nor the University of California nor any of their employers, makes any warranty, express or implied, or assumes any legal Hubility or responsibility for the accuracy, completeness, or metioness of any information, appearatus, pendent, or process disclosed, or represents that its me woold not infringe privately sound rights. Reference herein to any specific commercial products, process, or nervice by trade same, trademark, manefacturer, or otherwise, does not necessarily condition or imply its endorsement, recommendation, or favoring by the United States Government or the University of California. The views and opinions of authors expressed herein do not necessarily state or reflect those of the University of California, and shall not be used for obvertising or product endorsement purposes.

Printed in the United States of America Available from National Technical Information Service U.S. Department of Commerce \$285 Fort Royal Road Springfield, VA 22161 Price: Printed Copy 5 : Microfiche \$4.50

Page Range	Domestic Price	Page Range	Domestic Price
001-025	\$ 7.00	326-350	\$ 26.50
026-050	8.50	351-375	28.00
051-075	10.00	376-400	29.50
076-100	11.50	401-426	31.00
101-125	13.00	427-450	32.50
126-150	14.50	451-475	34.00
151-175	16.00	476-500	35.50
176-200	17.50	501-525	37.00
201-225	19.00	526-550	38.50
226-250	20.50	551-575	40.00
251-275	22.00	576-600	41.50
276-300	23.5D	601-up <sup>1</sup>	
301-325	25.00	•	

<sup>1</sup>Add 1.50 for each additional 25 page increment, or portion thereof from 601 pages up.

# Metallurgical Analysis of a 304L Stainless Steel Canister from the Spent Fuel Test--Climax

H. Weiss, R. A. Van Konynenburg, and R. D. McCright
April 23, 1985

### ABSTRACT

Results of a metallurgical examination of a type 304L stainless steel canister that had been used to store spent nuclear fuel in an underground granite formation for about three years are reported. No observable corrosion or cracking were found. The results are applied to waste packages in a potential high level nuclear waste repository in tuff.

Work performed under the auspices of the U.S. Department of Energy by th Lawrence Livermore National Laboratory under contract number W-7405-ENG-48.

### INTRODUCTION

In April and May of 1980, Lawrence Livermore National Laboratory emplaced ll spent nuclear-reactor fuel assemblies and six electrical heater assemblies in the Climax stock quartz monzonite at the Nevada Test Site. Known as the Spent Fuel Test--Climax (SFT-C), the test was conducted as part of the Nevada Nuclear Waste Storage Investigations (NNWSI) for the U.S. Department of Energy.

The overall objective of the SFT-C was to evaluate the feasibility of safe and reliable short-term storage of spent fuel assemblies at a plausible repository depth in a typical granitic rock and to retrieve the fuel afterwards. An additional objective of the original concept was to evaluate the differences, if any, between the effects of real fuel storage and electrical simulation of the thermal output. (1)

While the SFT-C was underway, planning moved ahead on the selection of a site for the first permanent U.S. high level nuclear waste repository. One candidate site that was identified is located in tuff rock at Yucca Mountain, at the western edge of the Nevada Test Site. The tuff site is also part of the responsibility of the NNWSI project. As information about the expected environment of the waste packages in tuff became available, we noticed some similarities between the two sites with respect to the fluid media (air and water), the temperature ranges, the radiation levels, and the dissolved chemical species. As planning progressed, the canister material that had been used in the SFT-C (304L stainless steel) was also selected as the reference material for the waste packages in the tuff repository. Because of the 300 to 1000 year period of containment required by the Nuclear Regulatory Commission for the repository, corrosion resistance emerged as the dominant property needed in this application. It occurred to us that we might be able to learn some useful information about the corrosion performance of our reference material in the tuff repository by examining its behavior in the Climax facility. This report documents what was learned.

When we reviewed the history of the SFT-C canisters, the canister that contained fuel assembly number D34 appeared to be of particular interest. This canister had been located in Climax Emplacement Hole #1 (CEH#1) where, as

a result of a liner leak, the bottom part of the canister was unintentionally submerged in water for a period of at least eight months. For the remainder of the three-year period, its environment was irradiated moist air. We decided to examine this canister for evidence of corrosion.

## CANISTER AND LINER DESCRIPTION(2)

The fuel assemblies used in the SFT-C were of Westinghouse pressurized water reactor (PWR) design. They had been removed from the core of the Turkey Point Unit #3 reactor about 2 1/2 years before their emplacement at the SFT-C. Each assembly consisted of a 15 x 15 square array of 2ircaloy-4 clad fuel rods.

Each spent fuel assembly was inserted into a stainless steel canister, as shown in Fig. 1. The canister consisted of a canister body and a closure lid. The main body of the canister was a standard 356 mm OD, 9.52 mm wall, Type 304L stainless steel pipe 3.92 m long. A standard 9.52 mm wall, Type 304L stainless steel ellipsoidal end cap was welded to the bottom of this pipe. A cruciform-shaped fixture fabricated from 19 mm thick Type 304L stainless steel was welded into the end cap. This fixture supported the fuel assembly and served as a loose-clearance keyway into which the fuel assembly bottom nozzle fitted.

The upper body of the canister consisted of a section of 356 mm 0D, 23.8 mm wall, Typed 304L stainless steel pipe, approximately 230 mm long. This section was welded to the top of the main body and contained all the machined mating features for the closure lid. The canister body welds were made in accordance with Section IX of the ASME Boiler and Pressure Vessel Code and were inspected by dye penetrant. All external canister welds were made using Type 308L stainless steel weld wire.

Welded to the inside of the canister body was a Type 304 stainless steel support cage to hold the fue<sup>1</sup> assembly, formed from standard angles tied together on four sides by thin plates at six elevations. This cage provided lateral support over the entire length of the fuel assembly, limiting its possible lateral movement to about 8 mm.

After each canister was fabricated and cleaned, the fuel assembly was inserted. The closure lid was screwed in and welded, and the canister was evacuated, backfilled with helium, and sealed.

The canisters were lowered into vertical holes drilled into the floor of the Climax facility, located 420 m below ground level and 1116 m above sea level. The holes had been lined with carbon steel liners prior to insertion of the canisters (see Fig. 2). These liners had been grouted in position at top and bottom. The liners had an OD of 457 mm and a wall thickness of 6.35 mm. The liners were about 4.9 m long, and were fabricated from two sections of carbon steel pipe. Six thermocouples were placed at various locations along both the liner wall and the outside surface of the canister.

### STORAGE HISTORY

The canister containing fuel assembly D34 was emplaced on April 25, 1980. On August 17, 1982, the canister was removed and inspected for a period of 5.3 hours. It was then reinstalled into the liner and remained there until final removal on March 3, 1983.

Thermocouple data from the canister midheight indicate a maximum temperature of between 135 and 140°C for a period of approximately two months. Of more significance, Fig.  $3^{(3)}$  shows the thermocouple data from near the bottom of the canister. It can be seen that the canister temperature rose to a level near the boiling point of water for this elevation (about 96.5°C) and remained there until a time corresponding to about 3.1 years out of the reactor core. At about 3.0 years out of core the thermocouple on the liner recorded an abrupt rise in temperature. It was noted that water was present outside the liner when the liner was emplaced. It is surmised that water had leaked through a crack in the liner early in the test and entered the annular region between the canister and liner as well as the region outside the liner. The rise in the liner temperature occurred when the water between the liner and the rock had completely departed, either by evaporation or percolation through the rock. This produced a poorer thermal conductance between them, because of the change in the primary thermal transport mechanism from conduction-convection to radiation, and allowed the decay heat from the

canister to raise the liner temperature. The canister temperature did not rise when this occurred because water remained in the canister-liner annulus. This was possible because the crack in the liner weld had sealed, probably due to precipitation of solute minerals. The boiling and refluxing of this water held the canister temperature nearly constant. The gradual rise in canister temperature was probably due to concentration of solute species by distillation, which raised the boiling point of the solution. The thermal output decreased with time by nuclear decay until boiling ceased at about 3.1 years out-of-core. The water in the canister-liner annulus slowly evaporated through the gap around the shield plug (see Fig. 2). In support of this suggestion, it should be noted that water was observed on the ledge under the concrete shield plug when it was lifted.

Upon removal of the canister and inspection of the components in August of 1982, it was observed that the interior of the liner was dry, thus confirming that water was no longer present in the annulus between the liner and the canister at that time. Water level measurements in the annulus between the liner and the rock established that water was again present in this region. The presence of water in the outer annulus coupled with its absence from the inner annulus supports the hypothesis that the crack in the liner had sealed by this time. A sample of this water was collected for analysis.

After the storage period of the SFT-C was completed, the liner was removed and inspected. It was observed that the welds holding the bottom end cap onto the liner had been performed with shallow penetration and had cracked, thus providing a path for the water to enter the liner. (4) Upon inspection of the canister, we did not see any evidence of a water mark or stain on the stainless steel. However, a stain was observed on the inside of the liner.

During the three years of storage, the gamma ray dose rate at the mid-line of the canister outside surface  $^{(5,-6)}$  decayed from a starting value of 1.9 x  $10^4$  rad/hr (53 mGy/s) to a final value of 8.0 x  $10^3$  rad/hr (22 mGy/s). The total dose during the three-year period was 3.2 x  $10^8$  rad (3.2 MGy). All these values are given on a lithium fluoride basis. At the top and bottom ends of the canister the dose rates and dose are estimated to be about half as large as at the mid-line.

In discussing the condition of the canisters, it is relevant to point out that an interesting observation was made on the corrosion of the liners: All eleven carbon steel liners that had contained spent fuel showed much more evidence of external corrosion near the top of the fueled section than those containing electrical simulators. At some locations, the depth of corrosion amounted to as much as 5 mm. In all likelihood this resulted from the production of nitric acid and other oxidizing chemical species by the irradiation of moist air and their condensation onto the coolest accessible regions of the liner, near the top of the fueled section.

The chemical composition of the water solution that was in contact with the canister can only be approximated, since it was not sampled directly. The water sample taken from the liner-rock annulus was analyzed by inductively-coupled plasma optical emission spectroscopy (ICP-0ES) and ion chromatography (IC). The results are shown in Table I. For comparison, analyses are also shown for water from the two sampling locations in the Climax facility that were nearest hole CEH#1, taken prior to spent fuel emplacement, (7) and from well J-13, near Yucca Mountain. (8) It can be seen that the Climax pre-emplacement water is relatively high in Na. Ca.  $50_4$ ,  $C1^{-}$ , and  $HC0_2^{-}$ . The water taken from the CEH#1 liner-rock annulus is significantly higher in K and lower in Ca,  $SO_n^{-}$ , and Cl<sup>-</sup>. (Unfortunately, HCO2 was not measured, but ionic balance would dictate a concentration in excess of 1300 mg/L.) We do not currently understand the details of the processes that led to these differences in composition. However, factors such as variation in equilibria with temperature, concentration by distillation, contact with the zinc-coated steel liner, interaction with the grout, radiolysis, and ion exchange with the rock probably contributed. It is possible that contamination by drilling detergent used in drilling the nearby access hole also occurred.

### METALLOGRAPHIC EXAMINATION

In June of 1984, the canister was examined at the E-MAD facility by the authors. At that time, the canister had been cut into seven cylindrical pieces and the bottom dome section, as shown in Fig. 4. All pieces were steam cleaned to remove any contamination and shipped to LLNL. Several areas were

selected for further inspection; specifically, areas containing two different types of welds, samples for chemical analysis, and a "suspicious" area that appeared to be a corrosion pit.

It was determined that the canister was fabricated from longitudinally welded pipe, with both inside and outside welds, as shown in Fig. 5. This weld appears to have been produced by an autogenous resistance-type process, based upon the large width of the fusion zone and the amount of upset in the center, unwelded region. The weld is sound with no fissures; however, one can find fault with the lack of penetration through the wall.

The end cap, Fig. 6, was attached using a multipass, filler weld process. A chemical analysis of the weld material suggests that it was probably AISI 308-type material. The weld appears to be sound and functional. The base material was also analyzed and all the analytical results are shown in Table II.

Metallographic examination of the "corrosion pit", Fig. 7 and 8, shows that the surface damage was due to an arc strike. Higher magnification, Fig. 9, indicates no evidence of pitting attack or intergranular corrosion penetrating into the metal.

### APPLICATION TO WASTE PACKAGES FOR TUFF REPOSITORY

Although the canister was subjected to only three years of storage, it is encouraging to note that the AISI 304L canister material suffered no observable corrosion or cracking. This observation is even more positive, considering that the liner surrounding the canister containing assembly D34 leaked and provided a more hostile aqueous environment.

In applying this result to the waste packages for the tuff repository, one must examine the environmental parameters that are known to be important to corrosion. These include the physical state of the corrosion medium (liquid or gaseous), the chemical nakeup of the medium, the temperature, the pressure, the pH, the redox potential, the flow rate, and the radiation dose rate.

In the tuff repository, we expect an extrinoment of steam and air initially, followed by some condensation after cooling below 95°C. Inundation with water is thought to be very unlikely. The chemical composition of groundwater in the tuff site is thought to be well represented by the J-13 well water composition, shown in Table I. The temperature is expected to range from rock ambient to a maximum of 270°C. The pressure will be atmospheric for an altitude of 880 m above sea level. The pH is expected to remain near neutral or slightly alkaline for water in contact with the rock. In regions of the package surfaces not in contact or in liquid diffusive communication with the rock, it is possible that lower pH values could arise, because of radiolytic fixation of nitrogen in the gas phase, followed by condensation and dissolution in water films on surfaces, producing nitric acid.

The redox conditions in the tuff repository will be oxidizing because of the presence of air and radiation. The flow rate is expected to be quite small, because the water infiltration rate is estimated to be less than 1 mm/year. The gamma ray dose rate at the waste packages is expected to range up to  $10^5$  rad/hr as a maximum, with older waste having lower levels.

In comparing these conditions to those in the SFT-C, one finds several similarities. First of all, we are dealing with Type 304L stainless steel in both cases. If hole liners are needed for retrievability in the tuff repository, carbon steel would likely be selected, as in the SFT-C. During most of the period in the SFT-C, the canister surface was below the boiling point and could maintain a water film, which we expect will be the most corrosive condition in the tuff repository. The water in SFT-C was more concentrated in total dissolved species, particularly in chloride, which is known to be detrimental to stainless steels. Although the temperatures in SFT-C were below the maximum for the repository, it is expected that the lower tamperatures will represent more severe corrosion conditions, as mentioned above. In any case, the tuff waste packages will eventually cool into this regime (see O'Neal et al. for calculated waste package thermal history). (10) The pressure is similar in the two cases, being atmospheric. The pH conditions are also comparable. (7) Both facilities have an oxidizing environment. The flow rate at the canister in the SFT-C was necessarily fairly low because the water came through a cracked weld. The radiation

levels are in the same regime for older fuel or defense waste in the repository. All in all, it appears that there are enough similarities that a useful comparison can be made. Probably the largest differences are in the chemical makeup of the water, but the Climax water appears to be more aggressive from a corrosion standpoint.

In conclusion, although conditions are not identical in the two facilities and only three years of exposure were performed, the excellent performance of Type 304L stainless steel in the SFT-C speaks well for its prospects in the tuff repository. Certainly if significant corrosion had been observed, we would have had great cause for pause, and it is reassuring that none was.

### REF ERENCES

- L. D. Ramspott et al., "Technical Concept for a Test of Geologic Storage of Spent Reactor Fuel in the Climax Granite, Nevada Test Site," UCRL-52796, Lawrence Livermore National Laboratory, Livermore, CA, (1979).
- 2. U. S. Department of Trengy Nevada Operations Office, "Safety Assessment Document for the Spent Reactor Fuel Geologic Storage Test in the Climax Granite Stock at the Nevada Test Site," NVO-210, (January 1980).
- 3. W. C. Patrick et al., "Spent Fuel Test--Climax: Technical Measurements Interim Report, Fiscal Year 1981," UCRL-53294, Lawrence Livermore National Laboratory, Livermore, CA, (1982).
- 4. W. C. Patrick et al., "Spent Fuel Test--Climax: Technical Measurements Interim Report, Fiscal Year 1983," UCRL-53294-83, Lawrence Livermore National Laboratory, Livermore, CA, (1942).
- T. P. Wilcox and R. A. Van Konynenburg, "Radiation Dose Calculations for Emplacement Holes in the Climax Granite, Nevada Test Site," UCRL-53159, Lawrence Livermore National Laboratory, Livermore, CA, (1981).
- R. A. Van Konymenburg, "Radiation Dose in Granite Around Emplacement Holes in the Spent Fuel Test--Climax (Final Report)," UCRL-53580, Lawrence Livermore National Laboratory, Livermore, CA, (1984).
- D. Isherwood, J. Harrar, and E. Raber, "Characterization of Climax Granite Ground Water," UCRL-53309, Lawrence Livermore National Laboratory, Livermore, CA, (1982).
- 8. V. M. Oversby, "Reaction of the Topopah Spring Tuff with J-13 Water at 120°C," UCRL-53574, Lawrence Livermore National Laboratory, Livermore, CA. (1984).

- R. A. Van Konynenburg and R. D. McCright, "Corrosion Performance of Metals and Alloys in a Tuff Geochemical Environment," UCRL-91740, to be published in Proc. of the Waste Management '85 Conference, University of Arizona, Tucson, AZ, (1985).
- 10. W. C. O'Neal et al., "Preclosure Analysis of Conceptual Waste Package Designs for a Nuclear Waste Repository in Tuff," UCRL-53595, Lawrence Livermore National Laboratory, Livermore, CA, (1984).

TABLE I Comparison of Water Analyses from Climax Facility and Well J-13 (mg/L)

	Climax Facility			Well J-13 <sup>(8)</sup>
Species	NH-01 <sup>(7)</sup>	UG-02 <sup>(7)</sup>	C EH#1	
	(0.4 um 1		(0.45 µm filtered)	(0.1 µm filtered)
Na	229	214.	273.	43.9 <u>+</u> 1.19
Ca	240.	114.	16.0	12.5 <u>+</u> 0.77
SiO2	22.5	23.9	1.4	57.7 ± 1.0
K	3.8	4.7	538.	$5.11 \pm 0.32$
Mg	4.8	1.5	<0.008	1.92 <u>+</u> 0.06
Sr	7.9	4.2	0.69	0.054
U	18.5	<0.1	<0.076	<0.084
Al	0.05	0.02	1.67	0.012 + 0.010
Fe	0.5ª	0.8ª	0.004	0.006 + 0.005
Zn	0.03 <sup>a</sup>	0.03 <sup>a</sup>	3.2	<0.008
Mn	0.008	0.05	<0.001	<0,0005
Li	0.17	0.17	0.40	0.042
Мо	0,22	0.09	0.029	0.013
Τi	0.02	<0.002	<0.002	N.D.
В	N.D.b	N.D.	0.047	0.128 <u>+</u> 0.008
P04	0.5	<0.3	N.D.	<0.3
SO <sub>4</sub>	850.	480.	193.	18.7 + 0.47
c1 T	160.	70.	30.	6.9 + 0.21
нсо <sub>з</sub>	65.	165.	N.M. <sup>C</sup> (1322) <sup>d</sup>	136. + 8.1
S	N.D.	3.0	N.D.	N.D.
F	N.D.	1.4	3.8	2.2 ± 0.32
NO3	N.D.	N.D.	2.5	9.6 <u>+</u> 3.63
TOTAL	1603.	1083.	(2386) <sup>d</sup>	295

a. Samples known to be contaminated from drill bit and wire mesh

b. N.D. -- Not detected

c. N.M. -- Not measured

d. Calculated from ionic balance

TABLE II
Chemical Analysis of Canister Materials

	308 Filler	Autogenous Weld	Base Material
Carbon	0.023%	0.017%	0.018%
Manganese	1.76	1.19	1.89
Phosphorus	0.017	0.021	0.020
Sulfur	0.011	0.014	0.011
Silicon	0.42	0.49	0.54
Chromium	20.52	18.24	18.46
Nickel	9.52	9.67	9.05
Molybdenum	0.05	0.73	0.50
Copper	0.09	0.42	0.25
Iron	Remainder	Remainder	Remainder




Fig. 1 Spent fuel canister assembly




Fig. 2 Drawing of emplacement of liner and canister in repository.




Fig. 3 Temperature histories of the canister and borehole liner located in CEHO1. Note the break in the trends of the curves at about 3.0 YOC which result from water being boiled out of the Canister-liner annulus.




Fig. 4 Sectioned canister from the D-34 fuel assembly emplaced in hole #1. Sections labeled A (top) through G (bottom).




Fig. 5 Autogenous assembly longitudinal weld on canister body, showing incomplete weld penetration and high deformation area (at arrow).




Fig. 6 Bottom circumferential weld section showing multipass filler wire process.




Fig. 7 Suspicious "corrosion" pit observed about four feet from bottom end cap.
Analysis revealed this to be a welding are strike.




Fig. 8 Suspicious "corrosion" pit from section F of canister.



200 µm

Fig. 9 Suspicious "corrosion" pit at higher magnification. No localized corrosion penetration observed.