

Wire Wool Failure of a Compressor Rotor

38th Turbomachinery Symposium Case Study

Presented By:

Bryan Barrington

Machinery Engineer

LyondellBasell Specialty Engineering Group

Keith Burnikell

Reliability Engineer

LyondellBasell Bayport Facility



Machine Characteristics

- Double flow beam type centrifugal compressor driven by an electric motor on one end and a steam turbine on the other
- 13,390 HP
- 8676 rpm
- 15-5 PH shaft material with low carbon manganese steel overlay in bearing journal areas

Area of Failure

6

VIEW "A"




F

G

F

A


E



4.56 (REF)
LENGTH OF OVERLAY

Area of Failure

.25
(REF)




Timeline of Events

- Machine restarted after complete overhaul and oil system flush
- Cooling water to oil cooler not lined up – oil supply to deck approaches 170 F
- Cooling water reinstated but vibration tracks oil supply temperature swings – swings caused by fouled cooler
- One cooler taken off-line to clean water (tube) side – bundle pulled

Timeline of Events (cont'd)

- Bundle reinstalled and cooler placed back on line
- Approximately 6 minutes later the journal bearing temperature began to increase
- Three minutes later the vibration dipped and then began a rapid increase
- Machine tripped out by board operator – 9 mils vibration recorded on Bently system



- With machine disassembled it was readily apparent that it had experienced a wire wool failure.
- Debris from machining appeared as wire wool.
 - Pre-disassembly
 - Shaft runout approaching 25 mils TIR
 - Spiral windings in oil drain line bull's eye



04.18.2008

Wire Wool Background

- Mechanism driven by:
 - Steels containing chromium in excess of 1-1.5%
 - 15-5 PH / 17-4 PH
 - 400 series stainless
 - Shaft speeds in excess of 67-80 feet/sec
 - Foreign particle (soft or hard)
 - References / Further Reading
 - API RP 687 Rotor Repair, First Edition p 1-157
 - *Metallurgical Considerations in Wire Wool Type Wear Bearing Phenomena*, F. Fidler, 1970

Wire Wool Background (cont'd)

- Typical Failure Sequence
 - Foreign particle introduced into tight clearance
 - Frictional heat generated due to particle rub at high speed
 - Chromium in the steel in the presence of a hydrocarbon oil is converted to hard chromium carbide
 - Chromium carbide particles embed in stationary component and act as a cutting tool
 - The mechanism self-propagates until something gives

Additional Findings

- Other bearing journals exhibited scoring
- Oil filter housing contained significant amount of large debris
- Oil pump suction screen mesh much tighter than large debris






Additional Findings

- Debris originated from:
 - Lube oil supply high temperature swings performed additional “cleaning”?
 - Oil temperature excursion to 170 F
 - Sudden oil temperature drop when cooler placed on line
 - Contaminated oil cooler bundle?
 - Would require passage through filter
Reference *Dynamic Filter Efficiency*
 - Combination of above?

Additional Findings

- Oil seal
 - Split design incorporated due to coupling on thrust bearing end
 - Spare thrust bearing oil seal had offsets at splitline
 - Existing oil seal design could lock up thus further forcing any trash against shaft

Spare Oil Seal – Example of Design and Manufacturing Flaws



Note radial offset here

And axial offset here

Modifications – Oil Seal

- Match marked halves
- Add dowels to splitline to improve alignment capability.
- Add anti-rotation slot to the lower half holder. This ensures that the anti-rotation pin does not accidentally get hung in the existing hole in the upper half. Plugged hole in upper half.
- Axial clearance changed to .005 to .010" (old design clearance was .002" to .005").
- Seal captured by bolted cover vs. relying on thrust bearing

Repairs – Previous Service Shaft

- Shaft of previous service rotor coated to eliminate high chrome at surface
 - Tungsten carbide coating, minimum thickness of .005” per side, but for this repair it was approximately .015” per side
 - Surface finish was made the same as the surrounding metal at a value of 18 Ra.
 - The coating is a JP-5000 coating.

Wire Wool Failures – Other Things to Watch For

- Oils with EP additives
- Oils with chlorinated paraffins (typically cutting oils)
- Issues in more traditional rotor metallurgy such as 4140 or 4340
- *Dry* failures in compressor interstage seal and balance piston areas.
 - Further reading - *“Wire Wool”, “Black Scab” or “Machining” Failure Mechanism in Turbomachinery – 5 Case Histories*, Tim Christ Turbomachinery Symposium Case Study – August 2001

Lessons Learned

- Historical success does not mean that design improvements do not exist
- Hindsight truly is 20/20
- Cleanliness is paramount when exposing the oil side of coolers to atmosphere
- Swapping from dirty to clean coolers should be performed smoothly to minimize temperature and viscosity swings