

Proceedings of WTC2005  
World Tribology Congress III  
September 12-16, 2005, Washington, D.C., USA

**WTC2005-63539**

**DRAFT**

## **ANALYSIS OF BLACK BEARING BALLS FROM A SPACE SHUTTLE BODY FLAP ACTUATOR**

Kenneth W. Street  
NASA Glenn Research Center  
MS 23-2  
21000 Brookpark Road  
Cleveland OH 44135

Marjorie F. Sovinski  
NASA Goddard Space Flight Center  
Code 541  
Bldg 30, Rm 112  
Greenbelt OH 20771

### **ABSTRACT**

A significantly deteriorated ball bearing mechanism from a body flap actuator on Space Shuttle OV-103 was disassembled and the balls submitted for analysis in conjunction with Return to Flight activities. The OV-103 balls, referred to as the "black balls", were subjected to X-ray photoelectron spectroscopy (XPS), Fourier transform infrared (FT-IR) and Raman micro spectroscopy, surface profilometry, and optical and electron microscopy. The spectroscopic results in combination with microscopy analysis allowed a determination of the lubricant degradation pathway. The chemical attack mechanism does not adequately explain the unique visual appearance of the black balls. Numerous efforts have unsuccessfully focused on duplication of the phenomena causing this unique surface structure and appearance of the black balls. Further detail will be presented supporting these conclusions along with plausible explanations of the unique black appearance to the balls.

### **INTRODUCTION**

The space shuttle body flap contains four actuators to drive it. Four similar actuators in the tail drive the rudder and speed break. These actuators are deemed as Critical I components where failure means loss of vehicle and crew. These components are connected in series, hence failure of one actuator in a section of the craft causes complete loss of function in that section of the craft. To date many actuators that have seen service and have been disassembled for maintenance and refurbishment. Only one bearing from all of the actuators examined thus far has the unique appearance of the "black

balls". The appearances of the balls from this bearing are best described as black mirrors.

A large number of techniques are available for the elucidation of problems encountered in tribology. Both qualitative techniques such as visual microscopy and quantitative techniques like the spectroscopic ones when combined provide a great amount of information regarding the physical and chemical conditions leading to the end of useful life of mechanical components. We have employed a variety of microscopic, surface topographical and spectroscopic techniques to examine the black balls from OV-103 in order to determine what conditions lead to the unique appearance.

### **RESULTS AND DISCUSSION**

The as received balls (both black balls and used balls from a body flap actuator on OV-104) had been solvent cleaned with Fluoroclean TM cleaning solvent. No further details were provided on the Black Balls and the used balls. It is unfortunate that none of the extract was maintained for chemical analysis which might have indicated degradation of the lubricant itself. These bearings were previously lubricated with Braycote 601 which contains a perfluoropolyether (PFPE) base oil, Bray 815Z oil. New balls from stock were sonicated in clean Freon 113 for 3 minutes prior to taking measurements on them.

Black balls were submitted for micro FT-IR and micro Raman analysis. Spectra were run on all balls at a minimum of three arbitrary locations. All IR spectra clearly showed no lubricant which is consistent with the solvent cleaning applied to the balls prior to submission for analysis. The IR did show weak indications of a thin layer of "End Stage Lubricant" in all

