



Joint Rating Copy  
2-27-80

Progress Report  
for  
Iowa Highway Research Board  
Project HR 203

*[Faint handwritten notes and signatures]*

# Transverse Joint Sealing with Various Sealants



Highway Division  
July 1979

in cooperation with  
Dallas County  
Secondary Road Department

### DISCLAIMER

The contents of this report reflect the views of the author and do not necessarily reflect the official views or policy of the Iowa Department of Transportation. This report does not constitute a standard, specification or regulation.

*Final Report*  
~~PROGRESS REPORT~~

FOR  
IOWA HIGHWAY RESEARCH BOARD  
PROJECT HR-203

TRANSVERSE JOINT SEALING  
WITH  
VARIOUS SEALANTS

BY

VERNON J. MARKS  
RESEARCH ENGINEER  
(515) ~~296~~ 1447  
239

OFFICE OF MATERIALS  
HIGHWAY DIVISION  
IOWA DEPARTMENT OF TRANSPORTATION  
AMES, IOWA 50010

IN COOPERATION WITH  
THE DALLAS COUNTY  
SECONDARY ROAD DEPARTMENT

JULY, 1979

## TABLE OF CONTENTS

INTRODUCTION	1
PROBLEM	3
OBJECTIVE	6
PROJECT SELECTION AND LOCATION	6
PAVING DESIGN	7
CONTRACTOR AND PERSONNEL	7
PAVING MATERIALS	8
JOINT SEALING MATERIALS	9
Sealants	9
Backing Materials	9
CONSTRUCTION OPERATION	10
JOINT LAYOUT AND IDENTIFICATION	11
JOINT SAWING	12
JOINT PREPARATION	12
INSERTING BACKING MATERIAL	14
JOINT SEALING OPERATION	16
COST COMPARISON	22
PERFORMANCE EVALUATION	23
Visual Inspection	23
Joint Heave	24
Core Drilling and Testing	24
ACKNOWLEDGEMENTS	29
REFERENCES	30

## TRANSVERSE JOINT SEALING WITH VARIOUS SEALANTS

### INTRODUCTION

Iowa's first PC Concrete pavement was constructed in 1904 in the City of LeMars. A portion of that pavement served traffic until 1974 at which time it was resurfaced. The first rural Iowa PCC pavement (16' wide, 6" to 7" thick) was constructed under the direction of the Iowa State Highway Commission in 1913. Some of Iowa's early pavements had transverse joints at 25 foot spacings. At that time, joint spacings across the nation ranged from 24 to 100 ft.<sup>1</sup> There have been many changes in joint design over the years with some pavements being constructed without transverse joints.

Joint spacing on Iowa primary pavements has generally remained around 20 <sup>feet</sup> with this spacing having been adopted as an Iowa standard in 1954. Until <sup>1975</sup> ~~recently~~, it was common to specify a 40 foot joint spacing on secondary pavements.

The performance of the pavements with joint spacings greater than 20 feet, and in some cases no contraction joints, generated a 1955 research project on joint spacing.<sup>2</sup> This project was 16 miles long containing sections without contraction joints and sections with joints sawed at intervals of 20, 50 and 80 feet. Approximately half of the sawed joints were left unsealed. The results of this research supported the

20 foot spacing, but were inconclusive regarding the benefits of sealing.

One of the desired characteristics of joint sealing material is that it should act as a moisture barrier and prevent the intrusion of surface water. It was generally accepted from past experience that the hot poured-type joint seals did not provide this effective moisture barrier.

In an effort to identify an effective joint sealing system, research project HR-125 was initiated in 1966 to evaluate the use of performed neoprene joints.

Over the years, Iowa has maintained a standard practice of sealing joints on new PCC pavement construction. The standards have required hot poured bituminous materials. Prior to 1948, the materials were unmodified asphalt cements. From 1948 though 1964, the sealant material was an asphalt cement product with a mineral filler. A blend of recycled rubber and asphalt cement was used from 1964 through 1977. <sup>From</sup> ~~In~~ <sup>through 1981.</sup> the present specification was adopted requiring a blend of virgin rubber and asphalt cement meeting Federal Standard Specification SS-S-1401. *Add II*

Some transverse joints in Iowa have been formed utilizing parting strips, but for the most part have been imparted by sawing. <sup>Prior to 1936,</sup> Specifications ~~have~~ required a minimum width of 1/8" and a minimum depth of one fourth the slab thickness. In recent

The minimum width of saw cut is now 1/4 inch.

years, the common practice has been to make that saw cut with a 3/16" or 7/32" abrasive blade.

There is no record of the use of filler or backing material beneath the hot poured sealant on any Iowa project prior to 1978.

Highway engineers over the years have been concerned with joint sealing materials and procedures. A small experimental study utilizing a one component, polyvinyl chloride coal tar elastomeric type, hot poured sealer was incorporated into a US 30 project at the southwest corner of Ames in 1972. The sealant reservoir was cut 1/2 inch wide and cleaned by sandblasting prior to hot pour sealing.

#### PROBLEM

Deterioration of joints and joint related distress of PCC pavements continues to be a major maintenance problem. These joints are constructed to control cracking and provide for movement due to variation in temperature. The difficulty of maintaining these joints in a sealed condition is primarily caused by the opening and closing of the joint, but movement produced by traffic is a contributing factor. Unfortunately the poured sealants and present joint design and construction practices have not been able to adequately provide for this movement. Even under ideal conditions, the life of most poured

sealants rarely exceeds three years.<sup>1</sup> The bond between the sealant and the concrete fails and allows the joint to leak. (Figure 1).




Figure 1 - Bond Failure of Sealant Material

Failure of the joint seal results in additional problems. Surface water is allowed to enter the joint. This additional water detracts from the stability of the base material. It further causes erosion of the base both from gravity and by pumping. The freezing of this concentration of water during winter months causes joint heaving resulting in poor riding quality.

Blowups are the most dramatic of the joint failures. The generally accepted major contributing factor to blowups is



incompressibles deposited in the joints (Figure 2) during the winter months.




Figure 2 - Incompressibles in Transvere Joint

A combination of thermal expansion during the hot summer months, high moisture conditions and joints plugged with incompressibles results in numerous blowups. To alleviate this problem, the Iowa DOT initiated an extensive program of cutting pressure relief joints. The four inch wide cuts are placed at 1000 foot intervals. It has been typical for these pressure relief joints to close up rapidly. The four inches have closed to less than one inch within two years in many instances.

There has been a considerable amount of research on joint

sealing. The New York State Department of Public Works has researched preformed neoprene and a variety of poured sealants.<sup>3</sup> Their results from this 1955 to 1963 research demonstrated the short effective life of poured sealants and supported the superior performance of preformed neoprene. Economics, labor requirements and joint restrictions have continued to be a detriment to the use of preformed neoprenes.

A recent HRIS literature search (5-10-78) cited many abstracts on joint sealing. The Pennsylvania DOT has an active project in the use of various sealant materials with various sealant reservoirs. The Wisconsin DOT has a current project comparing sealed versus unsealed, sealant type and joint spacing.

#### OBJECTIVE

The objective of this research is to evaluate the performance of PCC pavement contraction joints utilizing a variety of sealants and joint preparations and to identify an effective sealant system. The variables to be evaluated are:

1. Sealant material
2. Joint preparation
3. Size of saw cut (sealant reservoir)
4. The use of backing material

#### PROJECT SELECTION AND LOCATION

The decision to pursue joint sealant research was made in March of 1978. By that time, most PCC paving projects were either let or in the process of being let. As the joint seal

performance is a long term evaluation (minimum of three years) and the winter period presents the severe test condition, it was considered desirable to incorporate the research into 1978 construction. Joint movement is greater on pavement with 40 foot spacing and was, therefore, one of the selection criteria to subject the joint seal to the most severe condition. This immediately eliminated primary roadways as a 20 foot spacing is standard. A majority of secondary PCC pavement has 20 foot spacing, but Dallas County project FM-25(2)--55-25 designed with a 40 foot spacing was selected. The project on Secondary Road R-30 begins  $1\frac{1}{4}$  mile west of Granger and extends southerly approximately  $8\frac{1}{2}$  miles.

#### PAVING DESIGN

The paving was 22' wide and 6" thick using Iowa DOT Standard Specification B-6 mix proportions. It had a 2" crown and the only reinforcing was 3' long #4 tie bars across the centerline at 48" centers.

#### CONTRACTOR AND PERSONNEL

The successful bidder on this paving project was Central Paving Corporation. Their project Superintendent on this project was Mack Capper. The jobber for most of the Central Paving Corporation miscellaneous supplies is Pittsburg-Des Moines Steel. The jobber cooperated with the research in providing all sealant and backer materials at invoiced cost and providing this cost information.

## PAVING MATERIALS

The materials and proportions of the Standard Specification B-6 mix used for this paving were:

### B-6 Mix Proportion

<u>Material</u>	<u>Absolute Volume</u>	<u>Batch Quantities pounds per cu.yd.</u>
Cement	0.098936	523
Fine Agg.	0.404409	1819
Coarse Agg.	0.269606	1204
Water	0.176049	297
Air	0.060000	

The cement was a Type I from the Penn-Dixie Cement Company of Des Moines, Iowa.

The fine aggregates (Sp.Gr. = 2.67) were produced from the Hallett Construction Company sand pit in West Des Moines (Polk County 7 & 8-79-24).

The coarse aggregate was a crushed limestone (100% passing 1½" screen) from the Hallett Construction Company Quarry near Gilmore City, Iowa (Pocahontas County NE¼ 36-92-31).

The air entraining agent was CSC from Contractor Steel Corporation of Des Moines, Iowa and the white pigmented curing compound was produced by Carter-Waters Corporation of Kansas City, Missouri.

JOINT LAYOUT AND IDENTIFICATION

The research proposal was developed to place groups of five joints with the same combination of variables. A repetitive group of five joints with the same combination of variables was to be placed at another location. The joint sealing variables to be considered were:

TABLE 1

Sealant Materials

- A- W. R. Meadows, "Hi-Spec" (Iowa Standard Specification 4136)
- B- Lion Oil Division, "Lion D-200" (Two Comp. Urethane)
- C- W. R. Meadows, "Gardox" (Two Comp. Neoprene)
- D- W. R. Meadows, "Poly-Jet Highway" (Polyvinyl Chloride)
- E- Dow Corning, "Dow Corning 888" (Silicone Rubber)
- F- W. R. Grace, "Para Plastic" (Iowa Standard Spec. 4136)

Cleaning

- 1. Air Jet
- 2. Sand Blast
- 3. Water Blast

Saw Cut

- 1. Nominal 1/8"
- 2. Nominal 1/4"
- 3. Nominal 3/8" x 1/2" deep
- 4. Nominal 3/8" x 1" deep
- 5. Nominal 1/2" x 1/2" deep
- 6. Nominal 1/2" x 1-1/4" deep

Backing Materials

- N- No Backing Materials
- T- Tape
- BH- Backer Rope (Hot Material)
- BC- Backer Rod (Cold Material)

Size of Backing

- 3- 3/8"
- 4- 1/2"
- 5- 5/8"

An installation code designation was established for ease of documentation. The variables for 581 <sup>560, numbered through 581</sup> joints were tabulated and are included in Appendix A. The research was to include at

least ten joints of each possible combination of the variables previously noted. Some alterations in placement were necessary to be compatible with the contractor's operation. Limitation of material or equipment reduced or eliminated the use of some combinations. No nominal 1/8" wide joints were used.

#### JOINT SAWING

The initial cutting was a typical operation of cutting joints 1½" deep (¼ of slab thickness) using a 3/16" thick carborundum blade to prevent random cracking. The required depth and width for each group of five joints were spray painted on the pavement. Dual 3/16" blades were used to obtain the 3/8" wide joints. Dual ¼" blades were used for the ½" wide joints.

#### JOINT PREPARATION

Many engineers have the opinion that one major factor in the failure of joint seals is inadequate cleaning. Three types of cleaning were utilized for this research. The standard for years has been air jet removal of the cutting dust.

The second method of cleaning was sand blasting. For this operation, the contractor rented a small Clemco Mighty-mite Sandblaster (Figure 3) and used bagged silica sand. A specially designed wand would have improved this operation. To effectively sand blast the joint, the operator had to hold the short metal section with the nozzle very close to the pavement.




Figure 3 - Sand Blast Equipment

A portable car wash unit (figure 4) that would supply about 500 psi of pressure was used for water blast removal of dust and dirt. This unit was operated from the roadway shoulder and, therefore, could not be used when the rainy weather produced impassible conditions.




Figure 4 - Water Blast Equipment


## INSERTING BACKING MATERIAL

Standard Iowa DOT joint sealing procedures do not include backing material. A number of the research joints were sealed without backing material. The most inexpensive type of backing material utilized in this research was tape. Another economical feature was that it required less depth on the step joints. The fiber backing tape requires only  $\frac{1}{2}$ " of depth where as the backer rod or backer rope requires 1" to  $1\frac{1}{4}$ " depending on their diameter. Proper placement of the fiber reinforced tape was very difficult. The shoulders of the step joint were generally not equally distributed or wear of the corborundum blade did not produce distinct shoulders for a bearing surface. (Figure 5). Due to difficulty in tape placement, the  $\frac{1}{2}$ " deep step joints were soon discontinued.


The backer rod material (Figure 6) comes in three sizes ( $\frac{3}{8}$ ",  $\frac{1}{2}$ " and  $\frac{5}{8}$ " diameter) that are matched to joint widths. It must be properly centered over the joint and rolled to the proper depth with a special tool (Figure 7). To obtain the desired  $\frac{1}{2}$  inch reservoir for the sealant, the knife edge on the roller had to be  $\frac{5}{8}$ " deep for the  $\frac{1}{2}$ " and  $\frac{5}{8}$ " diameter backer rod while a  $\frac{1}{2}$ " knife edge depth was sufficient to place the  $\frac{3}{8}$ " diameter backer rod.

The  $\frac{3}{8}$ ",  $\frac{1}{2}$ " and  $\frac{5}{8}$ " diameter sizes of backer rope, for use with the hot applied sealants, were installed with the same special tool.






(a) Step joint cut as designed



(b) Step joint with no shoulder on one side



(c) Step joint without distinct shoulders (rounded)

Figure 5 - Step Joints for Tape Backing




Figure 6 - Backer Rod Material




Figure 7 - Inserting Backer Rod Material

#### JOINT SEALING OPERATION

*Ad.* W. R. Meadows "Hi Spec"

The contractor's standard operation includes a specially constructed, hydraulically driven joint sealing unit (Figure 8) that spans the slab for ease in applying the standard sealant material. It was equipped to heat the sealant to the recommended pouring temperature of 390°F. The material was pumped through a wand with a special applicator tip.




Figure 8 - Contractor's Joint Sealing Unit

*B* • Lion Oil Company "Lion D-200"

The two component material was mixed per the manufacturer's instruction. The contractor made a mixing agitator by welding a 6" hinge onto  $\frac{1}{4}$ " diameter round stock. After component two was poured into component one, the contractor's personnel mixed the material thoroughly for 3 to 5 minutes. The viscosity of this material would not allow it to flow by gravity through the small orifice of an Iowa DOT crack sealing pot. All joints were hand poured using a five gallon bucket with one side bent to form a pouring spout (Figure 9).




Figure 9 - Manual Pouring of Joint Sealant

Operator experience and technique are very important in obtaining properly filled joints. The pot life of this sealant is one to two hours. Better joints are obtained if the sealant is used soon after mixing while very fluid. If only the right amount of sealant is added to the pouring bucket to complete one joint at a time, a better sealing job is obtained. The operator must proceed at a speed that is coordinated with the viscosity of the sealant. With hand operation, it is very difficult and near impossible to under fill the joint  $1/8$ " as desired. With some operator experience, reasonably neat appearing joints were obtained. Production type equipment could be developed to improve this sealing procedure and make it compatible with the contractor's operation.

C. W. R. Meadow's "Gardox"

Mixing and applying this two component material was very similar to product <sup>"B"</sup> above. The mixing time was normally in excess of five minutes. The viscosity and pouring techniques were very similar to the Lion D-200. The manufacturer claims a pot life of 2 to 3 hours, but it exhibits far better pouring characteristics immediately after mixing. The length of time after mixing is directly related to the adverse pouring characteristics.

D. W. R. Meadows "Poly-Jet Highway"

This hot pour material was applied with the contractor's normal sealing equipment. Even though the application of this material is very similar to that for the Standard Specification rubber asphalts, there are some additional limitations and precautions. This polyvinyl chloride coal tar is not compatible with the rubber asphalt, therefore, it was necessary to completely clean the sealing equipment before and after using Poly-Jet Highway. Furthermore, the materials cannot be used in contact with each other in the joints, so when the transverse joints were Poly-Jet Highway, the longitudinal joint was also Poly-Jet Highway.

Poly-Jet Highway cannot be reheated, as after heating, it gels. Any material remaining in the kettle at the end of the day's application must be discarded. Personnel must avoid the

the vapor produced while heating as it can cause irritation to the skin. The control of the heat must be precise with a recommended pouring temperature of 280°F and a maximum safe temperature of 300°F. Overheating causes the material to gel and additional heating will assure gelation.

The contractor was made aware of these precautions and the Poly-Jet Highway was installed without problems.

*E. D.* Dow Corning "Dow Corning 888"

A representative of the Dow Corning Corporation supplied the sealant and application equipment in addition to supervising the installation. The sealant for this research was supplied in 4.5 gallon pails and 11 ounce caulking tube samples. The "888" sealant is to be tooled in and, therefore, the manufacturer recommends the use of backer materials. A few of the ¼" wide joints were sealed using the caulking gun (Figure 10). Most of the research joints were sealed using the air operated bucket pump supplied by Dow Corning (Figure 11). The "888" sealant does not flow readily and, therefore, must be "tooled" into the joint. This tooling was done immediately after depositing the sealant. Round steel rods compatible with the width of joints were used in much the same manner as one would "strike" off the joints of a concrete block wall.






Figure 10 - Dow Corning 888 Sealing with a Caulking Gun




Figure 11 - Dow Corning 888 Sealing with Bucket Pump

This was the first paving project where the Dow Corning personnel had assisted in the field application. It was a relatively slow process and the Dow-Corning representative recognized that equipment modifications would improve the operation. A more efficient sealing system can be developed to increase the speed of application.

F. W. R. Grace "Para Plastic"

The contractor used his normal sealing equipment for this Standard Specification rubber asphalt sealant. There was no problems and the application was exactly the same as for the W. R. Meadows "Hi-Spec" sealant.

#### COST COMPARISON

It would be difficult if not impossible and not entirely fair or realistic to try to determine the true cost of the total sealing operation for each sealant. <sup>from this record</sup> Some sealants were applied with readily available equipment while others were applied by crude/hand equipment or equipment in the developmental stage.

The costs presented for comparison will be the contractor's cost of materials only (Table I).



Table I

Backer Rod - 3/8" diam. = \$0.015/lin.ft.  
 - 1/2" diam. = 0.021/lin.ft.  
 - 5/8" diam. = 0.030/lin.ft.

Backer Rope- 3/8" diam. = 0.04/lin.ft.\*  
 - 1/2" diam. = 0.029/lin.ft.  
 - 5/8" diam. = 0.033/lin.ft.

\*Purchased from another company on a small lot basis.

Sealant cost (Table II) present<sup>ed</sup> is estimated for a 1/4" wide 1/2" deep joint. This joint is selected to provide a definite volume for the cost comparison.

Table II

Sealant	Contractors Cost		Quantity for 1/4" x 1/2" joint	Price per lineal ft.
	Per/lb.	Per/gal.		
Hi-Spec	\$0.2415	\$ 2.16	5.85 lb per 100 lineal feet	\$0.015
Lion D-200	0.8211	7.80	154 lineal feet per gallon	0.051
Gardox	1.8907	19.38	0.7 gallon per 100 lin. ft.	0.136
Poly-Jet Hwy	0.5558**	5.89	6.888 lb/100 lin. ft.	0.038
Dow Corning 888	---	23.00	154 lineal ft. per gallon	0.149
Para Plastic	0.2415	2.16	5.85 lb. per 100 lin. ft.	0.015

\*\*Includes cost of flushing oil

PERFORMANCE EVALUATION

Visual Inspection

Visual observations of the entire project were made in February and April 1979. In general, all joints appeared to be tight and sealed. One joint seal had apparently been ripped

out and was missing entirely. Inspection of some joints was difficult due to a large amount of sand from winter ice control remaining on top of the sealant.

~~ADD~~  
Joint Heave

The riding quality of the pavement was determined using the Bureau of Public Roads type roughometer. Testing of both lanes soon after construction (11-30-78) resulted in an average of 71 inches per mile.

Evaluation of the joint heaving was conducted in February 1979 using a 25 foot profilometer. The profilometer is supported on each end by an assembly with six averaging wheels and the profile is determined by a large bicycle wheel. This bicycle wheel powers a chart drive and produces a chart plotted profile to a true vertical scale and a  $1\frac{1}{4} = 25'$  horizontal scale. The profile was obtained for the outside wheel track of both lanes. It does not show any joint heave at this time. This profile trace exhibiting no joint heave will serve as original data for comparison with subsequent profiles.

Core Drilling and Testing

One 4 inch diameter core was drilled from each combination of the joint sealing variables. A total of 68 cores (Appendix B) were drilled on April 16, 1979. One interesting and significant feature was noted while drilling. The cores were drilled with

an Acker drill which supplies cooling and flushing water through a Moyno pump. When drilling the Dow Corning 888 joints, the water was pumped to both edges of the slab where it spurting up in a small stream. This emphasized the tight seal of this joint. This type of spurting was not noted on joints with other types of sealant.

All cores were drilled between the wheel paths of the north-bound lane. The intent was to center the core over the transverse joint yielding a 4 inch length of joint seal for inspection and testing.

The cores were visually inspected and rated on the basis of their condition after drilling and transportation. Cores were classified as:

1. No Visible Failure - The bond was apparently tight on both interfaces for the entire 4 inch length.
2. Partial Seal Failure - There was a loss of bond on one interface for even a short length.
3. Broken Seal - The bond had completely failed on one interface and the core was no longer held together.

Using this criteria, the cores were rated and summarized in respect to sealant material, cleaning and saw cut (Appendix C). When considering the sealant and disregarding other variables, the Poly-Jet Highway and Dow Corning 888 exhibited no visible failures. The visual rating with respect to cleaning did not

yield results that would favor any one procedure. The water blast cleaning exhibited the poorest results. The  $\frac{1}{2}$  inch deep joints with tape backing had no visual failures in the saw cut summary.

The cores were grouped by sealant type and color slide photographs were taken (Figure 12).




Figure 12 - Cores From Dow Corning 888 Joints

The top portion (approximately 2") of the cores including the joint seal was cut off for the final test of the cores. Two C-Clamps were fitted with pull rods to be used in a Tinius Ohlsen testing machine (Figure 13). The C-Clamps were secured to the rod so they were not free to rotate. The rods were free




Figure 13 - Joint Seal Testing Apparatus

to move for alignment. All cores that were bonded sufficiently to transmit load were tested. Even some that were rated "partial seal failure" yielded a significant maximum load at failure. The load was applied at the rate of 0.3 inch per minute. The maximum load, elongation at maximum load (not available for all cores) and elongation at failure are tabulated in Appendix B. The Dow Corning 888 exhibited outstanding elongation (Figure 14). Some Para Plastic joints had a very deep seal that resulted in high maximum load (Figure 15). A maximum load of 89.5 pounds was obtained on a Para Plastic joint. The point of failure was somewhat arbitrary, but certain criteria were established for this determination. First, if the bond was destroyed on 80% of the 4" length on either




Figure 14 - Elongation of Dow Corning 888




Figure 15 - Deep Seal of a Para Plastic Joint

interface, it had failed. Second, it failed if a load greater than 20 lbs. had been obtained followed by a reduction below 10 lbs.

The maximum loads and maximum elongations were summarized with respect to the same variables as the visual rating (Appendix C). This testing exhibited poor strength and elongation for the Lion D-200 and Hi-Spec sealants. There was no significant difference due to the cleaning procedure. As expected, the  $\frac{1}{4}$ " saw cut yielded the poorest elongation capabilities.

#### ACKNOWLEDGEMENTS

We wish to express our appreciation to Gene Hardy and the Dallas County Secondary Road Department for their participation in this research. We also wish to thank Central Paving Corporation for their cooperation with a special thanks to Mac Capper and Jim Draper. We also wish to thank Gary Hankins and Pittsburg-Des Moines Steel Company for their cooperation.

Hossein Foadian of the Iowa Department of Transportation contributed much to the success of the research by providing direction, inspection and documentation.

REFERENCES

1. "Joint-Related Distress in P.C.C. Pavement Cause, Prevention and Rehabilitation" NCHRP Synthesis 56 (January 1979) 36 pp.
2. DeYoung, Clarence "Spacing of Undoweled Joints in Plain Concrete Pavement" Highway Research Record No. 112 (1966) pp 46-54.
3. Graham, M.C. et al "New York State Experience with Concrete Pavement Joint Sealers" Highway Research Record No. 80 (1965) pp 42-48.



APPENDIX A:  
JOINT VARIABLE TABULATION

## HR-203, "Joint Sealing with Various Sealants"

Installation Code Designations

A-	3-	5-	B	3
-	-	-	-	-
Material	Cleaning	Saw Cut	Backing Materials	Size of Backing

Sealant Materials

- A- W. R. Meadows, "Hi-Spec" (Iowa Standard Specification 4136)
- B- Lion Oil Division, "Lion D-200" (Two Comp. Urethane)
- C- W. R. Meadows, "Gardox" (Two Comp. Neoprene)
- D- W. R. Meadows, "Poly-Jet Highway" (Polyvinyl Chloride)
- E- Dow Corning, "Dow Corning 888" (Silicone Rubber)
- F- W. R. Grace, "Para Plastic" (Iowa Standard Spec. 4136)

Cleaning

- 1. Air Jet
- 2. Sand Blast
- 3. Water Blast

Saw Cut

- 1. Nominal 1/8"
- 2. Nominal 1/4"
- 3. Nominal 3/8" x 1/2" deep
- 4. Nominal 3/8" x 1" deep
- 5. Nominal 1/2" x 1/2" deep
- 6. Nominal 1/2" x 1-1/4" deep


Backing Material.

- N- No Backing Materials
- T- Tape
- BH- Backer Rope (Hot Sealant)
- BC- Backer Rod (Cold Sealant)

Size of Backing

- 3- 3/8"
- 4- 1/2"
- 5- 5/8"

SCHEMATIC JOINT SEALANT LAYOUT



Visual Rating 1 good

A-4

2 3' or less broken seal  
 3 3' or more broken seal

APPENDIX A

Joint Variable Tabulation and Visual Evaluation

All stations were determined by pacing and, therefore, are approximate.

Joint Number	Station	Installation Code Designation	Visual Evaluation	Joint Number	Station	Installation Code Designation
1	82+52	B-3-2-BC3		36	1 97+80	B-2-4-BC4 ✓
2	82+88	"		37	1 98+23	"
3	83+25	"		38	2 98+65	"
4	83+70	"		39	1 99+09	"
5	84+02	"		40	2 99+49	"
	84+50	Broken		41	1 99+90	B-2-6-BC5 ✓
6	84+85	B-3-4-BC4 ✓		42	2 100+30	"
7	85+34	"		43	2 100+75	"
8	85+70	"		44	1 101+35	"
9	86+15	"		45	1 101+65	"
10	86+56	"		46	3 102+02	C-3-2-BC3 ✓
11	86+88	B-3-6-BC5 ✓		47	3 102+45	"
12	87+35	"		48	3 102+90	"
13	87+75	"		49	3 103+40	"
14	88+20	"		50	3 103+85	"
15	2 88+62	"		51	3 104+25	C-3-4-BC4 ✓
16	88+98	B-1-2-BC3 ✓		52	3 104+75	"
17	89+50	"		53	3 105+25	"
18	2 89+85	"		54	2 105+65	"
19	3 90+35	"		55	3 105+94	"
20	3 90+70	"		56	3 106+45	C-3-6-BC5 ✓
21	2 91+96	B-1-4-BC4 ✓		57	2 106+85	"
22	1 91+52	"		58	3 107+20	"
23	3 91+85	"		59	3 107+60	"
24	1 92+35	"		60	3 108+01	"
25	3 92+70	"		61	3 108+37	C-1-2-BC3 ✓
26	1 93+15	B-1-6-BC5 ✓		62	3 108+79	"
27	2 93+55	"		63	3 109+25	"
28	2 93+88	"		64	1 109+60	"
29	1 94+34	"		65	1 110+10	"
30	2 94+67	"		66	1 110+55	C-1-4-BC4 ✓
31	2 95+00	B-2-2-BC3 ✓		67	3 110+90	"
32	3 95+45	"		68	3 111+42	"
	95+85	Broken		69	2 111+75	"
33	2 96+15	B-2-2-BC3		70	3 112+10	"
34	3 96+62	"		71	3 112+58	C-1-6-BC5 ✓
35	2 96+97	"		72	2 112+88	"
	3 97+40	Broken				

3-16-83  
 2-27-80  
 2-26-81  
 4-16-82

Visual Evaluation  
 2-27-80  
 2-26-81  
 3-16-83

23  
 190  
 21

## APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
73	3 113+33	C-1-6-BC5 ✓	118	1 131+66 2	A-1-6-BH5 ✓
74	3 113+72	"	119	3 132+05	"
75	2 114+03 3	"	120	3 132+50 3	"
76	1 114+51 3	C-2-2-BC3 ✓	121	3 132+90	A-2-2-N ✓
77	3 114+85	"	122	3 133+30	"
78	1 115+27 2	"	123	3 133+75	"
79	3 115+69	"	124	3 134+20	"
80	3 116+03 1 ✓	"	125	3 134+58	"
81	3 116+36	C-2-4-BC4 ✓	126	2 134+97 1 ✓	A-2-4-BH3 ✓
82	3 116+78 2 ✓	"	127	3 135+38	"
83	3 117+15	"	128	1 135+75 2 3	"
84	3 117+55 3	"	129	3 136+15	"
85	3 118+02	"	130	3 136+50 2 3	"
86	2 118+40 1 ✓	C-2-6-BC5 ✓	131	3 136+90	A-2-6-BH5 ✓
87	2 118+90	"	132	1 137+30 1 ✓ C	"
88	2 119+28 1	"	133	3 137+70	"
89	2 119+60	"	134	2 138+10 1 ✓	"
90	1 120+05 1 ✓	"	135	3 138+45	"
91	3 120+40	A-3-2-N ✓	136	1 138+85	A-3-2-N ✓
92	2 120+80 1 ✓	"	137	3 139+30	"
93	3 121+22	"	138	3 139+70	"
94	2 121+62 1 ✓	"	139	2 140+00	"
95	3 121+98	"	140	3 140+35	"
96	3 122+33	A-3-4-BH3 ✓	141	3 140+80	A-3-4-BH3 ✓
97	3 122+80 1 ✓	"	142	3 141+15	"
98	3 123+25	"	143	3 141+60	"
99	3 123+60	"	144	3 141+97	"
100	3 124+00	"	145	3 142+30	"
101	3 124+36	A-3-6-BH5 ✓	146	3 142+65	A-3-6-BH5 ✓
102	3 124+78	"	147	3 143+10	"
103	3 125+20	"	148	3 143+43	"
104	3 125+55	"	149	3 143+82	"
105	3 126+00	"	150	3 144+20	"
106	3 126+40	A-1-2-N ✓	151	3 144+60	A-1-2-N ✓
107	3 126+80	"	152	2 145+05	"
108	3 127+20	"	153	1 145+45	"
109	3 127+60	"	154	2 145+78 1 ✓	"
110	3 128+00 1 ✓	"	155	3 146+20	"
111	3 128+45	A-1-4-BH3 ✓	156	3 146+65	A-1-4-BH3 ✓
112	3 128+90 2	"	157	3 147+00	"
113	3 129+30	"	158	2 147+40 3	"
114	2 129+72 1 ✓	"	159	3 147+80	"
115	3 130+18	"	160	2 148+20 3	"
116	3 130+70	A-1-6-BH5 ✓	161	3 148+60	A-1-6-BH5 ✓
117	3 131+100 2 ✓	"	162	3 148+95	"

X

## APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
163	149+35	A-1-6-BH5 ✓	207	166+86 3	D-3-6-BH5 ✓
164	149+70	"	208	167+25 3	"
165	150+10	"	209	167+67 ✓	"
166	150+50	A-2-2-N ✓	210	168+10	"
167	150+90	"	211	168+50 ✓	D-2-2-BH3 ✓
168	151+30 2 ✓	"	212	168+92 ✓	"
169	152+03 1 ✓	"	213	169+30 ✓	"
170	152+48	"	214	169+70 ✓	"
171	152+83	A-2-4-BH3 ✓	215	170+15 3	"
172	153+25	"	216	170+55 2	D-2-4-BH4 ✓
173	153+65	"	217	170+95 ✓	"
174	154+00	"	218	171+35 ✓	"
175	154+40	"	219	171+75 2	"
176	154+80 1 ✓	A-2-6-BH5 ✓	220	172+20 2	"
177	155+20	"	221	172+60 2	D-2-6-BH5 ✓
178	155+60 2 3	"	222	173+04	"
179	155+91	"	223	173+45	"
180	156+30	"	224	173+85 3	"
181	156+70	D-3-2-BH3 ✓	225	174+35 ✓	"
182	157+10	"	226	174+75 ✓	D-2-2-BH3 ✓
183	157+50 3	"	227	175+18 ✓	"
184	157+90 3	"	228	175+63 ✓	"
185	158+30 2 ✓	"	229	176+08 ✓	"
186	158+70 2 ✓	D-3-4-BH4 ✓	230	176+50 ✓	"
187	159+05 1 ✓	"	231	176+88 ✓	D-2-4-BH4 ✓
188	159+43 1 ✓	"	232	177+30 ✓	"
189	159+80 2 ✓	"	233	177+70 ✓	"
190	160+20 1 2	"	234	178+10 ✓	"
191	160+60 1 2	D-3-6-BH5 ✓	235	178+50 ✓	"
192	161+00 2 3	"	236	178+94 3	D-2-6-BH5 ✓
193	161+40 1 2	"	237	179+35 2	"
194	161+75	"	238	179+75	"
195	162+15 3	"	239	180+10 ✓	"
196	162+55 2 3	D-3-2-BH3 ✓	240	180+50 ✓	"
197	162+93	"	241	180+90 ✓	D-1-2-BH3 ✓
198	163+30	"	242	181+30 3	"
199	163+70	"	243	181+70 2 ✓	"
200	164+10	"	244	182+10 2 ✓	"
201	164+50 1 2	D-3-4-BH4 ✓	245	182+50	"
202	164+85 1 2	"	246	182+85 3	D-1-4-BH4 ✓
203	165+30 1 2	"	247	183+25 3	"
204	165+70 1 2	"	248	183+65	"
205	166+06 3	"	249	184+10	"
206	166+46 1 2	D-3-6-BH5 ✓	250	184+50	"

APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
251	3 184+90	D-1-6-BH5 ✓	293	2 202+60 3	B-2-4-BC4 ✓
252	3 185+10	"	294	2 203+00 3	"
253	2 185+65	"	295	2 203+40	"
254	1 186+10 3	"	296	2 203+80 2 ✓	B-2-6-BC5 ✓
255	2 186+50 3	"	297	2 204+20	"
256	3 186+88	F-1-2-BH3 ✓	298	1 204+60 ✓	"
257	2 187+30 2	"	299	1 204+98 2	"
258	3 187+70	"	300	1 205+38 ✓	"
259	3 188+08	"	301	2 205+75	B-1-2-BC3 ✓
260	3 188+48	"	302	2 206+12	"
261	3 188+88	F-1-4-BH4 ✓	303	2 206+53	"
262	3 189+30	"	304	2 206+94	"
263	3 189+70	"	305	2 207+32	"
264	3 190+10	"	306	2 207+68	B-1-4-BC4 ✓
265	3 190+50	"	307	2 208+09	"
266	3 191+10	F-1-6-BH5 ✓	308	2 208+50	"
267	3 191+50	"	309	2 208+88	"
268	3 191+95	"	310	2 209+25 3	"
269	3 192+40	"	311	2 209+65 2 3	B-1-6-BC5 ✓
270	2 192+80 3	"	312	2 210+03 2 3	"
271	2 193+28	B-3-2-BC3 ✓	313	1 210+43 2 3	"
272	2 193+70	"	314	1 210+85 1 3	"
273	2 194+20	"	315	2 211+20	"
274	2 194+75	"	316	2 211+67	F-1-2-BH3 ✓
275	3 195+08	"	317	2 212+07	"
276	1 195+48 3	B-3-4-BC4 ✓	318	2 212+47	"
277	3 195+88	"	319	2 212+86	"
278	1 196+30 3	"	320	3 213+25	"
279	2 196+70	"	From Sta. 213+25 to Hwy 44, all the joints are under the following code: F-1-2-N. The longitudinal joint material is "F".		
280	2 197+12	"	From Hwy. 44 to Sta. 128+65 all the joints including the longitudinal joint up to Sta. 201+36 are under the following code: A-1-2-N.		
281	2 197+52 3	B-3-6-BC5 ✓	321	128+65 3	C-1-3-BC3
282	2 197+95	"	322	129+05 1 ✓	"
283	1 198+35 3	"	323	129+45 2	"
284	1 198+80 3	"			
285	2 199+25 3	"			
286	2 199+70	B-2-2-BC3 ✓			
287	2 200+15	"			
288	3 200+60	"			
289	3 201+03	"			
290	3 201+40	"			
291	3 201+80	B-2-4-BC4 ✓			
292	2 202+20 3	"			

APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
324	129+85	C-1-3-BC 3	368	147+80	A-1-2-N
325	130+25	"	369	148+30	"
326	130+65	C-1-4-BC4	370	148+60	"
327	131+09	"	371	148+99	A-1-3-N
328	131+40	"	372	149+40	"
329	131+75	"	373	149+75	"
330	132+25	"	374	150+25	"
331	132+65	C-1-5-BC4	375	150+60	"
332	133+06	"	376	150+90	A-1-4-N
333	133+40	"	377	151+30	"
334	133+75	"	378	151+70	"
335	134+30	"	379	152+10	"
336	134+65	C-1-6-BC5	380	152+55	"
337	135+12	"	381	152+80	A-1-5-N
338	135+48	"	382	153+12	"
339	135+90	"	383	153+45	"
340	136+35	"	384	153+90	"
341	136+70	C-1-2-BC3	385	154+35	"
342	137+09	"	386	154+75	A-1-6-N
343	137+44	"	387	155+20	"
344	137+80	"	388	155+60	"
345	138+25	"	389	156+00	"
346	138+60	A-1-3-N	400	156+35	"
347	139+00	"	401	156+75	A-1-2-N
348	139+36	"	402	157+30	"
349	139+70	"	403	157+70	"
350	140+15	"	404	158+20	"
351	140+60	A-1-4-N	405	158+50	"
352	141+30	"	406	158+90	A-1-3-N
353	141+70	"	407	159+30	"
354	142+22	"	408	159+75	"
355	142+60	"	409	160+20	"
356	143+09	A-1-5-N	410	160+60	"
357	143+45	"	411	161+03	A-1-4-N
358	143+90	"	412	161+40	"
359	144+35	"	413	161+83	"
360	144+75	"	414	162+30	"
361	145+10	A-1-6-BH5	415	162+70	"
362	145+52	"	416	163+10	A-1-5-N
363	145+88	"	417	163+55	"
364	146+30	"	418	163+95	"
365	146+65	"	419	164+40	"
366	147+00	A-1-2-N	420	164+83	"
367	147+45	"	421	165+20	A-1-6-N

End

3

C

7

C

C

have

not working

End survey 4/16/82



## APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
422	1 165+65 1	A-1-6-N	467	2 184+80	C-2-5-BC4
423	1 166+01 2	"	468	1 185+20 2	"
424	2 166+39 2	"	469	1 185+60	"
425	1 166+77	"	470	1 186+10	"
426	1 167+35 1	A-1-2-N	471	2 186+55 2	C-2-6-BC5
247	2 167+75 3	"	472	2 186+94 2	"
428	2 168+15 2	"	473	2 187+35	"
429	1 168+65	"	474	2 187+75 2	"
430	1 169+02 1	"	475	1 188+20 1	"
431	2 169+40	C-1-3-BC3	476	2 188+60	C-2-2-BC3
432	1 169+85 1	"	477	1 189+09 1	"
433	1 170+25 1 C	"	478	2 189+40	"
434	1 170+75	"	479	2 189+85	<del>C-2-2-N</del>
435	1 171+09 2	"	480	0 190+35	<del>C-2-2-N</del>
436	1 171+60 1	C-1-4-BC4	481	0 190+76	C-3-3-BC4
437	1 171+96	"	482	0 191+16	"
438	1 172+43 1	"	483	0 191+56 2	"
439	1 172+80 2	"	484	0 192+01	"
440	2 173+25 2	"	485	0 192+43	"
441	2 173+65 2	C-1-5-BC4	486	0 192+90	C-3-4-BC4
442	2 174+02	"	487	1 193+30	"
443	1 174+38	"	488	0 193+70	"
444	2 174+75 2	"	489	0 194+15 2	"
445	2 175+20	"	490	1 194+55 1 C	"
446	2 175+73 2	C-1-6-BC5	491	0 194+96	C-3-5-BC4
447	3 176+15	"	492	0 195+40	"
448	1 176+58	"	493	0 195+80	"
449	3 176+91	"	494	0 196+22	"
450	2 177+30 2	"	495	0 196+62	"
451	3 177+80	C-1-2-BC3	496	0 197+04	C-3-6-BC5
452	1 178+17 2	"	497	0 197+44	"
453	1 178+65 2	"	498	0 197+82	"
454	1 179+04	"	499	0 198+30	"
455	1 179+50 1	"	500	0 198+75	"
456	2 179+94 2	C-2-3-BC3	501	1 199+25 1 C	C-3-2-BC3
457	2 180+35	"	502	0 199+70	"
458	2 180+75 3	"	503	0 200+09	"
459	2 181+17	"	504	0 200+50	"
460	2 181+60	"	505	0 200+97	"
461	3 181+99	C-2-4-BC4	506	1 201+36	F-3-3-N
462	1 182+40	"	507	1 201+80 1	"
463	2 182+80	"	508	1 202+20 1	"
464	1 183+30 1	"	509	1 202+60 1	"
465	1 183+70	"	510	2 203+06 2	"
466	2 184+42	C-2-5-BC4	511	1 203+46 1	F-3-4-N

APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
512	203+86	F-3-4-N	557	222+58	E-2-2-BC3
513	204+33	"	558	222+88	"
514	204+73	"	559	223+30	"
515	205+17	"	560	223+70	"
516	205+56	F-3-5-N	561	224+09	"
517	206+02	"	562	224+50	E-2-6-BC5
518	206+42	"	563	224+82	"
519	206+82	"	564	225+24	"
520	207+22	"	565	225+64	"
521	207+62	F-3-6-N	566	226+00	"
522	208+05	"	567	226+40	E-2-5-T
523	208+45	"	568	226+80	"
524	208+85	"	569	227+20	"
525	209+36	"	570	227+60	"
526	209+67	E-3-2-BC3	571	228+10	"
527	210+08	"	572	228+50	F-1-4-N
528	210+60	"	573	228+90	"
529	211+03	"	574	229+30	"
530	211+43	"	575	229+70	"
531	211+90	F-1-2-N	576	230+10	"
532	212+36	E-1-2-BC3	577	230+50	F-1-3-N
533	212+73	"	578	230+90	"
534	213+20	"	579	231+33	"
535	213+62	"	580	231+72	"
536	214+03	"	581	232+15	"
537	214+42	E-1-6-BC5			
538	214+85	"			
539	215+26	"			
540	215+67	"			
541	216+06	"			
542	216+46	E-1-5-T			
543	217+05	"			
544	217+42	"			
545	217+82	"			
546	218+25	"			
547	218+63	E-1-4-BC4			
548	219+03	"			
549	219+36	"			
550	219+78	"			
551	220+21	"			
552	220+55	E-1-3-T			
553	220+95	"			
554	221+40	"			
555	221+82	"			
556	222+13	"			

Remarks:

From Sta. 82+00 to Sta. 156+30 the longitudinal joint material is "A"

From Sta. 156+30 to Sta. 186+50 the longitudinal joint material is "D"

From Sta. 186+50 to Sta. 213+25 the longitudinal joint material is "F"

From Hwy. 44 to Sta. 201+36 the longitudinal joint material is "A"

From Sta. 201+36 to F-31 the longitudinal joint material is "F"

From Sta. 232+15 to F-31 all the joints including the longitudinal joint are under the following code:

F-1-2-N

## APPENDIX B - CORE DRILLING AND TESTING TABULATION

(From cores drilled 4-16-79)

Core No.	Station	Installation Code Designation	Visual Rating *	CORE TESTING		
				Maximum Load	Elongation at Maximum Load	Elongation at Failure
1	139+70	A-3-2-N	P	4.0	---	0.19
2	141+60	A-3-4-BH3	B	0.0		
3	143+43	A-3-6-BH5	B	4.3	---	0.19
4	147+40	A-1-4-BH3	N	19.3	0.64	1.34
5	151+30	A-2-2-N	N	10.0	0.45	0.55
6	153+65	A-2-4-BH3	B	0.0		
7	155+60	A-2-6-BH5	N	13.2	0.83	1.21
8	163+30	D-3-2-BH3	N	11.6	0.38	0.50
9	165+30	D-3-4-BH4	N	26.1	0.71	2.00
10	167+25	D-3-6-BH5	N	--	---	
11	175+63	D-2-2-BH3	N	15.1	0.50	0.70
12	177+70	D-2-4-BH4	N	24.1	---	1.45
13	179+75	D-2-6-BH5	N	20.3	---	1.32
14	181+70	D-1-2-BH3	N	15.5	0.51	0.71
15	183+65	D-1-4-BH4	N	11.9	0.51	0.79
16	185+65	D-1-6-BH5	N	20.2	0.72	1.59
17	187+70	F-1-2-BH3	N	0.0		
18	189+70	F-1-4-BH4	P	3.7	0.83	0.91
19	191+95	F-1-6-BH5	N	2.3	0.57	0.60
20	194+20	B-3-2-BC3	P	0.0		
21	196+75	B-3-4-BC4	P	6.1		0.56
22	198+35	B-3-6-BC5	N	12.2	0.93	1.31
23	200+60	B-2-2-BC3	B	0.0		
24	203+00	B-2-4-BC4	N	21.6	---	1.24
25	204+60	B-2-6-BC5	N	9.3	0.89	1.57
26	206+53	B-1-2-BC3	P	2.3	---	0.13
27	208+50	B-1-4-BC4	N	14.2	---	0.89
28	210+43	B-1-6-BC5	N	18.9	1.74	1.97
29	212+47	F-1-2-BH3	B	0.0		
30	145+88	A-1-6-BH5	B	0.0		
31	147+80	A-1-2-N	N	7.4	0.55	0.73
32	149+75	A-1-3-N	N	35.6	0.36	1.45
33	151+70	A-1-4-N	N	48.4	1.40	2.17
34	153+45	A-1-5-N	N	13.5	1.77	2.12

\*N-No Visible failure; P- Partial Seal Failure; B- Broken Seal

APPENDIX B  
Continued

## CORE TESTING

Core No.	Station	Installation Code Designation	Visual Rating *	Maximum Load	Elongation At Maximum Load	Elongation at Failure
35	166+01	A-1-6-N	N <i>N</i>	7.8	0.64	3.10
36	168+15	A-1-2-N	N <i>N</i>	14.9	0.92	1.28
37	170+25	C-1-3-BC3	N <i>N</i>	60.8	0.62	1.19
38	172+43	C-1-4-BC4	N <i>N</i>	82.0	0.57	18.2
39	174+38	C-1-5-BC4	N <i>N</i>	25.4	---	0.80
40	176+58	C-1-6-BC5	N <i>N</i>	38.0	0.47	0.99
41	178+65 <i>24</i>	C-1-2-BC3	N <i>N</i>	27.2	0.57	1.04
42	180+75	C-2-3-BC3	N <i>N</i>	63.0		2.36
43	182+80	C-2-4-BC4	P <i>N</i>	9.9	0.47	0.61
44	185+20	C-2-5-BC4	N <i>N</i>	27.0	---	1.02
45	187+35	C-2-6-BC5	P <i>N</i>	11.2	0.38	0.65
46	<del>189+09</del> <i>7</i>	C-2-2-BC3 <i>N</i>	N <i>N</i>	43.0	1.11	1.56
47	<del>189+85</del>	C-2-2-N	N <i>N</i>	41.7	0.42	0.89
48	191+56	C-3-3-BC4	N <i>N</i>	77.0	0.73	1.94
49	193+70	C-3-4-BC4	P <i>N</i>	16.9	0.58	1.47
50	<del>195+80</del>	C-3-5-BC4	N	41.2	0.45	0.80
51	<del>197+82</del>	C-3-6-BC5	P	2.7		0.22
52	<del>200+09</del>	C-3-2-BC3	P	52.5	0.91	1.21
53	202+20	F-3-3-N	N <i>N</i>	22.6	1.37	1.72
54	204+33	F-3-4-N	N <i>N</i>	24.6	1.58	1.94
55	206+42	F-3-5-N	N <i>N</i>	35.2	0.93	1.92
56	208+45	F-3-6-N	N <i>N</i>	40.9	1.50	2.91
57	210+60 <i>2</i>	E-3-2-BC3	N <i>N</i>	43.3	1.21	1.97
58	213+20 <i>11</i>	E-1-2-BC3	N <i>N</i>	24.2	1.01	1.72
59	215+26	E-1-6-BC5	N <i>N</i>	14.9	0.79	1.22
60	217+42	E-1-5-T	N <i>N</i>	44.5	1.95	2.18
61	219+36	E-1-4-BC4	N <i>N</i>	30.1		2.44
62	221+40 <i>)</i>	E-1-3-T	N <i>N</i>	28.0	1.82	2.10
63	223+30	E-2-2-BC3	N <i>N</i>	19.3	---	1.05
64	225+24 <i>2</i>	E-2-6-BC5	N <i>N</i>	25.3	---	1.71
65	227+20 <i>4</i>	E-2-5-T	N <i>N</i>	22.9	---	1.50
66	229+30	F-1-4-N	N <i>N</i>	73.3	1.54	1.78
67	231+33	F-1-3-N <i>2114</i>	N <i>N</i>	89.5	1.32	2.13
68	242+03 <i>1</i>	E-1-2-N <i>2114</i>	N <i>N</i>	57.7	1.41	2.70

\* N-No Visible failure; P- Partial Seal Failure; B- Broken Seal

APPENDIX C - JOINT SEAL EVALUATION SUMMARY

(From cores drilled 4-16-79)

VISUAL RATING

CORE TESTING SUMMARY

Sealant Material	VISUAL RATING			CORE TESTING SUMMARY	
	No Visible Failure	Partial Seal Failure	Broken Seal	Average Maximum Load, pounds	Average Maximum elongation, inches
A. W. R. Meadows "Hi-Spec"	9	1	4	12.7	1.0
B. "Lion D-200"	5	3	1	9.4	0.9
C. W. R. Meadows "Gardox"	11	5	0	38.7	1.2
D. W. R. Meadows "Poly-Jet Highway"	9	0	0	18.1	1.1
E. "Dow Corning 888"	9	0	0	28.1	1.8
F. W. R. Grace "Para Plastic"	9	1	1	31.8	1.5
<u>Cleaning</u>					
1. Air Jet	27	2	2	26.8	1.4
2. Sand Blast	14	2	2	20.9	1.1
3. Water Blast	11	6	2	23.4	1.2
<u>Saw Cut</u>					
2. Nominal 1/4"	14	4	2	19.5	0.8
3. Nominal 3/8" x 1/2" deep	7	0	0	43.2	1.8
4. Nominal 3/8" x 1" deep	11	4	2	24.2	1.3
5. Nominal 1/2" x 1/2" deep	7	0	0	30.0	1.5
6. Nominal 1/2" x 1 1/4" deep	13	2	2	15.1	1.3

# Summary Tabulation of Joint Variables and Their Ratings

A-1-2-N	25 @ 2.68	
A-1-3-N	15 @ 2.00	
A-1-4-N	15 @ 2.00	
A-1-4-BH3	10 @ 2.90	49 @ 2.80
A-1-5-N	15 @ 2.20	
A-1-6-N	10 @ 2.00	
A-1-6-BH5	14 @ 2.93	
A-2-2-N	10 @ 2.80	30 @ 2.80
A-2-4-BH3	10 @ 2.90	
A-2-6-BH5	10 @ 2.70	
A-3-2-N	9 @ 2.40	29 @ 2.78
A-3-4-BH3	10 @ 2.90	
A-3-6-BH5	10 @ 3.00	

163 @ 2.54

$$581 - 10 - 10 = 561$$

560

89

1- 19  
 2- 34  
 3- 110  
 ---  
 163

B-1-2-BL3	10 @ 3.00	}	30 @ 2.93
B-1-4-BL4	10 @ 2.80		
B-1-6-BL5	10 @ 3.00		
B-2-2-BL3	10 @ 3.00	}	29 @ 2.90
B-2-4-BL4	10 @ 2.70		
B-2-6-BL5	9 @ 3.00		
B-3-2-BL3	10 @ 3.00	}	30 @ 2.97
B-3-4-BL4	10 @ 3.00		
B-3-6-BL5	10 @ 2.90		

89 @ 2.93

1	-
2	- 2
3	- 85

44

C-1-2-BC3	15 @	2.87	}	45 @	2.76
C-1-3-BC3	10 @	2.50			
C-1-4-BC4	15 @	2.67			
C-1-5-BC4	10 @	2.80			
C-1-6-BC5	15 @	2.73			
C-2-2-BC3	8 @	2.75	}	28 @	2.50
C-2-3-BC3	5 @	2.80			
C-2-4-BC4	10 @	2.70			
C-2-5-BC4	5 @	2.40			
C-2-6-BC5	10 @	2.10			
C-3-2-BC3	10 @	2.80	}	30 @	2.77
C-3-3-BC4	5 @	2.80			
C-3-4-BC4	10 @	2.50			
C-3-5-BC4	4 @	2.75			
C-3-6-BC5	10 @	3.00			

142 @ 2.68

1	-	10
2	-	25
3	-	107
		<hr/>
		142

45



D-1-2-BH3	5 @ 2.80	} 15 @ 2.93
D-1-4-BH4	5 @ 3.00	
D-1-6-BH5	5 @ 3.00	
D-2-2-BH3	10 @ 2.20	} 30 @ 2.33
D-2-4-BH4	10 @ 2.20	
D-2-6-BH5	10 @ 2.60	
D-3-2-BH3	10 @ 3.00	} 30 @ 2.87
D-3-4-BH4	10 @ 2.70	
D-3-6-BH5	10 @ 2.90	

75 @

1 -	5
2 -	15
3 -	55
	<hr/>
	70

75

E-1-2-B23 5 @ 1.20  
E-1-3-T 5 @ 1.20  
E-1-4-B24 5 @ 1.00  
E-1-5-T 5 @ 1.40  
E-1-6-B25 5 @ 1.00  
E-2-2-B23 5 @ 1.00  
E-2-5-T 5 @ 1.20  
E-2-6-B25 5 @ 1.00  
E-3-2-B23 5 @ 1.40

45 @ 1.16

1 39  
2 5  
3 1  

---

45

F-1-2-N	1	@	1.00
F-1-2-BH3	10	@	3.00
F-1-3-N	5	@	1.60
F-1-4-N	5	@	1.80
F-1-4-BH4	5	@	3.00
F-1-6-BH5	5	@	3.00
F-3-3-N	5	@	2.00
F-3-4-N	5	@	2.20
F-3-5-N	5	@	3.00
F-3-6-N	5	@	2.60

51 @ 2.49

1 -	7
2 -	12
3 -	<u>32</u>
	51

A-1-2-N 1 1  
2 ~~HT~~ 1  
3 ~~HT~~ ~~HT~~ ~~HT~~ III

A-1-4-BH3 1  
2 1  
3 ~~HT~~ IIII

A-1-6-BH5 1  
2 1  
3 ~~HT~~ ~~HT~~ IIII

A-2-2-N 1  
2 II  
3 ~~HT~~ III

A-2-4-BH3 1  
2 1  
3 ~~HT~~ IIII

A-2-6-BH5 1 1  
2 1  
3 ~~HT~~ III

A-3-2-N 1  
2 III  
3 ~~HT~~ 1

A-3-4-BH3 1  
2 1  
3 ~~HT~~ IIII

A-3-6-BH5 1  
2  
3 ~~HT~~ ~~HT~~

A-1-3-N 1 ~~HT~~ 1  
2 III  
3 ~~HT~~ 1

A-1-4-N 1 ~~HT~~  
2 ~~HT~~  
3 ~~HT~~

A-1-5-N 1 III  
2 ~~HT~~ 1  
3 ~~HT~~ 1

A-1-6-N 1 III  
2 IIII  
3 III

A-1-2-N  
1  
2

B  
A-1-4-B<sup>c</sup>3  
1

2  
3

B  
A-1-6-B<sup>c</sup>5  
1

2  
3 HT HT

B  
A-2-2-N  
1

2  
3

B  
A-2-4-B<sup>c</sup>3  
1

2  
3 HT IIII

B  
A-2-6-B<sup>c</sup>5  
1

2  
3 HT IIII

B  
A-3-2-N  
1

2  
3

B  
A-3-4-B<sup>c</sup>3  
1

2  
3 HT HT

B-3-4-BC4  
1  
2

3 HT HT  
B-1-2-BC3  
1

2  
3 HT HT

B-1-4-BC4  
1 1

2  
3 HT IIII

B-2-2-BC3  
1

2  
3 HT HT

B-2-4-BC4  
1 1

2  
3 HT IIII

B-3-2-BC3  
1

2  
3 HT HT

C-1-2-N	1	C-3-2-BC3	1 1	<del>C-3-5-BC4</del>
	2		2	2 1
	3		3 (H) III	3 III
C-1-4-BH3	1	C-3-4-BC4	1 II	
	2		2 1	
	3		3 (H) II	
C-1-6-BH5	1	C-1-2-BC3	1	
	2 III		2 II	
	3 (H) (H) I		3 (H) (H) III	
C-2-2-N	1	C-1-4-BC4	1 1	
	2		2 III	
	3		3 (H) (H) I	
C-2-4-BH3	1	C-2-2-BC3	1 1	
	2		2	
	3		3 (H) II	
C-2-6-BH5	1 II	C-2-4-BC4	1	
	2 (H)		2 III	
	3 III		3 (H) II	
C-3-2-N	1	C-1-3-BC3	1 II	
	2		2 1	
	3		3 (H) II	
C-3-4-BH3	1	C-1-5-BC4	1	
	2		2 II	
	3		3 (H) III	
C-3-6-BH5	1	<del>C-3-3-BC3</del>	1	
	2	C-1-3-BC3	2 1	
	3 (H) (H)		3 III	
<del>C-3-3-BC4</del>	1	<del>C-2-5-BC4</del>	1 1	
C-3-3-BC4	2 1	C-2-5-BC4	2 1	
	3 III		3 III	

D	A-1-2-N	1	
		2	D-3-2-BH3 1
		3	2
D	A-1-4-BH3	1	3 <del>III</del> <del>III</del>
		2	D-3-4-BH4 1
		3	2 III
D	A-1-6-BH5	1	3 <del>III</del> II
		2	D-2-2-BH3 1 1 1 7
		3 <del>III</del>	2 <del>III</del> 4
D	A-2-2-N	1	3 <del>III</del> 4
		2	D-2-4-BH4 1 III
		3	2 II
D	A-2-4-BH3	1	3 <del>III</del>
		2	D-1-2-BH3 1
		3	2 I
D	A-2-6-BH5	1	3 <del>III</del>
		2 III	D-1-4-BH4 1
		3 <del>III</del> I	2
D	A-3-2-N	1	3 <del>III</del>
		2	
		3	
D	A-3-4-BH3	1	
		2	
		3	
D	A-3-6-BH5	1	
		2 I	
		3 <del>III</del> <del>III</del>	

E  
A-1-2-N 1  
2  
3  
A-1-4-BH3 1  
2  
3  
E  
A-1-6-BH5 1 ~~1~~ ~~1~~  
2  
3  
E  
A-2-2-N 1  
2  
3  
E  
A-2-4-BH3 1  
2  
3  
E  
A-2-6-BH5 1 ~~1~~ ~~1~~  
2  
3  
E  
A-3-2-N 1  
2  
3  
E  
A-3-4-BH3 1  
2  
3  
E  
A-3-6-BH5 1  
2  
3

E-3-2-BC3 1 IIII  
2  
3  
E-1-2-BC3 1 IIII  
2  
3  
E-1-5-T 1 III  
2  
3  
E-1-4-BC4 1 ~~1~~ ~~1~~  
2  
3  
E-1-3-T 1 IIII  
2  
3  
E-2-2-BC3 1 ~~1~~ ~~1~~  
2  
3  
E-2-5-T 1 IIII  
2  
3



F	A-1-2-N	1 1	F-1-2-BH3	1
		2		2
F		3		3 IIII
	A-1-4-BH3	1	F-1-4-BH4	1
		2		2
F		3		3 III
	A-1-6-BH5	1	F-3-3-N	1
		2		2 III
F		3 III		3
	A-2-2-N	1	F-3-4-N	1 1
		2		2 II
F		3		3 III
	A-2-4-BH3	1	F-3-5-N	1
		2		2
F		3		3 III
	A-2-6-BH5	1	F-3-6-N	1
		2		2 II
F		3		3 III
	A-3-2-N	1	F-1-4-N	1 II
		2		2 II
F		3		3 I
	A-3-4-BH3	1	F-1-3-N	1 III
		2		2 I
F		3		3 I
	A-3-6-BH5	1		
		2		
		3		

2 3 or less broken seal  
 3 3 or more broken seal

APPENDIX A

Joint Variable Tabulation

All stations were determined by pacing and, therefore, are approximate.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
1	82+52	B-3-2-BC3 ✓	36	1 97+80 (2)C	B-2-4-BC4 ✓
2	82+88	"	37	1 98+23	"
3	83+25	"	38	2 98+65°	"
4	83+70	"	39	1 99+09	"
5	84+02	"	40	2 99+49	"
	84+50	Broken	41	1 99+90	B-2-6-BC5 ✓
6	84+85	B-3-4-BC4 ✓	42	2 100+30	"
	85+34	"	43	2 100+75	"
8	85+70	"	44	1 101+35	"
9	86+15	"	45	1 101+65	"
10	86+56	"	46	3 102+02	C-3-2-BC3 ✓
11	86+88	B-3-6-BC5 ✓	47	3 102+45	"
12	87+35	"	48	3 102+90	"
13	87+75	"	49	3 103+40	"
14	88+20	"	50	3 103+85	"
15	88+62	"	51	3 104+25	C-3-4-BC4 ✓
16	88+98	B-1-2-BC3	52	3 104+75	"
17	89+50	"	53	1 105+25	"
18	89+85	"	54	2 105+65	"
19	90+35	"	55	2 105+94	"
20	90+70	"	56	2 106+45	C-3-6-BC5 ✓
21	91+96	B-1-4-BC4 ✓	57	2 106+85	"
22	91+52	"	58	2 107+20	"
23	91+85	"	59	3 107+60	"
24	92+35	"	60	3 108+01	"
25	92+70	"	61	3 108+37	C-1-2-BC3 ✓
26	93+15	B-1-6-BC5 ✓	62	3 108+79	"
27	93+55	"	63	3 109+25	"
28	93+88	"	64	1 109+60	"
29	94+34	"	65	3 110+10	"
30	94+67	"	66	1 110+55	C-1-4-BC4 ✓
31	95+00	B-2-2-BC3 ✓	67	1 110+90	"
32	95+45	"	68	3 111+42	"
	95+85	Broken	69	1 111+75	"
33	96+15	B-2-2-BC3	70	3 112+10	"
34	96+62	"	71	1 112+58	C-1-6-BC5 ✓
35	96+97	"	72	1 112+88	"
	97+40	Broken			

3-16-83

2-27-80

2-26-81

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25  
26  
27  
28  
29  
30  
31  
32  
33  
34  
35

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
73	113+33	C-1-6-BC5 ✓	118	131+66	A-1-6-BH5 ✓
74	113+72	"	119	132+05	"
75	114+03 3	"	120	132+50 3	"
76	114+51 3	C-2-2-BC3 ✓	121	132+90	A-2-2-N ✓
77	114+85	"	122	133+30	"
78	115+27 2	"	123	133+75	"
79	115+69	"	124	134+20	"
80	116+03 1	"	125	134+58	"
81	116+36	C-2-4-BC4 ✓	126 2	134+97 1 ✓	A-2-4-BH3 ✓
82	116+78 2 ✓	"	127	135+38	"
83	117+15	"	128	135+75 3	"
84	117+55 3	"	129	136+15	"
85	118+02	"	130	136+50 2 3	"
86	118+40 1	C-2-6-BC5 ✓	131	136+90	"
87	118+90	"	132 1	137+30 1 ✓ C (3)	A-2-6-BH5 ✓
88	119+28 1	"	133	137+70	"
89	119+60	"	134	138+10 1 ✓	"
90	120+05 1	"	135	138+45	"
91	120+40	A-3-2-N ✓	136 1	138+85 1 ✓	A-3-2-N ✓
92	120+80 1	"	137	139+30	"
93	121+22	"	138	139+70	"
94	121+62 1	"	139	140+00	"
95	121+98	"	140	140+35	"
96	122+33	A-3-4-BH3 ✓	141	140+80	A-3-4-BH3 ✓
97	122+80	"	142	141+15	"
98	123+25	"	143	141+60	"
99	123+60	"	144	141+97	"
100	124+00	"	145	142+30	"
101	124+36	A-3-6-BH5 ✓	146	142+65	A-3-6-BH5 ✓
102	124+78	"	147	143+10	"
103	125+20	"	148	143+43	"
104	125+55	"	149	143+82	"
105	126+00	"	150	144+20	"
106	126+40	A-1-2-N ✓	151	144+60 3	A-1-2-N ✓
107	126+80	"	152	145+05	"
108	127+20	"	153	145+45	"
109	127+60	"	154	145+78 1 ✓	"
110	128+00 1	"	155	146+20	"
111	128+45	A-1-4-BH3 ✓	156	146+65	A-1-4-BH3 ✓
112	128+90 2	"	157	147+00	"
113	129+30	"	158	147+40 3	"
114	129+72 1 ✓	"	159	147+80	"
115	130+18	"	160	148+20 3	"
116	130+70	A-1-6-BH5 ✓	161	148+60	A-1-6-BH5 ✓
117	131+10 2 ✓	"	162	148+95	"

## APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
163	149+35	A-1-6-BH5 ✓	207	166+86	D-3-6-BH5 ✓
164	149+70	"	208	167+25 3	"
165	150+10	"	209	167+67	"
166	150+50	A-2-2-N ✓	210	168+10	"
167	150+90	"	211	168+50 ✓	D-2-2-BH3 ✓
168	151+30 2	"	212	168+92	"
169	152+03 1	"	213	169+30	"
170	152+48	"	214	169+70 ✓	"
171	152+83	A-2-4-BH3 ✓	215	170+15 3	"
172	153+25	"	216	170+55 2	D-2-4-BH4 ✓
173	153+65	"	217	170+95 ✓	"
174	154+00	"	218	171+35 ✓	"
175	154+40	"	219	171+75 2	"
176	154+80 1	A-2-6-BH5 ✓	220	172+20 2	"
177	155+20	"	221	172+60 2	D-2-6-BH5 ✓
178	155+60 2 3	"	222	173+04	"
179	155+91	"	223	173+45	"
180	156+30	"	224	173+85 3	"
181	156+70	D-3-2-BH3 ✓	225	174+35	"
182	157+10	"	226	174+75 4	D-2-2-BH3 ✓
183	157+50 3	"	227	175+18	"
184	157+90 3	"	228	175+63 ✓	"
185	158+30 2	"	229	176+08	"
186	158+70	D-3-4-BH4 ✓	230	176+50 ✓	"
187	159+05	"	231	176+88 ✓	D-2-4-BH4 ✓
188	159+43	"	232	177+30 ✓	"
189	159+80 ✓	"	233	177+70 ✓ 5	"
190	160+20 2	"	234	178+10 ✓	"
191	160+60 2	D-3-6-BH5 ✓	235	178+50 ✓	"
192	161+00 3	"	236	178+94 3	D-2-6-BH5 ✓
193	161+40 2	"	237	179+35 2	"
194	161+75	"	238	179+75	"
195	162+15 3	"	239	180+10 ✓	"
196	162+55	D-3-2-BH3	240	180+50 ✓	"
197	162+93	"	241	180+90 ✓	D-1-2-BH3 ✓
198	163+30	"	242	181+30 3	"
199	163+70	"	243	181+70 2	"
200	164+10	"	244	182+10 2 ✓	"
201	164+50 2	D-3-4-BH4 ✓	245	182+50	"
202	164+85 2	"	246	182+85 3	D-1-4-BH4 ✓
203	165+30 2	"	247	183+25 3	"
204	165+70 ✓	"	248	183+65	"
205	166+06 3	"	249	184+10	"
206	166+46 2	D-3-6-BH5 ✓	250	184+50	"

## APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
251	3 184+90	D-1-6-BH5	293	2 202+60	B-2-4-BC4 ✓
252	2 185+10	"	294	2 203+00	"
253	2 185+65	"	295	2 203+40	"
254	1 186+10	"	296	2 203+80 ✓	B-2-6-BC5 ✓
255	2 186+50	"	297	2 204+20	"
256	3 186+88	F-1-2-BH3 ✓	298	1 204+60 ✓	"
257	2 187+30	"	299	1 204+98 ✓	"
258	2 187+70	"	300	1 205+38 ✓	"
259	3 188+08	"	301	2 205+75	B-1-2-BC3 ✓
260	2 188+48	"	302	2 206+12	"
261	3 188+88	F-1-4-BH4 ✓	303	2 206+53	"
262	3 189+30	"	304	2 206+94	"
263	3 189+70	"	305	2 207+32	"
264	3 190+10	"	306	2 207+68	B-1-4-BC4 ✓
265	2 190+50	"	307	2 208+09	"
266	3 191+10	F-1-6-BH5 ✓	308	2 208+50	"
267	3 191+50	"	309	2 208+88	"
268	3 191+95	"	310	2 209+25 3	"
269	3 192+40	"	311	2 209+65 2 3	B-1-6-BC5 ✓
270	2 192+80	"	312	2 210+03 2 3	"
271	3 193+28	B-3-2-BC3 ✓	313	1 210+43 2 3	"
272	3 193+70	"	314	1 210+85 1 3	"
273	3 194+20	"	315	3 211+20	"
274	3 194+75	"	316	2 211+67	F-1-2-BH3 ✓
275	3 195+08	"	317	2 212+07	"
276	1 195+48 3	B-3-4-BC4	318	2 212+47	"
277	3 195+88	"	319	2 212+86	"
278	1 196+30 1	"	320	3 213+25	"
279	3 196+70	"	From Sta. 213+25 to Hwy 44, all the joints are under the following code: F-1-2-N. The longitudinal joint material is "F".		
280	2 197+12	"	From Hwy. 44 to Sta. 128+65 all the joints including the longitudinal joint up to Sta. 201+36 are under the following code: A-1-2-N.		
281	2 197+52	B-3-6-BC5 ✓	321	128+65 3	C-1-3-BC3
282	2 197+95	"	322	129+05 1	"
283	1 198+35 3	"	323	129+45 3	"
284	1 198+80 3	"			
285	2 199+25	"			
286	3 199+70	B-2-2-BC3 ✓			
287	3 200+15	"			
288	3 200+60	"			
289	3 201+03	"			
290	3 201+40	"			
291	2 201+80	B-2-4-BC4 ✓			
292	2 202+20 3	"			

APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
324	129+85	C-1-3-BC 3	368	147+80	A-1-2-N
325	130+25	"	369	148+30	"
326	130+65	C-1-4-BC4	370	148+60	"
327	131+09	"	371	148+99	A-1-3-N
328	131+40	"	372	149+40	"
329	131+75	"	373	149+75	"
330	132+25	"	374	150+25	"
331	132+65	C-1-5-BC4	375	150+60	"
332	133+06	"	376	150+90	A-1-4-N
333	133+40	"	377	151+30	"
334	133+75	"	378	151+70	"
335	134+30	"	379	152+10	"
336	134+65	C-1-6-BC5	380	152+55	"
337	135+12	"	381	152+80	A-1-5-N
338	135+48	"	382	153+12	"
339	135+90	"	383	153+45	"
340	136+35	"	384	153+90	"
341	136+70	C-1-2-BC3	385	154+35	"
342	137+09	"	386	154+75	A-1-6-N
343	137+44	"	387	155+20	"
344	137+80	"	388	155+60	"
345	138+25	"	389	156+00	"
346	138+60	A-1-3-N	400	156+35	"
347	139+00	End Survey	401	156+75	A-1-2-N
348	139+36	4/16/82	402	157+30	"
349	139+70	"	403	157+70	"
350	140+15	"	404	158+20	"
351	140+60	C6 A-1-4-N	405	158+50	"
352	141+30	"	406	158+90	A-1-3-N
353	141+70	"	407	159+30	"
354	142+22	"	408	159+75	"
355	142+60	"	409	160+20	"
356	143+09	A-1-5-N	410	160+60	"
357	143+45	"	411	161+03	A-1-4-N
358	143+90	"	412	161+40	"
359	144+35	"	413	161+83	"
360	144+75	"	414	162+30	"
361	145+10	A-1-6-BH5	415	162+70	"
362	145+52	"	416	163+10	A-1-5-N
363	145+88	"	417	163+55	"
364	146+30	"	418	163+95	"
365	146+65	"	419	164+40	"
366	147+00	A-1-2-N	420	164+83	"
367	147+45	"	421	165+20	A-1-6-N

## APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
422	165+65	A-1-6-N	467	184+80	C-2-5-BC4
423	166+01	"	468	185+20	"
424	166+39	"	469	185+60	"
425	166+77	"	470	186+10	"
426	167+35	A-1-2-N	471	186+55	C-2-6-BC5
427	167+75	"	472	186+94	"
428	168+15	"	473	187+35	"
429	168+65	"	474	187+75	"
430	169+02	"	475	188+20	"
431	169+40	C-1-3-BC3	476	188+60	C-2-2-BC3
432	169+85	"	477	189+09	"
433	170+25	"	478	189+40	"
434	170+75	"	479	189+85	C-2-2-N
435	171+09	"	480	190+35	"
436	171+60	C-1-4-BC4	481	190+76	C-3-3-BC4
437	171+96	"	482	191+16	"
438	172+43	"	483	191+56	"
439	172+80	"	484	192+01	"
440	173+25	"	485	192+43	"
441	173+65	C-1-5-BC4	486	192+90	C-3-4-BC4
442	174+02	"	487	193+30	"
443	174+38	"	488	193+70	"
444	174+75	"	489	194+15	"
445	175+20	"	490	194+55	"
446	175+73	C-1-6-BC5	491	194+96	C-3-5-BC4
447	176+15	"	492	195+40	"
448	176+58	"	493	195+80	"
449	176+91	"	494	196+22	"
450	177+30	"	495	196+62	"
451	177+80	C-1-2-BC3	496	197+04	C-3-6-BC5
452	178+17	"	497	197+44	"
453	178+65	"	498	197+82	"
454	179+04	"	499	198+30	"
455	179+50	"	500	198+75	"
456	179+94	C-2-3-BC3	501	199+25	C-3-2-BC3
457	180+35	"	502	199+70	"
458	180+75	"	503	200+09	"
459	181+17	"	504	200+50	"
460	181+60	"	505	200+97	"
461	181+99	C-2-4-BC4	506	201+36	F-3-3-N
462	182+40	"	507	201+80	"
463	182+80	"	508	202+20	"
464	183+30	"	509	202+60	"
465	183+70	"	510	203+06	"
466	184+42	C-2-5-BC4	511	203+46	F-3-4-N

APPENDIX A Cont.

Joint Number	Station	Installation Code Designation	Joint Number	Station	Installation Code Designation
512	203+86	F-3-4-N	557	222+58	E-2-2-BC3
513	2 204+33	"	558	222+88	"
514	204+73	"	559	223+30	"
515	205+17	"	560	223+70	"
516	205+56	F-3-5-N	561	224+09	"
517	206+02	"	562	224+50	E-2-6-BC5
518	206+42	"	563	224+82	"
519	206+82	"	564	225+24	"
520	207+22	"	565	225+64	"
521	207+62	F-3-6-N	566	226+00	"
522	208+05	"	567	226+40	E-2-5-T
523	208+45	"	568	2 226+80	"
524	208+85	"	569	227+20	"
525	209+12	"	570	227+60	"
526	209+67	E-3-2-BC3	571	228+10	"
527	210+08	"	572	228+50	F-1-4-N
528	210+60	"	573	228+90	"
529	211+03	"	574	229+30	"
530	211+43	"	575	229+70	"
531	211+90	F-1-2-N	576	230+10	"
532	212+36	E-1-2-BC3	577	230+50	F-1-3-N
533	212+73	"	578	230+90	"
534	213+20	"	579	231+33	"
535	213+62	"	580	231+72	"
536	214+03	"	581	232+15	"
537	214+42	E-1-6-BC5			
538	214+85	"			
539	215+26	"			
540	215+67	"			
541	216+06	"			
542	2 216+46	E-1-5-T			
543	217+05	"			
544	217+42	"			
545	217+82	"			
546	218+25	"			
547	218+63	E-1-4-BC4			
548	219+03	"			
549	219+36	"			
550	219+78	"			
551	220+21	"			
552	220+55	E-1-3-T			
553	220+95	"			
554	221+40	"			
555	221+82	"			
556	222+13	"			

Remarks:

From Sta. 82+00 to Sta. 156+30 the longitudinal joint material is "A"

From Sta. 156+30 to Sta. 186+50 the longitudinal joint material is "D"


From Sta. 186+50 to Sta. 213+25 the longitudinal joint material is "F"

From Hwy. 44 to Sta. 201+36 the longitudinal joint material is "A"

From Sta. 201+36 to F-31 the longitudinal joint material is "F"

From Sta. 232+15 to F-31 all the joints including the longitudinal joint are under the following code F-1-2-N





Joint

Variables

A - "Hi-Sy~~9888~~

F-Para Plastic

X-1-2-BX3	25 @ 2.20	10 @ 3.00
X-1-4-BX4	10 @ 2.00	5 @ 3.00
X-1-6-BX5	14 @ 2.00	5 @ 3.00
	49 @ 2.07	20 @ 3.00

X-2-2-BX3	10 @ 2.00	N.P.
X-2-4-BX4	10 @ 2.	N.P.
X-2-6-BX5	10 @ 2.00	N.P.
	30 @ 2.00	N.P.

X-3-2-BX3	9 @ 2.40	N.P.
X-3-4-BX4	10 @ 2.	5 @ 2.20
X-3-6-BX5	10 @ 3	5 @ 2.60
	29 @ 2.40	10 @ 2.40

A. 1.16	2.1.16	2.70
1. No v		
2. 3 fe		
3. Mor		
N.P. - No		
X - inser.		
a - no bac		