

 <b>National Aeronautical Laboratory</b>	<b>Documentation Sheet</b>	<i>Document Classification</i> RESTRICTED
<i>Title</i> : Investigation of aileron control cable failure of a Pushpak aircraft	<i>Document No.</i> PD MT 8921  <i>Date of issue:</i> June 1989	
<i>Author(s)</i> : A.C. Raghuram, R.V. Krishnan, R. Rangaraju and M.A. Venkataswamy	<i>Contents</i>  1 page 2 figures	
<i>Division</i> : Materials Science	<i>No. of copies:</i> 13	
<i>External participation</i> : -	<i>NAL Project No.</i> MT-9-001	
<i>Sponsor</i> : -	<i>Sponsor's Project No.</i>	
<i>Approval</i> : Dr A.C.Raghuram		
<i>Remarks</i> :		
<i>Keywords</i> : Control cable failure		
<i>Abstract</i> : This is an investigation on the failure of aileron control cable in a Pushpak aircraft carried out at the request of the Deputy Director General of Civil Aviation. The nature of failure is analysed.		