



**National
Aeronautical
Laboratory**

Documentation Sheet

Document Classification
Restricted

Title : Failure of a Steam Turbine

Document No.
PD MT 8731

Date of issue: Oct. '87

Author(s) : A.C.Raghuram, S.Radhakrishnan,
R.V.Krishnan and V.Ramachandran

Contents . . 2 pages &
4 figures

Division : Materials Science

No. of copies: 12

**External
participation** :

NAL Project No.
MT-9-871

Sponsor :

Sponsor's Project No.

Approval : A.C.Raghuram

Remarks :

Keywords : Steam turbine, shaft, turbine disk,
locking nut, locking pins

Abstract :

A steam turbine developed excessive vibration due to the shift of the turbine disk on the shaft. The nut intended to lock the disk had loosened from the shaft threads and come out of the shaft. The investigation revealed that the locking mechanism for the disk was not proper.