

	National Aeronautical Laboratory Documentation Sheet	<i>Document Classification</i> Restricted
<i>Title</i> : Fracture of a Wheel Hub of the Islander Aircraft EX-132	<i>Document No.</i> PD MT 8661 <i>Date of issue:</i> Dec. '86	
<i>Author(s)</i> : S.Radhakrishnan, R.V.Krishnan and R.Rangaraju	<i>Contents</i> 7 pages incl. 8 figures	
<i>Division</i> : Materials Science	<i>No. of copies:</i> 12	
<i>External participation</i> :	<i>NAL Project No.</i> MT-9-861, MT-1-167	
<i>Sponsor</i> : Aeronautics R & D Board	<i>Sponsor's Project No.</i> Aero/RD-134/100/10/	
<i>Approval</i> : A.C.Raghuram	84-85/394	
<i>Remarks</i> :		
<i>Keywords</i> : Islander aircraft, Tyre burst, Wheel hub failure, Circumferential cracking, Cleavage fracture		
<i>Abstract</i> : A tyre burst had occurred while charging the wheel of an Islander aircraft. The wheel hub made of magnesium-aluminium alloy had sheared off. Circumferential cracking parallel to the fracture surface of the hub was noticed. The failure of the hub was due to excessive pressure of air charged to the tyre.		