



ERRATUM

The article “Steel beam–column joint with discontinuous vertical reinforcing bars” by J.-Y. Hu, W.-K. Hong published in the Journal of Civil Engineering and Management 23(4): 440–454, (<https://doi.org/10.3846/13923730.2016.1210217>), contained the following error:

- Figures 18 and 19 were missing in page 453.




Fig. 18. Maximum moment resisting capacity versus number of continuous reinforcing bars




Fig. 19. Degree of deterioration for each specimen versus number of discontinuous reinforcing bars

The Authors J.-Y. Hu, W.-K. Hong and the publisher apologise for this error.