# Worcester Polytechnic Institute Digital WPI

Interactive Qualifying Projects (All Years)

Interactive Qualifying Projects

October 2017

# Evaluating the Vulnerability of Boston's Inner Harbor Designated Port Areas to Sea Level Rise and Coastal Storms

Austen E. Crawford Worcester Polytechnic Institute

Caroline M. Warchol Worcester Polytechnic Institute

Jacob N. Bouchard Worcester Polytechnic Institute

Kyle James Whittaker Worcester Polytechnic Institute

Follow this and additional works at: https://digitalcommons.wpi.edu/iqp-all

#### **Repository Citation**

Crawford, A. E., Warchol, C. M., Bouchard, J. N., & Whittaker, K. J. (2017). Evaluating the Vulnerability of Boston's Inner Harbor Designated Port Areas to Sea Level Rise and Coastal Storms. Retrieved from https://digitalcommons.wpi.edu/iqp-all/165

This Unrestricted is brought to you for free and open access by the Interactive Qualifying Projects at Digital WPI. It has been accepted for inclusion in Interactive Qualifying Projects (All Years) by an authorized administrator of Digital WPI. For more information, please contact digitalwpi@wpi.edu.





# **Evaluating the Vulnerability of Boston's Inner Harbor**

# **Designated Port Areas to Sea Level Rise and Coastal Storms**

An Interactive Qualifying Project Report Submitted to the Faculty of the WORCESTER POLYTECHNIC INSTITUTE in partial fulfillment of the requirements for the

# **Degree of Bachelor of Science**

# Written By:

Jacob Bouchard (PH) Austen Crawford (CE) Caroline Warchol (CH) Kyle Whittaker (ME)

Professor Seth Tuler, Worcester Polytechnic Institute Professor Jennifer deWinter, Worcester Polytechnic Institute Jill Valdes Horwood, Boston Harbor Now

This report represents the work of four WPI undergraduate students submitted to the faculty as evidence of completion of a degree requirement. WPI routinely publishes these reports on its website without editorial or peer review. For more information about the projects program at WPI, please see: http://www.wpi.edu/Academics/Projects

Submitted To:

# Abstract

As climate change raises sea levels (SLR) and exacerbates storm surges, the frequency and severity of coastal flooding will increase. Boston's shoreline is increasingly vulnerable to flooding. Industries in the Designated Port Areas (DPAs) of Boston Harbor pose risks to public health and the environment because of toxic chemicals used and stored on-site. The goal of this project was to assess the vulnerability of DPAs in Boston harbor to SLR and coastal storms. We evaluated three different aspects of vulnerability: exposure, sensitivity, and ability to cope on 18 different sites within four of Boston's DPAs. Our report highlights the need for more systematic evaluation and planning by stakeholders to mitigate the risks associated with flooding due to SLR and coastal storm surge.

# Acknowledgements

We would like to thank the following people and organizations for making this project possible:

- Boston Harbor Now
- Jennifer deWinter, Worcester Polytechnic Institute
- Lisa Berry Engler, Massachusetts Coastal Zone Management
- Jill Valdes Horwood, Boston Harbor Now
- Paul Kirshen, University of Massachusetts Boston
- Steve Lehmann, NOAA
- Massachusetts Coastal Zone Management
- MassDOT
- Massachusetts Emergency Management Agency
- Dan Ryan, Channel Fish Co.
- Seth Tuler, Worcester Polytechnic Institute
- Sarah White, Massachusetts Emergency Management Agency

We would like to extend a special thank you to our advisors Seth Tuler and Jennifer deWinter for providing guidance and support. We would also like to thank Jill Valdes Horwood and the rest of Boston Harbor Now for encouraging us and providing us with insight and experience.

# **Executive Summary**

The goal of this project was to assess the vulnerability of Designated Port Areas in Boston Harbor to sea level rise and coastal storms. Boston is notably vulnerable to flooding events because of its proximity to three rivers and its position on the Atlantic Coast. Since 1991 the City of Boston has experienced 21 flooding events that have triggered federal or state disaster declarations (Climate Ready Boston, 2016, P. 2). Over the entire twentieth century sea levels rose about 9 inches relative to land in Boston (Climate Ready Boston, 2016, P. 8). With the pace of relative sea levels rise accelerating, by 2030 another eight inches of sea level rise may occur, and as much as 3 ft. by 2070 (City of Boston Hazard Mitigation Plan, 2014). Severe flooding in Boston could result in damage to infrastructure, public health, environment and the economy (City of Boston, 2014). The Boston Hazard Mitigation Plan states that "In Boston, Massachusetts, the increase in flooding caused by sea level rise this century could cost up to \$94 billion from damage to buildings, loss of building contents, and associated emergency activities, depending on the amount of sea level rise and adaptation measures taken" (US EPA, n.d.). Areas within Boston Harbor will continue to have accelerated rates of vulnerability unless precautions are implemented to protect the coast from the effects of sea level rise.

Since 2007 Boston has maintained a climate action plan which details measures the city has taken, and intends to take, in order to mitigate the impacts of climate change. The City of Boston's Climate Ready Report (Walsh, 2014), City of Boston Natural Hazard Mitigation Plan (The City of Boston, 2014), and Greenovate Boston (Greenovate Boston, 2012) are all parts of the city's climate action plans. The plans that have been implemented come together to reduce the vulnerability to different climate risks. Vulnerability can be defined by three dimensions: the exposure to a threat, the sensitivity to a threat, and the ability to cope with a threat and its impacts. Although these reports and proposals do a thorough job of evaluating the vulnerability of residential and mixed use areas in Boston, they do not complete a thorough evaluation regarding the vulnerability of the working port.

Boston is home to a vibrant working port that deals with a wide array of industries and employs a large number of people (Martin Associates, 2012). Boston specifically has areas classified as Designated Port Areas (DPA), which are set aside for water-dependent industrial uses on Boston's coast. Our project has focused on the four inner harbor DPAs: Chelsea Creek, Mystic River, East Boston, and South Boston. The impacts associated with sea level rise and storm surge on industrial businesses along the harbor shoreline have not been evaluated (Climate Ready Boston, 2016). Understanding the vulnerability of harbor based industries is a crucial step for Boston to help identify the impacts of sea level rise and allow for better preventative measures to be taken in DPAs in the future.




Figure i: Inner Boston Harbor DPA Boundaries courtesy of Massachusetts Government. (2016). Chapter 91, The Massachusetts Public Waterfront Act | MassDEP. Retrieved April 24, 2017

## Assessing the Vulnerability of DPAs

The DPAs of Boston's inner harbor consist of over 60 water dependent industrial businesses. A representative sample of 18 parcels was investigated in our study. A list of the selected parcel can be seen in Table i.

Name Of Business	DPA	Industry
Preferred Freezer	Mystic	Cargo
Distrigas of Massachusetts Everett Marine LNG Terminal Wharf	Mystic	Fuel
Prolerized New England Co. Everett Wharf	Mystic	Cargo
Winnisimmet Landing Pier No. 1-5	Mystic	Mooring
Constellation Mystic Power, LLC Mystic Station Wharf	Mystic	Old Industrial
MA Port Authority, Paul W. Conley Marine Terminal Berth #14-17	South Boston	Vacant
MA Port Authority, South Boston Ship Dock and Barge Dock	South Boston	Old Industrial
Boston Marine Industrial Park Berth No. 6	South Boston	Cargo
Perini Corp. Quarterdeck Marina	Chelsea	Cargo
Global Revco Terminal LLC Revere Terminal Ship Pier	Chelsea	Fuel
Gulf Oil Chelsea Terminal Tanker Wharf	Chelsea	Fuel
Vacant Land with Bulkhead	Chelsea	Vacant
245 & 257 Marginal St. LLC Bulkhead	Chelsea	Vacant/Parkin g
Channel Fish Co. Inc. Pier	Chelsea	Fishing
Irving Oil Terminals Inc Revere Terminal Pier Global Revco Berth No. 1	Chelsea	Fuel
Mahoney Terminal LLC Chelsea (AKA Eastern Salt Co.)	Chelsea	Salt
Boston Forging & Welding	East Boston	Boat Repair
Boston Towing & Transportation; Boston Fuel Transportation	East Boston	Fuel

**Table i: Selected Parcels** 

The vulnerability of each parcel was assessed by looking at the exposure, sensitivity, and ability to cope to SLR and coastal storm surge. If the parcel was within the predicted flood zone from the Surging Seas: Risk Zone Map, then it was not deemed vulnerable in terms of exposure. Sensitivity was determined by the condition of the flood prevention infrastructure on the parcel and by whether or not the business on the parcel stores chemicals in large quantities. Ability to cope was determined by looking at the net worth of the business, what emergency flood plans the business had in place, and the potential cost of damages the business could receive from flooding from SLR and storm surge. Miscellaneous data was also gathered relating to the effects that DPA flooding could pose on the surrounding area. What we have evaluated are indicators for the corresponding dimensions of vulnerability, they are not direct measurements.

Preliminary information for each of the 18 selected parcels was found online. Area, industry, chemical storage, land and building value, as well as the net worth of the business could all be found on their city's assessor's parcels (Boston, Chelsea, Everett, Revere). The predicted flood zone in and around the parcels was determined using Surging Seas: Risk Zone Map for 5ft of sea level rise by 2100, which is the likely estimate for emissions scenarios used in Climate Ready Boston (Climate Ready Boston, 2016).

We attempted to get in touch with DPA businesses either through email or over the phone. The companies that got back to us were sent emails that contained variations of our

generic interview questions. They were given the option to respond by email or call us to go over their answers. We hoped their responses would give us insight to their day to day operations as well as their opinion of their vulnerability to SLR and coastal storms.

A water taxi was taken out along the shorelines of the parcels that were selected. We took pictures of each site that we were able to visit on the taxi. Photos from the harbor were used in order to understand the current state of SLR infrastructure. We used these photos in conjunction with the 2009 Storm Smart Coasts CZM report to analyze the exposure of sites to SLR and coastal storm surge.

#### **Potential Vulnerability and Risks of DPAs**

We determined that Boston's Inner Harbor DPAs are potentially vulnerable to sea level rise and coastal storm surge, as these areas have never fully been investigated. We have also found that this vulnerability has the potential to pose great risk to the city and its inhabitants.

The immediate exposure to SLR and coastal storms greatly increases the vulnerability of the majority of parcels within Boston's working port. Of the investigated parcels, 88% are expected to be in the predicted flood zone for 5 feet of SLR (Global climate change, n.d.). With the DPA's direct access to the waterfront, they are exposed to the effects of SLR and coastal storms more than other areas of Boston.

SLR preventative infrastructure on our selected DPA sites can be improved. Of our 18 selected parcels, only 6 had publicly listed SLR preventative infrastructure (CZM, 2009). Of those 6 parcels, five were ranked as needing a moderate level of action or higher according to CZM (CZM, 2009).

During our water taxi tour, we were able to look at some SLR preventative infrastructure. The high water mark on SLR preventative infrastructure was less than five feet from the top of the structures. Since 5 feet of SLR is expected by 2100, when coastal storms hit, these areas will most likely experience flooding. The SLR preventative infrastructure on these sites demonstrates the exposure to SLR and coastal storms, adding to the vulnerability of these working port areas.

The fact that many businesses within the DPAs store hazardous chemicals on site makes them more sensitive to sea level rise. Many of the companies we evaluated would lose their ability to function for a time should their chemicals damaged or lost. Ten of the parcels in the sample use chemicals in their day to day operations. We know of nine chemicals that are present in large quantities within the DPAs. The sheer amount of these chemicals along the harbor, in addition to their hazardous nature, is alarming because in extreme events they may find their way into the harbor. For example, within the investigated parcels, there are over 345,811,200 gallons of fuel stored. The issues presented by the release of the chemicals could impact public health, the environment, and the economy of Boston.

Based off of the information available to us, one third of the businesses investigated potentially have the resources to recover from severe flooding events. The sheer cost of the land and infrastructure on many of these parcels would make it difficult for businesses to rebuild after severe flooding. After reviewing the land and building value provided by tax assessor's websites, we identified that out of the parcels investigated, 61% of them were worth over \$1M. Only six of the eighteen businesses that we evaluated were publicly traded and those businesses were all worth well over \$100M. The other twelve parcels are either abandoned or local businesses. During major flooding events, 66% of businesses are expected to have between \$10M-\$100M of predicted damage per acre. The other 33% are predicted to experience between \$1M- \$10M of damage per acre to their property. Since two thirds of all investigated businesses have no public

information on their net worth, one third of the businesses evaluated could possibly have the resources to rebuild after a severe flood.

Based off of interviews and the information available to us, few of the businesses within the DPAs that we investigated have public emergency plans to deal with flooding. Of the 16 businesses that we contacted, only two answered any of our interview questions. One of the businesses that we contacted said that they had an emergency plan in place, but that it was not public information. This lack of transparency regarding emergency planning makes it impossible to make any accurate statement on the level of preparedness that exists within the DPAs.

We found that the regulation of the DPAs is split between MEMA, CZM, USCG, and the EPA. In our research of emergency preparedness plans within the DPAs, we conducted an interview with a hazard mitigation expert from MEMA, we learned that the only regulating body that deals with hazardous materials is local fire departments. Local fire departments enforce EPA regulations concerned with the handling of hazardous materials. The EPA only requires that businesses report the quantity of hazardous materials on their sites to their area fire department and the EPA. The Massachusetts Tier II Reporting Entities main purpose is to "provide the framework and methodology to efficiently respond to hazardous materials emergencies" (Hazardous materials emergency plan, 2011). The current regulations are reactionary in nature, only having plans for chemicals once they spill. We have found no measures in place to help prevent the release of toxic chemicals into the environment. The only other regulatory body that exists within Boston's harbor is the United States Coast Guard. The Coast Guard is mostly concerned with ships and materials that are moving on the water. They receive hazardous cargo manifests from ships entering the harbor in order to keep updated on the hazardous materials within Boston harbor. From our research it doesn't seem that there is much communication between these groups. This lack of communication means that in an emergency situation important information may not be available to first responders.

#### **Recommendations to Better Prepare DPAs to SLR and Coastal Storms**

There are still major gaps in data concerning vulnerability of Boston to SLR and storm surges. Many of the vulnerability assessments do not address the DPAs in any capacity. As students reaching out to businesses, we found many unwilling to participate or even get back to us. Though we managed to gather a lot of information on DPAs in a short amount of time, there is a lot more data that should be gathered. We recommend that the Massachusetts Coastal Zone Management (CZM) and The Boston Green Ribbon Commission (GRC) continue their partnership and produce a vulnerability assessment of the DPAs. This is the partnership that produces the Climate Ready Boston report, which provides an in depth understanding of Boston's vulnerability to climate change. With their previous experience, they can conduct a vulnerability assessment to give a more detailed description of the state that the DPAs are in. This report, in conjunction with the Climate Ready Boston report, could create a more complete understanding of the vulnerability of Boston and its harbor to climate change.

Throughout the completion of this project, we found that there is no organization that directly regulates emergency preparedness plans in the DPAs. <u>We recommend that</u> <u>Massachusetts Coastal Zone Management (CZM), the Department of Environmental Protection (DEP), the Massachusetts Emergency Management Agency (MEMA), and the United States Coast Guard (USCG) form a regulatory committee concerned with emergency preparedness plans within the DPAs. The partnership should integrate CZM's knowledge of businesses and infrastructure within the DPAs, DEP's experience with brownfield remediation, USCG's</u>

authority over the harbor and the cargo within it, and MEMAs experience with emergency management in Massachusetts.

The committee should have a set of regulations to enforce on the DPA businesses. The two regulations that we are recommending this committee enforce are: that chemicals and hazardous materials used by businesses within the DPAs must be stored in flood-proof containers, and that more frequent inspections and repairs be performed on the SLR prevention infrastructure within the DPAs. The first regulation would reduce business sensitivity to SLR and coastal storms by reducing the risk of chemical spills. The second regulation would reduce the business's exposure to SLR and coastal storms by ensuring that the SLR prevention infrastructure on the sites are up to date and in good condition.

If these regulations were to be put in place, they could reduce the vulnerability of DPA businesses to sea level rise and coastal storm surges by limiting exposure and sensitivity. This committee and its regulations would ensure that the unique needs of these industrial areas are met, while simultaneously keeping the surrounding communities and environment safe during flooding events.

#### Conclusion

Over the course of seven weeks we learned a lot about DPAs and their uniquely industrial nature. We understand that our work has limitations stemming from the short amount of time that we had to complete this project as well as the lack of transparency on the part of the DPA businesses. There still remains a gap in knowledge on the vulnerability of the DPAs, and further investigation is needed to fully understand Boston's vulnerability to SLR and coastal storm surge.

# **Table of Contents**

Abstract		i
Acknowledg	ementsi	i
Executive Su	ımmaryii	ii
List of Figur	es x	i
List of Table	·s x	i
Chapter 1.0:	Introduction	1
Chapter 2.0:	Background on DPAs and Climate Change	3
2.1 Design	ated Port Areas in Boston Harbor	3
2.2 Vulner	ability of Coastal Cities to Major Flooding Events in a Time of Climate Change	4
2.2.1 Se	a Level Rise in the Northeastern United States	5
2.2.2	Flooding From Storm Surge	5
2.3 Imp	pacts of Storm Surge and Coastal Urban Flooding	б
2.3.1	Failed Infrastructure Effects from SLR and Storm Surge	б
2.3.2	Impacts of Storms and Flooding on Public Health	б
2.3.3	Impacts of Storms and Flooding on the Environment	7
2.3.4	Impacts of Storms and Flooding on the Economy	7
2.4 Gap	os in Knowledge	8
Chapter 3.0:	Assessing the Vulnerability of DPAs	9
3.1 Selecti	ng Parcels for Assessment	9
3.2 Gather	ing Data10	0
3.2.1 Ga	thering Data From Online Resources	0
3.2.2 Co	ontacting DPA Businesses Representatives	1
3.2.3 Ev	aluating Sites from the Water	1
3.3 Data A	nalysis	1
Chapter 4.0:	Potential Vulnerability and Risks of DPAs14	4
4.1 - Expo	sure of DPAs to SLR and Coastal Storms	4
4.1.1 - P	Predicted Flood Zones14	4
4.1.2 - D	DPA Business Interview Response Regarding Exposure	б
4.2 - Sensi	tivity to SLR and Coastal Storms	7
4.2.1 - I	nfrastructure Evaluations1	7

4.2.2 - Sensitivity due to Chemical Storage	19
4.3 Parcel's Ability to Cope with SLR and Coastal Storms	20
4.3.1 Financial Aspects	20
4.3.2 - Emergency Plans	20
4.4 DPAs Impacts on Boston During Flooding Events	21
4.4.1 Populations at Risk from Flooding in DPAs	21
4.4.2 Risks Posed by Chemicals in the DPA	22
4.5 Lack of Transparency Within the DPAs	24
Chapter 5.0: Recommendations to Better Prepare DPAs to SLR and Coastal Storms	25
5.1 Recommendations to Better Understand Vulnerability within DPAs	25
5.1.1 Use of More Sophisticated Models for Vulnerability Assessments	25
5.2 Centralized Regulations for Emergency Preparedness Plans	26
Chapter 6.0: Conclusions	28
Chapter 7.0: References	29
Chapter 8.0: Appendices	33
Appendix A: Mystic River DPA Boundaries	33
Appendix B: Chelsea Creek DPA Boundaries	34
Appendix C: South Boston DPA Boundaries	35
Appendix D: East Boston DPA Boundaries	36
Appendix E: Boston Inner Harbor DPA Boundaries	37
Appendix F: Python Code	38
Appendix G: Parcel Land Use	39
Appendix H: Generic Email and Phone Script	40
Appendix I: Generic Questions	41
Appendix J: Water Taxi Route	42
Appendix K: CZM Infrastructure Sheets	43
Appendix L: Hazardous Materials Emergency Plan	59
Appendix M: Vulnerable Population Maps	63
Appendix N: Authorship	65

# **List of Figures**

Figure i: Inner Boston Harbor DPA Boundaries	iv
Figure 1: Inner Boston Harbor DPA Boundaries	4
Figure 2: Predicted Sea Level Rise in Boston	5
Figure 3: Effects of Flooding on Boston's Economy	8
Figure 4: Chelsea Creek DPA Flood Zone	15
Figure 5: Mystic River DPA Flood Zone	15
Figure 6: South Boston DPA Flood Zone	16
Figure 7: East Boston DPA Flood Zone	16
Figure 8: Flooding in East Boston	17
Figure 9: Riprap Located at Prolerized	18
Figure 10: Bulkhead Located at Eastern Salt	18
Figure 11: Potential Flooding of 5 Feet with Spring Tide	26

# **List of Tables**

Table i: Selected Parcels	v
Table 1: List of Selected Businesses.	
Table 2: Selected DPA Parcel Data	12
Table 3: Chemical Storage Information	19
Table 4: Vulnerable Residential Populations Surrounding DPAs	
Table 5: Chemical Effects on Public Health and the Environment	23

# **Chapter 1.0: Introduction**

Climate change is a growing problem facing coastal cities. Though climate change is accompanied with many consequences, perhaps the most threatening to the populations of coastal urban cities are the rise in sea levels paired with the rise in coastal storm frequency. The impacts of coastal flooding on a city's infrastructure, public health, environment, and economy have been experienced throughout the country (US EPA,). These impacts can be highlighted during severe hurricanes. For example, during Hurricane Katrina, New Orleans' lack of adequate infrastructure coupled with the severity of the storm would lead to disaster for the city. The City of New Orleans did have levees in place in order to help minimize the effects of severe coastal storms, but those levees were "...built in a disjointed fashion using outdated data" (Hoar, 2006). In addition to major issues to infrastructure sea level rise and coastal storms are dangerous to public health. For example in the aftermath of Hurricane Harvey, flood waters from storms contained many different and dangerous chemicals (Sifferlin, 2017). Harvey's flood waters were dangerous enough in Houston, Texas to cause death from flesh eating bacteria (Astor, 2017). Major flooding events also pose many dangers to the environment. For example, the impacts of Hurricane Sandy has caused significant damage to some local islands flora, an estimated 90% of the mature mangroves have been destroyed, and an estimated 100,000 gallons of fuel has spilled in the Simpson Bay Lagoon from over 120 shipwrecked vessels (Nature Foundation, 2017). Finally, the economy of area can also be greatly impacted by a severe coastal storm and SLR. During Hurricane Sandy, the New York Stock Exchange was forced to shut down for two days (Library, 2016). The impacts on infrastructure, public health, environment, and economy caused by these severe storms highlight some of the negative effects of extreme coastal flooding for modern port cities such as Boston.

Boston is notably vulnerable to flooding events because of its proximity to three rivers and its position on the Atlantic Coast. Since 1991 the City of Boston has experienced 21 flooding events that have triggered federal or state disaster declarations (Climate Ready Boston, 2016, P. 2). Over the entire twentieth century sea levels rose about 9 inches relative to land in Boston (Climate Ready Boston, 2016, pg. 8). With the pace of relative sea levels rise accelerating, by 2030 another eight inches of sea level rise may occur, with about 1.5 ft. by 2050, and as much as 3 ft. by 2070 (City of Boston Hazard Mitigation Plan, 2014). Thus the likelihood of coastal and riverine flooding will continue to increase. With higher sea levels, storm water outfalls may not be able to discharge or may even start to backflow (City of Boston Hazard Mitigation Plan, 2014). Severe flooding in Boston could result in damage to infrastructure, public health, environment and economy similar to that experienced in New Orleans (City of Boston, 2014). The Boston Hazard Mitigation Plan states that "In Boston, Massachusetts, the increase in flooding caused by sea level rise this century could cost up to \$94 billion from damage to buildings, loss of building contents, and associated emergency activities, depending on the amount of sea level rise and adaptation measures taken" (US EPA,). Areas within Boston Harbor will continue to have accelerated rates of vulnerability unless precautions are implemented to protect the coast, infrastructure, and people from the effects of sea level rise.

Since 2007 Boston has maintained a climate action plan which details measures the City has taken, and plans to take, in order to mitigate the impacts of climate change (City of Boston Hazard Mitigation Plan, 2014). The City of Boston's Climate Ready Report (Walsh, 2014), City of Boston Natural Hazard Mitigation Plan (The City of Boston, 2014), and Greenovate Boston

(Greenovate Boston, 2012) are all parts of the city's climate preparedness actions. The plans that have been implemented are intended to reduce the vulnerability to different climate risks, including exposure to threats, sensitivity to threats, and ability to cope after events occur (Bralower, 2017). With this in mind, some of the adaptations being implemented are to increase the amount of permeable ground, improving drainage systems, updating building codes, and restoring building and hazard mitigation infrastructure (The City of Boston, 2014). There are also several proposals being reviewed by the City of Boston with regards to different sea level rise adaptations, such as a large sea wall that completely surrounds the harbor. "City officials are exploring the feasibility of building a vast sea barrier from Hull to Deer Island, forming a protective arc around Boston Harbor" (Abel, 2017).

Although these reports and proposals do a thorough job of evaluating the vulnerability of residential and mixed use areas in Boston, they do not complete a thorough evaluation regarding the vulnerability of the working port.

The goal of this project was to assess the vulnerability of designated port areas in Boston Harbor to sea level rise and coastal storms. Our project focused on the four inner harbor DPAs: Chelsea Creek, Mystic River, East Boston, and South Boston. We selected a sample of DPA businesses to represent each industry and DPA located within the harbor. An analysis of selected sites was conducted, by reviewing tax assessors info, interviewing business representatives, and looking at SLR prevention infrastructure to determine the overall vulnerability of Boston's DPA's. Our assessment resulted in a report that may be used to inform policy and interested stakeholders of the vulnerability of working port areas in Boston Harbor to sea level rise.


# **Chapter 2.0: Background on DPAs and Climate Change**

As sea levels rise and coastal storms become more frequent, it is necessary for coastal cities to understand their vulnerability. The City of Boston has done vulnerability assessments focused on residential and mixed use areas but no assessment of the DPAs has been conducted. In order to understand the context in which the DPAs exist, some background information is necessary. We will start by describing Boston Harbor and its designated port areas, then move into why there is an increased risk of severe flooding in the project area. We then address the negative effects that would be experienced during severe flooding events.

#### 2.1 Designated Port Areas in Boston Harbor

Boston is a historic city built around its harbor. Boston Harbor has emerged into a large trading market, which increased the industrialization of the city because of its location on the Atlantic Ocean. The harbor is critical to Boston's economy. In 2012, \$4.6 billion was generated by Boston's port in overall economic value, while the business' themselves generated \$1.2 billion in revenue (Woolhouse, 2014). Due to the port industry's importance to the economic value of Boston, the Commonwealth of Massachusetts wanted to protect more industrial sectors of the port from being displaced by non-industrial uses. Designated Port Areas (DPAs) were the regulatory mechanism created by the Commonwealth to ensure access to the water for water dependent industrial businesses. DPAs were created in 1978 by the Massachusetts Coastal Zone Management (CZM) "to satisfy both the unforeseeable and unanticipated space needs of industrial use that depend on the withdrawal/discharge of large volumes of process water" (New England School of Law, 2009). Site characteristics and infrastructure needs of designated port areas include a developed waterfront, adjacent land suitable for industrial use, and access to land transportation for industrial purposes (Mass.gov, n.d.).

DPA's ensure that water dependent industries have access to Boston Harbor. There are 10 DPA's in Massachusetts, four of which will be the main focus of this project: Mystic River (Appendix A), Chelsea Creek (Appendix B), East Boston (Appendix C), and South Boston (Appendix D). A map of all four DPAs being investigated by our team can be seen in Figure 1. A variety industries utilize access to the waterfront that these DPAs provide. Some examples of industries within the DPAs are commercial fishing and processing, fuel transportation and storage, as well as import and export businesses.



**Figure 1: Inner Boston Harbor DPA Boundaries** courtesy of Massachusetts Government. (2016). Chapter 91, The Massachusetts Public Waterfront Act | MassDEP. Retrieved April 24, 2017.


DPAs pose a threat to Boston Harbor. Industrial sites within DPAs often contain hazardous chemicals that if released would pose significant risks to Boston's public health and environment. These threats are exacerbated with the threat of sea level rise and severe flooding events anticipated as a result of changing climate.


## 2.2 Vulnerability of Coastal Cities to Major Flooding Events in a Time of Climate Change

Impacts from climate change are not a new issue for the City of Boston. The City has been hit by 8 significant hurricanes in the past 75 years and has been developing different hazard mitigation preparations to minimize the risks from storm surge and storm water for over 100 years. But, as the climate continues to change, the risk of coastal urban flooding is continuing to increase, and most cities are not prepared for the up-surging threats outlined in this section.

#### 2.2.1 Sea Level Rise in the Northeastern United States

Cities along coastal Northeastern United States are predicted to encounter escalating sea level rise (SLR). In the Northeast, the relative sea level has risen by approximately one foot, since 1900, which has caused more frequent flooding of coastal areas (Climate Change in the Northeast, 2016). Boston's sea level is predicted to have a minimum increase of 2.4 feet and a maximum of 7.4 feet, by the year of 2100, as shown in Figure 2 (Climate Ready Boston, 2016). Reducing Boston's SLR to less than 2.4 feet. by the end of the century would require massive and unprecedented cuts in greenhouse gases worldwide (Climate Ready Boston, 2016). The lower end of this range assumes moderate cuts in global greenhouse gas emissions, with the upper end of this range assuming no changes in global emissions. SLR is driven by a combination of melting land ice, the expansion of water as its temperature increases, and changes in the amounts of water extracted from below ground or stored behind dams (Climate Change Indicators: Sea Level, 2014). Most of the coastal Northeast is expected to exceed the global average sea level rise due to local land subsidence, with the possibility of even greater regional sea level rise if the Gulf Stream weakens (Chapter 16 Northeast, 2014). Rising sea level will result in areas within coastal cities, such as Boston, to become more vulnerable to flooding by exacerbating impacts accompanied with storm surge.





#### 2.2.2 Flooding From Storm Surge

Another threat facing coastal urban cities is the predicted increase in severe coastal storms, which is intensifying by sea level rise (Pierre-Louis, 2017). A storm surge is an abnormal rise in sea level accompanying a hurricane or other intense storm, and whose height is the difference between the observed level of the sea surface and the level that would have occurred in the absence of the storm (Hurricane Science: Storm Surge, 2015). With global sea levels

already on the rise, storms will cause more flooding in the future than they would today. This is because "the higher water level provides a higher base for the waves so they are able to strike structures that might otherwise be elevated above the waves; effect and shore erosion caused by sea level rise allows the waves to strike farther inland" (Greenhouse effect and Sea Level Rise, 2007). An example of an overwhelming and unanticipated storm surge coupled with precipitation, occurred during Hurricane Harvey. This hurricane unloaded nearly 33 trillion gallons of water in the U.S (Fritz & Samenow, 2017). This unprecedented amount of water had displaced over one million people and about 185,000 homes have been either damaged or destroyed across the Southeast US (Gallagher, 2017). Storm surges are particularly damaging in cities or other areas with high population densities, such as Boston.

#### 2.3 Impacts of Storm Surge and Coastal Urban Flooding

Coastal urban flooding has many negative Impacts on its surroundings. Impacts of coastal flooding can affect infrastructure, public health, the environment, and the economy of coastal cities and regions.

## 2.3.1 Failed Infrastructure Effects from SLR and Storm Surge

As flooding severity worsens, the challenge of keeping important SLR prevention infrastructure, such as riprap and bulkheads, in good conditions increases. However, once the upkeep is not continued the infrastructure will deteriorate, putting it more at risk of failure under flooding conditions (Portland, 2014).

Failure of infrastructure during severe flooding events often exacerbates the issues caused by severe flooding. One potentially devastating form of infrastructure failure is the failure seawalls and other sea level rise prevention infrastructure. For example, if New Orleans had maintained their infrastructure, the flooding would not have been as detrimental from Hurricane Katrina: "Flood protection systems such as levee, canal systems, etc., were constructed to safeguard the city of New Orleans. However, these systems were poorly maintained and did not withstand the impact of the hurricane resulting in widespread damage to the city of New Orleans," (Deshmukh *et al.*, 2011). Upkeep of flood protection systems is critical to helping mitigate the impacts of SLR.

Similarly, the state of a building plays a role in the effect SLR has on it. The City of Boston has fully adopted the International Building Code (IBC) set of standards for building construction. The IBC does not adequately prepare the City of Boston for SLR (International Code Council, n.d.). To combat this, the Commonwealth of Massachusetts has made its own modification to the IBC to be implemented in the state (Massachusetts Board of Building Regulations and Standards, 2010). Although these modifications improve upon the IBC in regards to SLR building code criteria, more research should be done to ensure that buildings are able to withstand more severe coastal flooding. The impacts of collapsed or damaged buildings would not only affect the aesthetic of the city, they could damage the health of the city's residents.

## 2.3.2 Impacts of Storms and Flooding on Public Health

Floods pose many threats to the health of a community, including discharging pollutants into water and forcing people to reside within damp toxic living conditions. A major threat to

Boston's public health from DPAs is the use and storage of harmful chemicals. If storage systems were to fail, dangerous chemicals have the ability to contaminate water. Some major hazardous materials that could spill into Boston Harbor are formaldehyde, petroleum, ammonia, and salt (Environmental, Health, and Safety Guidelines for Fish Processing, April 30, 2007). If during a severe flooding event these chemicals were to get into the water, they would have detrimental impacts on people's health.

Public health can also be negatively impacted from increased storms and floods that lead to damp air and living/working conditions (Climate Ready Boston, 2016). If the water does not dry completely, mold and mildew can start to appear in buildings. This was the case after Hurricane Sandy hit areas of New York (Nir, 2013). The dampened conditions lead to increased growth of black mold. Residents are subjected to increased allergen exposure due to mold growth in flooded homes and other structures (Climate Change Impacts in the Unites States, 2014). Depending on the severity of the mold and mildew exposure, there can be various effects on the health of residents and citizens working in the area. Mold can cause minor effects such as coughing or something as serious as severe lung infections (National Center for Environmental Health, 2014). Many areas directly surrounding DPAs are residential, so flooding from SLR would likely have a negative impact on the public.

#### 2.3.3 Impacts of Storms and Flooding on the Environment


Just as the public health is threatened by what can happen during sea level rise and storm surges, the environment is as well. In May, NOAA predicted a 45 percent chance that the 2017 Atlantic Hurricane season—which runs from June 1 through November 30—would be more active than normal (Pierre-Louis, 2017). With increased water levels and severity of storms, there will be wider areas of ecosystems that will be vulnerable. Vulnerability assessments have been able to start looking at what the potential impacts on the environment could be (Climate Ready Boston, 2016).

Wildlife faces many similar threats that the public does. Petroleum and salt are particularly hazardous to aquatic life. Another threat posed to the environment from SLR is the increase of runoff and sediment into waterways (Huston, 2010). Storm surge can cause more erosion and carry pollutants, into waterways and large bodies of water (Huston, 2010). This increase in pollutants can lead to increases in algal blooms (Huston, 2010) which are already a problem in Boston waterways. Algal blooms are one of the causes of a decrease in dissolved oxygen in water (Hewett, 2016). When there is less oxygen in the water fish and aquatic plants suffer because they do not have access to the needed amount of oxygen. Less oxygen also leads to higher water temperatures, which can cause distress for the aquatic life that is used to cooler temperatures (Hewett, 2016).

#### 2.3.4 Impacts of Storms and Flooding on the Economy

The economy of a region can be affected directly and indirectly by a changing climate. In the above sections, some of the general impacts of sea level rise, flooding, and storms have been described. In the end, all of these impacts can subsequently affect the economy of a region. Some effects from flooding will be more immediate, while others may take a while to appear and be fixed. Figure 3 below shows some of the potential long term or short term impacts that can come from flooding to coastal cities. If important structures fall into disrepair, then they will need to be repaired (Massachusetts Department of Conservation and Recreation, 2009). When Texas was

ravaged by Hurricane Harvey in 2017 many of the oil refineries on the coast were damaged and, "almost 22 percent of current oil production in the Gulf of Mexico has been 'shut-in'..." (Rosoff, 2017). Oil refining made up a majority of the economy in Texas's ports, and it is predicted that because of Harvey, "it could be months or even years before the region is experiencing some sense of normalcy again" (O'Keefe & Williams, 2017). Harvey not only affected Texas' economy, it had an impact on the whole country, "analysts said prices at the pump are likely to rise between 5 cents and 15 cents nationwide in the weeks ahead" (Ivanova, 2017).



#### Effects of Flooding on the Economy

#### 2.4 Gaps in Knowledge

The City of Boston has done quite a bit of work to protect residential and mixed-used areas from sea level rise, but there is still one area that the vulnerability assessments has not focused on: DPAs. A vulnerability assessment of the working port on the inner harbor of Boston has not been completed. Gaps in information include the exposure of DPAs to SLR and coastal storms, current state of infrastructure within the DPAs, the toxic chemicals stored within these DPAs and their potential effects on the harbor and its residents, as well as the ability for the working port to recover after damage occurs. Understanding the vulnerability of Boston's working port to SLR and coastal storms is necessary. This understanding will allow Boston to have a complete idea of the risks posed to the city by SLR and coastal storm surge.

# **Chapter 3.0: Assessing the Vulnerability of DPAs**

The goal of this project was to assess the vulnerability of designated port areas in Boston Harbor to sea level rise and coastal storms. We focused on the four Boston inner harbor DPAs which are Chelsea Creek, Mystic River, East Boston, and South Boston (See Appendices A-D). Within these DPAs we selected a sample of parcels to represent the different industries. The vulnerability of individual parcels was assessed to help determine the vulnerability DPAs as a whole. Our project resulted in a report that has been given to Boston Harbor Now (BHN) for their use to inform policy and interested stakeholders of our findings. In this chapter we outline how we picked parcels and how the parcels were studied and evaluated.

#### **3.1 Selecting Parcels for Assessment**

The DPAs of Boston's inner harbor consist of over 60 water dependent industrial businesses. To complete a vulnerability assessment of these parcels, a representative sample of 18 was selected, due the limited timeframe of this project. To reduce bias in our sampling process, we utilized random sampling to select each business. A database of parcels within the four inner harbor DPAs was obtained from Massachusetts Coastal Zone Management (CZM). We classified the businesses in the DPAs into eight different industries: mooring, cargo, fish processing, fuel, boat repair, salt, old industrial, and vacant/parking lots. Each industry is unique in how it operates, making each one vulnerable in different ways from each other.

To accurately represent the DPAs, a variety of each industry needed to be selected. First, we calculated the percentage of land each industry occupied within the DPAs. Based on the percentage of land each industry took up, parcels were selected weighted to that percentage. For example, cargo occupied 20.52% of land within all four inner harbor DPAs, and 20% of 15 parcels is roughly 4 parcels, therefore four cargo parcels were randomly selected (Appendix G).

In order to conduct a random sample, each parcel was assigned a number 1-55, 55 being the total amount of businesses. The parcels were grouped by industry. For example, Boat Repair included parcel numbers 1-9, Cargo was parcel numbers 10-21, and so on. Then to select the specific parcels, we randomly selected numbers using a Python script (Appendix F). We discovered two of the selected parcels were the same parcel but separated into two industries. This resulted in us having selected a total 14 businesses.

After we identified all of the parcels, we discovered that East Boston DPA was not represented. In order to ensure that each DPA and industry was represented in our study, we decided to add more parcels to our selection. Another random sample with just the parcels in the East Boston DPA was conducted, resulting in the selection of Boston Forging and Welding and Boston Towing and Transportation. Two industries were not represented in any of our random parcel selections: salt and fish processing. To select a salt parcel, we again ran the above script to randomly select one of the two salt parcels within the DPAs, which resulted in Eastern Salt Co. There was only one fish processing parcel to choose from: Channel Fish Co. The final selected businesses/parcels can be seen in Table 1 below.

Table 1:	List of	Selected	Businesses
----------	---------	----------	------------

Name Of Business	DPA	Industry
Preferred Freezer	Mystic	Cargo
Distrigas of Massachusetts Everett Marine LNG Terminal	Mystic	Fuel
Wharf		
Prolerized New England Co. Everett Wharf	Mystic	Cargo
Winnisimmet Landing Pier No. 1-5	Mystic	Mooring
Constellation Mystic Power, LLC Mystic Station Wharf	Mystic	Old Industrial
MA Port Authority, Paul W. Conley Marine Terminal Berth	South	Vacant
#14-17	Boston	
MA Port Authority, South Boston Ship Dock and Barge Dock	South	Old Industrial
	Boston	
Boston Marine Industrial Park Berth No. 6	South	Cargo
	Boston	
Perini Corp. Quarterdeck Marina	Chelsea	Cargo
Global Revco Terminal LLC Revere Terminal Ship Pier	Chelsea	Fuel
Gulf Oil Chelsea Terminal Tanker Wharf	Chelsea	Fuel
Vacant Land with Bulkhead	Chelsea	Vacant
245 & 257 Marginal St. LLC Bulkhead	Chelsea	Vacant/Parkin
		g
Channel Fish Co. Inc. Pier	Chelsea	Fishing
Irving Oil Terminals Inc Revere Terminal Pier Global Revco	Chelsea	Fuel
Berth No. 1		
Mahoney Terminal LLC Chelsea (AKA Eastern Salt Co.)	Chelsea	Salt
Boston Forging & Welding	East Boston	Boat Repair
Boston Towing & Transportation; Boston Fuel Transportation	East Boston	Fuel

# **3.2 Gathering Data**

To characterize the vulnerability of each parcel, we gathered preliminary data from the internet, we attempted to interview representatives from each business, and conducted site reviews by water taxi.

# 3.2.1 Gathering Data From Online Resources

Preliminary information for each selected parcel within the DPAs was found online. Area, industry, elevation, chemical storage, land and building value, as well as the net worth of the business could all be found on the respective city's tax assessor's website (Boston, Chelsea, Everett, Revere). The predicted flood zone in and around the parcels was determined using Surging Seas: Risk Zone Map for 5ft of sea level rise by 2100, which is the likely/ middle of the road for emissions scenarios used in Climate Ready Boston (Climate Ready Boston, 2016). This same sea level rise viewer was used to gather the predicted property exposure, social vulnerability exposure, and the vulnerable population exposure of the population surrounding each parcel.

### **3.2.2 Contacting DPA Businesses Representatives**

Using the contact information available to us, we attempted to get in touch with the businesses either through email or a phone call. We utilized a generic email template and phone script (Appendix H). The companies that got back to us were sent emails that contained variations of our generic interview questions (Appendix I). They were given the option to respond by email or call us to go over their answers.

## 3.2.3 Evaluating Sites from the Water

A water taxi was taken out along the shorelines of the parcels that were selected. Based on the location of our selected parcels and the location of shoreline stabilization structures, a water taxi route was mapped out (Appendix J). We took pictures of each site that we were able to get to with the taxi. We used these photos in conjunction with the 2009 Storm Smart Coasts CZM report in order to understand the current state of SLR infrastructure.

## 3.3 Data Analysis

All of the data gathered through interviews and site visits was compiled into a spreadsheet.

Table 2:	: Selected	DPA	Parcel	Data
----------	------------	-----	--------	------

Vulnerability	Evaluated	Source	Why?
	DPA	CZM Spreadsheet	What DPA the parcel is in.
	Industry	CZM Spreadsheet	What industry the parcel is in.
	Area (sq ft)	Assessor's Parcel Viewer	More land exposed to flooding.
Exposure	In Predicted Flood Zone for SLR by 2100 (5ft SLR) (Y/N)	Surging Seas: Risk Zone Map	Parcel is predicted to be flooded by 2100.
	SLR Preventative Infrastructure	Water Taxi/2009 Storm Smart Coasts	Poor condition of SLR prevention infrastructure adds to sensitivity.
	Chemical Type	CZM Spreadsheet	Different chemicals are dangerous in different ways.
Sensitivity	Chemical Quantity	CZM Spreadsheet	High quantity of chemicals could cause more damage.
201191011109	Chemical Storage	CZM Spreadsheet	Proper chemical storage can prevent against chemical spills, lowering overall sensitivity.
	Building Condition	Interviews	Poor building condition adds to the parcels sensitivity to SLR and storm surge.
	Predicted Property Exposure 5ft Sea Level Rise (Price per acre)	Surging Seas: Risk Zone Map	Expensive damages require more money to repair.
Ability to	Net Worth of Business	Assessor's Parcel Viewer	Smaller businesses may not be able to afford repairs.
Cope	Emergency Plans	Interviews	How well a company can respond to flooding events and related outcomes affects their ability to cope.
Misc.	Social Vulnerability Exposure 5ft SLR	Surging Seas: Risk Zone Map	The citizens in the surrounding area's ability to prepare and respond to flooding.
	Vulnerable Population Exposure 5ft SLR (People per square mile)	Surging Seas: Risk Zone Map	More vulnerable people surrounding parcel.
	Land and Building Value (\$)	Assessor's Parcel Viewer	Higher valued land/buildings may cost more to repair.

The vulnerability of each parcel was assessed by looking at the exposure, sensitivity, and ability to cope to SLR and coastal storm surge. If the parcel was within the predicted flood zone from the Surging Seas: Risk Zone Map, then not was deemed vulnerable in terms of exposure. Sensitivity was determined by the condition of the flood prevention infrastructure on the parcel and by whether or not the business on the parcels stores chemicals in large quantities. Ability to cope was determined by looking at the net worth of the business, what emergency flood plans the business had in place, and the potential cost of damages the businesses could receive from

flooding from SLR and storm surge. Miscellaneous data were also gathered relating to the effects that DPA flooding could pose on the surrounding area shown in Table 2. What we have evaluated are indicators for the corresponding dimension of vulnerability, they are not direct measurements.

# **Chapter 4.0: Potential Vulnerability and Risks of DPAs**

Boston's Inner Harbor DPAs are potentially vulnerable to sea level rise and coastal storm surge. There is a gap in knowledge as these areas have never fully been investigated. We have also found that this vulnerability has the potential to greatly impact the city and its inhabitants.

This chapter outlines our findings relating to the three dimensions of vulnerability: exposure, sensitivity, and ability to cope. Within each of these dimensions, we have evaluated many different variables that all contribute to the parcels overall vulnerability. We also discuss the DPA's potential impact on the city of Boston during flooding events. We then highlight the lack of transparency throughout the businesses within the DPAs in regards to contacting representatives and gathering information.

#### 4.1 - Exposure of DPAs to SLR and Coastal Storms

In order for an area to be vulnerable to SLR and coastal storms, it needs to be exposed to SLR and coastal storms. A sites location within Boston Harbor greatly affects its potential exposure. Depending on a sites elevation and proximity to the harbor, it will be exposed to different levels of flooding.

#### 4.1.1 - Predicted Flood Zones

The exposure to SLR and coastal storms greatly increases the vulnerability of the majority of parcels within Boston's working port. With moderate cuts in carbon emissions, the likely amount of sea level rise by the year 2100 is 5 ft (Global Climate Change, n.d.). Of the investigated parcels, 88% are expected to be underwater by 2100. With the DPA's situated directly on the water, they are more exposed to the effects of SLR and coastal storms than other areas of Boston. Figures 4-7 are maps of the four DPA's, showing the predicted flood zones (PFZ) during 5 ft SLR.




Figure 4: Chelsea Creek DPA Flood Zone From: (2017). Surging Seas: Risk Zone Map, | NOAA. Retrieved April 5, 2017



Figure 5: Mystic River DPA Flood Zone From: (2017). Surging Seas: Risk Zone Map, | NOAA. Retrieved April 5, 2017




Figure 6: South Boston DPA Flood Zone From: (2017). Surging Seas: Risk Zone Map, | NOAA. Retrieved April 5, 2017



Figure 7: East Boston DPA Flood Zone From: (2017). Surging Seas: Risk Zone Map, | NOAA. Retrieved April 5, 2017

## 4.1.2 - DPA Business Interview Response Regarding Exposure

In response to our interview questions, a representative from Channel Fish Co. Inc. said that he was very concerned for his business's safety regarding SLR and coastal storms. This

representative stated "We are very concerned that our backyard could flood and portions of the property could be damaged by severe storms."

Channel Fish Co. is located in the East Boston DPA, with direct access to the waterfront along Chelsea Creek. The East Boston area has been prone to serious erosion along the coast, and is located within the boundaries of the PFZ with regards to 5 feet SLR, shown in Figure 7 above. The representative stated that his business has been prone to flooding in the past, with an example of this flooding shown below in Figure 8. In regards to flooding on this property, the representative said "It's been pretty severe at times: the most recent occurrence on Aug. 2, the standing water was about a foot tall. It's also gotten into our basement in the past."

It is evident this business located within the DPA has extreme exposure to flooding, increasing its overall vulnerability to SLR and coastal storm surge.



Figure 8: Flooding Within East Boston August 2, 2017 From: Margaret Farmer

## 4.2 - Sensitivity to SLR and Coastal Storms

A sites vulnerability to SLR and coastal storms is also a function of its sensitivity. For the purpose of this project, the sensitivity analysis is based on the state of the infrastructure on the parcel. The infrastructure that we evaluated included both the sea level rise prevention infrastructure, chemical type, chemical storage, and chemical quantity. These are all indicators of sensitivity that contribute to the overall vulnerability of a parcel.

# 4.2.1 - Infrastructure Evaluations

SLR preventative infrastructure on DPA our selected DPA sites can be improved. Of our 18 selected parcels, only 6 had publicly listed SLR preventative infrastructure (CZM, 2009). Of those 6 parcels, five were ranked as needing a moderate level of action or higher according to CZM (CZM, 2009) (Appendix K). After our water taxi tour, we did not have an adequate amount of information to correctly correlate each parcels SLR prevention infrastructure to the previous CZM report.

During our water taxi tour, we were unable to visit all of the parcels from our sample due to limited time and travel restrictions. We were able to look at some SLR preventative infrastructure near some of the sites. Figure 9 shows riprap located on Prolerized. It can be seen that the high water mark on the rocks is more than halfway up the structure. We were not able to gain the exact measurements of the height of the rip rap, but we can safely estimate there is less than 5 feet of riprap above the high water mark. This is concerning due to the fact that 5 feet of SLR is expected by 2100, and if coastal storms hit the area, they will most likely experience more than 5 feet of coastal storm surge, resulting in the Prolerized site being flooded. Similar flooding would be experienced at the Eastern Salt site under the same future conditions. As seen in Figure 10, the Eastern Salt parcel has bulkheads. However, the high water mark is also located less than 5 feet from the top of the structure. The quality of SLR prevention infrastructure on these sites demonstrates the exposure to SLR and coastal storms, adding to the vulnerability of these working port areas.



Figure 9: Riprap located at Prolerized



Figure 10: Bulkhead located at Eastern Salt

## 4.2.2 - Sensitivity due to Chemical Storage

The fact that many businesses within the DPAs rely on large amounts of chemicals stored on site to function makes them more sensitive to sea level rise. Different types of chemicals are stored differently. The condition of the storage facilities can contribute to how vulnerable the site is to flooding. The worse the condition is the more vulnerable the area is. Unfortunately we were unable to analyze the condition of the storage facilities themselves. Since we could not analyze the storage facilities we investigated which companies would lose their ability to function for a time should they damage or lose the chemicals. Ten of the parcels that we investigated use chemicals in their day to day operations. The companies that store chemicals on these ten parcels would not be able to function normally without their chemicals. This limit in their ability to function is what makes them vulnerable in the sense of chemical storage.

Business	Chemical Type	Chemical Quantity	Chemical Storage
Preferred Freezer	Ammonia	N/A	N/A
Distrigas of Massachusetts	Liquid Natural Gas (LNG)	25,000 gallons	2 Cryogenic, 3 Tanks
Constellation Mystic Power	Petroleum/ LNG	590,000 barrels	4 Tanks
MA Port Authority South Boston Ship and Barge Dock	Petroleum Molasses	2,292,000 barrels 4,437,000 Gallons	26 Tanks 12 Steel Tanks
Boston Marine Industrial Park Berth 6	Cement	N/A	2 Storage Silos
Global Revco Terminal	Petroleum	1,400,000 Barrels	24 Steel Tanks
Gulf Oil	Petroleum	1,677,600 Barrels	21 Steel Tanks
Channel Fish Co. Inc. Pier	Salt Formaldehyde Ammonia	N/A	N/A
Irving Oil Terminal	Petroleum	1,300,000 Barrels	18 Steel Tanks
Eastern Salt	Salt Coal	170,000 Tons	Pile

**Table 3: Chemical Storage Information** 

#### 4.3 Parcel's Ability to Cope with SLR and Coastal Storms

A site's vulnerability is also a function of its ability to cope after a major flooding event has happened. If a site can respond and recover quickly from SLR or a major storm, they are less vulnerable to it. Things such as a business's worth and income can give some indication on a business's ability to reconstruct their site. Emergency plans that are in place when flooding occurs also will reduce that sites vulnerability to SLR and coastal storms. If a site has the ability to cope with SLR and coastal storms both during and after they occur, they are consequently less vulnerable.

#### **4.3.1 Financial Aspects**

The sheer cost of the land and infrastructure on many of these parcels would make it difficult for businesses rebuild after severe flooding. After reviewing the land and building value provided by tax assessor's websites, we identified that out of the parcels investigated, 61% of them were worth over \$1M. Only six of the eighteen businesses that we evaluated were publicly traded and those businesses were all worth well over \$100M. The other twelve parcels are either abandoned or local businesses. During major flooding events, 66% of businesses are expected to have between \$10M-\$100M of predicted damage per acre. The other 33% is predicted to experience between \$1M- \$10M of damage per acre to their property. Since two thirds of all investigated businesses have no public information on their net worth, one third of the businesses evaluated could possibly have the resources to rebuild after a severe flood, this is still undetermined.

#### 4.3.2 - Emergency Plans

To our knowledge, few of the businesses within the DPAs have publicly available emergency plans to deal with flooding. One of the businesses that we contacted said that they had an emergency plan in place, but that it was not public information. Businesses are not required to make their emergency plans public, due to risks associated with terrorism. Through an interview with a hazard mitigation expert from MEMA, we learned that the only real regulating body that deals with hazardous materials is local fire departments. Local fire departments enforce EPA regulations concerned with the handling of hazardous materials. The EPA only requires that businesses report the quantity of hazardous materials on their sites to their area fire department and the EPA. According to the Massachusetts Tier II Reporting Entities, a source referred to us by MEMA, the hazard mitigation plan's main purpose is to "provide the framework and methodology to efficiently respond to hazardous materials emergencies"(Hazardous materials emergency plan, 2011)(template version of Hazardous Materials Emergency Plan can be seen in Appendix L). The current regulations are reactionary in nature, only having plans for chemicals once they spill. We found no regulatory requirements to help prevent the release of toxic chemicals into the environment.

The only other agency that regulates industrial activities within Boston's harbor is the United States Coast Guard. The Coast Guard is mostly concerned with ships and materials that are moving on the water. They receive hazardous cargo manifests from ships entering the harbor in order to keep updated on the hazardous materials within Boston Harbor.

We learned that the regulation of the DPAs is split between MEMA, CZM, USCG, and the EPA. From our research it doesn't seem that there is much communication between these groups. This is based off of our experience with these agencies representatives. We were continually being referred to different people within various state agencies, none of whom knew much about regulations within the DPAs. This lack of communication means that in an emergency situation important information may not be available to first responders.

#### 4.4 DPAs Impacts on Boston During Flooding Events

DPAs vulnerability to SLR and coastal storms is a problem, but the effects that those flooded DPAs may have on the surrounding areas is another issue. Populations that live behind these DPAs are at risk due to their proximity to the water as well as being exposed to the toxic chemicals that are stored on some DPA properties. The impacts of flooded DPAs on the surrounding areas of Boston is also a threat.

## 4.4.1 Populations at Risk from Flooding in DPAs

Residential populations located directly behind the DPA's can be vulnerable to the effects SLR. If you refer to the vulnerable populations table (Appendix M), you can see many of the inhabitants surrounding the DPA parcels will be exposed to the effects of SLR. Using the Surging Seas: Risk Zone Map we were able to apply Social Vulnerability and Vulnerable Population layers. The Social Vulnerability Exposure ranks how the population can prepare and react to SLR and flooding events. The businesses that have a rank of "Low" have populations behind them with low exposure, meaning they have a better ability to prepare and respond to the flooding. "High" means that the population surrounding the parcel are not able to respond and prepare well for flooding events. The Vulnerable Population Exposure is how many people per square mile that would be impacted by a 5 foot sea level rise. These show that the populations behind the DPA's are vulnerable to SLR and coastal storms. During major flooding events, floodwater from the DPA's pose the risk of spreading contaminants to the surrounding areas. This has the potential to exacerbate the impacts of flooding on the already vulnerable residential populations.

Business	Social Vulnerability Exposure 5 ft. SLR (Ability to prepare and respond to flooding)	Vulnerable Population Exposure 5 ft. SLR (People per square mile)
Preferred Freezer	Medium	None
Distrigas of MA Everett Marine LNG Terminal Wharf	Medium	None
Polerized New England Co. Everett Wharf	Medium	None
Winnisimmet Landing Pier No. 1-5	High	1000-9999
Constellation Mystic Power, LLC Mystic Station Wharf	Medium	None
MA Port Authority, Paul W. Conley Marine Terminal Berth #14-17	N/A	None
MA Port Authority, South Boston Ship Dock and Barge Dock	N/A	None
Boston Marine Industrial Park Berth No. 6	N/A	1000-9999
Perini Corp. Quarterdeck Marina	Low	1000-9999
Global Revco Terminal LLC Revere Terminal Ship Pier	Low	1000-9999
Gulf Oil Chelsea terminal Tanker Wharf	Medium	None
Vacant Land with Bulkhead	High	Below 100
245 & 257 Marginal st. LLC Bulkhead	Low	1000-9999
Channel Fish Co. Inc. Pier	Low	None
Irving Oil Terminals Inc Revere Teminal Pier Global Revco Berth No. 1	Low	None
Mahoney Terminal LLC Chelsea (AKA Eastern Salt Co. )	High	None
Boston Forging & Welding	High	None
Boston Towing & Transportation; Boston Fuel Transportation	High	None

**Table 4: Vulnerable Residential Populations Surrounding DPA's** 

Info taken from Climate Central. (2016). Surging seas: Risk zone map. Retrieved from

https://ss2.climatecentral.org/#12/40.7298/-74.0070?show=satellite&projections=0-RCP85-SLR&level=5&unit=feet&pois=hide

# 4.4.2 Risks Posed by Chemicals in the DPA

Many of the chemicals located in the harbor could have detrimental effects on Boston and the other cities bordering the harbor, demonstrated in Table 5. We know, from the CZM spreadsheet of parcels, of nine chemicals that are present in large quantities within the DPAs. The sheer amount of these chemicals along the harbor, in addition to their hazardous natures, is alarming because in extreme events they may find their way into the harbor. For example, within the investigated parcels, there are over 345,811,200 gallons of fuel stored. The issues presented by the release of the chemicals could impact public health, the environment, and the economy.

Chemical	Public Health	Environment
Petroleum (CHEMTREC, n.d.)	Toxic	Acute aquatic toxicity, flammable
LNG (Elengy, 2014)	Frostbite, severe burns	Flammable
Liquid Nitrogen(Airgas, 2016)	Frostbite, severe burns	N/A
Salt (MSDS, n.d.)	Skin irritant, eye irritant	N/A
Cane Molasses (Sugar Australia, n.d.)	Eye irritant	Depletes Oxygen levels in Water
Ammonia (Airgas, 2017)	Frostbite, severe burns	Acute Aquatic Toxicity
Formaldehyde (MSDS, n.d.)	Toxic, Carcinogen	Flammable
Coal (URSI, 2008)	Carcinogen	Flammable
Portland Cement (PPC, 2016)	Skin irritant	Lowers pH of water

Table 5: Chemical Effects on Public Health and Environment

Of the nine chemicals that we know are present in the harbor, six of them are would cause harm to a person if they were exposed. Petroleum oil and formaldehyde are the only toxic chemicals to humans, while formaldehyde and coal dust are classified as carcinogens. The other three chemicals that we identified as being dangerous to public health are ammonia, liquid natural gas, and liquid nitrogen. These chemicals are stored under great pressure in their liquid form, once exposed to the atmosphere, they would vaporize, making them less likely to be ingested. Despite this, they can still be very harmful. Each can cause severe burns similar to frostbite. They are also dangerous if inhaled and can cause unconsciousness. Rock salt, portland cement, and cane molasses are all relatively safe for humans to be around. The first two can cause skin irritation while all three can cause eye irritation. Chemicals pose many dangers to the environment as well.

Flooding could cause facilities' chemical storage to leak. Petroleum and ammonia are both chemicals that are acutely toxic to aquatic life. Portland cement can change the pH of the water and the molasses will lower the oxygen levels; these effects would lead to a heightened mortality of aquatic life. In addition to being toxic and unstable, four of the chemicals are highly flammable. Should they get into the harbor many of them will not mix with the water. Should this mixture of chemicals somehow come into contact with a spark or flame, it could cause a large portion of the harbor to catch on fire. Leakage of chemicals could also cause a detrimental effect on the economics of region.

Both salt and petroleum would impact the economy of the surrounding area in more severe ways than the other chemicals that we are aware of. The salt pile in Chelsea is the main source of rock salt for the roads in the Greater Boston area. If the large portions of the salt were to be washed away, the Boston Metropolitan Area would need to obtain salt from elsewhere in short notice. Boston could also lose a large amount of petroleum during major flooding events. With Logan International Airport being one of the largest consumers of petroleum in the area, with over 38,000 passenger flights in August 2017 alone (MassPort, 2017), it would be greatly impacted should the petroleum in the DPAs be lost. Planes would not be able to refuel at the airport for some time, effectively shutting it down.

#### 4.5 Lack of Transparency Within the DPAs

The businesses in the DPA lack transparency about flooding preparedness. Of the 16 businesses that we contacted, only two responded to us. We emailed a set of 15 different questions to the businesses. The response below was all we had received from one of the business representatives.

In response to your questions below, the... [Parcel]...has not had a problem with flooding at this facility in the past, nor do we foresee any problems for the future. This facility is highly regulated, and those regulations call for contingency plans to cover all types of scenarios, from natural disasters to manmade events. These contingency plans are not public information.

This shows how difficult it has been for us to get information from these businesses. We were unable to gather a lot of data about different businesses beyond what is publically available online. This lack of transparency makes it impossible to make any accurate statement on the level of preparedness that exists within the DPAs. Without clear communication from DPA businesses about their SLR preparedness, neither the city of Boston nor a third-party could accurately predict the effects of flooding in the Boston area. This lack of transparency may come down to the fact that we are college students and businesses may not have been sure of our intentions, possibly afraid of self-incriminating answers.

# **Chapter 5.0: Recommendations to Better Prepare DPAs to SLR and Coastal Storms**

Within Boston's inner harbor DPAs, many improvements can be made to planning and regulations in order to reduce their vulnerability to SLR and coastal storms. Further research can also be conducted in order to further evaluate the vulnerability of DPAs in the harbor. A committee that could regulate DPA businesses' emergency preparedness plans as well infrastructure evaluations could help to decrease their vulnerability.

#### 5.1 Recommendations to Better Understand Vulnerability within DPAs

Major gaps in data concerning vulnerability of Boston to the sea level rise and storm surges still exist. The vulnerability assessment, Climate Ready Boston does not address the DPAs in any capacity. As students reaching out to businesses, we found many unwilling to participate or even get back to us. Though we managed to gather a lot of information on DPAs in a short amount of time, a lot more data regarding the businesses in the DPA's should still be gathered.

<u>We recommend that the Massachusetts Coastal Zone Management (CZM) and The</u> <u>Boston Green Ribbon Commission (GRC) continue their partnership and produce a vulnerability</u> <u>assessment of the DPAs.</u> This is the partnership that produces the Climate Ready Boston report, which provides an in depth understanding of Boston's vulnerability to climate change. With their previous experience, they can conduct their own vulnerability assessment that will give a more detailed description of the state that the DPAs are in. This report, in conjunction with the Climate Ready Boston report, will create a more complete understanding of the vulnerability of Boston and its harbor to Climate Change.

#### 5.1.1 Use of More Sophisticated Models for Vulnerability Assessments

To complete our initial vulnerability assessment of the given DPA's parcels we utilized the Surging Seas: Risk Zone Map to gather information about potential flood zones. Using this source we were able to gather some preliminary information about sea level rise and its effects on the harbor, but no detailed information such as flood depths were available for our group. According to Paul Kirshen, a professor at the University of Massachusetts Boston, the Surging Seas: Risk Zone Map uses the "bathtub model" to predict sea level rise. This model is not the most detailed and or accurate ways to predict sea level rise. As we neared the end of our project, we were given access to an extremely accurate sea level rise viewer that is not open to the public, courtesy of the Massachusetts Department of Transportation. Due to the lack of time we were not able to utilize these GIS maps to their fullest potential. An example of this GIS can be found below in Figure 11. We recommend that whoever continues this research within the DPA's should utilize this resource as it will add extremely accurate and in depth data.



Figure 11:Potential Flooding of 5 Feet with Spring Tide From: given citation (2017). MassDOT-FHWA Pilot Project Report, | Bosma *et. al.*. Retrieved October 3, 2017

#### **5.2 Centralized Regulations for Emergency Preparedness Plans**

Throughout the completion of this project, we found that\_no existing organization directly regulates emergency preparedness plans in the DPAs. We believe this to be a serious issue. During Hurricane Harvey the Akema chemical plant in Crosby Texas lost power to its refrigeration units. These units were critical as without them, the stored chemicals would ignite and explode (Gallagher, 2017). Had the Akema chemical plant been required to keep an updated flood preparedness plan, it may not have lost power to its refrigeration units.

Without a centralized organization governing emergency preparedness in these industrial areas, the City of Boston cannot be certain that the businesses will be prepared to handle flooding events. We recommend that Massachusetts Coastal Zone Management (CZM), the Department of Environmental Protection (DEP), the Massachusetts Emergency Management Agency (MEMA), and the United States Coast Guard (USCG) form a regulatory committee concerned with emergency preparedness plans within the DPAs. The partnership should integrate CZM's knowledge of businesses and infrastructure within the DPAs, DEP's experience with brownfield remediation, USCG's authority over the harbor and the cargo within it, and MEMAs experience with emergency management in Massachusetts.

The committee should have a set of regulations to enforce on the DPA businesses. The two regulations that we are recommending this committee enforce are: that chemicals and hazardous materials used by businesses within the DPAs must be stored in flood-proof containers, and that more frequent inspections and repairs be performed on the SLR prevention infrastructure within the DPAs. The first regulation would reduce business sensitivity to SLR and coastal storms by reducing the risk of chemical spills. The second regulation would reduce the business's exposure to SLR and coastal storms by ensuring that the SLR prevention infrastructure on the sites are up to date and in good condition.

If these regulations were to be put in place, the city could be more confident that the DPA businesses may better withstand flooding events. These regulations could reduce the vulnerability of DPA businesses to sea level rise and coastal storm surges by limiting exposure and sensitivity. This committee and its regulations would ensure that the unique needs of these industrial areas are met, while simultaneously keeping the surrounding communities and environment safe during flooding events.

# **Chapter 6.0: Conclusions**

The goal of this project was to assess the vulnerability of designated port areas in Boston harbor to sea level rise and coastal storms. By selecting a sample of representative parcels within the four inner Boston Harbor DPA's, we were able to gain a representative sample of DPA businesses that could then be analyzed for their vulnerability to SLR and coastal storms. Three dimensions of vulnerability were considered for each parcel: exposure, sensitivity, and ability to cope to SLR and coastal storms.

In spite of data limitations, we discovered that many of the sites in Boston Harbor are within the predicted flood zone for 2100, and many things including chemicals, poor infrastructure, and lack of planning on those sites cause them to be more vulnerable to SLR and coastal storms. The reluctance of businesses to answer questions puts further emphasis on the importance of this problem. Also, the lack of central regulation of emergency preparedness plans within the Boston Harbor DPAs is very concerning. The combination of these problems may put Boston in an underprepared state to deal with SLR and coastal storms.

Boston Harbor's ecosystem could be damaged, billions of dollars could be lost, homes destroyed, and lives threatened. The City of Boston has started to prepare for SLR and coastal storms with their reports such as Climate Ready Boston and Greenovate Boston, but a plan for industrial port areas does not yet exist. This gap in planning is a problem for Boston. Our group concludes that a committee be developed in order to review and regulate DPA businesses emergency preparedness plans, as well as that further research be conducted into this topic. Boston Harbor's DPAs are multifaceted areas that vulnerability needs to be more fully evaluated.

Modern port cities, such as Boston, are being increasingly threatened by SLR and coastal storms. Major cities around the country, such as New York, Houston, and New Orleans, have been impacted by hurricanes throughout the past 20 years. The storms that hit these cities caused major negative impacts to the area's infrastructure, public health, environment, and economy, devastating the region. For example, in 2012 when Hurricane Sandy hit Staten Island, 23 people died, many by drowning in flood waters (Sandy and its Impacts.2012). When Hurricane Harvey hit Texas in 2017 much of the oil refining that made up a majority of the economy in Texas's ports, was damaged. "It could be months or even years before the region is experiencing some sense of normalcy again" (O'Keefe & Williams, 2017). In 2005 when Hurricane Katrina hit New Orleans, the lack of adequate infrastructure coupled with the severity of the storm lead to disaster for the city. The City of New Orleans did have levees in place in order to help minimize the effects of severe coastal storms, but those levees were "...built in a disjointed fashion using outdated data"(Hoar, 2006). Storms such as Hurricane Katrina, Sandy, Harvey, and Irma highlight the imminent threat that SLR and coastal storms pose to coastal cities. Port cities around the world need to learn from these storms and prepare for coastal flooding to help reduce the negative impacts.

# **Chapter 7.0: References**

Airgas. (2016). Material Safety Data Sheet, Liquid Nitrogen. n.p.

Airgas. (2017). Material Safety Data Sheet Ammonia. n.p.

Astor, M. (2017). '*Flesh-Eating Bacteria' From Harvey's Floodwaters Kill A Woman*.' The New York Times Retrieved from https://www.nytimes.com/2017/09/28/health/necrotizing-fasciitis-houston-texas.html

Bosma, K., Douglas, E., Kirshen, P., McArthur, K., Miller, S., & Watson, C. (2015). *MassDOT-FHWA Pilot Project Report. MassDOT*. Boston: MassDOT

Chapter 91, The Massachusetts Public Waterfront Act. (2012). Retrieved from http://www.mass.gov/eea/agencies/massdep/water/watersheds/chapter-91-the-massachusetts-public-waterfront-act.html

CHEMTREC. (n.d). Safety data sheet: Crude Oil. n.p.: CHEMTREC.

City of Boston. (2014). *Boston Revised Hazard Mitigation Plan: 2014 update*. n.p.: City of Boston

City of Boston. (2016). Climate Ready Boston. n.p.: City of Boston.

Climate Central. (2016). Surging Seas: Risk zone map. Retrieved from https://ss2.climatecentral.org/#12/40.7298/-74.0070?show=satellite&projections=0-RCP85-SLR&level=5&unit=feet&pois=hide

Elengy. (2014). Material Safety Data Sheet LNG. n.p.: Elengy.

*Environmental, Health, and Safety Guidelines For Fish Processing*; (2007). n.p.: International Finance Corporation

Fritz, A., & Samenow, J. (2017). Harvey Unloaded 33 Trillion Gallons of Water in the U.S. Retrieved from https://www.washingtonpost.com/news/capital-weather-gang/wp/2017/08/30/harvey-has-unloaded-24-5-trillion-gallons-of-water-on-texas-and-louisiana/

Gallagher, J. J. (2017). Hurricane Harvey Wreaks Historic Devastation: By the Numbers. Retrieved from http://abcnews.go.com/US/hurricane-harvey-wreaks-historic-devastation-numbers/story?id=49529063

EPA. (2011). Hazardous Materials Emergency Plan.n.p.: EPA

Health, National Center for Environmental.CDC - Mold - General Information. Retrieved from http://www.cdc.gov/mold/dampness\_facts.htm

Hewett, F. (2016). Dirty water: Good and Bad News About the Future of the Charles River. Retrieved from http://www.wbur.org/cognoscenti/2016/08/26/boston-climate-change-frederick-hewett

Hoar, J. (2006). Katrina Report Blames Levees. Retrieved from https://www.cbsnews.com/news/katrina-report-blames-levees/

Horton, R., & Yohe, G. (2014). Chapter 16 Northeast. n.p. globalchange.gov.

Hurricane science: Storm Surge. (n.d.). Retrieved from http://www.hurricanescience.org/glossary/?letter=S#glossaryword347

Inventories of Seawalls and Other Coastal Structures. (2013). Retrieved from http://www.mass.gov/eea/agencies/czm/program-areas/stormsmart-coasts/seawall-inventory/index.html

Ivanova, I. (2017). How Hurricane Harvey is Affecting Gas Prices. Retrieved from https://www.cbsnews.com/news/how-hurricane-harvey-is-affecting-gas-prices/

Library, C. N. N. (2016). Hurricane Sandy Fast Facts. Retrieved from http://www.cnn.com/2013/07/13/world/americas/hurricane-sandy-fast-facts/index.html

Martin Associates. (2012). Economic Impact of the Port of Boston.(n.p.).Martin Associates.

MassPort. (2017). *Boston-Logan International Airport Monthly Airport Traffic Summary - August 2017*.n.p.:MassPort.

MSDS. (a). Material Safety Data Sheet Formaldehyde 37% Solution MSDS.(n.d.). n.p.:n.p.

MSDS. (b). Material Safety Data Sheet Sodium Chloride (Rock Salt) MSDS.(n.d.). n.p.:n.p.

Nature Foundation. (2017, September, 17). Assessments of Environmental Damage Carried Out Post Hurricane Irma by The Sint Maarten Nature Foundation. Saint Martin News Network Retrieved from http://smn-news.com/st-maarten-st-martin-news/27074-assessments-ofenvironmental-damage-carried-out-post-hurricane-irma-by-the-sint-maarten-naturefoundation.html

NOAA.Sea level rise viewer. Retrieved from https://coast.noaa.gov/digitalcoast/tools/slr

O'Keefe, L., & Williams, C. (2017). Harvey Hammers Oil Refineries, Impacts Spill Into Commercial Real Estate. Retrieved from https://www.bisnow.com/national/news/energy/harveyslams-into-us-refineries-why-the-commercial-real-estate-industry-should-care-78293

Pierre-Louis, K. (2017, August 25,). Hurricane Harvey is Hitting Texas Even Harder Than Expected. Here's What You Need To Know. Popular Science,

Portland. (2014). Risk and Vulnerabilities Assessment Climate Change Preparation Strategy. Retrieved from https://multco.us/file/36550/download

PPC. (2016). Material Safety Data Sheet For Cement. Retrieved from https://www.ppc.co.za/media/18085/MSDS-Cementitous-Materials-Safety.pdf

Rosoff, M. (2017). Hurricane Harvey: Refineries Shutting Down. Retrieved from https://www.cnbc.com/2017/08/27/hurricane-harvey-refineries-shutting-down.html

City of New York. (2012). Sandy and Its Impacts. n.p.: City of New York.

Sifferlin, A. (2017, Aug 29,). Here's How Dirty Flood Water Really Is. Time.

Sugar Australia. Material Safety Data Sheet Cane Molasses. (n.d.). n.p.: Sugar Australia

URSI. (2008). Material Safety Data Sheet Coal Dust. n.p.:URSI.

US EPA, O. A. (a). Climate Change Indicators: Sea Level. Retrieved from https://www.epa.gov/climate-indicators/climate-change-indicators-sea-level

US EPA, O. A. (b). Climate Impacts in The Northeast. Retrieved from https://www.epa.gov/climate-impacts/climate-impacts-northeast


Walsh, M. J. (2014). *Greenovate Boston: 2014 Climate Action Plan Update*. Boston: City of Boston

Woolhouse, M. (2014). Report Touts Economic Impact Value of Port of Boston - The Boston Globe. Retrieved from https://www.bostonglobe.com/business/2014/07/20/report-touts-economic-impact-value-port-boston/44iuIALcbuyvlgw6RtrWrM/story.html


# **Chapter 8.0: Appendices**

#### **Appendix A: Mystic River DPA Boundaries**

The following DPA boundary maps outline DPA boundaries.




Mystic River DPA Boundaries courtesy of Massachusetts Government. (2016). Chapter 91, The Massachusetts Public Waterfront Act | MassDEP. Retrieved April 24, 2017.



Appendix B: Chelsea Creek DPA Boundaries

Chelsea Creek DPA Boundaries courtesy of Massachusetts Government. (2016). Chapter 91, The Massachusetts Public Waterfront Act | MassDEP. Retrieved April 24, 2017.




Appendix C: South Boston DPA Boundaries

South Boston DPA Boundaries courtesy of Massachusetts Government. (2016). Chapter 91, The Massachusetts Public Waterfront Act | MassDEP. Retrieved April 24, 2017.

## **Appendix D: East Boston DPA Boundaries**



East Boston DPA Boundaries courtesy of Massachusetts Government. (2016). Chapter 91, The Massachusetts Public Waterfront Act | MassDEP. Retrieved April 24, 2017



## **Appendix E: Boston Inner Harbor DPA Boundaries**

Inner Boston Harbor DPA Boundaries courtesy of Massachusetts Government. (2016). Chapter 91, The Massachusetts Public Waterfront Act | MassDEP. Retrieved April 24, 2017.

## **Appendix F: Python Code**

```
def RandomPicker():
    n=int(input('How many numbers would you like to generate? '))
    a=int(input('What is the lower bound? '))
    b=int(input('What is the upper bound? '))
    c=r.sample(range(a,b),n)
    print(c)
    RandomPicker()
```

This is the Python 3.5 code for our parcel picking process

# Appendix G: Parcel Land Use

Industry	% of land used	Number of parcels selected
Boat Repair	9.72	0
Cargo	20.52	4
Fish Processing	0.28	0
Fuel	35.25	5
Mooring	7.83	1
Old Industrial	16.52	2
Salt	0.59	0
Vacant/Parking	9.13	3

This is a table showing the percentage of land in the DPAs used by each industry. These percentages were used to weight our random sample.

#### **Appendix H: Generic Email and Phone Script**

Dear\_\_\_\_\_,

We are a team of four Worcester Polytechnic Institute (WPI) students completing our Interactive Qualifying Project (IQP), which is a research project all students are required to complete in order to graduate. For our project, our sponsor is the nonprofit Boston Harbor Now. We are gathering data about specific businesses within the Designated Port Areas of Boston Harbor and we were hoping to ask you a few questions about your business. We are on a tight schedule and it would be helpful if we could hear back from you by September 15th. If you would be willing to meet with us either in person or over the phone it would be greatly appreciated. You can contact us at boston17harbor@bostonharbornow.org.


Thank you,


Austen Crawford, Caroline Warchol, Jacob Bouchard, And Kyle Whittaker This is the generic email that we initially sent out to each DPA business that we wanted to talk to.

#### **Appendix I: Generic Questions**

- 1. How long have you been working at\_\_\_\_?
- 2. What is your job here?
- 3. What does your business "do" (have specific questions based on the business)
- 4. Have you experienced flooding in the past?
  - a. If so, how severe was it and how did you cope?
  - b. What are your emergency flooding plans at this company?
- 5. Are you familiar with the SLR prevention infrastructure on your property?
  - a. If so, do you believe it to be in good condition?
  - b. Did it help to prevent/ lessen the flooding
- 6. When was this building last refurbished/updated?
- 7. What types of chemicals does this company use?
  - a. How are they stored?
  - b. Has your company thought about changing the way chemicals are stored?
- 8. Is your company concerned about SLR or severe storms?
  - a. Are there any plans being made to address these concerns

This is the list of generic questions that we asked businesses to answer either over the phone or through email.





This the map of the route that we planned to take on our water taxi. In reality we did not go as far up Chelsea Creek.

# Appendix K: CZM Infrastructure Sheets

These structure assessment forms were taken from CZM's Coastal Infrastructure Inventory and Assessment. The below forms are for structures on our selected parcels.

	Assessment Form	and Assessment		Town: Ch Structure ID: 011	-015-000-004-100
Property Owner:		Location			o-block-parcel-structure
State		Eastern Aver	0.10	Dat	7/24/2007
		1		1	1/24/2007
Presumed Structu State	re Owner:	Based On Co	xmment:		
Contraction of the second		1			
Owner Name: MA-DCR		Earliest Struc 1986	cture Record:	Estimated Recons	struction/Repair Cost:
hur and		1.~~			\$22,433.00
phillipping and	Elevation: FIRM Map 2	statistics processing and the state		Martin Contractor	
55 Feet Feet	NAVD 88	1	N/A		
		Feet NC		The second second	Contraction of the second
Primary Type: Bulkhead/ Seawa	Primary Material:	Primary Height: 10 to 15 Feet		and the second	
Secondary Type: Revetment	Secondary Material:	Secondary Heigi	ht:		
		10.0.19.000		A State of the second second	
Structure Summa A granite block w	all that is capped with approxi-	mately 2 feet of concrete	a. The structure has	s a riprap slope comprised of mos	stly cobbles and
small boulders w	Ith an average stone size of 1 f	oot diameter. The struc	ture appears to gene	erally be in good condition.	
Condition	в		Priority		
Rating	Good		Priority Rating	Low Priority	
Level of Action	Minor		Action	Future Project Consideration	
Description	Structure observed to exhib problems, superficial in natu to landform is present. Str adequate to provide protecti coastal storm with no dama to prevent / limit future deter life of structure.	ure. Minor erosion ucture / landform tion from a major ige. Actions taken	Description	Inshore Structures Present w potential for Significant Infras	
Structure Imag	es:	Structure Docume	nts:		
011-015-000-004-	100-PHO1A JPG		ents: anuary 198 (Desig	an of Riprap (011-015-000	-004-100-DCR1A
-	100-PHO1A JPG			gn of Riprep (011-015-000	-004-100-DCR1A
011-015-000-004-	100-PHO1A JPG			gn of Riprap (011-015-000	004-100-DCR1A

	frastructure Inv		ssessment		Town: Chelsea	
itructure A	ssessment	Form			Structure ID: 011-015-000- Key: community-map-block-pa	
roperty Owner:			Locations			A COLOR OF OCCUM
State			Eastern Avenue		Date:	7/24/2007
			1	2011-22	1	1124/2001
resumed Structure Rate	e Owner;		Based On C	omment:	an in the second second second	
			1			
Wher Name: MA-DCR			Earliest Stru 1986	cture Record:	Estimated Reconstruction/I	the second second second
in pen		Next come the	11900			\$93,773.00
and the second s	levation: FI	RM Map Zone:	FIRM Map Elev	and the second se	A TENNEY	
120	1	A3	1	N/A		
	IAVD 88		Feet N	GVD	在座	
rimary Type: Revetment	Primary M Stone	laterial:	Primary Height 10 to 15 Feet	<u></u>	All and a second second	
econdary Type:	Secondary	Material			and the state of the second	
over mer A 1 Abe:	- Secondary	Pidicindi:	Secondary Heig	pric.	Section 11 march	
tructure Summary			100		E Cathorn Street Contraction	
combination of o	oncrete debris mixe	ed with approxim	ately 1 foot diam	eter stones and gran	ite blocks that have been loosely dumped	on an
xisting slope. It is	s in fair condition w	ith movement of	stone and ceme	nt pieces evident.		
Condition	c			Priority	ш	
Rating	Fair			Rating	Moderate Priority	
Level of Action	Moderate			Action	Consider for Active Project Improvem	ent
Description	Structure is sound deterioration, sect			Description	Listing Inshore Structures with potential for	
	undermining, and to withstand majo	for scour. Structi	ire adequate	15eacr aprilon	Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling im	
	moderate damage	. Actions taken	to reinforce		100 feet of shoreline)	pacieu /
	structure to provid coastal storm and					
	structure. Modera landform exists. L					
	to fully protect sho	preline during a r	najor coastal			
	storm. Actions tak material for full pr					
tructure Image	25;	Stru	cture Docume	ents:		
11-015-000-004-2	00-PHO2A.JPG	MA-	DCR	January 198 Desi	gn of Riprap 011-015-000-004-200	-DCR2A
					and the second se	
					Prepared By: Bourne Consultin	

		cture Inventory and Sment Form		11.	Structure	wn: Boston e ID: 006-010-366-8000-100 nunity-map-block-parcel-structure
Property Owner:			Location	1:		Date:
Local				on - Border Street		7/3/2007
Presumed Struct	ure Owner:		Based On	Comment:		1
Local			r			
Owner Name:			Earliest S	ructure Record:	Estimal	ted Reconstruction/Repair Cost:
Boston			1973			\$247,447.00
Length: Top	Elevation:	FIRM Map Zo	ne: FIRM Map El	evation:		
910			AZ	10		-
Feet Feet	NAVD 88		Feet	NGVD	an and the second	Contraction of the local division of the loc
Primary Type:		Primary Material:	Primary Heig	ht:	es	THE REAL PROPERTY.
Bulkhead/ Seawa		Stone	5 to 10 Feet			
Secondary Type: Revelment		Secondary Material: Stone	Secondary H 5 to 10 Feet		1	EN DO
Structure Summa		provide and a second se	Is to reveel		10	
A granite block v	vall with a t	typical block size of 3 o in front of the seawa	feet by 2 feet by 2 f all.	eet with riprap behind	it with an average stor	ne size of 1 foot diameter. In
Condition	в			Priority	8	
Rating	Good			Rating	Low Priority	
Level of Action Description		re observed to exhibit	where minor	Action Description	Future Project Cor	Present with Limited
	to landf adequa coastal to preve	ns, superficial in natur lorm is present. Strut te to provide protectio storm with no damag ent / limit future deteri tructure.	cture / landform in from a major e. Actions taken			icant Infrastructure Damage
Structure Imag	Contraction of the second second		Structure Docur	nents:		
005-010-366-800			USACE			6-010-366-8000-100-COE1A
00-010-366-800			DEP	May 1974 Plan	Accompanying 00	6-010-366-8000-100-LIC1A
06-010-366-800	0-100-PHC	ne.JPG				
006-010-366-800 006-010-366-800						

	frastructure Inventory and A ssessment Form	Structure I	n: Boston D: 006-010-367-9000-100 nity-map-block-parcel-structu	re		
Property Owner:		Location:			Date:	1
Local		East Bostor	- Border Street and	Condor Street	7/3/200	07
Presumed Structur	e Owner:	Based On C	comment:			
Local	and the second					-
Owner Name: Boston		Earliest Str.	acture Record:	Estimated	Reconstruction/Repair Cost \$153,153.00	
255	Avation: FIRM Map Zone: A2 AVD 88 Primary Material: Stone	FIRM Map Elev Feet N Primary Height 5 to 10 Feet	10 IGVD	A		
Secondary Type:	Secondary Material:	Secondary Heig	ght:	E. La		
Structure Summary				North Cold State		
A granite block sea supports the roady <i>Condition</i>	awall with an approximate block siz way directly behind it.	e of 4 feet by 2 fe		I shows some signs of m	ovement. The wall also	
Rating	Fair		Priority Rating	High Priority		
Level of Action	Moderate Structure is sound but may exhibit		Action	Consider for Next Pro	oject Construction Listing Structures with Potential	
Description	deterioration, section loss, cracki undermining, and/or scour. Struct to withstand major coastal storm moderate damage. Actions taken structure to provide full protection coastal storm and for extending il structure. Moderate wind or wave landform exists. Landform may in to fully protect shore/the during a storm. Actions taken to provide a material for full protection and ext	ure adequate with little to to reinforce from major fe of e damage to ot be sufficient major coastal ddition	Description	for infrastructure Den Density Residential ( impacted / 100 feet o	nage and/or Moderate Dwelings ( 1-10 dwelings If shoreline)	
Structure Image 005-010-367-9000-	100-PHO1A.JPG	ucture Docum	ents:			
				Prepared By: Bo	urne Consulting Engine	erir

operty Owner:       Location:       Date:         coal       South Boston - East First Street       7/12/2007         esumed Structure Owner:       Based On Comment:       7/12/2007         coal       Earliest Structure Record:       Estimated Reconstruction/Repair Cost:         coal       Image:       FIRM Map Zone:       FIRM Map Elevation:       \$531,828.00         ngth:       Top Elevation:       FIRM Map Zone:       FIRM Map Elevation:       \$531,828.00         ngth:       Top Elevation:       FIRM Map Zone:       First Structure Record:       Estimated Reconstruction/Repair Cost:         340       Feet       Feet NAVD 88       Feet NGVD       \$531,828.00         fmary Type:       Primary Material:       Primary Height:       10       Feet NGVD         fmary Type:       Secondary Material:       Secondary Height:       Image:       Image:         ructure Summary :       coastal bank. The slope is covered with debris, small cobbles 6 inch-8 inch diameter and is vegetated 2 feet above high tide line. This would enererally provide little protection during a major storm.         Condition       D       Priority       I         fating       Poor       Rating       Low Priority       I         fating       Poor       Rating       Low Priority       I </th <th></th> <th>frastructure Inventory and A Assessment Form</th> <th>Structure ID:</th> <th>Boston 006-060-281-7020-100 y-map-block-parcel-structure</th>		frastructure Inventory and A Assessment Form	Structure ID:	Boston 006-060-281-7020-100 y-map-block-parcel-structure		
testamed Structure Doner:	Property Owner:		Location:		Key. commune	
xnar	Local		South Bosto	n - East First Street		7/12/2007
winer Name:	Presumed Structur	e Owner:	Based On Co	mment:		
oston	Local					
340       A2       10         Feet       Feet NGVD       Feet NGVD         imary Type:       Primary Material:       Primary Height:       Intervent State         icondary Type:       Scondary Material:       Scondary Height:       Intervent State         icondition       D       Procentry       Intervent State       Intervent State         icondition       D       Structure archites at State       Procentry       Intervent State         icondition       Structure Breaded Intervent State       Str	Owner Name: Boston		Earliest Struc	cture Record:	Estimated R	
coastal bank. The slope is covered with debris, small cobbles 6 inch-8 inch diameter and is vegetated 2 feet above high tide line. This would meraily provide little protection during a major storm.         condition       D       Rating       Low Priority         evel of Action       Major       Structure exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or socur.       Description       Inshore Structures Present with Limited potential for Significant Infrastructure Damage         indiring major coastal storm. Landform not adequate to provide protection during major coastal storm. Landform not adequate to provide protection during major coastal storm.       Actions taken to reconstruction can be inflated. Actions taken to recreate landform to adequate to provide protection during major coastal storm.         curdter Images:       Structure Documents:         6x06v281-7020-100-PHO1A_JPG       Structure Documents:	340	AZ NAVD 88 Primary Material: Stone	Feet NO Primary Height: 10 to 15 Feet	10 GVD		
6-060-281-7020-100-PHO1B.JPG 8-080-281-7020-100-PHO1B.JPG	A coastal bank. Th Jenerally provide I Condition Rating Level of Action Description	D Poor Major Structure exhibits advanced levels deterioration, section loss, crackin undermining, and/or scour. Struct strong risk of significant damage a failure during a major coastal ston should be monitored until repairs/leconstruction can be initis taken to reconstruct structure to re capacity to resist a major coastal is Landform eroded, stability threate Landform not adequate to provide during major coastal storm. Action recrease landform to adequate lim	tof g, spalling, ure has ind possible m. Structure ited. Actions statem. hed. protection s taken to is tor full	Priority Rating Action	II Low Priority Future Project Conside Inshore Structures Pre-	ration sent with Limited
Prepared By: Bourne Consulting Enginee	06-060-281-7020-	100-PHO1A JPG	icture Docume	nts:		
Prepared By: Bourne Consulting Enginee						
					Prepared By: Bour	ne Consulting Engineer

	Assessme	int Portin				006-060-267-4000-110 -map-block-parcel-structure
Property Owner:			Location:			Date:
Local			South Bosto	n - Summer Street		7/12/2007
Presumed Structu	re Owner:		Based On Co	omment:		
Local			-			
Owner Name:			Earliest Stru	cture Record:	Estimated R	econstruction/Repair Cost:
Boston Redevelop	ment Authority		1		1	\$257,400.00
and the local division of the local division	levation:	FIRM Map Zone:	FIRM Map Eleve			
150		A2	-	10	. (1) 1 1 1 ( . C. C.	CALCO ADM
	NAVD 88		Feet N		AVERAND AUTON	IN COLUMN TWO IS NOT
Primary Type: Bulkhead/ Seawal	tere protocological	ry Material:	Primary Height: Over 15 Feet		a with bury	2, 23
Secondary Type:	Second	lary Material:	Secondary Heig	ht:	- Antoning Street	1.14
	- 1-		1	100		8 . 12. STF
Structure Summar		hind a nile supporter	wharf The she	et nile is in a fair con	dition with active corrosion	
		nino a pile supporter	A MINISTRA THE SHE			
Condition	с			Priority	н	
Rating	Fair			Rating	Low Priority	
Level of Action Description		ound but may exhibit		Action Description	Future Project Conside Inshore Structures Pres	
	undermining, a to withstand m moderate dam structure to pr coastal storm structure. Mo landform exist to fully protect storm. Actions	section loss, crackin and/or socur. Structu nage, coastal storm v nage, Actions taken ovide full protection and for extending lif derate wind or wave ts. Landform may no tahoreline during a r taken to provide ad li protection and exte	are adequate with little to to reinforce from major a of damage to t be sufficient najor coastal dition		potential for Significant	Infrastructure Damage
Structure Imag	and the second se		ucture Docume	ents:		
006-060-267-4000						

	nfrastructure Inventory and A Assessment Form	2	Structure ID:	Boston 006-060-267-4000-120 map-block-parcel-structure	
Property Owner:		Location:			Date:
Local Presumed Structur	n Ounar	and a second sec	n - Summer Street		7/12/2007
Local	e owner.	Based On Co	mmenic		
Owner Name:		Fadlact Chau	thum Decemb	Following D	
Boston Redevelopment Authority		Earliest Structure Record:		Estimated Reconstruction/Repair Cost: \$162,835.00	
80 Feet Feet M Primary Type: Bulkhead/ Seawall Secondary Type: Revetment	Secondary Material:	FIRM Map Eleva Feet NC Primary Height: 10 to 15 Feet Secondary Heigi 10 to 15 Feet	10 SVD		
Structure Summary A concrete buikhea	ad with riprap in front, mixed size st	ones. The stone s	sizes vary from 2 fee	t by 2 feet by 4 feet blocks	to cobbles. The placed
Condition Rating Level of Action Description	e in good condition but other areas C Fair Moderate Structure is sound but may exhibit deterioration, section loss, crackin	minor	Priority Priority Rating Action Description	are at higher risk to erosio II Low Priority Future Project Consider Inshore Structures Pres potential for Significant	ration ent with Limited
	undermining, and/or scour. Structu to withstand major coastal storm w moderate damage. Actions taken 1 structure to provide full protection coastal storm and for extending lift structure. Moderate wind or wave landform exists. Landform may not to fully protect shoreline during a n storm. Actions taken to provide ad material for full protection and exten	vith little to to reinforce from major e of damage to t be sufficient najor coastal dition			9.9 (9540) (3430) (3490) <b>*</b> (3
	IS: Stru 120-PH012A.JPG 120-PH012B.JPG	cture Docume	nts:		

Prepared By: Bourne Consulting Engineering

https://paper/source       Location:       Date:         coal       South Boston - Summer Street       7/12/2007         https://tesumed.Structure Owner:       Based On Comment:		nfrastructure Inventory and A Assessment Form	lssessment		Town: Boston Structure ID: 006-060-267-4000-200
coal     Date:     7/12/2007       Presumed Structure Owner:     Based On Comment:     7/12/2007       Coal     Earliest Structure Record:     Estimated Reconstruction/Repair Cost:       Scool no dovelopment Authority     Earliest Structure Record:     Estimated Reconstruction/Repair Cost:       420     A2     ID       Feet     Feet NAVD B8     Feet NGVD       Primary Ype:     Secondary Height:     ID       Bachead/ Scawall     Steel     ID       Besed Structure Record:     Estimated Reconstruction/Repair Cost:       Bachnady Spawall     Freet NAVD B8     Freet NGVD       Primary Ype:     Secondary Height:     ID       Bachead/ Scawall     Structure is a steel sheetpile wall with a small concrete cap. The bowing out of the structure       Mainer     D     Priority     III       Mainer     D     Priority     III       Condition     D     Priority     III       Condition     D     Priority     Moderate Priority       Condition     D     Description     III       Structure exhibits advanced sevels of deferroration, section loss, cracking, spainfor, underming, and/or scow, Structure has a steed sheetpile wall with a small concrete cap. The bowing out of the structure Listing     Consider for Action Project Improvement Listing       Condition     D     Consi	Property Owner:				Key: community-map-block-parcel-structure
required Structure Owner:       Based On Comment:         Data       Based On Comment:         Data       Based On Comment:         Data       Based On Comment:         Structure Record:       Structure Record:         Top Elevation:       First Map Zone:         Feet       Freet NAVD BB         Primary Type:       Primary Naterial:         Based Structure Record:       Structure Record:         Based Structure Record:       Structure Record:         Based Structure Record:       Structure Record:         Primary Type:       Secondary Material:       Geordary Height:         Based Structure Record:       Secondary Material:       Geordary Height:         Based Structure Records:       Secondary Material:       Geordary Height:         Based Structure Records:       Secondary Height:       Dit D 15 Feet         Based Structure Records:       Secondary Height:       Dit D 15 Feet         Based Structure Records:       Secondary Height:       Dit D 15 Feet         Based Structure Records:       Secondary Height:       Dit D 15 Feet         Based Structure Records:       Secondary Height:       Dit D 15 Feet         Based Structure Records:       Secondary Height:       Dit D 15 Feet         Based Structure Records Str			-		
Deal       Earliest Structure Record:       Estimated Reconstruction/Repair Cost:         Structure Name:       Top Elevation:       FIRM Map Zone:       FIRM Map Elevation:       Item Structure Record:       Structure Record:         endth:       Arrian Y Top:       Arrian Y Material:       Fore:	Juca		Joong Bost	on - Summer Street	7/12/2007
American Redevelopment Authority       Entet Structure Record:       Stanted Construction/Repair		re Owner:	Based On C	Comment:	
baston Redevelopment Authority       Information in the structure information in the structure information in the structure information in the structure is a steel structure with a small concrete cap. The bowing out of the structure information in the structure is a steel structure with a small concrete cap. The bowing out of the structure is a steel structure in the structure is a steel in the structure in the structure is a steel structure in the structure is a steel structure in the structure is a steel in the structure is a steel in the structure in the structure is a steel in the structure in the structure is a steel in the structure in the structure is a steel in the structure in the structure is a steel in the structure is a steel in the structure is a steel in the structure in the structure is a steel in the structure is a steel in the structure is a steel in the structure in the structure is a steel in the structure is a steel in the structure in the structure is a steel in the structure is a steel in the structure in the structure is a structure in the structure is a structure in the structure is a structure in the structure in the structure in the structure is a structure in the structure in the structure	Local				
angth:       To Elevation:       FRM Map Zone:       FRM Map Elevation:         420       Image:       Image:       Image:       Image:         Feet NAND 88       Primary Material:       Dig to 15 Feet       Image:       Image:       Image:         iscondary Type:       Primary Material:       Dig to 15 Feet       Image:	Owner Name:		Earliest Stru	ucture Record:	Estimated Reconstruction/Repair Cost:
420       A       10         Primary Type:       Primary Material:       Primary Height:       10 13 Freet         Builcheard, Seawall       Exercise       Secondary Height:       10         Builcheard, Seawall       Finder Type:       Secondary Height:       10       Secondary Height:         Builcheard, Seawall       Finder Type:       Secondary Height:       10       Secondary Height:         Builcheard, Seawall       Finder Type:       Secondary Height:       10       Secondary Height:         Indextes that it is in need of repart and in poor condition.       Poor       No       No         Rating       Poor       No       No       No         Condition       O       Poor       No       No         Carl of Action       Meior       Structure exhibits advanced levels of developing and possible structure should be considered wing a major coastal storm. Structure should be constal storm finite of regain full capacity to resist a major coastal storm. Structure should be monited until repairs/reconstruction can be initiated. Actions taken to reconstal storm. Structure should be monited by the coastal storm.       No         Landform moda, stability threadered for the prime regain full capacity to resist a major coastal storm.       No       No         Landform moda, stability threadered to provide protection during major coastal storm.       No       No       N	Boston Redevelop	ment Authority			\$1,053,360.00
he steel is corroring and starting to bow outward. There is a steel sheetpile wall with a small concrete cap. The bowing out of the structure dicates that it is in need of repar and in poor condition. Condition D Rating Poor Sincture exhibits advanced levels of deterioration, section loss, cracking, spalling, undermining, and/or socur. Structure has strong risk of significant damage and possible failure during a major cossible structure should be monitored until repairs/reconstruction can be initiated. Actions taken to reconstruct structure to regain full capacity to resist a major cossible to provide protection during major cossible storm. Landform not adequate to provide protection during major cossible storm. Structure Images: Decorption Structure Images: Decorption Structure Images: Decorption De	420 Feet Feet I Primary Type: Bulkhead/ Seawal Secondary Type:	A2 VAVD 88 Primary Material: Steel Secondary Material:	Feet N Primary Height 10 to 15 Feet	10 IGVD	
06-060-267-4000-200-PHO2A_JPG	ndicates that it is Condition Rating Level of Action Description	In need of repair and in poor condit D Poor Major Structure exhibits advanced level deterioration, section loss, crackir undermining, and/or scour. Struc strong risk of significant damage : tailure during a major coastal should be monitored until repairs/reconstruction can be initii taiken to reconstruct structure to r capacity to resist a major coastal Landform eroded, stability threate Landform not adequate to provide during major coastal storm. Action recreate landform to adequate lim	s of lig, spalling, ture has and possible m. Structure ated. Actions sgain full storm. ned. protection is taken to its for full	Priority Rating Action	III Moderate Priority Consider for Active Project Improvement Listing Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings ( <1 dwelling impacted /
Prepared By: Bourne Consulting Engineeri	_		icture Docum	ents:	
Prepared By: Bourne Consulting Engineeri					

tructure /	nfrastructure Inventory and A Assessment Form	ssessment			Boston 006-060-267-4000-400
				Key: community	-map-block-parcel-structure
operty Owner:		Location:			Date:
ocal		South Bost	on - Summer Street		7/12/2007
esumed Structur	re Owner:	Based On C	comment:		
ocal					
wner Name:		Earliest Stru	ucture Record:	Estimated Re	construction/Repair Cost:
oston Redevelop	ment Authority				\$2,545,620.00
ngth: Top E	Elevation: FIRM Map Zone:	FIRM Map Elev	ation:		1
1015	V4		14		1
Feet Feet M	NAVD 88	Feet N	GVD	server to the	and the
imary Type:	Primary Material:	Primary Height	:	State of the second	The second
ulkhead/ Seawall	,	10 to 15 Feet			A STREET AND
condary Type:	Secondary Material:	Secondary Heig	ht:		
ructure Summar	v:	,			A ALL
steel sheetpile w	vall with a concrete cap and timber p	piles in front. The	e bulkhead is deterior	ating and corrosion has cau	sed holes to form in the
ructure.					
ondition	D		Priority	111	
ating	Poor		Rating	Moderate Priority	
evel of Action	Major Structure exhibits advanced levels	at	Action	Consider for Active Proj Listing	ect Improvement
escription	deterioration, section loss, crackin	g, spalling,	Description	Inshore Structures with	
	undermining, and/or scour. Struct strong risk of significant damage a	ind possible		Infrastructure Damage a Residential Dwellings (	
	failure during a major coastal storr should be monitored until			100 feet of shoreline)	
	repairs/reconstruction can be initia taken to reconstruct structure to re				
	capacity to resist a major coastal : Landform eroded, stability threater	storm.			
	Landform not adequate to provide	protection			
	during major coastal storm. Action recreate landform to adequate limit	ts for full			
	protection from a major coastal sto	xm.			
ucture Image		cture Docume	ents:		
5-060-267-4000-	400-PHO4A.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG 400-PHO4B.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG 400-PHO4B.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG 400-PHO4B.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG 400-PHO4B.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG 400-PHO4B.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG 400-PHO4B.JPG	cture Docume	ents:		
5-060-267-4000- 5-060-267-4000-	400-PHO4A.JPG 400-PHO4B.JPG	cture Docume	ents:		


CZM Coastal Infrastructure Inventory and As Structure Assessment Form	ssessment			Boston 006-060-267-4000-500
Scructure Assessment Form				-map-block-parcel-structure
Property Owner:	Location:			Date:
Local	South Boston -	Summer Street		7/12/2007
Presumed Structure Owner:	Based On Com	ment:		
Owner Name: Boston Redevelopment Authority	Earliest Structu	re Record:	Estimated R	econstruction/Repair Cost: \$3,950,100.00
Length:       Top Elevation:       FIRM Map Zone:         1575        V4         Feet       Feet NAVD 88       V4         Primary Type:       Primary Material:       V4         Bulkhead/ Seawall       Concrete       Secondary Material:         Secondary Type:       Secondary Material:       Secondary Material:         Structure Summary :	Feet NGV Primary Height: 10 to 15 Feet Secondary Height:			
A derelict concrete drydock. The walls are in poor cond as railings and walkways are also corroding. The lock a Condition D Rating Poor Level of Action Major Description Structure exhibits advanced levels deterioration, section loss, cracking undermining, and/or scour. Structu- strong risk of significant damage ar failure during a major coastal storm should be monitored until repairs/reconstruct structure to rej capacity to resist a major coastal storm Landform not adequate to provide p during major coastal storm. Actions recreate landform to adequate limit protection from a major coastal stor	of g, spalling, ure has nd possible h. Structure led. Actions gain full torm. ed. protection s taken to s for full	osed and the doc Priority Rating Action Description	III Moderate Priority Consider for Active Proj Listing Inshore Structures with Infrastructure Damage a Residential Dwellings ( 100 feet of shoreline)	ject Improvement potential for and/or Limited
06-060-267-4000-500-PHO5A.JPG 06-050-267-4000-500-PHO5B.JPG 06-060-267-4000-500-PHO5C.JPG 06-060-267-4000-500-PHO5D.JPG	cture Document	S:		
06-060-257-4000-500-PHO5E.JPG				
			Prepared But, Bourg	ne Consulting Engineering

CZM Coastal I	infrastructure Inventory and A	ssessment		Town:	Boston
Structure	Assessment Form			Structure ID:	005-060-267-4000-600
				Key: community	/-map-block-parcel-structure
Property Owner:		Location:			Date:
Local		South Bosto	on - Summer Street		7/12/2007
Presumed Structu	ire Owner:	Based On C	omment:		
Local					·····
Owner Name:		Earliest Stru	cture Record:	Estimated R	econstruction/Repair Cost:
Boston Redevelop	pment Authority				\$2,583,240.00
ength: Top I	Elevation: FIRM Map Zone:	FIRM Map Elev	ation:		
1030	V4		14	100	
Feet Feet	NAVD 88	Feet N	GVD	are - mailed	
Primary Type:	Primary Material:	Primary Height	:	A Contraction of the second second	THE R. LAND
Bulkhead/ Seawai		10 to 15 Feet		and the second second	
Secondary Type:	Secondary Material:	Secondary Heig	jht:		
structure Summar	IV:				The Part of the
A steel sheet pile	cell construction with timber sheeting	in front of the t	he cells to form cond	rete that was placed as a re	epair for the coroding
teel. There are r	multiple sinkholes located within the	cells indicating so	ome kind of cell failur	e which could not be seen t	from this survey.
Condition	D		Priority	ш	
Rating	Poor		Rating	Moderate Priority	
evel of Action		đ	Action	Consider for Active Pro Listing	ject Improvement
Description	Structure exhibits advanced levels deterioration, section loss, crackin	g, spalling,	Description	Inshore Structures with	potential for
	undermining, and/or scour. Struct strong risk of significant damage a			Infrastructure Damage Residential Dwellings (	
	failure during a major coastal storr should be monitored until			100 feet of shoreline)	and any any any and a
	repairs/reconstruction can be initia				
	taken to reconstruct structure to re capacity to resist a major coastal s				
	Landform eroded, stability threater Landform not adequate to provide				
	during major coastal storm. Action	s taken to			
	recreate landform to adequate limi protection from a major coastal sto				
tructure Imag	jes: Stru	cture Docume	ents:		
	-600-PHO6A.JPG				
	-600-PHO6B.JPG				
06-060-257-4000	-600-PHO6C.JPG				
	· · · · · · · · · · · · · · · · · · ·				
				Prepared By: Bour	ne Consulting Engineeri

Structure Assessment Form	Assessment		Structure ID	Boston 006-060-267-4000-700 y-map-block-parcel-structure
roperty Owner: ocal	Location:			Date:
resumed Structure Owner:	Based On C	on - Summer Street		7/12/2007
wner Name: oston Redevelopment Authority	Earliest Stru	cture Record:	Estimated F	teconstruction/Repair Cost: \$551,760.00
ength:       Top Elevation:       FIRM Map Zone:         220	FIRM Map Elevi Feet N Primary Height: 10 to 15 Feet Secondary Heig	10 GVD	ding from behind the wall	
Condition         D           Rating         Poor           evel of Action         Major           Description         Structure exhibits advanced levels           deterioration, section loss, cracking undermining, and/or secure. Structure strong risk of significant damage a failure during a major coastal storm should be monitored until repairs/reconstruction can be initial taken to reconstruct structure to major coastal. Landform eroded, stability threate Landform not adequate to provide during major coastal storm. Action recreate landform to adequate lim protection from a major coastal storm.	s of log, spalling, ture has and possible m. Structure ated. Actions sgain full storm. ned. protection is taken to lis for full	Priority Rating Action Description	IV High Priority Consider for Next Proje High Value Inshore Str for Infrastructure Dama	act Construction Listing uctures with Potential ge and/or Moderate eilings (1-10 dwellings
	ucture Docume	nte.		
ructure Images: Stru 6-060-267-4000-700-PHO7A_JPG	cture Docume	nis:		
		ng:		

CZM Coastal Infrastructure Inventory and Assessment Structure Assessment Form			12		Boston 006-060-267-4000-800
ou uccure y	ssessment rorm				y-map-block-parcel-structure
Property Owner:		Location:			Date:
Local Presumed Structure Owner:		South Boston - Summer Street Based On Comment:			7/12/2007
Local					
Owner Name: Boston Redevelopment Authority		Earliest Structure Record:		Estimated Reconstruction/Repair Cost: \$359,713.00	
Revetment	Stone	10 to 15 Feet	-	and a state of the	and the second second
Secondary Type: Secondary Material:		Secondary Height:		and the second se	
Structure Summary		1		Constant in the	A STATE
Rating Level of Action Description	Minor Structure observed to exhibit very problems, superficial in nature. Mil to landform is present. Structure adequate to provide protection fron coastal storm with no damage. Ac to prevent / limit future deterioration life of structure.	nor erosion / landform n a major tions taken	Rating Action Description	Low Priority Future Project Conside Inshore Structures Pre potential for Significant	657 RE95301 File 807
tructure Image 06-060-267-4000-		cture Documen	ts:		
06-050-267-4000-					
06-060-267-4000-	800-PHOSC.JPG 800-PHOSD.JPG				
www.uuurzo(~4UUU+	500-FROSD JPG				

	nfrastructure Inventory and A Assessment Form	ssessment	14	Town: Structure ID:	Boston 006-060-267-4000-900	
			Key: community-map-block-parcel-structure			
Property Owner:		Location		D	ate:	
Local Presumed Structure Owner:		South Bost	on - Summer Street	[	7/12/2007	
		Based On Comment:		and the second sec		
Local						
Owner Name:		Earliest Structure Record:		Estimated Reconstruction/Repair Cost:		
Boston Redevelop	ment Authority				\$7,207,200.00	
ength: Top E	Sevation: FIRM Map Zone:	FIRM Map Ele	vation:	internet set	ALL TAXABLE	
2100	V4	1	14			
Feet Feet I	NAVD 88	Feet 1	IGVD	19-2- 20	and the second s	
Primary Type: Bulkhead/ Seawal	Primary Material:	Primary Heigh	<u>ti</u>		E MAN	
	and the second second	Over 15 Feet				
Secondary Type:	Secondary Material:	Secondary Hei	gnt:			
tructure Summar	·:				<b>新省委員會</b>	
A steel bulkhead to	hat is in poor condition with a concre wall. There is a small section that ha	ete cap and cond	trete and timber piles	in front that have mostly faile	d but support a pier	
standing on the t	wais. There is a small seculor that he	is ubrab onumbe	a in front of the sheet	ing as a repair.		
Condition	D		Priority	ш		
Rating	Poor		Rating	Moderate Priority		
Level of Action Description	Major Structure exhibits advanced levels	of	Action	Consider for Active Projec Listing	t Improvement	
Description	deterioration, section loss, crackin undermining, and/or scour. Struct strong risk of significant damage a failure during a major coastal storr should be monitored until	g, spalling, ure has ind possible	Description	Inshore Structures with po Infrastructure Damage an Residential Dwellings ( <1 100 feet of shoreline)	d/or Limited	
	repairs/reconstruction can be initia taken to reconstruct structure to re capacity to resist a major coastal a Landform not adequate to provide during major coastal storm. Action recreate landform to adequate limi protection from a major coastal stor	gain full storm. protection s taken to ts for full				
tructure Image 06-060-267-4000- 06-060-267-4000- 06-060-267-4000	900-PHO9A.JPG	cture Docum	ents:			
					Consulting Engineerir	



Property Owner:       Location:       Date:         Local       [South Boston - Summer Street]       7/12/200         Presumed Structure Owner:       Based On Comment:	Structure Assessment Form	ssessment	Town: Boston
Property Owner:       Location:       Date:         Local       [South Boston - Summer Street]       7/12/200         Presumed Structure Owner:       Based On Comment:			Structure ID: 006-060-267-4010-100
Local     Journel Namer     Estimated Reconstruction/Repair Cost:       Journel Name:     Earliest Structure Record:     Estimated Reconstruction/Repair Cost:     \$708,510.00       Seston Redevelopment Authonity     Ari     Tiz     Feet NavD 88     \$708,510.00       Singth:     Top Elevation:     FiRM Map Zone:     Firet NaVD 8     \$708,510.00       Singth:     Top Elevation:     Firet NaVD 88     Journel Namer Namer     Journel Namer Na			Key: community-map-block-parcel-structure
Local     South Boston - Summer Street     7/12/200       Presumed Structure Owner:     Based On Comment:     Estimated Reconstruction/Repair Cost:       Local     Earliest Structure Record:     Estimated Reconstruction/Repair Cost:       Øoner Name:     FIRM Map Zone:     FIRM Map Elevation:       Soft     Top Elevation:     FIRM Map Zone:     Feet NoVD       Feet     Feet NAVD 88     Primary Material:     Primary Height:       Bulkhead/ Seawall     Concrete     Primary Height:     III       Bulkhead/ Seawall     Concrete     Secondary Height:     III       Structure Summary :     A concrete wall in front of an old steel sheetpile wall. The concrete still has timber forms on it. From what was evident of the structure it appears that it is in fair condition.     III       Condition     C     Priority     III       Rating     Fair     Rating     Moderate Priority       Level of Action     Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermaing, and/or soure; Structure adequate to withstand major coastal storm with title to maderate admage. Actions taken to reinforce atructure to provide full protection form major coastal storm wing a major coastal storm wing an agor coastal storm of a stored addition material for full protection and extended life.	Property Owner:	Location:	Date:
Local       Earliest Structure Record:       Estimated Reconstruction/Repair Cost: \$708,510.00         Local       Earliest Structure Record:       Estimated Reconstruction/Repair Cost: \$708,510.00         Local       Feet Structure Record:       \$208,510.00         Local       Image: Structure Record:       \$208,510.00         Local       Feet NavD 88       Feet NGVD         Primary Type:       Primary Material:       Primary Height:         Builkhead/ Seawall       Concrete       Ji to 15 Feet         Secondary Type:       Secondary Material:       Secondary Height:         Structure Summary :       A concrete wall in fornt of an old steel sheetpile wall. The concrete still has timber forms on it. From what was evident of the structure it appears that it is fair condition         Condition       C       Priority       II         Rating       Fair       Rating       Moderate Priority       Consider for Active Project Improvement Listing         Description       Structure is sound but may exhibit minor delerioration major coastal storm wave damage to landform exists. Landform may not be sufficient to fully protection from major coastal storm and for extending life of structure admage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind one wave damage to landform exists. Landform may not be sufficient to fully protection and extended life.	Local	South Boston - Summer Stre	
Owner Name:       Earliest Structure Record:       Estimated Reconstruction/Repair Cost:         Boston Redevelopment Authority       FiRM Map Zone:       Image: Structure Record:       Image: Structure Record: <t< td=""><td>Presumed Structure Owner:</td><td>Based On Comment:</td><td>,</td></t<>	Presumed Structure Owner:	Based On Comment:	,
Boston Reclevelopment Authority       Fired Vacuation         January Top:       Fire Fire NAVD 88         Primary Type:       Primary Material:         Buildhead/ Seawaii       Concrete         Buildhead/ Seawaii       Concrete         Secondary Type:       Secondary Material:         Structure Summary :       A concrete still has timber forms on it. From what was evident of the structure it appears that it is in fair condition.         Condition       C         Rating       Fair         Rating       Fair         Rating       Fair         Rating       Fair         Busching, and/or scue. Structure adaquate to treinforce structure is sound but may exhibit minor deterioration, section taken to reinforce structure is protection from major coastal storm with fitte to moderate damage. Actions taken to reinforce structure is modered damage. Actions taken to reinforce structure is modered adard to reinforce or shoreitime)         Image: Actions taken to provide addition major coastal storm with or wave damage to handform may not be sufficient to full protection form major coastal storm and extended life.	Local		
Length:       Fight Map Zone:       FIRM Map Zo	Owner Name:	Earliest Structure Record:	Estimated Reconstruction/Repair Cost:
565       A4       12         Feet       Feet NaVD 88       Feet NGVD         Primary Type:       Primary Material:       Primary Height:         Bulkhead/ Seawall       Concrete       10 to 15 Feet         Secondary Type:       Secondary Material:       Secondary Height:       Image: Concrete secondary Height:         Structure Summary :       A concrete wall in front of an old steel sheetpile wall. The concrete still has timber forms on it. From what was evident of the structure it appears that it is in fair condition.         Condition       C       Priority       III         Rating       Fair       Rating       Moderate Priority         Level of Action       Moderate       Consider for Active Project Improvement Listing         Description       Structure is sound but may exhibit minor deterioration, section to section reinforce astructure barrending iffe of structure to provide full protection from major coastal storm with little to moderate dramage. Actions taken to reinforce astructure to provide full protection from major coastal storm actions taken to be sufficient to fruit protection may one be sufficient to fruit protection may not be sufficient to fruit protection and extended life.	Boston Redevelopment Authority		\$708,510.00
A concrete wall in front of an old steel sheetpile wall. The concrete still has timber forms on it. From what was evident of the structure it appears that it is in fair condition.         Condition       C       Priority       III         Rating       Fair       Rating       Moderate Priority         Level of Action       Moderate       Action       Consider for Active Project Improvement Listing         Description       Structure is sound but may exhibit minor deterioration, section loss, cracking, spaling, undermining, and/or scour. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm with little to full protect shoreline during a major coastal storm with little to full protect shoreline during a major coastal storm with little to fully protect shoreline during a major coastal storm may not be sufficient to fully protect shoreline during a major coastal storm may not be sufficient to fully protect shoreline during a major coastal storm material for full protection and extended life.       Noterate difference of the store of	565     A4       Feet     Feet NAVD 88       Primary Type:     Primary Material:       Bulkhead/ Seawall     Concrete       Secondary Type:     Secondary Material:	12 Feet NGVD Primary Height: 10 to 15 Feet	A REAL PROVIDE NO
Rating       Fair       Rating       Moderate Priority         Level of Action       Moderate       Action       Consider for Active Project Improvement Listing         Description       Structure is sound but may exhibit minor deterioration, section loss, cracking, spalling, undermining, and/or socur. Structure adequate to withstand major coastal storm with little to moderate damage. Actions taken to reinforce structure to provide full protection from major coastal storm and for extending life of structure. Moderate wind or wave damage to landform exists. Landform may not be sufficient to full protection and extended life.       Description       Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted / 100 feet of shoreline)	A concrete wall in front of an old steel sheetpile wall.	The concrete still has timber forme	s on it. From what was evident of the structure it appears
tructure Images: Structure Documents:	Rating Fair Level of Action Moderate Description Structure is sound but may exhibit deterioration, section loss, crackin undermining, and/or scour. Structur to withstand major coastal storm v moderate damage. Actions taken structure to provide full protection coastal storm and for extending lif structure. Moderate wind or wave landform exists. Landform may no to fully protect shoreline during a n storm. Actions taken to provide ad	Rating Action trainor g, spalling, ure adequate with little to to reinforce from major e of damage to t be sufficient major coastal dition	Moderate Priority Consider for Active Project Improvement Listing Inshore Structures with potential for Infrastructure Damage and/or Limited Residential Dwellings (<1 dwelling impacted /
06-060-267-4010-100-PHO1A.JPG			
	-	icture Documents:	

Massachusetts Department of Conservation and Recreation Office of Waterways. (2009). *Massachusetts coastal infrastructure inventory and assessment project*. ().

#### **Appendix L: Hazardous Materials Emergency Plan**

### THE COMMONWEALTH OF MASSACHUSETTS EXECUTIVE OFFICE OF PUBLIC SAFETY AND SECURITY

#### MASSACHUSETTS EMERGENCY MANAGEMENT AGENCY 400 Worcester Road Framingham, MA 01702-5399

TO: Massachusetts Tier II Reporting Entities

FROM: Kurt N. Schwartz Director, Massachusetts Emergency Management Agency Chair, Massachusetts State Emergency Response Commission

**THROUGH:** Massachusetts State Emergency Response Commission

CC: Massachusetts Emergency Planning Committees and Fire Departments

**RE:** Tier II Reporting Year 2016: Massachusetts State Emergency Response Commission Reporting Requirements

DATE: December 29, 2016

Facilities covered by the reporting requirements of the federal <u>Emergency Planning and</u> <u>Community Right-to-Know Act (EPCRA)</u> must submit Tier II reports to their: <u>Emergency</u> <u>Planning Committee</u> (EPC), their <u>Local Fire Department</u>, and the <u>State Emergency</u> <u>Response Commission</u> (SERC) annually. Tier II Reports for 2016 must be filed by March 1, 2017.

The Massachusetts Emergency Management Agency (MEMA) has, per Governor's Executive Memorandum, been designated as the State Emergency Response Commission (SERC) in Massachusetts.

This memorandum is being sent to Massachusetts Tier II reporting entities on behalf of the Massachusetts SERC. This memorandum is specific to the Massachusetts SERC Tier II reporting requirements for Reporting Year (RY) 2016.

For Reporting Year 2016, the Massachusetts SERC will require filers to submit reports via

the web-based Tier II Manager System. The SERC will not accept reports developed or submitted via other means.

This only affects how Tier II reports are submitted to the Massachusetts SERC; this does not change any Massachusetts EPC and/or Fire Department reporting requirements.

Filers should contact their respective EPC and Fire Department regarding their reporting requirements.

The fact that you are receiving this memorandum does not necessarily mean you are required to file a Tier II report. It does mean you should determine whether the federal Tier II regulations are applicable to your facility. Please use the reference table below to assist in this determination.

**Tier II reporting thresholds:** 

Extremely hazardous substances (EHS)*	500 pounds (227 kg) or threshold planning quantity, whichever is less.
All other hazardous substances:	10,000 pounds (4,540 kg) for any material that has an SDS
-	HS substances on the EPA website here: rule-extremely-hazardous-substance-list- es-emergency

#### **Use of the Tier II Manager System:**

The Tier II Manager System is now ready for 2016 reporting. The URL for the Tier II system is: <u>http://massachusetts.idsimaps.com</u>.

New filers must first register to use the Tier II Manager System. Registration is a one-time process; if you have already registered you do not need to do so again.

To register, please follow the steps outlined within MEMA's <u>Tier II Manager System: Filer</u> <u>Registration Process</u> memo, which may be found on MEMA's website at: <u>http://www.mass.gov/eopss/agencies/mema/resources/serc/</u>. This memo also contains the system requirements needed to use the Tier II Manager System. Once you have successfully registered, you may use the Tier II Manager System. If you have lost or forgotten your Username and/or Password, you may re-set them via the System's website.

If you have filed a Tier II report with MEMA in a prior year, but do not see this in the System please contact MEMA for assistance.

A User's Guide (comprised of powerpoint slides and FAQ's) and training video will be available on the Tier II Manager System website. To access the User's Guide materials, login to the System, click Continue, then click the green '?'

A link to the training video will be on the Tier II Manager System's home page. The training video provides an overview on how to access and use the System, including changes to the System's 'export tool'. MEMA highly recommends that filers review the User's Guide materials and/or training video prior to developing their RY 2016 report.

To facilitate use of the Tier II Manager System by filers, MEMA is providing a 'Tier II Submit export tool' within the Tier II Manager System. There have been some changes to this tool, and directions on use of this tool may be found within the User's Guide materials and training video.

Once a filer completes and submits a report via the Tier II Manager System, the export tool will convert their report into a format that may be used with the EPA's Tier II Submit software and CAMEO.

The converted file may then be submitted – by the filer – to its respective EPC and Fire Department per their reporting requirements.

As a change from last year, the exported reports function will work off-line. This is being done to minimize disruptions to the System. Detailed instructions on use of the export tool may be found in the User's Guide materials and training video. As an additional change, exported reports will be converted directly into a .t2s format that is compatible with the EPA's Tier II Submit software.

Once you have created a file using the Export Tool it is important that you carefully review the export file to ensure that it is accurate. In particular, if converting a Tier II Manager file to a Tier II Submit file, you may receive Tier II Submit validation errors for: attachments over 2MB; latitude and longitude coordinates; NAICS codes; or facility contact last name. If you receive a validation error, you must open the Tier II Submit file and manually correct the information before the file is sent to the EPC and/or FD.

#### Massachusetts-Specific Tier II Reporting Fields:

Massachusetts uses state-specific Tier II data fields and guidance on how filers should complete these fields is found within the Tier II Manager System.

#### **Other SERC Tier II Reporting Information:**

The following apply to the Massachusetts SERC. Your EPC and/or Fire Department may have different reporting requirements.

§ If you submit a report via the Tier II Manager System you will receive an automatic reply acknowledging receipt.

§ Submitting a report via the Tier II Manager System does NOT fulfill your EPC and Fire Department reporting requirement. Filers must still submit reports to their respective EPC and Fire Department.

**§** There is no filing fee for the SERC.

**§** The SERC does not require submission of SDS' or facility site plans.

§ A list of EPCs in Massachusetts may be found on MEMA's website here: http://www.mass.gov/eopss/docs/mema/resources/serc/all-epc-spreadsheet-november-2016.pdf

If you have any questions regarding this memorandum please contact Mayra Quintana (508.820.204; Mayra.Quintana@state.ma.us); Jeff Timperi (508.820.2019; Jeff.Timperi@state.ma.us); or Paula Krumsiek (508.820.1424; Paula.Krumsiek@state.ma.us).


From: http://www.mass.gov/eopss/agencies/mema/resources/serc/

#### **Appendix M: Vulnerable Population Maps**




**Boston Inner Harbor Vulnerability Population Exposure Map** From: (2017). Surging Seas: Risk Zone Map, | NOAA. Retrieved April 5, 2017

This map defines social vulnerability as the ability of communities to prepare and respond to hazards like flooding. "High" and "low" indicate the 20% most and least vulnerable in coastal areas of each state during a 5 ft. SLR scenario. The yellow color represents low exposure, orange represents medium exposure, and red represents high exposure. Census tract resolution data. Data source: Hazards and Vulnerability Research Institute (HVRI)'s Social Vulnerability Index. (Map layer currently available only within the U.S.)



**Boston Inner Harbor Affected Population Map** From: (2017). Surging Seas: Risk Zone Map, | NOAA. Retrieved April 5, 2017

This map shows the people per square mile exposed to flooding events during 5 ft SLR. The key for this map can be seen below.



#### **Appendix N: Authorship**

Abstract - Primary Writer: All, Primary Editors: All

1.0 Introduction – Primary Writers: All Primary Editors: All

- 2.0 Background Primary Writers: All, Primary Editor: All
  - 2.1 Primary writer: Austen Crawford
  - 2.2 Primary writer: Kyle Whittaker
  - 2.3 Primary writer: All
  - 2.4 Primary writer: All

3.0 Methodology – Primary Writers: All, Primary Editor: All

- 3.1 Primary writer: Austen Crawford and Jacob Bouchard
- 3.2 Primary writer: All
- 3.3 Primary writer: Caroline Warchol, Kyle Whittaker, Jacob Bouchard
- 4.0 Findings Primary Writers: All, Primary Editor: All
  - 4.1 Primary writer: Jacob Bouchard and Kyle Whittaker
  - 4.2 Primary writer: Austen Crawford and Caroline Warchol
  - 4.3 Primary writer: All
  - 4.4 Primary writer: Caroline Warchol and Kyle Whittaker
  - 4.5 Primary writer: Jacob Bouchard and Kyle Whittaker

5.0 Recommendation - Primary Writers: All, Primary Editor: All

- 5.1 Primary writer: Jacob Bouchard and Kyle Whittaker
- 5.2 Primary writer: Jacob Bouchard and Kyle Whittaker
- 6.0 Conclusion- Primary Writers: All, Primary Editor: All
- 7.0 References Primary Writer: Jacob Bouchard
- 8.0 Appendices Primary writer: All