N88-15607

S6 -24
116708
248

1987

NASA/ASEE SUMMER FACULTY FELLOWSHIP PROGRAM

MARSHALL SPACE FLIGHT CENTER
THE UNIVERSITY OF ALABAMA

Prepared by: Mark V. Bower, Ph.D., P.E.

Academic Rank: Assistant Professor

University and Department: The University of Alabama
                                   in Huntsville
                                Department of
                                   Mechanical Engineering

NASA/MSFC:
   Laboratory: Materials and Processes
   Division: Non-Metallic Materials
   Branch: Polymers and Composites

MSFC Colleague: Frank E. Ledbetter III

Date: September 22, 1987

Contract No.:   The University of Alabama
                                   in Huntsville
                                   NGT-01-008-021

INVESTIGATION OF LOW VELOCITY IMPACT DAMAGE ON FILAMENTARY COMPOSITE MATERIALS

by

Mark V. Bower
Assistant Professor of Mechanical Engineering
The University of Alabama in Huntsville
Huntsville, Alabama

ABSTRACT

This report presents the results of an experimental investigation of the affect of low velocity impact on the residual modulus and residual strength of flat filamentary composite materials. Theoretical analysis of composite materials indicates that the modulus of the material must decrease as impact damage increases. This dectease must also correlate to the decrease in residual strength. This study is an initial investigation to verify these hypotheses.

Graphite/epoxy laminates (AS4/3501-6) of various fiber orientations ($8[0°]$, $2[\pm 45°]_8$) were impacted using a falling weight impact tester. Impact energies ranged from 0.42 to 1.55 ft.-lb., with impact velocities from 2.03 to 3.98 ft./sec. The results show that there is a reduction in residual modulus of the plate as the impact energy increases.

ACKNOWLEDGEMENTS

I wish to thank Dr. Gerald Karr, Mr. Frank
Ledbetter, and Dr. Jerry Patterson for the opportunity to
return to Marshall for this third summer in the NASA/ASEE
Summer Faculty Fellowship Program. I have benefitted once
again from the opportunity and I look forward to a long and
fruitful relationship with each of you.

My special thanks goes to Mr. Frank Ledbetter for
his assistance in the conduct of this research. He
contributed many ideas which were essential to the success
of this project. I greatly appreciate the time he took
from his work to assist me throughout the summer.

LIST OF FIGURES

C-2

LIST OF TABLES

INTRODUCTION

The concept of a reinforcing materials with filaments dates back to the time of the Egyptian empire. However, the application of this concept has been, until the twentith century, limited in practice. Developments in chemistry and manufacturing techniques have resulted in the recent growth of the use of filamentary composite materials. As with many of man's developments, the ability to produce a structure from filamentary composite materials has exceeded the understanding and/or the ability to analyize.

The use of filamentary composite materials has grown rapidly since the 1940's. The principal material being glass fibers suspended in an epoxy matrix. The early applications of the material were to non-structural components where the analysis of the additional stiffness provided was not necessary and where damage to the material did not reduce the strength of the structure. The use of fiber glass/epoxy in structural applications has increased as the confidence in the material has grown. Typically, in the early stages of use, analyses performed on these structures involved application of principals derived from the behavior of metals. With the appropriate application of engineering judgement, the structures produced proved to be safe. Today, more advanced fibers are available for use. These new fibers have been developed for application as primary structural members which are ligher than comparable metalic members. As the use of composite materials in critical areas increases it becomes ever more important that the behavior of these materials be thoroughly understood.

One area in which the behavior of filamentary composite materials is only beginning to be understood is in response to damage. Experience with metals has demonstrated that as the level of damage increases in a structure, there is a reduction in the remaining strength of the structure. The damage may be due to either impact loads or fatigue. Composite materials have been shown to have the same basic behavior [1-2]. Composite materials of glass and graphite are more sensitive to impact damage than metals, due to the brittle nature of the fibers. Metals to not demonstrate a reduction in stiffness as the level of damage increases. It is only recently that it has been postulated, and shown, that filamentary composites have a reduction in stiffness

as the level of fatigue increases [3]. It is then proposed that the stiffness of the composite should decrease as the level of impact damage increases. If the modulus of the material is dependent on the damage level, this will adversely affect any analysis of the structure. A positive aspect of this behavior may be that for a specific level of damage, it should be possible to correlate the residual strength with the residual modulus. This then provides a mechanism for easily measuring the residual strength of the structure by non-destructive methods.

The following section presents a statement of the objectives of this research. The third section is a discussion of the rule of mixtures as it applies to the analysis of damaged filamentary composites. The test program is discussed in the section on methodology. The results from the tests performed on the graphite/epoxy panels is presented in the fifth section. Finally, the last section of the report contains the conclusions and recommendations.

OBJECTIVES

The objective of this research is to determine if the
modulus of a filamentary composite material is dependent on
the level of impact damage.

The initial investigation will attempt to determine the
affect of low velocity impact on the residual modulus of
graphite/epoxy composite panels. If the residual modulus
does depend on the impact damage an attempt will be made to
correlate the residual strength with the residual modulus.

THEORY

The rule of mixtures has been proven to be an upper bound
on the modulus for a lamina [1]. The rule of mixtures is:

$$E_1 = E_f v_f + E_m v_m$$

where E_1 is the modulus of elasticity of the lamina in the
principal material direction, E_f and E_m are the moduli of
the fiber and matrix respectively, and v_f and v_m are the
volume fractions of the fiber and matrix respectively. In
the undamaged state

$$v_m = 1 - v_f .$$

Thus, to determine the modulus of the lamina it is only
necessary to know the volume fraction of the fiber or
matrix and the moduli of the fiber and matrix. However, if
the lamina is damaged the rule of mixtures can only provide
an upper bound to the lamina moduli.

The rule of mixtures as adapted to include damage is

$$E_1 = E_f f(v_f, v_d) + E_m v_m$$

where f is a function of the total volume fraction of
fibers and the volume fraction of damaged fibers, v_d. The
form of f is such that

$$f(v_f, 0) = v_f \quad \text{and} \quad f(v_f, v_f) \geq 0.$$

The first restriction provides that in the undamaged state
the origional form of the rule of mixtures applies. The
second provides that there is a contribution to the
stiffness in the principal direction, even if all the
fibers are broken (resulting in a directional particulate
composite). To fully develop f it will be necessary to
analyze the load transfer from one fiber to another around
the region of damaged, e.g. broken fibers. It has been
shown that there is a characteristic length associated with
the load transfer between fibers. This length then will
contribute to the volume fraction of the damaged fiber.
Development of f from a theoretical analysis is left for
future study.

METHODOLOGY

MATERIAL PREPARATION

The material used for this project is Hercules AS4/3501-6
graphite/epoxy. The test panels used were made from
prepreg stock according the to cure cycle indicated. Three
unidirectional panels, 12 inches by 12 inches, with eight
ply were laidup for the tests. Eight ply was selected
based on the ASTM guidelines for determining the principal
material direction properties. An additional set of four
laminate panels were laidup with an orientation of
$2[\pm45°]_s$. This configuration was selected to investigate
the effect of laminate orientation on the level of damage
developed.

The unidirectional panels were cut up into ten specimens,
ten inches by one inch, after the ASTM method. The four
$\pm45°$ panels were cut into seven specimens, eight inches by
one inch.

IMPACT TESTING

An MTS falling weight impact test machine was modified for
use in these tests. The falling weight impact test machine
used a General Research Corporation data aquisition system.
The impact tup of the GRC system had a weight of
approximately four pounds. Combined with the carriage the
total impactor weight was 8.9 lbs. This was determined to
be to large for practical use. After modification the
total weight is 6.49 lbs. This is still a large value,
however, time did no permit further modifications to reduce
the total weight. This introduces a limit to the velocity
of impact.

The anvil of the impact tester has a 0.52 inch hole for the
tup to pass through. This diameter was selected to provide
support to the edges of the one inch wide test specimens.
To minimize the cutting of fibers a nylon plate of .15
inches in thickness was used as a support for the
specimens. The penetrator hole in the nylon back plate has
an outside diameter of 0.53 inches on the specimen side and
an interior diameter of 0.52 inches on the anvil side.
This is also acts to reduce fiber cutting.

For the unidirectional panels nine samples were tested at

drop heights ranging from one inch to three inches. The
tenth sample was not impacted to provide an undamaged
sample for comparison. The maximum drop height was
determined such that there were no fibers cut in an impact.
All samples were impacted at their mid points.

The ±45° laminates were tested in the same maner as the
unidirectional panels. Six of the seven samples were
impacted from drop heights from one inch to 2.25 inches.

TENSILE TESTING

The tensile tests were performed using an INSTRON universal
test machine. Due to equipment problems it was necessary
to measure the specimen elongation by the cross-head
deflection. This is a method which is less than desirable
and which had a strong adverse impact on the results
obtained.

After the samples had been impacted they were prepared for
the tensile tests by attaching clamping pads. These pads
were attached by adhesives to minimize the fiber breakage
due to the jaws of the grips.

The ultimate load for each specimen was obtained directly
from the tensile test. The modulus of each sample is a
tangent modulus obtained from the cross-head position and
load data.

RESULTS

The results obtained from the tests performed are shown in
Figures VI-1 through VI-6 and Tables VI-1 and VI-2.
Figures VI-1 and VI-2 are plots from the impact tests,
while the remaining plots are from the tensile tests.

IMPACT RESULTS

In all of the samples tested the location of the impact
site is clearly observable by the naked eye. In the
unidirectional samples at higher impact energies the fibers
on the side of the sample opposite the impacter were broken
along lines perpendicular to the fibers. In addition, some
of the samples were clearly fractured lengthwise by the
impact.

Figure IV-1 is a plot of the impact load verse time and
impact energy verse time for a unidirectional sample at a
drop height of 2.5 inches. The load trace is
characteristic of the impact of fiber reinforced materials.
At a load of approximately 30 lbs the curve has a
discontinuity which indicates a fiber or fibers breaking.
Again at a load of approximately 190 lbs. there is a sharp
drop in load which indicates breaking several fibers. The
maximum load is achieved, just prior to more fibers
breaking. The oscilations in the load curve at times
greater than 10 msec are not related to physical processes
occuring in the sample. Rather, they relate to the
response of the tup on rebound after impact.

Figure IV-2 is a plot of the impact load verse time and
impact energy verse time for a ±45° laminate sampled at a
drop height of 1.25 inches. Much less fiber breakage is
observed in this plot than in that for the unidirectional
sample. The changes at approximately 90 lbs. and at
approximately 180 lbs. indicate fibers breaking. The loads
at which fibers broke do not appear to have any pattern,
occuring in a seemingly random pattern.

The energies and velocities of the impacts are listed in
Tables VI-1 and VI-2. For the method used to release the
carriage the comparitively small standard deviation in the
energies is quite surprising.

TENSILE RESULTS

Figures IV-3 and IV-4 show results from the tensile tests of the unidirectional samples. Figure IV-3 is a plot of the average ultimate stress verse the impact energy. The bars indicate one standard deviation above and one standard deviation below the average value. A least squares interpolation of the points yields

$$X(\psi) = -42170 \, \psi + 171000$$

where ψ is the impact energy, and X is the ultimate stress. The confidence level for the least squares approximation is 0.49 (1.0 indicating a perfect fit). This indicates that a linear least squares approximation does not fit the data well.

The handbook value for ultimate strength is 312.7 kpsi. The ultimate stress obtained in these tests for the undamaged state do not compare to this value. This is probably due to difficulties encountered in clamping the samples without breaking the fibers.

Figure IV-4 is a plot of the modulus of the unidirectional samples verses the impact energy. As in the ultimate stress plot, the bars indicate one standard deviation above and one standard deviation below the plotted average. The plot indicates that there is a reduction in the modulus as impact energy increases. A linear least squares approximation yields

$$E_1(\psi) = -1112000 \, \psi + 5165000$$

The confidence level for the approximation is 0.53.

The unidirectional modulus obtained in the undamaged state does not compare to the handbook values for this material ($E_1 = 20.7$ Mpsi). One undamaged specimen was tested using a strain indicator. The results of that test produced $E_1 = 20.0$ Mpsi. Since the values are consistent, the conclusion is that the error is systematic, resulting from measuring the elongation by cross-head deflection. This then requires that the data be compared only among these tests or tests performed using the same methods.

The results for the unidirectional samples are listed in Table IV-1.

One important observation of the failure mode for the

unidirectional samples is made. In the samples with
discernable breaks in the fibers the flaws did not
propagate in the plane of the flaw. Rather, the flaw
propagated in the direction of the fibers. The result, a
rectangular opening at the site of impact. This
observation supports the conclusions reached in [4].

Figure IV-5 is a plot of the average ultimate stress for
the ±45° laminates verses impact energy. The bars denote
the plus one and minus one standard deviation band. There
is considerable scatter in the data. Table IV-2 is a list
of the results for the ±45° laminates. Examining the data
it is clear that panel 2 is of higher quality than the
other panels. This contributes to the scatter.

A linear least squares approximation of the data in the
figure yields

$$X(\psi) = -1450\psi + 18740$$

with a confidence of 0.82.

A plot of the modulus verses the impact energy is shown in
Figure IV-6. As with the unidirectional tests the modulus
measured does not compare to the expected value (E = 3.63
Mpsi). This supports the conclusion that the fault lies in
the method of deflection measurement. The plot shows that,
again, the modulus decreases as the impact energy
increases. Applying a power form of the least squares
approximations produces

$$E_1(\psi) = 606400\, \psi^{-0.08}.$$

The confidence level is 0.80. The negative exponent
demonstrates the inverse relation between modulus and
impact engergy.

CONCLUSIONS AND RECOMMENDATIONS

The results from this investigation show that the modulus
of a filamentary composite material decreases as the level
of impact energy and hence damage increases.

Insufficient data was obtained to determine if a
relationship exists between the residual modulus and
residual strength.

This is only a preliminary study. Due to equipment
problems this data is at best self consistent.
Nevertheless, these results call for further investigation.
In these investigations larger sample sets should be used
and the modulus measurements should be performed using an
extenseometer.

Figure VI-1.
Plot of Impact Load and Impact Energy vs.
Time for a Unidirectional Sample.   Drop
Height of 2.5 inches.

Specimen Id	Temp	Veloc.	Energy		Time		Load	Energy	
	(f)	(ft/sec)	(ft-lb)		(msec)		(lb)	(ft-lb)	
				Max Ld	Total		Max	Maxld	Total
40	70.	3.48	1.22	5.95	10.70		255.3	.982	1.209

Figure VI-2.
Plot of Impact Load and Impact Energy vs.
Time for a 2[±45°]$_s$ Laminate. Drop Height
of 1.25 inches.

Specimen Id	Temp	Veloc.	Energy	Time		Load	Energy	
	(f)	(ft/sec)	(ft-lb)	(msec)		(lb)	(ft-lb)	
				Max Ld	Total	Max	Maxld	Total
08	70.	2.52	.64	3.05	6.55	248.8	.640	.524

Figure VI-3.
Plot of Ultimate Tensile Stress vs. Impact Energy for Unidirectional Graphite/Epoxy.

Figure VI-4.
Plot of Modulus, E_1, vs. Impact Energy
**for Unidirectional Graphite/Epoxy.**

Figure VI-5.
Plot of Ultimate Tensile Stress vs. Impact   VI-14
Energy for a 2[±45]$_s$ Graphite/Epoxy Laminate.

Figure VI-6.
Plot of Modulus, E_x, vs. Impact Energy for   VI-15
a $2[\pm 45]_s$ Graphite/Epoxy Laminate (x is the
direction of the axis of the specimen).

TABLE VI-1.
Results from Tensile Tests on Unidirectional Graphite/Epoxy (AS4/3501-6).

Drop Height in	Panel Number	Impact Energy ft-lb	Ultimate Stress kpsi	Modulus Mpsi
0.00	2	0.00	167.1	4.49
	3	0.00	169.3	5.02
	Average	0.00	166.2	4.75
1.00	1	0.52	170.3	4.78
	2	0.45	127.3	4.79
	3	0.44	160.5	4.66
	Average	0.46	152.7	4.74
1.25	1	0.61	155.7	4.87
	2	0.60	102.5	4.06
	3	0.55	113.1	4.19
	Average	0.59	123.8	4.37
1.50	1	0.72	153.8	4.84
	2	0.74	161.5	4.66
	3	0.76	116.5	3.86
	Average	0.74	143.9	4.46
1.75	1	0.87	175.0	4.70
	2	0.84	167.2	4.72
	3	0.95	158.8	4.64
	Average	0.87	167.0	4.69
2.00	1	0.95	138.9	4.39
	2	1.01	98.0	4.05
	3	0.99	184.0	4.78
	Average	0.98	140.3	4.41
2.25	1	1.14	158.9	5.14
	2	1.12	159.2	4.32
	3	1.09	139.2	4.90
	Average	1.12	152.4	4.79
2.50	1	1.18	136.6	4.19
	2	1.22	75.0	3.09
	3	1.13	57.1	3.00
	Average	1.18	152.7	3.43
2.75	1	1.37	59.9	1.84
	2	1.36	165.9	4.03
	3	1.36	100.3	2.96
	Average	1.36	108.7	2.94
3.00	3	1.55	96.7	3.27

TABLE VI-2.
Results from Tensile Tests on 2[±45]$_s$ Graphite/Epoxy (AS4/3501-6) Laminates.

Drop Height in	Panel Number	Impact Energy ft-lb	Ultimate Stress kpsi	Modulus kpsi
0.00	1	0.00	18.8	
	2	0.00	19.9	640.
	3	0.00	18.9	675.
	4	0.00	17.3	563.
	Average	0.00	18.7	626.
1.00	1	0.42	17.6	578.
	2	0.45	21.0	706.
	3	0.41	17.8	672.
	4	0.41	17.1	645.
	Average	0.42	18.4	650.
1.25	1	0.56	17.9	631.
	2	0.64	18.5	614.
	3	0.61	17.3	596.
	4	0.59	16.3	645.
	Average	0.60	17.5	621.
1.50	1	0.70	16.8	620.
	2	0.75	19.7	671.
	3	0.64	18.5	628.
	4	0.72	17.1	655.
	Average	0.72	18.0	643.
1.75	1	0.83	18.0	651.
	2	0.72	20.5	642.
	3	0.80	18.2	675.
	4	0.91	12.1	527.
	Average	0.87	17.2	624.
2.00	1	1.00	17.3	624.
	2	0.99	19.0	658.
	3	0.97	17.8	648.
	4	0.96	15.8	528.
	Average	0.98	17.5	615.
2.25	1	1.10	17.4	648.
	2	1.09	19.5	610.
	3	1.48	15.5	597.
	4	1.12	15.7	492.
	Average	1.36	17.0	587.

REFERENCES

1. Jones, R.M., Mechanics of Composite Materials, McGraw-Hill, New York (1975).

2. Carlsson, L.A. and Pipes, R.B., Experimental Characterization of Advanced Composite Materials, Prentice-Hall, Englewood Cliffs, New Jersey (1987).

3. Almorgrabhy, M., "An Investigation of the Effect of Fatigue Damage on Residual Modulus and Internal Damping" a Master's Thesis, The University of Alabama in Huntsville, in progress.

4. Bower, M.V., "Fracture Toughness Testing of Epoxy Matrix Composite Materials," NASA CR-178709 (1985).