

University of Nebraska - Lincoln  
**DigitalCommons@University of Nebraska - Lincoln**

---

Historical Materials from University of Nebraska-  
Lincoln Extension

Extension

---

April 2014

## CC267 Dairy Producer Waste Guidelines

E. A. Olson

P. H. Cole

Follow this and additional works at: <http://digitalcommons.unl.edu/extensionhist>

---

Olson, E. A. and Cole, P. H., "CC267 Dairy Producer Waste Guidelines" (2014). *Historical Materials from University of Nebraska-Lincoln Extension*. 3111.

<http://digitalcommons.unl.edu/extensionhist/3111>

This Article is brought to you for free and open access by the Extension at DigitalCommons@University of Nebraska - Lincoln. It has been accepted for inclusion in Historical Materials from University of Nebraska-Lincoln Extension by an authorized administrator of DigitalCommons@University of Nebraska - Lincoln.

DAIRY PRODUCER WASTE GUIDELINES

by E. A. Olson and P. H. Cole

CC 267

UNIVERSITY OF NEBR.  
LIBRARY

JUN 17 1988

AGRI  
S  
544.3  
NR33X

1

Producer makes application to  
DEC\* for NPDES\*\* Permit



2

DEC makes inspection and notified producer that waste controls are needed, with copies to SCS and Bureau of Dairies.\*\*\* DEC notice will include dates for submittal of plans and completion of required facilities. An NPDES Permit will be issued containing the same compliance dates. Bureau of Dairies will advise local health official.

2

DEC makes inspection and producer is issued letter of exemption from NPDES Permit Program with copies to SCS and Bureau of Dairies. Bureau of Dairies will advise local health officials of same.

3

If eligible for cost-sharing producers applies for funds at local ASCS office. Producer has system designed by SCS, registered engineer, or others. System designs are also discussed and reviewed with local health officials. (If producers obtain ASCS cost-sharing funds, SCS approval of completed facility will be needed).

3

No further action required by producer unless a change in his operation could result in a possible discharge.

4

When waste control plans are completed the producer has plans reviewed and approved by Bureau of Dairies who will then forward them to DEC.

5

When approved DEC advises producer, with copies to SCS and Bureau of Dairies; DEC reminds producer of date for completion of facilities. Bureau of Dairies advises local health official that plans have been approved.

6

Producer arranges for layout of facilities by designer and engages local contractor or builds himself.

7

When facilities are complete, producer has SCS or registered engineer certify that construction is according to plans. For ASCS Cost-Sharing Funds SCS approval is mandatory.

8

Producer sends certification to DEC to verify compliance with NPDES Permit.

9

Producer must operate and manage system in accordance with NPDES Permit.

10

Approved facilities are subject to inspection by DEC and/or health officials at any time.

\* Department of Environmental Control, 1424 P St., Box 94653, State House Station, Lincoln, NE 68509 Telephone - (402) 471-2186.

\*\* (NPDES) National Pollutant Discharge Elimination System

\*\*\* Bureau of Dairies, State Dept. of Agriculture, State Capitol, Lincoln, NE 68508. Telephone (402) 471-2536

"Prepared by a committee with representatives from Cooperative Extension, University of Nebraska, Department of Environmental Control, Soil Conservation Service, Bureau of Dairies, local health officials, Milk Association and the State Department of Health"

EXTENSION WORK IN "AGRICULTURE, HOME ECONOMICS AND SUBJECTS RELATING THERETO,"  
THE COOPERATIVE EXTENSION SERVICE, INSTITUTE OF AGRICULTURE AND NATURAL RESOURCES,  
UNIVERSITY OF NEBRASKA-LINCOLN, COOPERATING WITH THE COUNTIES AND THE U.S. DEPARTMENT OF AGRICULTURE  
LEO E. LUCAS, DIRECTOR

The Cooperative Extension Service provides information and educational programs to all people without regard to race, color or national origin.