

Gary S. Was

---

# Fundamentals of Radiation Materials Science

Metals and Alloys

With 381 Figures

4) Springer

# Contents

---

*Movies accompanying the text are located at: [www.sitemakerumich.edulwas](http://www.sitemakerumich.edulwas).*

---

## Part I Radiation Damage

---

<b>1 The Radiation Damage Event .....</b>	<b>3</b>
1.1 Neutron—Nucleus Interactions .....	4
1.1.1 Elastic Scattering .....	4
1.1.2 Inelastic Scattering .....	11
1.1.3 ( $n$ , $2n$ ) Reactions .....	14
1.1.4 ( $n$ , $y$ ) Reactions .....	15
1.2 Interactions Between Ions and Atoms .....	17
1.2.1 Interatomic Potentials .....	17
1.2.2 Collision Kinematics .....	24
1.3 Ionization Collisions .....	44
1.3.1 Energy Loss Theory .....	44
1.3.2 Range Calculations .....	57
Nomenclature .....	66
Problems .....	68
References .....	71
<b>2 The Displacement of Atoms .....</b>	<b>73</b>
2.1 Elementary Displacement Theory .....	73
2.1.1 Displacement Probability .....	74
2.1.2 The Kinchin and Pease Model for Atom Displacements .....	75
2.1.3 The Displacement Energy .....	78
2.1.4 The Electron Energy Loss Limit .....	83
2.2 Modifications to the K—P Displacement Model .....	85
2.2.1 Consideration of $E_d$ in the Energy Balance .....	85
2.2.2 Realistic Energy Transfer Cross Sections .....	86
2.2.3 Energy Loss by Electronic Excitation .....	87
2.2.4 Effects of Crystallinity .....	91
2.3 The Displacement Cross Section .....	105
2.3.1 Elastic Scattering .....	106
2.3.2 Inelastic Scattering .....	107
2.3.3 ( $n$ , $2n$ ) and ( $n$ , $y$ ) Displacements .....	107
2.3.4 Modifications to the K—P Model and Total Displacement Cross Section .....	108

## XVI Contents

2.4 Displacement Rates .....	109
2.5 Correlation of Property Changes and Irradiation Dose .....	113
2.6 Displacements from Charged Particle Irradiation .....	115
Nomenclature .....	119
Problems .....	121
References .....	123
<b>3 The Damage Cascade .....</b>	<b>125</b>
3.1 Displacement Mean Free Path .....	125
3.2 Primary Recoil Spectrum .....	126
3.3 Cascade Damage Energy and Cascade Volume .....	131
3.4 Computer Simulations of Radiation Damage .....	133
3.4.1 Binary Collision Approximation (BCA) Method .....	133
3.4.2 Molecular Dynamics (MD) Method .....	136
3.4.3 Kinetic Monte Carlo (KMC) Method .....	138
3.5 Stages of Cascade Development .....	140
3.6 Behavior of Defects within the Cascade .....	143
Nomenclature .....	152
Problems .....	153
References .....	154
<b>4 Point Defect Formation and Diffusion .....</b>	<b>155</b>
4.1 Properties of Irradiation-Induced Defects .....	155
4.1.1 Interstitials .....	155
4.1.2 Multiple Interstitials .....	160
4.1.3 Interstitial—Impurity Complexes .....	161
4.1.4 Vacancies .....	162
4.1.5 Multiple Vacancies .....	162
4.1.6 Solute—Defect and Impurity—Defect Clusters .....	162
4.2 Thermodynamics of Point Defect Formation .....	164
4.3 Diffusion of Point Defects .....	167
4.3.1 Macroscopic Description of Diffusion .....	168
4.3.2 Mechanisms of Diffusion .....	169
4.3.3 Microscopic Description of Diffusion .....	172
4.3.4 Jump Frequency, $\nu$ .....	174
4.3.5 Jump Frequency, $\nu_0$ .....	176
4.3.6 Equations for $D$ .....	177
4.4 Correlated Diffusion .....	180
4.5 Diffusion in Multicomponent Systems .....	182
4.6 Diffusion along High Diffusivity Paths .....	184
Nomenclature .....	187
Problems .....	188
References .....	190

<b>5 Radiation-Enhanced and Diffusion Defect Reaction Rate Theory</b>	191
5.1 Point Defect Balance Equations .....	192
5.1.1 Case 1: Low Temperature, Low Sink Density .....	194
5.1.2 Case 2: Low Temperature, Intermediate Sink Density .....	196
5.1.3 Case 3: Low Temperature, High Sink Density .....	197
5.1.4 Case 4: High Temperature .....	199
5.1.5 Properties of the Point Defect Balance Equations .....	201
5.1.6 Deficiencies of the Simple Point Defect Balance Model ..	203
5.2 Radiation-Enhanced Diffusion .....	203
5.3 Defect Reactions .....	206
5.3.1 Defect Production .....	209
5.3.2 Recombination .....	210
5.3.3 Loss to Sinks .....	210
5.3.4 Sink Strengths .....	211
5.4 Reaction Rate-Controlled Processes .....	211
5.4.1 Defect—Void Interaction .....	211
5.4.2 Defect—Dislocation Interaction .....	212
5.5 Diffusion-Limited Reactions .....	212
5.5.1 Defect—Void Reactions .....	213
5.5.2 Defect—Dislocation Reactions .....	215
5.6 Mixed Rate Control .....	217
5.7 Defect—Grain Boundary Reactions .....	218
5.8 Coherent Precipitates and Solutes .....	219
Nomenclature .....	222
Problems .....	223
References .....	227

---

## Part II Physical Effects of Radiation Damage

---

<b>6 Radiation-Induced Segregation .....</b>	231
6.1 Radiation-Induced Segregation in Concentrated Binary Alloys .....	233
6.1.1 Solution to the Coupled Partial Differential Equations .....	239
6.1.2 Interstitial Binding .....	240
6.1.3 Solute Size Effect .....	241
6.1.4 Effect of Temperature .....	242
6.1.5 Effect of Dose Rate .....	245
6.2 RIS in Ternary Alloys .....	246
6.3 Effect of Local Composition Changes on RIS .....	250
6.4 Effect of Solutes on RIS .....	253
6.5 Examples of RIS in Austenitic Alloys .....	256
6.6 RIS in Ferritic Alloys .....	259
Nomenclature .....	263
Problems .....	264
References .....	265

<b>7 Dislocation Microstructure .....</b>	267
<b>7.1 Dislocation Lines .....</b>	267
7.1.1 Dislocation Motion .....	270
7.1.2 Description of a Dislocation .....	274
7.1.3 Displacements, Strains and Stresses .....	276
7.1.4 Energy of a Dislocation .....	280
7.1.5 Line Tension of a Dislocation .....	281
7.1.6 Forces on a Dislocation .....	283
7.1.7 Interactions Between Dislocations .....	289
7.1.8 Extended Dislocations .....	292
7.1.9 Kinks and Joggs .....	294
<b>7.2 Faulted Loops and Stacking Fault Tetrahedra .....</b>	294
<b>7.3 Defect Clusters .....</b>	298
7.3.1 Fraction of Defects Forming Clusters .....	298
7.3.2 Types of Clusters .....	300
7.3.3 Cluster Mobility .....	304
<b>7.4 Extended Defects .....</b>	306
<b>7.5 Effective Defect Production .....</b>	311
<b>7.6 Nucleation and Growth of Dislocation Loops .....</b>	313
7.6.1 Loop Nucleation .....	313
7.6.2 Clustering Theory .....	319
7.6.3 Production Bias-Driven Cluster Nucleation .....	321
<b>7.7 Dislocation Loop Growth .....</b>	325
<b>7.8 Recovery .....</b>	329
<b>7.9 Evolution of the Interstitial Loop Microstructure .....</b>	332
<b>Nomenclature .....</b>	335
<b>Problems .....</b>	338
<b>References .....</b>	341
<b>8 Irradiation-Induced Voids and Bubbles .....</b>	343
<b>8.1 Void Nucleation .....</b>	343
8.1.1 Equilibrium Void Size Distribution .....	345
8.1.2 Void Nucleation Rate .....	348
8.1.3 Effect of Inert Gas .....	355
8.1.4 Void Nucleation with Production Bias .....	362
<b>8.2 Void Growth .....</b>	365
8.2.1 Defect Absorption Rates and Concentrations at Sink Surfaces .....	366
8.2.2 Point Defect Balances .....	370
<b>8.3 Void Growth Equation .....</b>	372
8.3.1 Temperature Dependence .....	377
8.3.2 Dose Dependence .....	380
8.3.3 Role of Dislocations as Biased Sinks .....	384
8.3.4 Dose Rate Dependence .....	385
8.3.5 Irradiation Variable Shifts .....	388

8.3.6 Stress Dependence .....	393
8.3.7 Effect of RIS .....	397
8.3.8 Effect of Production Bias .....	399
8.3.9 Void Lattices .....	402
8.3.10 Effect of Microstructure and Composition .....	404
8.3.11 Effect of Reactor Operating History .....	409
8.4 Bubble Growth .....	415
8.4.1 Bubble Mechanics .....	415
8.4.2 Growth Law .....	418
8.4.3 Bubble Growth by Dislocation Loop Punching .....	421
8.4.4 Bubble Lattices .....	422
8.4.5 Helium Production .....	423
Nomenclature .....	423
Problems .....	427
References .....	430
<b>9 Phase Stability Under Irradiation .....</b>	<b>433</b>
9.1 Radiation-Induced Segregation and Radiation-Induced Precipitation .....	433
9.2 Recoil Dissolution .....	436
9.3 Radiation Disordering .....	445
9.4 Incoherent Precipitate Nucleation .....	450
9.5 Coherent Precipitate Nucleation .....	455
9.6 Metastable Phases .....	460
9.6.1 Order—Disorder Transformations .....	461
9.6.2 Crystal Structure Transformations .....	461
9.6.3 Quasicrystal Formation .....	463
9.7 Amorphization .....	463
9.7.1 Heat of Compound Formation and Crystal Structure Differences .....	464
9.7.2 Solubility Range of Compounds and Critical Defect Density .....	467
9.7.3 Thermodynamics and Kinetics of Amorphization .....	470
9.8 Phase Stability in Reactor Core Component Alloys .....	480
Nomenclature .....	484
Problems .....	487
References .....	488
<b>10 Unique Effects of Ion Irradiation .....</b>	<b>491</b>
10.1 Ion Irradiation Techniques .....	491
10.2 Composition Changes .....	494
10.2.1 Sputtering .....	495
10.2.2 Gibbsian Adsorption .....	501
10.2.3 Recoil Implantation .....	503
10.2.4 Cascade (Isotropic, Displacement) Mixing .....	506

10.2.5 Combination of Processes Affecting Surface Compositional Changes .....	518
10.2.6 Implant Re-Distribution During Ion Implantation .....	522
10.3 Other Effects of Ion Implantation .....	525
10.3.1 Grain Growth .....	525
10.3.2 Texture .....	527
10.3.3 Dislocation Microstructure .....	528
10.4 High Dose Gas Loading, Blistering and Exfoliation .....	530
10.5 Solid Phases and Inert Gas Bubble Lattices .....	535
Nomenclature .....	537
Problems .....	540
References .....	543
<b>11 Simulation of Neutron Irradiation Effects with Ions .....</b>	<b>545</b>
11.1 Motivation for Using Ion Irradiation as a Surrogate for Neutron Irradiation .....	545
11.2 Review of Aspects of Radiation Damage Relevant to Ion Irradiation .....	547
11.3 Particle Type Dependence of RIS .....	550
11.4 Advantages and Disadvantages of the Various Particle Types .....	557
11.4.1 Electrons .....	558
11.4.2 Heavy Ions .....	562
11.4.3 Protons .....	564
11.5 Irradiation Parameters for Particle Irradiations .....	565
11.6 Emulation of Neutron Irradiation Damage with Proton Irradiation ..	567
Nomenclature .....	574
Problems .....	575
References .....	576

---

### Part III Mechanical Effects of Radiation Damage

---

<b>12 Irradiation Hardening and Deformation .....</b>	<b>581</b>
12.1 Elastic and Plastic Deformation	581
12.1.1 Elasticity .....	581
12.1.2 Plasticity .....	587
12.1.3 Tension Test .....	589
12.1.4 Yield Strength .....	592
12.2 Irradiation Hardening .....	594
12.2.1 Source Hardening .....	595
12.2.2 Friction Hardening .....	597
12.2.3 Superposition of Hardening Mechanisms .....	606
12.2.4 Hardening in Polycrystals .....	612
12.2.5 Saturation of Irradiation Hardening .....	613
12.2.6 Comparison of Measured and Predicted Hardening .....	617
12.2.7 Radiation Anneal Hardening .....	620

12.2.8 The Correlation Between Hardness and Yield Strength . . . . .	622
12.3 Deformation in Irradiated Metals .....	626
12.3.1 Deformation Mechanism Maps .....	630
12.3.2 Localized Deformation .....	632
Nomenclature .....	636
Problems .....	638
References .....	640
<b>13 Fracture and Embrittlement .....</b>	<b>643</b>
13.1 Types of Fracture .....	643
13.2 The Cohesive Strength of Metals .....	644
13.3 Fracture Mechanics .....	647
13.4 Fracture Mechanics Tests .....	653
13.5 Elastic-Plastic Fracture Mechanics .....	655
13.6 Brittle Fracture .....	658
13.7 Irradiation-Induced Embrittlement in Ferritic Steels .....	664
13.7.1 Notched Bar Impact Testing .....	664
13.7.2 DBTT and Reduction in the Upper Shelf Energy .....	666
13.7.3 Master Curve Approach .....	669
13.7.4 Factors Affecting the Degree of Embrittlement .....	673
13.7.5 Embrittlement of Ferritic-Martensitic Steels .....	677
13.7.6 Annealing and Re-Irradiation .....	678
13.7.7 Fatigue .....	679
13.8 Fracture and Fatigue of Austenitic Alloys at Low to Intermediate Temperatures .....	685
13.8.1 Effect of Irradiation on Fracture Toughness .....	686
13.8.2 Effect of Irradiation on Fatigue .....	689
13.9 High-Temperature Embrittlement .....	690
13.9.1 Grain Boundary Voids and Bubbles .....	692
13.9.2 Grain Boundary Sliding .....	697
13.9.3 Grain Boundary Crack Growth .....	700
13.9.4 Fracture Mechanism Maps .....	703
Nomenclature .....	703
Problems .....	705
References .....	707
<b>14 Irradiation Creep and Growth .....</b>	<b>711</b>
14.1 Thermal Creep .....	712
14.1.1 Dislocation Creep .....	716
14.1.2 Diffusional Creep .....	723
14.2 Irradiation Creep .....	725
14.2.1 Stress-Induced Preferential Nucleation of Loops (SIPN) ..	726
14.2.2 Stress-Induced Preferential Absorption (SIPA) .....	729
14.2.3 Climb and Glide due to Preferential Absorption (PAG) ..	731
14.2.4 Climb and Glide Driven by Dislocation Bias .....	733

## XXII Contents

14.2.5 Transient Creep .....	734
14.2.6 Loop Unfaulting .....	738
14.2.7 Recovery Creep .....	739
14.2.8 Diffusional Creep: Why There is no Effect of Irradiation	740
14.2.9 Comparison of Theory with Creep Data .....	741
14.2.10 Irradiation-Modified Deformation Mechanism Map .....	744
14.3 Irradiation Growth and Creep in Zirconium Alloys .....	746
14.3.1 Microstructure of Irradiated Zirconium Alloys .....	747
14.3.2 Irradiation Growth .....	750
14.3.3 Irradiation Creep .....	753
Nomenclature .....	758
Problems .....	760
References .....	762
<b>15 Environmentally Assisted Cracking of Irradiated Metals and Alloys .</b>	<b>765</b>
15.1 Stress Corrosion Cracking: A Tutorial .....	768
15.1.1 SCC Tests .....	770
15.1.2 SCC Processes .....	772
15.1.3 Metallurgical Condition .....	774
15.1.4 Crack Initiation and Crack Propagation .....	774
15.1.5 Mechanisms of Stress Corrosion Cracking .....	783
15.1.6 Predictive Model for Crack Propagation .....	786
15.1.7 Mechanical Fracture Models .....	788
15.1.8 Corrosion Fatigue .....	790
15.1.9 Hydrogen Embrittlement .....	790
15.2 Effects of Irradiation on Water Chemistry .....	791
15.2.1 Radiolysis and its Effect on Corrosion Potential .....	791
15.2.2 Effect of Corrosion Potential on IASCC .....	794
15.3 Service and Laboratory Observations of Irradiation Effects on SCC	797
15.3.1 Austenitic Alloys .....	797
15.3.2 Ferritic Alloys .....	802
15.4 Mechanisms of IASCC .....	805
15.4.1 Grain Boundary Chromium Depletion .....	805
15.4.2 Irradiation Hardening .....	806
15.4.3 Deformation Mode .....	807
15.4.4 Selective Internal Oxidation .....	809
15.4.5 Irradiation-Induced Creep .....	809
Nomenclature .....	809
Problems .....	811
References .....	812
<b>Index .....</b>	<b>815</b>