

SINERGI Vol. 28, No. 1, February 2024: 93-102 http://publikasi.mercubuana.ac.id/index.php/sinergi http://doi.org/10.22441/sinergi.2024.1.010



# Design of supply chain risk mitigation system using house of risk and Fuzzy AHP methods in precast concrete



## Made Arya Teguh Dvaipayana<sup>\*</sup>, Iphov Kumala Sriwana, Yudha Prambudia

Department of Industrial Engineering, School of Industrial and System Engineering, Telkom University, Indonesia

## Abstract

Today's global supply chain has many risk factors. These risks include supply disruptions, supply delays, demand fluctuations, price fluctuations, and exchange rate fluctuations. Risks that arise and cannot be mitigated properly in the supply chain can disrupt the company's business processes in various sectors. Companies in the construction sector when working on construction projects face many risks during the project cycle, especially risks in the supply chain process. Partial risk management, namely only on construction projects and not specifically on the supply chain process, causes potential risks in the supply chain process not to be identified in detail, and mitigation strategies cannot be determined effectively for risks in the supply chain. This research was conducted to identify risks and determine appropriate mitigation strategies using the house of risk as a framework and a fuzzy analytical hierarchy process weighting method to select the best mitigation strategy. The research results showed that there were 26 risk events and 21 risk agents identified, and the 5 best mitigation strategies were chosen from the 10 formulated strategies for a mitigation monitoring system. Based on research results, the best risk mitigation strategy can be used as a reference for risk mitigation actions in the company's supply chain as outlined in the form of a dashboard monitoring system.

# Keywords:

Fuzzy AHP; HOR; Monitoring System; Risk Mitigation; Supply Chain;

#### Article History:

Received: July 5, 2023 Revised: August 18, 2023 Accepted: August 22, 2023 Published: February 2, 2024

#### Corresponding Author:

Made Arya Teguh Dvaipayana Industrial Engineering Department, Telkom University, Indonesia Email:

dvaipayanaarya@gmail.com

This is an open access article under the CC BY-SA license



### **INTRODUCTION**

A country's national economic growth is influenced by various sectors such as the level of national and international trade, the level of public consumption, and the rate of development of a region [1][2]. One of the previously mentioned sectors, namely the regional development level, also plays a role in increasing the national economy [1][3]. Regional development is closely related to infrastructure development to support the development of a region, where this sector is usually handled by parties related to the construction sector [1][3].

The construction sector is a sector or industry that is engaged in infrastructure development activities in an area whose activities consist of various supply chain processes such production as the of material construction materials, delivery. purchasing of raw materials, and planning of supply chain processes carried out to support the projects being carried out [1]. Several construction companies face various constraints and the impact of risks that cannot be mitigated in business processes which result in construction projects not being realized [1]. One of the common business processes found in the construction sector and which has a high potential for risk is supply chain activity [1].

The current supply chain has many risk factors. These risks include supply disruptions, supply delays, demand fluctuations, price fluctuations, and exchange rate fluctuations [2]. Some things cause the supply chain to face a lot of risk, namely due to the increasingly complex level of supply chain activity and changes in one supply chain process sometimes have a negative effect on other processes [3]. The company's supply chain activities, especially on a global scale, will always be affected by an event that cannot be identified beforehand so that considerations for conducting risk management in the supply chain continue to increase and experience renewal [4]. The impact of emerging risks such as supply disruptions, price fluctuations, and demand that cannot be mitigated properly in the supply chain can disrupt the course of the company's business processes in various industrial sectors [2][5]. Companies engaged in the construction sector in carrying out construction projects face many risks during the project cycle. This is due to the various complex needs of various parties, especially the logistics and supply chain departments. The absence of an effective risk analysis tool for project managers means the increased potential risks that arise cannot be effectively mitigated [1].

PT XYZ is a company engaged in the construction sector in the Province of Bali. The company's main business lines are projected contractor service providers and providers of construction materials and products. Construction projects handled by the company are in the form of infrastructure projects and public works such as the construction of asphalt roads and bridges. One of the company business units is the Batching Plant which oversees the production of ready-mix and precast concrete. The supply chain process at the Batching Plant which is a sub-business at the company carries out supply chain activities in the form of procuring raw materials in the form of sand, crushed stone, and cement, then production of precast and readymix concrete products, and delivery of concrete products to the project site.

Regarding risk management, risk management carried out by the company is generally used for projects that are carried out, but it does not cover the details of the supply chain process. Details of production activities, especially in the batching plant and stone crusher plant, are not included in the project risk analysis that has been made. These potential risks that have not been identified also do not have mitigation actions, and if these potential risks arise, supply chain failure or disruption may occur. In addition, the company'ssupply chain does not have a specific risk management tool that is used as an assessment tool for supply chain risk analysis. Construction companies that have concrete production business units need risk analysis and risk impact to determine

mitigation actions to minimize losses that can be caused by product defects and other production disruptions.

Meanwhile, there is a distinct potential risk in supply chain activities at the company which can cause a loss both in time and financially and indirectly also impact construction projects. Potential risks such as machine breakdown, lack of production materials, operator negligence, delivery delays, and other potential risks related to the supply chain that have not been assessed and mitigated, can disrupt future projects [6].

The novelty in this research is in the form of risk assessment results and mitigation strategies with a combined method, namely HOR and Fuzzy AHP which are implemented into an information system in the form of a monitoring dashboard that can be used as a monitoring tool for mitigation actions being carried out. The limitation of this research is that the risk analysis was carried out specifically in the precast concrete supply chain process at the company and the selected mitigation strategy was not further investigated until the implementation stage by the company.

## METHOD

There are three main methods used in conducting this research, namely the house of risk method, risk mitigation strategy with FAHP, and system design [6, 9, 16].

### House of Risk

The House of Risk (HOR) assessment model provides an assessment of risk factors a model that can be used to address risk causes or risk agents [6]. This model consists of two stages, namely HOR 1 and HOR 2, where HOR 1 functions to determine the level of each risk cause or risk agent through the Aggregate Risk Potential (ARP) value [6].

The HOR 2 model is used to provide a priority assessment of risks that arise in the supply chain [8]. The application of the HOR 1 model aims to determine the priority of risk agents to take proactive action according to the significance of the risk [8]. In the first stage of the HOR 1 model, namely identifying risk events, we use the Supply-Chain Operations Reference (SCOR) model as a mapping of business processes specifically for supply chain activities which consist of several parts, namely plan, make, source, deliver, and return [8].

### **Fuzzy AHP**

The Analytical Hierarchy Process (AHP) is a decision-making method where in the decisionmaking process the problems faced are broken down into sub-problems so that the criteria to be processed are obtained by providing an assessment and ranking of each criterion where the initial value determination for each criterion is subjective. based on the scale of the level of importance [6].

The AHP method combined with fuzzy logic aims to anticipate subjective judgments on the criteria obtained from the AHP importance level scale. The scale value on the results of the PCJM questionnaire was replaced with a fuzzy number which aims to tolerate the subjectivity of the assessment on the criteria [9]. The fuzzy-AHP method is used to determine the best risk mitigation strategy.

One of the ways that can be used for the formulation of risk mitigation strategies in the supply chain is benchmarking with the previous relevant research and discussion with company stakeholders. This way is used to formulate specific mitigation strategies for supply chain activities where the formulation of mitigation strategies focuses on increasing the organization's ability to continue to grow and survive business process disruptions [13].

## **Design of Monitoring System**

The System Development Life Cycle (SDLC) waterfall is a method of developing software or information systems with several stages such as analysis of system requirements, design of activities on the system, system implementation, and system testing [16].

System requirements analysis in this study is described by components in the form of risk assessment and risk mitigation results. The design of system activities is illustrated with use case diagrams and data flow diagrams to see what activities can be carried out on the system. System implementation in the form of a monitoring dashboard interface for monitoring the risk mitigation process. Finally, for system testing using user validation.

## **Respondent Characteristics**

This research uses a questionnaire as an assessment tool for risk mitigation strategies with the AHP method which involves the respondent assessor. The following are the as an characteristics of the respondents used as a condition for evaluating the questionnaire, namely, the respondent is part of the company's top-level management with a minimum position of department respondent manager, the understands risk management and the company's supply chain flow, and the respondent's work experience in the company for at least 10 years.





## **Research Methodology**

Figure 1 shows the stages carried out during the research. The initial stage is data collection and problem definition of risks from the supply chain process in the company. The second stage is risk identification to obtain risk events and risk agents using the SCOR model with each process namely plan, source, make, deliver, and return.

The next step is to evaluate the risk event and agent and calculate the ARP value using HOR. Next is the formulation of a risk mitigation strategy based on a risk agent with high-risk potential. Next is an assessment of risk mitigation strategies to obtain the best strategy for each risk agent using the fuzzy-AHP method. The final stage is designing a risk mitigation monitoring system using the SDLC waterfall method.

## **RESULTS AND DISCUSSION** Risk Event and Risk Agent Identification

The first stage in efforts to achieve supply chain risk mitigation is to identify risks in the supply chain process. Identification results are obtained by mapping business processes or supply chain processes for precast concrete products using the SCOR model [9].

Identification of risks in the sourcing process relates to several risks that may arise or have the potential to cause losses in the material procurement process. The supply chain process is carried out in material procurement, namely the purchase of excavation areas for sand and stone, the purchase of cement materials for concrete mixtures, as well as the preparation of documents or letters of purchase of materials.

The manufacturing activities in the supply chain of precast concrete products at the company are divided into two manufacturing processes. The first is a manufacturing process to produce sand and crushed stone materials and the second is a precast concrete manufacturing process.

The fourth stage in SCOR in mapping and identifying risks is the delivery process. This process is related to the activity of shipping excavated materials and shipping precast concrete to the construction project site.

The final stage in mapping the supply chain process with the SCOR model is the return process. This process is related to the process of returning defective products or those that do not meet consumer specifications and requests. The return process that occurs in the supply chain of concrete products is that there are precast concrete products that are not by the quality so they cannot be used and sent to the project location.

#### **Risk Event and Risk Agent Assessment**

Risk grouping is carried out based on five risk categories using process categories in the SCOR model: plan-process risk, source-process risk, make-process risk, deliver-process risk, and return-process risk. Risk grouping is carried out to determine the types of risks that have the potential to arise in the concrete product supply chain process [8].

Table 1. Identification of Risk Event

E1       The error rate of forecasting the demand for precast concrete is high       2.29         E2       Production material data does not match actual conditions       2.52         E3       The available fleet data does not match the actual number       1.26         E4       Sudden changes in procurement planning changes       3.00         E5       Procurement planning changes       2.62         E6       The supplier is unable to fulfill the material request       1.26         E7       Cancellation of material purchases at suppliers       2.52         E8       Incorrect purchase amount data       2.00         E9       Material payments to suppliers are delayed       7.32         E10       Production planning changes       2.00         E11       Delay in unloading material production of sand and crushed stone       1.26         E13       There are scattered production materials       7.23         E14       The dust of crushed stone becomes a pollutant in the STC area       7.61         E15       Incorrect products do not meet the quality and specifications       1.59         E17       The size and dimensions of the concrete molding tools are not ready for use       3.11         E20       The size and dimensions of the concrete frame are out of specification       2.00         E18	Code	Risk Event	Severity
the demand for precast concrete is high2.29E2Production material data does not match actual conditions2.52E3The available fleet data does not match the actual number1.26E4Sudden changes in procurement planning, production, and fleet allocation3.00E5Procurement planning changes2.62E6The supplier is unable to fulfill the material request1.26E7Cancellation of material purchases at suppliers2.52E8Incorrect purchase amount data with procurement planning data2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area2.52E15Incorrect crushed stone size production materials2.00E16Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete molding tools are not ready for use3.11E20The size and dimensions of the barching plant2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials production materials2.29E23Material excavation delay specification2.00E24Delays in material delivery to STC2.00E25Delay in delivery of ma	E1	The error rate of forecasting	20.0.ij
Concrete is high2.29E2Production material data does not match actual conditions2.52E3The available fleet data does not match the actual number1.26E4Sudden changes in procurement planning, production, and fleet allocation3.00E5Procurement planning changes2.62E6The supplier is unable to fulfill the material request1.26E7Cancellation of material purchases at suppliers2.52E8Incorrect purchase amount data with procurement planning changes2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production materials7.23E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications2.00E17The concrete mixture is not evenly distributed in the mold specification2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials pecification2.00E23<		the demand for precast	
E2       Production material data does not match actual conditions       2.52         E3       The available fleet data does not match the actual number       1.26         E4       Sudden changes in procurement planning, production, and fleet allocation       3.00         E5       Procurement planning changes       2.62         E6       The supplier is unable to fulfill the material request       1.26         E7       Cancellation of material purchases at suppliers       2.52         E8       Incorrect purchase amount data with procurement planning data       2.00         E9       Material payments to suppliers are delayed       7.32         E10       Production planning changes       2.00         E11       Delay in unloading material production of sand and crushed stone       1.26         E13       There are scattered production materials       7.23         E14       The dust of crushed stone becomes a pollutant in the STC area       7.61         E15       Incorrect crushed stone size       2.00         E16       Concrete molding tools are not ready for use       3.11         E20       The size and dimensions of the concrete frame are out of specification       2.00         E14       The does of production materials       2.52         E15       Incorrect concrete mixture is not ev		concrete is high	2.29
doesnotmatchactualconditions2.52E3The available fleet data does not match the actual number1.26E4Suddenchangesinproduction,andfleet allocation3.00E5Procurementplanning changes2.62E6The supplier is unable to fulfill the material request1.26E7Cancellationofmurchases at suppliers2.52E8Incorrect purchase amount data2.00E9Materialpaymentstosuppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material production of sand and crushed stone1.26E13Therearescattered production materialsproduction materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size2.00E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E33Material	E2	Production material data	
Conditions2.52E3The available fleet data does not match the actual number1.26E4Suddenchangesinprocurementplanning, production,and fleet allocation3.00E5Procurementplanning changes2.62E6The supplier is unable to fulfill the material request1.26E7Cancellationof material purchases at suppliers2.52E8Incorrect purchase amount datawith procurement planning data2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in del		does not match actual	
E3       The available fleet data does not match the actual number       1.26         E4       Sudden       changes       in procurement       planning, production,       and       fleet allocation         E5       Procurement       planning       2.62         E6       The supplier is unable to fulfill the material request       1.26         E7       Cancellation       of material purchases at suppliers       2.52         E8       Incorrect purchase amount data       with procurement planning data       2.00         E9       Material       payments       to suppliers are delayed       7.32         E10       Production planning changes       2.00         E11       Delay in unloading material from the transport fleet       2.00         E12       Postponement of material production materials       7.23         E14       The dust of crushed stone becomes a pollutant in the STC area       7.61         E15       Incorrect crushed stone size       2.00         E16       Concrete mixture is not eventy distributed in the mold       2.00         E17       The concrete mixture is not eventy distributed in the mold       2.00         E16       Concrete molding tools are not ready for use       3.11         E20       The size and dimensions of the concrete f	50	conditions	2.52
FeatureNot match the actual number1.26E4Suddenchangesinprocurementplanning,production, and fleetallocation3.00E5Procurementplanningchanges2.62E6The supplier is unable to fulfillthe material request1.26E7Cancellationofpurchases at suppliers2.52E8Incorrect purchase amountdatawith procurementplanning data2.00E9Material paymentstosuppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading materialfrom the transport fleet2.00E12Postponement of materialproduction of sand andcrushed stone1.26E13There are scatteredproduction materials7.23E14The dust of crushed stonebecomes a pollutant in the STC areaSTC area7.61E15Incorrect crushed stone sizeE10Concrete molding tools are not ready for useand specification2.00E18Cracks on the surface of precast concreteprecast concrete frame are out of specification2.00E21An incorrect concrete mix ratioE20The size and dimensions of the concrete frame are out of specificationE21An incorrect concrete mix ratioE22Lack of production materialsE	E3	The available fleet data does	4.00
L4       Subtern       changes       11         procurement       planning,       3.00         E5       Procurement       planning         changes       2.62         E6       The supplier is unable to fulfill         the material request       1.26         E7       Cancellation       of material         purchases at suppliers       2.52         E8       Incorrect purchase amount       data         data       with       procurement         planning data       2.00         E9       Material payments       to         suppliers are delayed       7.32         E10       Production planning changes       2.00         E11       Delay in unloading material       from the transport fleet       2.00         E13       There       are       scattered       production of sand and         crushed stone       1.26       E13       There are scattered       production materials       7.23         E14       The dust of crushed stone       becomes a pollutant in the       STC area       7.61         E15       Incorrect crushed stone size       2.00       E16       Concrete moldure to the mold       2.00         E17       <	<b>E</b> 4	Sudden changes in	1.26
production,andfleetallocation3.00E5Procurementplanningchanges2.62E6The supplier is unable to fulfillthe material request1.26E7Cancellation ofmaterial request2.52E8Incorrect purchase amountdatawithplanning data2.00E9Material paymentstosuppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading materialfrom the transport fleet2.00E12Postponement ofmaterialproduction of sand andcrushed stone1.26E13There are scatteredproduction materials7.23E14The dust of crushed stonebecomes a pollutant in the STC area7.61E15Incorrect crushed stone size2.00E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00 <td>L4</td> <td>procurement planning</td> <td></td>	L4	procurement planning	
allocation3.00E5Procurementplanningchanges2.62E6The supplier is unable to fulfillthe material request1.26E7Cancellation of materialpurchases at suppliers2.52E8Incorrect purchase amountdatawith procurementplanning data2.00E9Material payments tosuppliers are delayed7.32E10Production planning changesCushed stone2.00E11Delay in unloading materialfrom the transport fleet2.00E12Postponement of materialproduction of sand andcrushed stone1.26E13There are scatteredproduction materials7.23E14The dust of crushed stonebecomes a pollutant in theSTC area7.61E15Incorrect crushed stone sizeE10Concrete products do notmeet the quality andspecifications1.59E17The concrete mixture is notevenly distributed in the mold2.00E18Cracks on the surface ofprecast concrete2.52E19Concrete frame are out ofspecification2.00E21An incorrect concrete mixratio2.00E22Lack of production materials229E23Material excavation delay1.59E24Delays in material delivery to STCSTC2.00<		production and fleet	
E5Procurement changesplanning changesE6The supplier is unable to fulfill the material request1.26E7Cancellation of material purchases at suppliers2.52E8Incorrect purchase amount data with procurement planning data2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications1.59E17The concrete mixture is not evenly distributed in the mold specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials specification2.00E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant2.00E26The high amount of defective concrete2.00		allocation	3.00
changes2.62E6The supplier is unable to fulfill the material request1.26E7Cancellation of material purchases at suppliers2.52E8Incorrect purchase amount data with procurement planning data2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area2.00E15Incorrect crushed stone size evenly distributed in the mold specifications1.59E17The concrete mixture is not evenly distributed in the mold specification2.00E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials sto the batching plant2.00E23Material excavation delay sto the batching plant2.00E24Delays in material delivery to STC concrete2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E5	Procurement planning	
E6       The supplier is unable to fulfill the material request       1.26         E7       Cancellation of material purchases at suppliers       2.52         E8       Incorrect purchase amount data with procurement planning data       2.00         E9       Material payments to suppliers are delayed       7.32         E10       Production planning changes       2.00         E11       Delay in unloading material from the transport fleet       2.00         E12       Postponement of material production of sand and crushed stone       1.26         E13       There are scattered production materials       7.23         E14       The dust of crushed stone becomes a pollutant in the STC area       7.61         E15       Incorrect crushed stone size becomes a pollutant in the STC area       7.61         E17       The concrete mixture is not evenly distributed in the mold specifications       2.00         E18       Cracks on the surface of precast concrete       3.11         E20       The size and dimensions of the concrete frame are out of specification       2.00         E21       An incorrect concrete mix ratio       2.00         E22       Lack of production materials       2.29         E23       Material excavatin delay the batching plant <td< td=""><td></td><td>changes</td><td>2.62</td></td<>		changes	2.62
the material request1.26E7Cancellation of material purchases at suppliers2.52E8Incorrect purchase amount data with procurement planning data2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications1.59E17The concrete mixture is not evenly distributed in the mold specification2.00E18Cracks on the surface of precast concrete2.52E19Concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials the concrete frame are out of specification2.00E23Material excavation delay to the batching plant1.59E24Delays in material delivery to STC STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E6	The supplier is unable to fulfill	
E7Cancellation of material purchases at suppliers2.52E8Incorrect purchase amount data with procurement planning data2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications1.59E17The concrete mixture is not evenly distributed in the mold specification2.00E18Cracks on the surface of precast concrete2.52E19Concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials stream2.29E23Material ecavation delay to the batching plant1.59E26The high amount of defective concrete2.29	_	the material request	1.26
E8Incorrect purchases at suppliers2.52E8Incorrect purchase amount data with procurement planning data2.00E9Material payments to suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications1.59E17The concrete mixture is not evenly distributed in the mold specification2.00E18Cracks on the surface of precast concrete2.52E19Concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials sto the batching plant2.29E23Material ecavation delay to the batching plant1.59E26The high amount of defective concrete2.29	E7	Cancellation of material	0.50
E8       Incorrect purchase amount planning data       2.00         E9       Material payments to suppliers are delayed       7.32         E10       Production planning changes       2.00         E11       Delay in unloading material from the transport fleet       2.00         E12       Postponement of material production of sand and crushed stone       1.26         E13       There are scattered production materials       7.23         E14       The dust of crushed stone becomes a pollutant in the STC area       7.61         E15       Incorrect crushed stone size       2.00         E16       Concrete products do not meet the quality and specifications       1.59         E17       The concrete mixture is not evenly distributed in the mold       2.00         E18       Cracks on the surface of precast concrete       2.52         E19       Concrete frame are out of specification       2.00         E21       An incorrect concrete mix ratio       2.00         E22       Lack of production materials       2.29         E23       Material ecavation delay       1.59         E24       Delays in material delivery to STC       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defe	<b>F</b> 0	purchases at suppliers	2.52
Latawith planning data2.00E9Material suppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications1.59E17The concrete mixture is not evenly distributed in the mold specification2.00E18Cracks on the surface of precast concrete3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials stream2.29E23Material ecavation delay stream1.59E24Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	Eð	data with procurement	
E9Material payments suppliers are delayed7.32E10Production planning changes from the transport fleet2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are production materials7.23E14There are production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size products do not meet the quality and specifications2.00E17The concrete mixture is not evenly distributed in the mold precast concrete2.00E18Cracks on the surface of precast concrete3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials STC2.29E23Material excavation delay to the batching plant1.59E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29		planning data	2 00
EtaSuppliers are delayed7.32E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications2.00E17The concrete mixture is not evenly distributed in the mold precast concrete2.52E19Concrete frame are out of specification3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials STC2.29E23Material excavation delay to the batching plant1.59E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	F9	Material payments to	2.00
E10Production planning changes2.00E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications2.00E17The concrete mixture is not evenly distributed in the mold precast concrete2.52E19Concrete frame are out of specification3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials 2.292.29E23Material excavation delay to the batching plant1.59E26Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	LU	suppliers are delayed	7.32
E11Delay in unloading material from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications2.00E17The concrete mixture is not evenly distributed in the mold precast concrete2.00E18Cracks on the surface of precast concrete frame are out of specification3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials STC2.29E23Material excavation delay to the batching plant1.59E26Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E10	Production planning changes	2.00
from the transport fleet2.00E12Postponement of material production of sand and crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size evenly distributed in the mold specifications2.00E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold precast concrete2.00E18Cracks on the surface of precast concrete3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials STC2.29E23Material excavation delay to the batching plant1.59E25Delays in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E11	Delay in unloading material	
E12       Postponement of material production of sand and crushed stone       1.26         E13       There are scattered production materials       7.23         E14       The dust of crushed stone becomes a pollutant in the STC area       7.61         E15       Incorrect crushed stone size       2.00         E16       Concrete products do not meet the quality and specifications       1.59         E17       The concrete mixture is not evenly distributed in the mold       2.00         E18       Cracks on the surface of precast concrete       2.52         E19       Concrete frame are out of specification       2.00         E20       The size and dimensions of the concrete frame are out of specification       2.00         E21       An incorrect concrete mix ratio       2.00         E22       Lack of production materials       2.29         E23       Material excavation delay       1.59         E24       Delays in material delivery to STC       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defective concrete       2.29		from the transport fleet	2.00
productionofsandandcrushed stone1.26E13Therearescatteredproduction materials7.23E14The dust of crushed stonebecomes a pollutant in theSTC area7.61E15Incorrect crushed stone size2.00E16Concrete products do notmeetmeetthe quality andspecifications1.59E17The concrete mixture is notevenly distributed in the mold2.00E18Cracks on the surface ofprecast concrete2.52E19Concrete molding tools arenot ready for use3.11E20The size and dimensions ofthe concrete frame are out ofspecificationspecification2.00E21An incorrect concrete mixratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery toSTC2.00E25Delay in delivery of materialsto the batching plant7.61E26The high amount of defectiveconcrete2.29	E12	Postponement of material	
crushed stone1.26E13There are scattered production materials7.23E14The dust of crushed stone becomes a pollutant in the STC area7.61E15Incorrect crushed stone size specifications2.00E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay to the batching plant1.59E25Delays in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29		production of sand and	
E13       There are scattered production materials       7.23         E14       The dust of crushed stone becomes a pollutant in the STC area       7.61         E15       Incorrect crushed stone size       2.00         E16       Concrete products do not meet the quality and specifications       1.59         E17       The concrete mixture is not evenly distributed in the mold       2.00         E18       Cracks on the surface of precast concrete       2.52         E19       Concrete frame are out of specification       3.11         E20       The size and dimensions of the concrete frame are out of specification       2.00         E21       An incorrect concrete mix ratio       2.00         E22       Lack of production materials       2.29         E23       Material excavation delay       1.59         E24       Delays in material delivery to STC       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defective concrete       2.29	540	crushed stone	1.26
E14The dust of crushed stone becomes a pollutant in the STC area7.23E15Incorrect crushed stone size STC area2.00E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E13	I here are scattered	7 22
E14       The ddst of eldshed stole         becomes a pollutant in the STC area       7.61         E15       Incorrect crushed stone size       2.00         E16       Concrete products do not meet the quality and specifications       1.59         E17       The concrete mixture is not evenly distributed in the mold       2.00         E18       Cracks on the surface of precast concrete       2.52         E19       Concrete molding tools are not ready for use       3.11         E20       The size and dimensions of the concrete frame are out of specification       2.00         E21       An incorrect concrete mix ratio       2.00         E22       Lack of production materials       2.29         E23       Material excavation delay       1.59         E24       Delays in material delivery to STC       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defective concrete       2.29	F14	The dust of crushed stone	1.23
STC area7.61E15Incorrect crushed stone size2.00E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	L 17	becomes a pollutant in the	
E15Incorrect crushed stone size2.00E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are 		STC area	7.61
E16Concrete products do not meet the quality and specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay sTC1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E15	Incorrect crushed stone size	2.00
meetthequalityandspecifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay STC1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E16	Concrete products do not	
specifications1.59E17The concrete mixture is not evenly distributed in the mold2.00E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay STC1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29		meet the quality and	
<ul> <li>E17 The concrete mixture is not evenly distributed in the mold 2.00</li> <li>E18 Cracks on the surface of precast concrete 2.52</li> <li>E19 Concrete molding tools are not ready for use 3.11</li> <li>E20 The size and dimensions of the concrete frame are out of specification 2.00</li> <li>E21 An incorrect concrete mix ratio 2.00</li> <li>E22 Lack of production materials 2.29</li> <li>E23 Material excavation delay 1.59</li> <li>E24 Delays in material delivery to STC 2.00</li> <li>E25 Delay in delivery of materials to the batching plant 7.61</li> <li>E26 The high amount of defective concrete 2.29</li> </ul>		specifications	1.59
E18Cracks on the surface of precast concrete2.52E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification3.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E17	The concrete mixture is not	2.00
E18       Clacks on the sunace of precast concrete       2.52         E19       Concrete molding tools are not ready for use       3.11         E20       The size and dimensions of the concrete frame are out of specification       2.00         E21       An incorrect concrete mix ratio       2.00         E22       Lack of production materials       2.29         E23       Material excavation delay       1.59         E24       Delays in material delivery to STC       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defective concrete       2.29	E10	Creake on the surface of	2.00
E19Concrete molding tools are not ready for use3.11E20The size and dimensions of the concrete frame are out of specification3.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	EIO	precast concrete	2 52
E10       Denote the minimum tests and dimensions of the concrete frame are out of specification       3.11         E20       The size and dimensions of the concrete frame are out of specification       2.00         E21       An incorrect concrete mix ratio       2.00         E22       Lack of production materials       2.29         E23       Material excavation delay       1.59         E24       Delays in material delivery to STC       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defective concrete       2.29	F19	Concrete molding tools are	2.02
E20The size and dimensions of the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29		not ready for use	3.11
the concrete frame are out of specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29	E20	The size and dimensions of	-
specification2.00E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29		the concrete frame are out of	
E21An incorrect concrete mix ratio2.00E22Lack of production materials2.29E23Material excavation delay1.59E24Delays in material delivery to STC2.00E25Delay in delivery of materials to the batching plant7.61E26The high amount of defective concrete2.29		specification	2.00
ratio 2.00 E22 Lack of production materials 2.29 E23 Material excavation delay 1.59 E24 Delays in material delivery to STC 2.00 E25 Delay in delivery of materials to the batching plant 7.61 E26 The high amount of defective concrete 2.29	E21	An incorrect concrete mix	
E22       Lack of production materials       2.29         E23       Material excavation delay       1.59         E24       Delays in material delivery to       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defective concrete       2.29	500	ratio	2.00
E23       Material excavation delay       1.59         E24       Delays in material delivery to STC       2.00         E25       Delay in delivery of materials to the batching plant       7.61         E26       The high amount of defective concrete       2.29	E22	Lack of production materials	2.29
E24     Delays in material derivery to       STC     2.00       E25     Delay in delivery of materials to the batching plant     7.61       E26     The high amount of defective concrete     2.29	E23	Delays in material delivery to	1.59
E25 Delay in delivery of materials to the batching plant 7.61 E26 The high amount of defective concrete 2.29	624	STC	2 00
to the batching plant     7.61       E26     The high amount of defective concrete     2.29	E25	Delay in delivery of materials	2.00
E26 The high amount of defective concrete 2.29		to the batching plant	7.61
concrete 2.29	E26	The high amount of defective	-
		concrete	2.29

Code	Risk Agent	Occurrence
A1	Significant increase in	
	demand for precast concrete	8.96
A2	Error measurement and data	
	recording	1.44
A3	Changes in material and fuel	
	prices	9.32
A4	Material suppliers do not	
	meet the criteria	1.26
A5	Failure to negotiate the	
	purchase price of materials	8.32
A6	Inadequate material storage	7.00
	locations	7.32
A7	Power supply interruption	1.82
A8	Soli material that is still	4.00
A 0	Attached to the rock	1.82
A9	Damage to the tool when	
	screening the size of crushed	0 22
A10	Operator pogligoneo	6.65
A10 A11	The material load exceeds	0.05
AII	the carrying capacity	1 44
A12	The concrete press is not	1.44
A12	clean and there is residual	
	concrete	8 96
A13	Iron frame design error	1.26
A14	Data errors and concrete mix	
	specifications	1.82
A15	Poor concrete vibration	
	process	1.44
A16	The drying temperature of the	
	concrete is too high	1.59
A17	The number of requests for	
	batching plant materials is	
	not fulfilled	1.44
A18	Transport fleet engine	
	damage during delivery	1.59
A19	The number of transport	
	fleets does not meet shipping	
	needs	2.52
A20	I rattic disruption during	E 05
4.04	aeiivery	5.65
A21	ine demand for precast	1 1 1
	concrete sent is insuncient	1.44

Table 2. Identification of Risk Agent

The results of risk identification obtained as many as twenty-six risk events which are divided into five risk categories. The Plan risk category includes risk events E1, E2, E3 and E4, the Source risk category includes risk events E5, E6, E7, E8, E9, the Make risk category includes risk events E10, E11, E12, E13, E14, E15, E16, E17, E18, E19, E20, E21, the Deliver risk category includes risk events E23, E24, E25 and the Return risk category includes risk event E26.

Furthermore, all the results of the risk identification will be assessed on the severity risk event scale or how big the negative impact will be if the risk occurs in the concrete product supply chain. Assessment or assessment of risks that have been identified for both risk events and risk agents have the same scale range, namely 1-10, but have differences in usage [6]. For the risk event, the severity value is used to determine the level of negative impact on the supply chain, while for the risk agent, the occurrence value is

used to see how likely the cause of the risk is to occur.

Table 1 and Table 2 show the severity and occurrence assessment results. This value consists of 10 values that have a low to high impact on the supply chain if the risk appears in the supply chain process. The assessment was carried out by respondents, namely precast concrete stakeholders of the company. Based on the assessment of 3 respondents, to obtain a single severity or occurrence value, the Geomean formula is used.

$$G = \sqrt[k]{Ai \, x \, Bi \, x \dots x \, Mi} \tag{1}$$

*Ai*: The i-th severity/occurrence value of the first respondent

*Bi*: The i-th severity/occurrence value of the second respondent

*Mi*: The i-th severity/occurrence value of the k-th respondent

k: Number of respondents

G: Geomean value

#### **ARP Calculation**

The ARP value is used to determine the ranking of the risk agent obtained by determining the relationship between each risk event and each risk agent [8]. The calculation of the ARP value is done by multiplying the value of the occurrence *j* risk agent by the total multiplication of each *i-risk* event which is mutually related to the *j* risk agent for each severity value of each related risk.

$$ARPj = Oj \left(\sum Si \times Rij\right)$$
(2)

Oj: Occurrence value for risk agent -j

Si: Severity value for risk event -i

*Rij:* Correlation value for each risk event -i to risk agent -j.

ARPj: Aggregate risk potential value for risk agent - j

The relationship value used to assess the relationship between each risk event and the risk agent, namely a value of 0 for no relationship, a value of 1 for a weak relationship, a value of 3 for a moderate relationship, and a value of 9 for a strong relationship [8].

Table 3 shows all the results of calculating ARP values performed using Microsoft Excel software. There are eleven ARP values obtained based on the number of identified risk agents. The calculation results also show the ranking of each risk agent with the highest rating based on the largest ARP value.

After all ARP values are obtained, then each ARP value rating and the cumulative percentage of ARP values are determined. This percentage is used to determine the level of contribution of the risk agent to the total ARP which is depicted on the Pareto diagram in Figure 2. The level of contribution to the total ARP is used to determine the priority risk agent for the formulation of risk mitigation strategies.

Based on the visualization of the cumulative value in the Pareto diagram of Figure 2, risk agents are selected that contribute to the total ARP value of 80%, which includes risk agents A6, A3, A12, A5, A9, A1, A20, A10, A19, and A14. According to [6], the cumulative ARP value that is included in 75% of the ARP value is a risk agent that is prioritized for mitigation, while according to [8], the cumulative ARP value used for mitigation that is equal to 80% of the total ARP.

#### **Mitigation Strategy Formulation**

The formulation of a risk mitigation strategy is used to determine proactive actions against risk agents who have a high level of risk based on the calculation of the ARP value and cumulative percentage [13]. The formulation of a supply chain risk mitigation strategy for precast concrete products at the company was formulated through a literature review relevant to the risk agent being mitigated, as well as the selection of strategies carried out with the company 's supply chain stakeholders.

Several risk mitigation strategies can be formulated for each selected risk agent. The following is a risk mitigation strategy that can be used as a supply chain risk mitigation action in Table 3

#### Strategy Weighting with Fuzzy AHP

Assessment and ranking of each risk mitigation strategy that has been formulated aim to determine the best strategy that can be used as a mitigation measure and can minimize the impact of risks in the supply chain process of precast concrete products.

Assessment and ranking use the fuzzy-AHP method where a risk agent that has several mitigation actions will determine the value of each mitigation action by comparing one mitigation action with another using a pairwise comparison matrix.

The consistency test on the AHP method aims to find out if a criterion assessment carried out by respondents is consistent or inconsistent. The results of the assessment criteria can be called consistent if they meet the requirements of the consistency test with the results of the consistency ratio value obtained from dividing the consistency index divided by the random index, namely  $\leq 0.1$ .

$$CR = \frac{CI}{RI} = \frac{\frac{\lambda \max - n}{n-1}}{\frac{RI}{RI}}$$
(3)

CR: Consistency ratio

*CI*: Consistency index

RI: Random index of n-criteria

n: Number of criteria

The defuzzification stage aims to form a value based on the fuzzy numbers in the normalization matrix. The results of this defuzzification are used to determine the rank of each strategy.

Based on Table 4, it can be seen that each strategy weighs in each risk agent. Furthermore, the strategy that has the best weight is used as a risk mitigation action that is selected, and its level of effectiveness is assessed.



Figure 2. Percent Cumulative Risk Agent

Strategy Formulation	Code
Application of 5S in material and	S1
concrete production	
Determination of strategic stocks	S2
in precast concrete warehouses	
Using third-party logistics	S3
services for the delivery of	
materials and concrete	
Make purchase contracts with	S4
consideration of fluctuations in	
material or fuel prices	
Ensure that the production	S5
department understands the SOP	
and concrete production flow	
Periodic checks and repairs on	S6
production machines or fleet	
machines	
Planning on alternative material	S7
suppliers	
Audit every result of recording	S8
data on sales, materials, fleet,	
and production	
Determine SOP for evaluation of	S9
material suppliers	_
Tracking each delivery fleet to	S10
monitor the real-time location	

Table 4. Weight of Each Strategy				
Crisp Valu	ie Co	de F	Rank	
0.13	S	1	5	
0.06	S	2	6	
0.01	S	3	10	
0.04	S	4	8	
0.17	S	5	2	
0.13	S	6	4	
0.05	S	7	7	
0.22	S	8	1	
0.04	S	9	9	
0.14	S1	0	3	
Table 5. Fuzzy NumberAHP ScaleFuzzy Number1(1,1,1)				
2		(1,2,3)		
3		(2,3,4)		
4		(3,4,5)		
5		(4,5,6)		
6		(5,6,7)		
1		(6,7,8)		
8		(7,8,9)		
9		(8,9,10)		
Table 6	. Consis	tency T	est	
Assessment	CI	RI	CR	
Matrix 1	0.11	1.49	0.072	
Matrix 2	0.13	1.49	0.090	
Matrix 3	0.12	1.49	0.083	
Table 7. Normalization of Fuzzy Number				
Crisp Value		<u>M</u>	<u> </u>	
S1	0.11	0.13	0.15	
S2	0.06	0.06	0.06	
S3	0.02	0.01	0.01	
54	0.05	0.04	0.04	
55	0.14	0.17	0.20	
50	0.11	0.13	0.16	
57	0.05	0.05	0.04	
58	0.18	0.22	0.27	
59	0.05	0.04	0.04	
510	0.12	0.14	0.17	
$F = (\frac{1}{2})(\alpha U + M)$	+ (1 - 0	α)L)		

F: The crisp value

U: The upper value of normalization fuzzy number

*M:* The middle value of normalization fuzzy number

L: The lower value of normalization fuzzy number  $\alpha$ : Confidence level (0 - 1)

## Selection of The Best Mitigation Strategy

Table 5 shows the fuzzy number that is paired in each AHP scale from 1 to 9. From (3), all the consistency tests for each matrix are consistent. Table 6 listed the consistency results. Table 7 shows the normalization result for each fuzzy number on the mitigation strategy.

The best risk mitigation strategy was selected from as many as 5 of the 10 best risk mitigation strategies assessed. Mitigation

strategies with the five highest values based on (4) as shown in Table 4 are, S8, S5, S10, S6, and S1.

#### **Mitigation Monitoring System Design**

The design of the monitoring system is intended to monitor the risks and mitigation actions carried out on the supply chain process to monitor the running conditions of the supply chain of precast concrete products.

### **Describing System Activities**

A use case diagram is a diagram that functions to describe activities that can be carried out by system users. In this diagram, system users are the company supply chain stakeholders who can enter and manage risk and assessment data.

Based on Figure 3, several activities that can be carried out by users in interaction with the monitoring system consist of inputting risk event data and risk agents, inputting the results of severity and occurrence assessments, inputting correlation values and difficulty levels, inputting data on mitigation strategies and performing mitigation strategy monitoring, and the flow is depicted in Figure 4.

All these flows of activities are shown in Figure 4 below. The flow of activities diagram shows how the User interacts with the System. There are two main parts namely the User, which gives input, and the System will show the output of feedback.



Figure 3. Use Case Diagram Monitoring System

(4)



Figure 4. Activity Diagram (BPMN)



Figure 5. Data Flow Diagram



Figure 6. Dashboard Monitoring Interface

The data flow diagram in Figure 5, shows the flow of information and data used to carry out risk assessments and risk mitigation strategies so that the calculated data on House of Risk 1 can

Scenario	Testing Case	Expected Result	Testing Result
View	The sees risk	The	Succeed
Dashboard	information	dashboard	
	and mitigation	page	
	strategies	successfully	
		opened	
Input risk	The user	Risk and	Succeed
and	inputs risk	mitigation	
mitigation	data and	data	
data	mitigation	entered	
	data	successfully	
Manage	the user	Risk and	Succeed
risk and	changes The	mitigation	
mitigation	risk data and	data	
data	mitigation	changed	
	data	successfully	
Delete risk	The user	Risk and	Succeed
and	deletes risk	mitigation	
mitigation	data and	data were	
data	mitigation	deleted	
	data	successfully	

Table 4. Validation Testing

be displayed on the monitoring dashboard and all activities carried out by stakeholders can be carried out on the precast concrete product risk mitigation monitoring system.

## **System Implementation**

Figure 6 shows risk monitoring and assessment system is made in the form of a dashboard that is useful for supply chain stakeholders to carry out risk monitoring and assessment and risk mitigation strategies that have been made. This dashboard includes two main sections, namely the risk assessment and the risk mitigation strategy assessment page.

## **System Validation**

Table 8 shows the validation testing of the risk mitigation system. There are four testing scenarios based on activities that are described in the use case diagram. All results of system validation testing were successfully carried out.

### CONCLUSION

Partial risk management is carried out by the company, namely only on project risk management, but has not been carried out in the supply chain process causing disruption to the supply chain which cannot be mitigated. House of risk was chosen as a method for identification and risk assessment with the identification results in the form of 26 risk events and 21 risk agents, with 10 risk agents selected as risks that contributed 80% to the ARP value. The 10 selected risk agents were mitigated using the fuzzy-AHP method as a strategic assessment to choose the best risk mitigation strategy as outlined in the monitoring system. Based on research results, identification and assessment of risks and risk mitigation strategies can be carried out on the system, with proposed best five mitigation actions that can be carried out sequentially, namely S8, S5, S10, S6, and S1.

Suggestions for academic research in the form of further research that needs to pay attention to the study of supply chain processes up to the concept of sustainability and the environment with the consideration of experts in the field.

### ACKNOWLEDGMENT

This research was supported by the company in data collection and discussion on research. The difficulty experienced in this research is detailing all complex precast concrete supply chain activities starting from the stages of planning, material procurement, delivery, concrete production, and storage. It requires an in-depth understanding of the application of the SCOR model as a tool for mapping supply chain activities which will later be used to carry out more detailed risk identification.

In addition, we thank our colleagues from the company and Telkom University who provided insight and expertise that greatly assisted the research, although they may not agree with all the interpretations/conclusions of this paper.

Recommendations that can be proposed for further research are to be able to carry out more specific risk identification by involving green aspects and supply chain sustainability and to be able to monitor the implementation of risk mitigation strategies in one period.

## REFERENCES

- [1] P. Shojaei, and S. A. Haeri, "Development of Supply Chain Risk Management Approaches for Construction Projects: A Grounded Theory Approach". Computer & Industrial Engineering, vol. 128, pp. 837-850 2019, doi: 10.1016/j.cie.2018.11.045
- [2] L. S. Kuburi, U. Umar and A. N. Oyedeji, "Risk Assessment of Petrol Filling Stations in a Metropolitical City of Kaduna State, Nigeria," *SINERGI*, vol. 27, no. 2, pp. 179-184, 2023, doi: 10.22441/sinergi.2023. 2.005
- [3] D. I. Navis et al., "Designing risk mitigation monitoring system of the asset recovery process in a sustainable supply chain using an integrated neutrosophic TOPSIS-CRITIC method," *The 2nd International Conference on Design, Energy, Materials and*

*Manufacture 2021* (ICDEMM 2021), vol. 2568, 2023, doi: 10.1063/5.0116203

- [4] Y. C. Saglam, S. Y. Cankaya and B. Sezen "Proactive Risk Mitigation Strategies and Supply Chain Risk Management Performance: An Empirical Analysis for Manufacturing Firms in Turkey", Journal of Manufacturing Technology Management, vol. 32, no.6, pp. 1224-1244, 2021, doi: 10.1108/JMTM-08-2019-0299
- [5] A. S. Nguyen and M. T. Le, " A Risk Management Tool for the Reverse Supply Chain Network," *International Conference on System Science and Engineering*, 2019, pp. 391-396, doi: 10.1109/ICSSE.2019. 8823470
- [6] R. Rakadhitya, N. Hartono, and Laurence, "Case Study Mitigation of Supply Chain with Integration of House of Risk and Fuzzy Logic at PT X," *Journal of Integrated System,* vol. 2, no. 2, pp. 192-207. 2019, doi: 10.28932/jisv2i2.1974
- [7] R. Jachryandestama, P. Nursetyowati, S. Fairus and B. Pamungkas, "Risk Analysis in Jakarta's Waste Cooking Oil to Biodiesel Green Supply Chain using Group AHP Approach," *SINERGI*, vol. 25, no. 2, pp. 227-236, 2021, doi: 10.22441/sinergi.2021. 2.014
- [8] H. L. Ma and W-H. C. Wong, "A Fuzzybased House of Risk Assessment Method for Manufacturers in Global Supply Chain", *Industrial Management & Data System*, vol. 118, no. 7, pp. 1463-1476, 2018, doi: 10.1108/IMDS-10-2017-0467.
- [9] Y. Liu, C. M. Eckert, and C. Earl, "A Review of Fuzzy AHP Methods for Decision-Making with Subjective Judgements", *Expert System with Applications*, vol. 161, pp. 113738, 2020, doi: 10.1016/j.eswa.2020.113738
- [10] R. Rostamzadeh, M. K. Ghorabaee, K. Govindan, A. Esmaeili and H. B. Nobar, "Evaluation of Sustainable Supply Chain Risk Management Using an Integrated Fuzzy TOPSIS – CRITIC Approach," *Journal* of Cleaner Production, vol. 175, pp. 651-669, 2018, doi: 10.1016/j.jclepro.2017.12. 071
- [11] S. Campbell et al., "Purposive Sampling: Complex or Simple? Research Case Example," *Journal of Research in Nursing*, vol. 28, no. 8, pp. 652-651, 2020
- [12] A. Chapelle. "Operational Risk Management," Cornwall: Wiley, 2019
- [13] I. Nugraha, S. Dewi, Y. C. Winursito, R. N. Sari and M. C. Islami. "Risk Analysis and Mitigation in Supply Chain with House of Risk (HOR) Approach in Bag Manufacturing

Industry at XYZ Ltd," Asia Pacific International Conference on Industrial Engineering and Operation Management, 2022, pp. 2621-2632.

- [14] K. S. Shahed, A. Azeem, S. M. Ali, and M. A. Moktadir, "A Supply Chain Disruption Risk Mitigation Model to Manage COVID-19 Pandemic Risk," *Environmental Science and Pollution Research*, 2021, doi: 10.1007/s11356-020-12289-4
- [15] M. F. Firdaus and H. C. Wahyuni, " Risk Analysis Using HOR and SWOT on Spice Importers Based on Organization and Industrial Taxonomy," *Journal of Applied Industrial Engineering-University of PGRI AdiBuana*, vol. 4, no. 02, pp. 125-130, 2021, doi: 10.36456/tibuana.4.02.4005.125-130
- [16] T. Rijanandi et al, "Web-Based Application withSDLC Waterfall Method on Population Administration and Registration Information System (Case Study: Karangklesem Village, Purwokerto)," Jurnal Teknik Informatika (JUTIF), vol. 3, no.1, pp. 99-104, 2022, doi: 10.20884/1.jutif.2022.3.1. 145
- [17] A. Nawaz, A. Waqar, S. A. Shah, M. Sajid, and M. I. Khalid, "An Innovative Framework for Risk Management in Construction Project in Developing Countries: Evidence from Pakistan," Young Researchers in Insurance and Risk Management, vol. 7, no. 1, 2019, doi: 10.3390/risks7010024
- [18] P. S. Muttaqin, N. Novitasari, and E. B. Setyawan, "Risk Management Analysis in Container Yard Development Projects in Eastern Indonesia," *Journal of Mechanical Electrical and Industrial Engineering*, vol. 5, no. 1, pp. 173-186, 2023, doi: 10.46574/ motivection.v5i1.183
- [19] N. H. Qudsy, J. W. Soetjipto and S. Arifin. "Project Delay Risk Analysis Using the House of Risk Method," *Journal of Applied Civil Engineering and Infrastructure Technology*, vol. 2, no. 1, pp. 19-26, 2021, doi: 10.52158/jaceit. v2i1.149
- [20] F. Moi and I.G.A.N. Purnawirati. "Risk Management Analysis on the Waebetu – Tarawaja New Road Development Project," *Jurnal Talenta Sipil*, vol. 4, no. 1, pp. 79-84, 2021, doi: 10.33087/talentasipil. v4i1.52
- [21] R. Sharma, A. Shisodia, S. Kamble, A. Gunasekaran, and A. Belhadi, "Agriculture Supply Chain Risk and COVID-19 Mitigation Strategies and Implication for the Practitioner," *International Journal of Logistic Research and Application*, pp. 1-27, 2020, doi: 10.1080/13675567.2020.1830049

- [22] J. Shen, X. Ma, and W. Qiao, "A Model to Evaluate the Effectiveness of the Maritime Shipping Risk Mitigation System by Entropybased Capability Degradation Analysis," *International Journal of Environmental Research and Public Health,* vol. 19, no. 15, ID: 9338, 2022, doi: 10.3390/ijerph19159338
- [23] A. Sibevei et al, "Developing a Risk Reduction Support System for Health System in Iran: A Case Study in Blood Supply Chain Management," *International Journal of Environmental Research and Public Health,* vol. 19, no. 4, ID: 2139, 2022, doi: 10.3390/ijerph19042139
- [24] R. Sukwadi and A. Caesar, "An Integrated Approach for Supply Chain Risk Management," *Engineering Management in Production and Services*, vol. 14, pp. 38-48, 2022, doi: 10.2478/emj-2022-0004
- [25] W. A. Teniwut et al, "Asymmetric Information Mitigation on Seaweed Supply Chain Using House of Risk and Fuzzy AHP Approach," *agriTECH*, vol. 40, no. 3, pp. 242-253, 2020, doi: 10.22146/agritech.27770
- [26] R. Ojha et al., "Bayesian Network Modelling for Supply Chain Risk Propagation," *International Journal of Production Research,* vol. 56, no. 17, pp. 5759-5819, 2018, doi: 10.1080/00207543.2018.1467059
- [27] R. A. Permana, A. Y. Ridwan, F. Yulianti and P. G. Artha Kusuma, "Design of Food Security System Monitoring and Risk Mitigation of Rice Distribution in Indonesia Bureau of Logistics," 2019 IEEE 13th International Conference on Telecommunication Systems, Services, and Applications (TSSA), Bali, Indonesia, 2019, pp. 249-254, doi: 10.1109/TSSA48701. 2019.8985485.
- [28] D. A. Alfazah, A. Yanuar Ridwan, F. Yulianti and P. G. Artha Kusuma, "Designing Procurement Process Monitoring Dashboard for Supporting Food Security Supply Chain Risk Management System in Indonesian Bureau of Logistics," 2019 IEEE 13th International Conference on Telecommunication Systems, Services, and Applications (TSSA), Bali, Indonesia, 2019, pp. 255-260, doi: 10.1109/TSSA48701. 2019.8985503.
- [29] N. Ruhyat et al., "Hydrodynamic study of drying on Qisthi Hindi using a Fluidized Bed Dryer," *Journal of Integrated and Advanced Engineering (JIAE)*, vol. 2, no. 2, pp. 97-106, 2022, doi: 10.51662/jiae.v2i2.67