

## General Disclaimer

### One or more of the Following Statements may affect this Document


- This document has been reproduced from the best copy furnished by the organizational source. It is being released in the interest of making available as much information as possible.
- This document may contain data, which exceeds the sheet parameters. It was furnished in this condition by the organizational source and is the best copy available.
- This document may contain tone-on-tone or color graphs, charts and/or pictures, which have been reproduced in black and white.
- This document is paginated as submitted by the original source.
- Portions of this document are not fully legible due to the historical nature of some of the material. However, it is the best reproduction available from the original submission.

SHOCK TESTING OF A NITROGEN TANK (CRYO DIFFUSION  
TYPE 220 VLR) ON THE MIDDLE WEIGHT SHOCK STAND

L.J. Wevers

(NASA-TM-77747)	SHOCK TESTING OF A NITROGEN	N85-15183
TANK (CRYO DIFFUSION TYPE 220 VLR) ON THE		
MIDDLE WEIGHT SHOCK STAND (National		
Aeronautics and Space Administration)	16 p	Unclas
HC A02/MF A01	CSCD 20K G3/39	11019

Translation of "Schokbeproeving van een stikstofvat (Cryo Diffusion Type 220 VLR) op de middengewicht schokbank," Institute TNO for Mechanical Constructions, Delft (Netherlands), November 1972.  
Report-4848/27, pp. 1-15



## STANDARD TITLE PAGE

1. Report No. NASA TM-77747	2. Government Accession No.	3. Recipient's Catalog No.	
4. Title and Subtitle SHOCK TESTING OF A NITROGEN TANK (CRYO DIFFUSION TYPE 220 VLR) ON THE MIDDLE WEIGHT SHOCK STAND		5. Report Date December 1984	6. Performing Organization Code
		8. Performing Organization Report No.	
7. Author(s) L. J. Wevers		10. Work Unit No.	
		11. Contract or Grant No. NASW-4005	
9. Performing Organization Name and Address Leo Kanner Associates Redwood City, California 94063		13. Type of Report and Period Covered Translation	
		14. Sponsoring Agency Code	
12. Sponsoring Agency Name and Address National Aeronautics and Space Administration Washington, D.C. 20546		15. Supplementary Notes Translation of "Schokbeproeving van een stikstofvat (Cryo Diffusion Type 220 VLR) op de middengewicht schokbank," Institute TNO for Mechanical Constructions, Delft (Netherlands), November, 1972. Report-4848/27, pp. 1-15.  73X 80888	
16. Abstract Results of shock tests on type 200 VLR nitrogen tank are given.			
17. Key Words (Selected by Author(s))		18. Distribution Statement  Unclassified - Unlimited	
19. Security Classif. (of this report) Unclassified	20. Security Classif. (of this page) Unclassified	21. No. of Pages 14	22.

SHOCK TESTING OF A NITROGEN TANK (CRYO DIFFUSION TYPE 220 VLR) ON THE  
MIDDLE WEIGHT SHOCK STAND

L. J. Weavers

Institute TNO for Mechanical Constructions, Delft

I. INTRODUCTION

/1\*

At the order of the Federal defense organization TNO in behalf of the Ministry of Defense (Navy), a nitrogen tank, type 200 VLR, of the Cryoson Technical Laboratory at Middenbeemster was shock tested. The test was performed in the laboratory of the Institute TNO for Mechanical Constructions at Delft on the Middle weight Shock stand.

The dates of the test were May 24 and 25, 1972.

The Ministry of Defense (Navy) had determined that the maximal increase on the nitrogen tank, mounted on YS 50-75-LBS springs, had to be in the area between 6 and 8 g. (g = increase of the force of gravitation). The apparatus had to be shocked in two directions perpendicular to each other.

Altogether two shock tests have been made.

During the shocktests the movement of the surface and the movement of the nitrogen tank were registered on a magnetic tape. The measuring system is discussed extensively in /3/.

The filling degree of the nitrogen tank with the vertical test was approximately 75%. For the horizontal test the filling degree was reduced to 25%. The manufacturer Cryoson deemed this necessary for safety reasons.

---

\*Numbers in the margin indicate pagination in the foreign text.

The damage inspection after each shocktest was done by the IWECO-TNO as far as this was possible.

There was not found any indication of visible exterior damage.

The nitrogen tank was returned to the Optical Industry N.V. at Delft after the tests.

## 2. MOUNTING OF THE NITROGEN TANK

2

The IWECO has the nitrogen tank mounted to springs of the type Yielding Strip 50-75 LBS-decktype for the vertical as well as for the horizontal test. The springs were somewhat modified by making normal holes of the slits.

The pictures, figures 1 to 5, give a clear picture of the mounting. It is indicated at the pictures where the movements of the nitrogen tank are measured during the shocktests.

3. SETUP OF THE MIDDLE WEIGHT SHOCK STAND

/3

The work method of the shock stand is not discussed in the present report. Reference to this has been made to /1/ and /3/.

The setup of the stand with the tests performed is found in Table I.

TABLE I

a Schok No.	b Schotelveren		e Slag (cm)	f Voorspanning		g Rubber- veren	h Massa's	
	Druk c	Trek d		Trek mm	Druk		i Hulp- constr. (kg)	App. (kg)
246	16/32	12/24	10	2	2	6	300	208
247	16/32	12/24	10	2	2	6	300	146

Key: (a) Shock No.; (b) Disk springs; (c) Pressure; (d) Pull;  
 (e) Beat; (f) Advance tension; (g) Rubber springs; (h) Masses;  
 (i) Auxiliary construction

#### 4. MEASUREMENT RESULTS

/4

In the figures 6 to 9 the time functions are found of the signals measured. In Table 2 the maximum values are given.

The maximum increase on the nitrogen tank was for the vertical and for the horizontal test in the increase area between 6 and 8 g. The remaining deformations of the YS-springs were between 1 and 3 mm.

TABLE 2

	a Beweging van het plateau		b Beweging van het stikstofvat <sup>xx</sup>	
	c Schok 246	Schok 247	Schok 246	Schok 247
d Versnelling (m.s <sup>-2</sup> )	330	280	54	80/47
e Snelheid (m.s <sup>-1</sup> )	0,95	1,10	0,59	0,41/0,44
f Verplaatsing (10 <sup>-3</sup> m)	2.2	2.4	16/21) <sup>x</sup>	19
g Vertraging (m.s <sup>-2</sup> )	110	100	54	93/60
T <sub>1</sub> (10 <sup>-3</sup> s)	10	70	30	22/30
T <sub>2</sub> (10 <sup>-3</sup> s)	9	80	-	-

)<sup>x</sup> The first and the second figure indicate the value of the first and the second recorder, respectively.

T<sub>1</sub> = the time in which the maximum speed is reached.

T<sub>2</sub> = the vibration time of the surface of the shock stand.

)<sup>xx</sup> the channels 4 and 7, respectively.

Key: (a) Movement of the surface; (b) Movement of the nitrogen tank;  
 (c) Shock; (d) Speed increase; (e) Speed; (f) Displacement;  
 (g) Speed decrease







Fig. 1. View from the left side

Key: (a) speed recorder of the mass of the nitrogen tank; (b) displacement recorder; (c) speed recorder of the shock stand surface; (d) displacement recorder on the shock stand surface



Fig. 2. Detail of the displacement recorder and of the  
YS confirmation

ORIGINAL PAGE IS  
OF POOR QUALITY



← 2 stuks verplaatsings-  
a opnemers

Fig. 3. View from the right side of the vertical test  
Key: (a) 2 displacement recorders




Fig. 4. Horizontal test

ORIGINAL PAGE IS  
OF POOR QUALITY




Fig. 5. Measurement areas for the horizontal test

Key: (a) displacement recorder; (b) speed recorder (channel 4);  
(c) displacement recorder (channel 9)




Fig. 6. Movement of the surface  
Key: (a) Shock 246

ORIGINAL FILE IN  
OF POOR QUALITY

a Schok 246.




Fig. 7. Movement of the nitrogen tank  
Key: (a) Shock 246; (b) displacement recorder




Fig. 8. Movement of the surface

Key: (a) Shock 247




Fig. 9. Movement of the nitrogen tank  
Key: (a) Shock 247; (b) channel



5. LITERATURE

/12

- (1) Regoord, R. "Handbook for shock as a result of underwater explosions," part 2, IWECO-report No. 4747/1, SA 69126.
- (2) Regoord, R. "Handbook for shock as a result of underwater explosions," part 3, IWECO-report No. 4747/1, SA 69127.
- (3) Schulze, R.A.P.J. "Shocktests to be executed by IWECO-TNO," IWECO - Memo No. 6909/56, SA 69068.