https://ntrs.nasa.gov/search.jsp?R=19810021547 2020-03-21T12:36:27+00:00Z

### NASA Contractor Report 166214

(NASA-CR-1662	14) ANALYSIS	OF MACH N	IUMBER	N81-30085
0.8 TURBOPROP				
INTERACTIONS	Final Report	(Douglas	Aircraft	
Co., Inc.) 84	4 p HC A05/MF	A01	CSCL 01A	Unclas
			G3,	/02 34269 🖕

Analysis of Mach Number 0.8 Turboprop Slipstream Wing/Nacelle Interactions

H. Robert Welge Dan H. Neuhart John A. Dahlin


McDonnell Douglas Corporation Douglas Aircraft Company Long Beach, California 90846

Contract NAS2-10881 August 6, 1981



National Aeronautics and Space Administration

Ames Research Center Moffett Field, California 94035



#### NASA Contractor Report 166214

N81-30085

ţ

### Analysis of Mach Number 0.8 Turboprop Slipstream Wing/Nacelle Interactions

H. Robert Welge Dan H. Neuhart John A. Dahlin

McDonnell Douglas Corporation Douglas Aircraft Company Long Beach, California 90846

Contract NAS2-10881 August 6, 1981



National Aeronautics and Space Administration

Ames Research Center Moffett Field, California 94035

> REPRODUCED BY U.S. DEPARTMENT OF COMMERCE NATIONAL TECHNICAL INFORMATION SERVICE SPRINGFIELD, VA 22161

### TABLE OF CONTENTS

Page

I	Summary	1
II	Introduction	3
III	Nomenclature	5
IA ,	Description of Test Model	7
۷	Analysis of Data	9
VI	Comparison With Theory	13
VII	Design Philosophy	17
VIII	Design Modification	23
IX	Conclusions and Recommendations	25
x	References	27

## Preceding page blank

iii

I. SUMMARY

An experimental test program of a powered propeller and nacelle mounted on a supercritical wing was conducted by the NASA Ames Research Center in the 14-Foot Tunnel. Analysis of this data by the Douglas Aircraft Company, under contract to NASA with Al Lavin as the program manager, is contained in this report. The design condition for this study was  $M_0 = 0.8$ .

Analysis of the data indicated that the installation of the nacelle significantly affected the wing flow and that the flow on the upper surface of the wing is separated near the leading edge under powered conditions. Comparisons of various theories with the data indicated that the Neumann surface panel solution and the Jameson transonic solution gave results adequate for design purposes. A modified wing design was developed (Mod 3) which reduces the wing upper surface pressure coefficients and section lift coefficients at powered conditions to levels below those of the original wing without nacelle or power. A contoured over-the-wing nacelle is described that can be installed on the original wing without any appreciable interference to the wing upper surface pressures.

# Page Intentionally Left Blank

The recent increases in fuel prices for aircraft has resulted in the consideration of alternate propulsion system concepts that would reduce fuel consumption. One of the primary candidates is a propeller-turboshaft (turboprop) powerplant. Several system studies have been conducted that indicate fuel savings from 15 to 30% in fuel burned for a given mission when compared to turbofan engines (References 1 through 6). Flight speeds of  $M_0 = 0.8$  are considered necessary for compatibility with existing airline operation and advanced propeller designs called Prop-Fans have been developed that give efficient performance at these speeds. A wing of the supercritical type is recommended to maximize performance.

One of the aerodynamic concerns about the turboprop installation is the interference drag that will result from the placement of the gas generator/nacelle and propeller on a supercritical type wing. Several years ago, a test was run by Douglas Aircraft under contract to NASA Ames (Reference 7) to experimentally evaluate interferences. these A flow-through ejector powered nacelle located ahead of the wing was used to simulate the onset flow of the propeller. This experimental approach permitted independently varying the various propeller parameters to obtain a basic understanding of the power-wing interactions. Many useful results and observations resulted from this early exploratory program but a more accurate representation of the flow is obtained by using an actual rotating propeller.

Preceding page blank

The test results discussed in this report used the same wing design as the previous simulator test. A semispan test installation was used mounted to the floor of the Ames 14-foot tunnel. Test conditions covered the Mach range from 0.6 to 0.85. The Reynolds numbers based on the mean aerodynamic chord varied from 7.8 x  $10^6$  at  $M_0 = 0.6$  to 9.1 x  $10^6$  at  $M_0 = 0.85$ . An air-driven motor powered an 8 bladed propfan propeller designated SR-2C (Reference 8). The installation, development of the motor, fabrication and testing were all done by NASA Ames. This report covers the analysis of the data, comparison with theory and configuration modifications performed by the Douglas Aircraft Company (a division of the McDonnell Douglas Corporation) located in Long Beach, California.

### III. NOMENCLATURE

AR	Wing aspect ratio
b	Wing span
с	Local chord
c <sub>D</sub>	Configuration drag coefficient
cl	Section lift coefficient
C <sub>LWB</sub>	Wing-body lift coefficient based on wing trapezoidal area
CLW	Wing lift coefficient based on exposed wing trapezoidal area
с <sub>р</sub>	Pressure coefficient
∆C <sub>D,</sub>	Incremental induced drag coefficient
C <sub>mac</sub>	Mean aerodynamic chord
Mo	Free stream Mach number
ML	Local Mach number
PT/PT0	Propeller total pressure to freestream total pressure ratio
R <sub>e</sub>	Reynolds number based on chord
RPM	Revolutions per minute
r/R	Propeller blade local radius divided by maximum radius
STRAPEXP	Exposed trapezodial reference area
t/c	Wing thickness to chord ratio
x,y,z '	Coordinate system x streamwise, y spanwise, z vertical
x/c	Fraction of local chord
α	Configuration angle of attack measured relative to fuselage reference plane
α <sub>s</sub>	Swirl angle, degrees
β	propeller blade angle setting, degrees
η	Percent semispan of wing

### Taper ratio

## Wing quarter chord sweep

6

λ Λc**/4**  A photograph of the model is shown in Figure 1. The wing coordinates were obtained from Douglas Aircraft. The wing had been tested previously as part of the Douglas Aircraft supercritical wing development program and had demonstrated good drag rise characteristics near  $M_o = 0.8$ . The design also had been used previously as part of an earlier NASA sponsored test where the propeller onset flow had been simulated by using an ejector powered flow through nacelle mounted ahead of the wing (Reference 7 and Figure 2). The planform of the NASA model with the nacelle installed is shown in Figure 3 including the location of pressure rows to be discussed later. Coordinates for the wing are given in Table 1 and Figure 4 shows a side view of the nacelle.

The propeller was an SR-2C design (Reference 8) and was powered by an air driven turbine. Air to power the turbine was supplied through the floor and wing and exhausted under the wing through a nozzle at about 50% chord.

# Page Intentionally Left Blank

#### Force Data

Analysis by NASA and Douglas determined that the force data for this test was not reliable. Subsequent analysis by NASA did result in some usable force data, but for the purposes of the work described in this report the force data will not be referred to.

#### Pressure Data

The pressure data on the wing were integrated to obtain the wing lift coefficient ( $C_{L_W}$ ), and these results are shown on Figure 5. The analysis will focus on an angle of attack of 2 degrees or a  $C_{L_W}$  near 0.5.

The pressure distributions on the wing are shown in Figures 6 through 12 for a fixed propeller blade angle of  $57^{\circ}$ . Figures 6 through 10 show the flow development for a fixed angle of attack of  $2^{\circ}$  and Figures 11 and 12 show the variation with angle of attack at  $M_{\circ} = 0.8$ . The data indicates that there is a significant effect of the nacelle on the pressures inboard of the nacelle at 36.5 and 41.5 percent semispan, but that there is a negligible effect outboard of the nacelle. The pressure distributions indicate that small separations may occur inboard due to the nacelle installation, and at  $M_{\circ} = 0.8$ , a normal shock is indicated. Available oil flow photographs shown in Figures 13 and 14 indicate that the flow has been significantly disturbed by the nacelle but large regions of flow separation are not apparent. The presence of the normal shock inboard of the nacelle can be seen in Figure 14.

Preceding page blank

When full propeller power is added, the flow velocities are increased in the propeller wash region (included on the figures) and there is also a change in the local angle of attack. The isolated propeller flow one blade chord downstream of the propeller is shown in Figure 15. (These data were not part of the current test but were measured separately as part of NASA's propeller development program.) The propeller rotation for this test created increased wing section angle of attack inboard of the nacelle (upwash) and decreased angle of attack outboard (downwash). The pressure distributions on the wing due to power show increased upper surface pressure peaks and as the Mach number is increased, the presence of a flow spearation becomes more apparent. Available oil flow photographs with power-on, shown in Figures 16 and 17, illustrate clearly that there is a significant flow separation and extreme inboard flow from the outboard region of the nacelle.

The section lift data obtained by integrating the above pressure distributions (and removing obviously bad points) are shown in Figures 18 and 19. The installation of the nacelle reduces the  $c_{\ell}$  at the inboard stations with little effect outboard. The windmilling propeller reduces the  $c_{\ell}$  further probably due to a loss in dynamic pressure. The application of power significantly increases the  $c_{\ell}$  values inboard due to propeller upwash and increases the velocity to levels which caused the flow separations. Outboard the  $c_{\ell}$  is reduced because of the propeller downwash.

At  $M_0 = 0.7$ , the  $c_{\ell}$  data (solid symbols Figure 20) was used to calculate the induced drag increment due to the nacelle installation by a Trefftz plane method. The increment was found to be 12 counts  $(\Delta C_{D_1} = 0.0012)$ .

To summarize these results for later reference during the wing redesign discussion (Section VII), the region outboard of the nacelle is not seriously affected by the installation of the nacelle or power and wing modifications are not required in this region. However, inboard the nacelle significantly increases the upper surface pressure peaks but not to levels that cause large flow separations. However, a significant 12 count induced drag penalty was calculated. At  $M_0 = 0.8$ , a small normal shock is present near the nacelle on the wing, further contributing to the drag. The increased flow velocity and upwash due to power are sufficient to increase upper surface pressure levels and  $c_l$ 's to conditions where attached flow can not be maintained by the original wing design.

#### Comparison With Simulator Data (Reference 7).

It was found that the flow from the ejector powered simulator most nearly matched the 59<sup>0</sup> blade angle data (Figure 21), therefore the comparisons are made for this blade angle. Since the simulator test did not have a nacelle mounted on the wing, only incremental effects due to power from each test are compared.

Figures 22 through 27 compare the pressure distributions and span loads between the two tests at  $M_0 = 0.7$  and 0.8. Qualitatively the pressure distributions agree fairly well, with the peak pressure levels and the general shape of the plots being very similar. It is interesting to note that the pressure increase near 60% chord at 50% semispan on the upper surface due to power is indicated in both sets of data (Figure 25).

The incremental  $c_{g}$  values are not as large for the simulator test as for the propeller test as shown on Figures 26 and 27. However, the  $c_{g}$ levels with power are comparable.

# Page Intentionally Left Blank

#### Lifting Line Program

The lifting line program is a method which uses a vortex filament at the quarter chord point at several spanwise locations on the wing and a control point at the three-quarter chord location. The wing zero-lift-line and the propeller onset flow are input. The nacelle geometry cannot be input. The strength of the vortex is then determined to satisfy the condition of tangential flow at the control point. Forces are calculated by repeated application of the Kutta-Joukowski law. This theory is compared to the simulator data in Figures 28 and 29. Agreement with the clean wing is good but the increments due to power are overpredicted. Both positive (up-inboard) and negative (up-outboard) swirl cases are shown.

Comparisons with the propeller data are shown in Figures 30 and 31. Increments due to the nacelle taken from the previous Figures (18 and 19) are indicated. At  $M_0 = 0.7$ , the clean wing data is below predictions inboard in contradiction to the data measured for the simulator case, suggesting a difference in wing geometry. This may have been caused by a difference in wing twist under load caused by the difference in wing fabrication methods or scale. The powered data are well predicted except in the region immediately outboard of the nacelle. At  $M_0 = 0.8$  the same conclusions apply except the clean wing data is underpredicted outboard, again suggesting a difference in wing twist.

In summary, the powered data for the simulator is underpredicted by the theory perhaps because of the presence of the ejector nacelle or nacelle

j.

Preceding page blank

13

a contraction of the second second

boundary layer flowing over the wing. Powered predictions for the propeller are generally good except just outboard of the macelle. Nacelle interferences, not included in the theory, may cause this discrepancy.

#### Neumann Theory

The Neumann program is an incompressible surface panel solution using unknown source and dipole singularities to satisfy the zero normal flow condition at control points located in a number of panels describing the body surface (Reference 9). In regions washed by the propeller, the propeller onset flow is input at each affected control point to be included with the free stream flow when the singularity strengths are found. The program can calculate flows about completely arbitrary configurations.

The program contains the option of using the Goethert correction for compressibility. However, when this option is applied, the zero normal flow boundary condition is not exactly satisfied. Because of the complex geometries dealt with and the small included angles between some body surface panels, the compressibility option was not employed in order to avoid potential numerical errors in some cases.

A description of the paneling used for the simulator case is shown in Figure 32. The results are shown in Figures 33 and 34. (The Neumann program is compared to the data at the same configuration  $C_{L_W}$ . Since the Neumann program did not include viscous effects, the same  $C_{L_W}$  is achieved at an angle of attack 1<sup>o</sup> less than the data, Figure 5.) The pressure distributions generally agree well but the upper surface peaks near the leading edge are underpredicted. Agreement is good if incremental effects are compared. The section lift agreement is good with the exception of the power and swirl case at 35% semispan.

The paneling for the propeller case is shown in Figure 35. The circular body extending aft of the wing trailing edge is the representation of the exhaust flow. The pressure distributions inboard and outboard of the nacelle for the clean wing, wing plus nacelle and wing plus nacelle plus power are shown in Figures 36 through 41. (Again, note the 1<sup>°</sup> angle difference. The powered data are for  $\beta = 57^\circ$ , run 69). The agreement of the theory with the data is good. The experimental separation inboard of the nacelle with power can be easily identified in Figure 38.

The section lift distribution data (Figure 42) does not agree as well. Neither the level nor the increments are reasonably predicted inboard of the nacelle but outboard the agreement is better. The disagreement inboard may be caused by local separations and transonic flows not correctly included in the theory.

The Neumann pressure distributions are compared to the data at the same angle of attack as the data  $(2^{\circ})$  in Figures 43 through 48.

#### Jameson Theory

. 1

The Jameson Theory is a fully transonic solution restricted to wings only. The wing is mapped into a computational plane and the full compressible potential flow equations are solved (Reference 10).

The Jameson theory agreement with the data for the clean wing is excellent as shown on Figures 49 and 50. To approximately account for propeller onset flow effects, the wing was twisted in accordance with the propeller swirl and an incremental free stream Mach number was applied to account for slipstream velocity increases. The nacelle effect is not

15 .

accounted for. These results are shown in Figures 51 through 56. As noted, if the incremental Mach effect is not included, the agreement between the theory and data is adequate to be used for design purposes.

The Jameson theory, applied in the manner discussed above, was the primary method used to design the modified wings described in the next section. This computer code was used because it is a transonic method and would give an adequate representation of the transonic flow development. However, nacelle effects are not properly accounted for and the Neumann computer code was used to include these effects. Uncertainty exists by using either program because of a limitation in the geometry capability (lack of a nacelle in Jameson) or transonic flow computational capability (Neumann). These factors will be discussed further during the discussion of the wing design in the next section.

#### Design Criteria

To reduce upper surface separations (Figures 16 and 17) and subsequent degredations in wing performance, it was necessary to reduce the magnitude of the high negative pressures on the wing upper surface inboard of the nacelle (Figures 7 and 9) and reduce the wing  $c_{\ell}$  values (Figures 18 and 19) to acceptable design limits. Since the clean original wing performed well and did not have any flow separations, the clean wing data was used to establish the design criteria. These criteria were minimum upper surface pressure levels, chordwise pressure gradients and spanwise upper surface isobar patterns. The  $c_{\ell}$  levels at any span station and the distribution of  $c_{\ell}$  as it affects induced drag were also used. The objective of the redesign work was to achieve levels on the new wing which were equal to or less than the above criteria.

#### Wing Redesign

The airfoil section shape inboard of the nacelle was modified to conform to the above described criteria within the constraints of the existing hardware. No problems were identified outboard of the nacelle so no modifications were made there. The hardware constraints were that the airfoil remain unchanged except for the forward or aft 20 to 25% of the chord.

Modified airfoils that fit within the existing planform could not be found which conformed to the design criteria. Therefore, a leading or trailing edge extension was required. A trailing edge extension was ruled out because of diffuculities with the aft pressure gradients and unsweeping

of the isobars. Therefore, a 15% leading edge extension was selected as shown on Figure 57. The closer proximity of the propeller to the leading edge is a concern and may shorten useable propeller test time.

The airfoil section for the modified planform was developed to reduce upper surface peaks and gradients at transonic conditions ( $M_0 = 0.8$ ,  $C_{L_W} = 0.5$ ) and fair smoothly into the existing airfoil shape at about 25% chord. The airfoil shapes were developed using a 2-D transonic analysis method prior to 3-D analysis to insure a pressure distribution over the entire airfoil that conformed to accepted design practice. The 3-D Jameson computer code was used to evaluate the various designs in three dimensions.

Two of the best designs developed are shown in Figures 58 through 62, and are identified as Mod 2 and Mod 3. The n= 0.12 section shape is the same for either Mod. The Jameson results with and without power, compared to the original wing, are shown in Figures 63 and 64. Mod 3 has pressure peaks near the leading edge about half of the original wing and the transonic flow over the entire upper surface is free of shock waves even with power. The  $C_p$  levels with power are less than the clean original wing, the gradients are less and constant  $C_p$  levels occur at similar x/c values indicating swept isobar patterns. Mod 2 has higher nose peaks than Mod 3 but, as will be discussed, Mod 2 may be less sensitive to nacelle interferences. The spanwise distribution of lift is shown on Figure 65 and the  $c_g$  values are less everywhere than for the clean original wing. The desired spanwise distribution of lift to reduce induced drag could not be achieved.

Incompressible Jameson solutions at  $M_0 = 0.1$  were calculated for reference to subsequent discussions of the incompressible Neumann solutions to follow which calculated results for the wing/fuselage and the nacelle.

The Jameson results are shown in Figures 66 and 67. Note that the Mod 3 design has higher nose peaks than Mod 2. However, the transonic development of Mod 3 was much better than Mod 2 indicating that at the design condition of  $M_0 = 0.8$ , Mod 3 will be the better design.

The incompressible Neumann solutions for the 3 wings (original wing, Mod 2, and Mod 3) with and without the nacelle and power at the 37% semispan station are shown in Figures 68, 69 and 70. In all cases, Mod 3 has lower pressure coefficients and gradient levels near the leading edge on the upper surface than the clean original wing, and it is also better than Mod 2.

The same data presentation is shown at the 41% semispan station in Figures 71, 72 and 73. At this station, the Mod 3 design significantly reduces the negative  $C_n$  peaks compared to the original wing, especially with power as shown in Figure 73. However, the negative  $C_p$  peaks are higher than the original wing without nacelle and power and are higher than Mod 2 with nacelle and power. The uncertainty here is whether the results shown at the 41% semispan would also occur at transonic conditions. The Mod 3 results were worse in the Jameson code at freestream conditions similar to the Neumann solution  $(M_{n} = 0)$  but the pressure distribution development into the transonic region ( $M_0 = 0.8$ ) was better. Since a transonic code including the nacelle body was not available for this study, the transonic development in the presence of the nacelle could not be evaluated. Since the Mod 3 design is better at 37% semispan using the Neumann and is better everywhere at transonic conditions as evaluated in the Jameson, it has been selected as the preferred design and is recommended for test. If the adverse effects nearer the nacelle (41%) occur during test, these effects can be treated locally with a small fillet.

.2

2

To evaluate whether or not the pressure peak calculated for Mod 3 at 41% semispan will cause a flow separation, the results shown on Figure 72 are compared to the power-off flow visualization photos on Figures 13 and 14. The flow photos did not indicate a large region of flow separation although a limited normal shock was indicated at  $M_0 = 0.8$ . The pressure peak calculated by the Neumann at these conditions was -1.4 as shown on Figure 72. Therefore, a -1.4 C<sub>p</sub> should be marginally acceptable to avoid significant flow separation.

The peak  $C_p$  for Mod 3 with nacelle and power calculated by the Neumann is -1.4 as shown on Figure 73. This level indicates that flow conditions similar to the power-off case on the original wing would occur (like Figure 13 and 14) and the powered performance of Mod 3 should be acceptable.

Figure 74 shows results for all the configurations and conditions at 56% semispan. In all cases, the pressure distributions are more favorable than the original wing.

The spanwise distribution of lift for all cases is shown in Figure 75. The desired  $c_{\ell}$  values (less than the original wing) are achieved inboard of the nacelle for either Mod 2 or 3.

To amplify the conclusions drawn and to indicate sensitivity to angle of attack, the Neumann results are shown at  $1^{\circ}$  higher angle of attack in Figures 76 through 81. All the conclusions drawn previously apply to these data. Note that in Figure 79, Mod 3 has a higher negative C<sub>p</sub> at the nose without nacelle and power than Mod 2, just like the Jameson results.

#### Nacelle Contouring

The streamlines about the isolated wing computed using the Neumann program are shown in Figures 82 and 83.

<u>Underwing Nacelle</u> - The nacelle geometry for this case was constrained to adding fairings to the existing nacelle or contouring aft of the motor so that installation of the air drive motor would be assured.

The aft part of the nacelle and nozzle centerline were contoured to the lower surface streamline as indicated in Figure 84. This contouring did not produce adequate favorable effects to warrant further consideration as shown in Figure 85.

Limited contouring of the nacelle was developed using the upper surface streamlines. As indicated in Figure 83, no contouring is possible inboard of the nacelle because of the relationship of the wing leading edge and rotating hub and propeller. A local fillet can be used outboard to fair between the nacelle and the wing leading edge. In the profile view (Figure 82) a local "bump" on the nacelle upper surface in the region of the wing leading edge will make the nacelle conform more closely with the streamline. The two fairings are shown by photographs of a subscale mock-up in Figure 86.

These limited fairings probably won't have a significant impact on the performance. The geometric limitations precluded contouring to the extent necessary. These fairings can be tested in the tunnel depending on test results of the modified wing and basic nacelle.

<u>Overwing Nacelle</u> - An overwing nacelle was also considered and is shown in Figure 87. For this case, the approach was to aerodynamically contour the nacelle and then determine if the air drive motor can be installed. Since this work was done in parallel with the development of Mod 3, the original

wing was used. Also, because the objective of this work was to evaluate what can be achieved by nacelle contouring with the power effects being treated using wing modifications, the power effects were not included.

The contouring was accomplished by maintaining the longitudinal cross-sectional area distribution of the nacelle to give the best chance of the motor fitting inside. The centers of these areas were shaped to conform to the flow streamlines. The resulting nacelle shape is shown in Figures 88 and 89. The contouring achieved excellent results as shown in Figures 90 through 92. At the 43% semispan location, the upper surface pressure peak and gradient with the nacelle installed is significantly less than for the non-contoured nacelle case and is almost identical to the original wing without the nacelle. Significantly better span loading is also achieved as shown in Figure 93, which should provide significantly less induced drag. It is recommended that this contoured nacelle and the non-contoured nacelle be tested to confirm these results.

The wing coordinates for Mod 3 are given at 10 spanwise locations in Table 2. These coordinates conform to the existing wing at approximately 25% of the original wing chord. The geometry of the overwing contoured nacelle has been given to NASA Ames in the form of a computer tape containing a parametric cubic definition of the nacelle. The plan and profile view were shown in Figures 88 and 89.

# Page Intentionally Left Blank

The following conclusions are drawn from this study:

- The force data could not be used during this study because of uncertainties in accuracy.
- 2) Both the nacelle and power had significant effects on the wing flow. With power, the upper surface of the wing was separated at a wing  $C_{L_W}$  near 0.5.
- 3) The increments in the pressure data due to power agreed fairly well between the earlier simulator test and the propeller test. The absence of a nacelle in the simulator test makes a direct comparison impossible.
- 4) The Lifting Line computer code agreed better with the propeller power-on data than with the previous simulator data. This program could be used for preliminary design purposes.
- 5) The Neumann Surface Panel computer code predicted the wing surface pressure distributions with sufficient accuracy for design purposes. The agreement with the propeller model Cp distributions was excellent. The  $c_0$  values were not predicted as well.
- 6) The Jameson Transonic Program gives results adequate for design purposes if the power effects are accounted for by wing twist.

Preceding page blank


- 7) A new wing planform and new airfoil sections were developed (Mod 3). At  $M_0 = 0.8$ , the upper surface peak  $C_p$  values with power for this configuration are approximately half of the original wing with power. The pressure distribution is shock free and should result in performance with power approaching that of the original clean wing without power. Some uncertainty is present regarding the effects of the nacelle on this wing at transonic speeds. It is recommended that test data on Mod 3 be obtained to evaluate its performance.
- 8) A contoured upper surface nacelle was developed for the original wing which can be installed on the wing without producing any appreciable interference to the wing pressures. It is recommended that this nacelle be built and tested to evaluate performance.

- J. P. Hopkins, and H. E. Wharton, "Study of the Cost/Benefit Tradeoffs for Reducing the Energy Consumption of the Commercial Air Transportation System." (LR-27769-1, Lockheed-California Co.; NASA Contract NAS2-8612.) NASA CR-137927, 1976.
- J. P. Hopkins, "Study of the Cost/Benefit Tradeoffs for Reducing the Energy Consumption of the Commercial Air Transportation System." (LR-27769-2, Lockheed-California Co.; NASA Contract NAS2-8612.) NASA CR-137926, 1976.
- E. F. Kraus, and J. C. Van Abkoude, "Cost/Benefit Tradeoffs for Reducing the Energy Consumption of the Commercial Air Transportation System. Vol. I: Technical Analysis." (MDC-J7340-Vol.-1, Douglas Aircraft Co., Inc.; NASA Contract NAS2-8618.) NASA CR-137923, 1976.
- Energy Consumption Characteristics of Transports Using the Prop-Fan Concept: Summary." (D6-75780, Boeing Commercial Airplane Co.; NASA Contract NAS2-9104.) NASA CR-137938, 1976.
- 5. "Energy Consumption Characteristics of Transports Using the Prop-Fan Concept: Final Report." (D6-75780, Boeing Commercial Airplane Co.; NASA Contract NAS2-9104.) NASA CR-137938, 1976.

- 6. I. M. Goldsmith, "A Study to Define the Research and Technology Requirements for Advanced Turbo/Propfan Transport Aircraft." (Douglas Aircraft Company; NASA Contract NAS2-10178) NASA CR 166138, February 1981.
- 7. H. R. Welge, and J. P. Crowder, "Simulated Propeller Slipstream Effects on a Supercritical Wing." (Douglas Aircraft Company; NASA Contract NAS2-9472.) NASA CR-152138, June 1978.
- 8. R. J. Jeracki, D. C. Mikkelson, and B. J. Blaha, "Wind Tunnel Performance of Four Energy Efficient Propellers Designed for Mach 0.8 Cruise." NASA TM-79124, April 1979.
- Hess, J. L.: The Problem of Three-Dimensional Lifting Potential Flow and Its Solution by Means of Surface Singularity Distribution, Computer Methods in Applied Mechanics and Engineering, Vol. 4, 1974, pp. 283-319.
- Henne, P. A.: Transonic Wing Analysis Using Advanced Computational Methods, AIAA Paper 78-105, 1978.

$ \begin{array}{c} 17.5 & 49.1401 & -5.9.6.29 & 50.2149 & -1.7.67.7 & 47.67.62 & -1.0274 & 77.8.716 & -7. 15. & 48.0713 & -5.7.071 & 47.4731 & -1.6.544 & 6.6.1157 & -7.7.03 & 72.88718 & -7. 19. & 57.000 & 45.7.723 & -1.4.544 & 6.6.715 & -7.7.03 & 72.88718 & -7. 19. & 45.9325 & -5.1.6.71 & 47.0194 & -1.0204 & 6.1.4.72 & -6.756 & 77.342 & -7. 19. & 45.9325 & -5.1.6.71 & 47.0194 & -1.020 & 60.1.4.72 & -6.756 & 77.342 & -7. 19. & 41.6.345 & -4.119 & 45.0126 & -7.517 & 59.1701 & -2.407 & 71.8767 & -7. 19. & 41.6.345 & -4.119 & 45.0126 & -7.517 & 59.1701 & -2.407 & 71.8762 & -7. 19. & 41.6.345 & -4.119 & 45.0126 & -7.517 & 59.1701 & -2.407 & 71.8762 & -7. 19. & 41.6.345 & -4.119 & 45.0126 & -7.517 & 59.1701 & -2.407 & 71.8762 & -7. 19. & 7.3.769 & -1.442 & 43.1624 & -3.525 & 55.12042 & -0.043 & 64.4411 & -7. 19. & 5.3.52377 & -7.670 & 40.7084 & -1.3055 & 59.4187 & 0.518 & 68.7317 & -7.6733 & -7.575 & -7.6733 & -7.575 & -7.673 & 49.741 & -0.022 & 54.2267 & 0.723 & 68.73277 & -7.6733 & -7.5741 & -0.022 & 54.2267 & 0.723 & 68.73277 & -7.7747 & -7.741 & -0.022 & 54.2267 & 0.723 & 68.73277 & -7.7774 & -7.741 & -0.022 & 54.2267 & 0.723 & 68.73277 & -7.7775 & -7.6733 & -7.741 & -0.022 & 54.2267 & 0.723 & 68.73277 & -7.7775 & -7.6733 & -7.741 & -0.022 & 54.2267 & 0.723 & 68.73277 & -7.747 & -7.75 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.747 & -7.750 & -7.750 & -7.750 & -7.750 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7577 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7577 & -7.7777 & -7.7577 & -7.7777 & -7.7577 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.7777 & -7.77777 & -7.77777 & -7.77777 & -7.7777777777$	Z 584 163 2378 1856 0181
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	Z 584 163 2378 1856 0181
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	12 53 5584 145 2378 1856 0981
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	163 1756 1856
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	163 2378 1856 0981
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	2378 1856 0981
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	1856
$ \begin{array}{c} 85 \\ 83, 7933 \\ \hline 8, 1119 \\ \hline 80 \\ \hline 81.6545 \\ \hline 81.119 \\ \hline 80.6 \\ \hline 81.6545 \\ \hline 81.119 \\ \hline 85.65 \\ \hline 99.5157 \\ \hline 93.6142 \\ \hline 93.6$	
75       19.5137       -3.6142 $43.6290$ 5352       58.1813      2127       70.6447         70       37.3769       3.1441 $42.1654$ 3529       57.1726      1077       70.0733         65       35.2377       -2.7370       40.7428      255       56.2442      0243       64.9417         51.5       32.4571       -2.1741       38.7913       -0595       54.912       .0517       68.3277         55       30.8601       -1.9062       37.7747       .0022       54.2667       .0823       68.3277         50       28.8209       -1.5504       36.3113       .0629       53.7661       .0187       67.7470         45       24.4681       -1.2214       24.8477       .1011       52.24747       .1155       67.1655         40       24.5433       -3193       33.3845       .1150       51.2610       1.0575       66.921         30       20.2655       -35.907       J0.9572       0.687       47.1352       .0947       64.8021         20       15.9876       .0243       27.6300       .0947       47.1352       .0004       64.4733         20       15.9876       .03867       13.17	
$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	0272
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0290
$ \begin{array}{ c c c c c c c c c c c c c c c c c c c$	1029
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	1253
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	13/6
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	<u>1312</u> 1228
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	.1059
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0801
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	0459
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	0573
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	283
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	189
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	2 768
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	3462 4425
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	516 <b>8</b>
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	ice
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	137
$\begin{array}{ c c c c c c c c c c c c c c c c c c c$	767 •
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	1/89
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	7605
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	141
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	542
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	9284
7.5 10.6400 -5.4873 23.8714 -3.0140 44.8350 -2.0285 63.8041 -1. 10. 11.7096 -5.8464 24.6032 -3.1621 45.3293 -2.1157 63.0948 -1. 15. 13.8484 -6.8087 26.0688 -3.3664 46.3346 -2.2414 63.6763 -1.	0089 1089
15. 13.8484 - 6.8087 26.0668 - 3.3664 46.3346 - 2.2414 63.67631.	707
	2151
20. 15.9876 -6.5932 27.5300 -3.5013 47.3064 -2.3/63 64 2578 +-1	2681
25. 18.1264 -6.7653 28.9936 -3.5936 48.2952 -2.3649 64.8193 -1.	3096
30. 20.2653 -6.8535 30.4572 - 3.6565 49.2239 - 2.3913 65.4207 -1.	3100
$\frac{35}{40} = \frac{21}{24} \frac{31}{5} \frac{31}{$	2997
45 26.6721 -6.9166 34.8433	2784
50. 28.8209 -6.7770 36.3113 -3.5782 53.1061 -2.2855 67.7470 -1.	2445
55 1 30 1631 -6.700 37.7749 -3.4428 54.200 -2.1866 68.3285 -1.	1266
1 10 1 55 417 1 - 6. 6 2 14 1 HO. 7022 2 0 0445 5 5 5 5 10 1	648
70 32.3767 4 4934 49 14 54	
75. 39.5157 -6.3422 43.6290 -2.5145 59.1813 -1.5129 70.64447	
80 41.6545 62869 45.0926 -22550 59.1201 -1.3276 71.3362 -1	r134
90 45.9325 6.1841 48.000 -1.1692 71.8177 -1	
92.5 47.0117 -6.1272 42.75/3 -18777 6144/5	134 899 743 745
	134 174 743 1745 1977
7. 460/18 -6.1320 49.4131 -1.4036 62.1359 -1.0600 -2.0010	134 899 743 1745 1977
97.5 49.1419 -6.1566 50.244 19940 -1.1036 42.1359 -1.0600 72.9810 -1	134 174 743 1745 1977

#### TABLE 1 **ORIGINAL AIRFOIL COORDINATES**



# Page Intentionally Left Blank

#### TABLE 2

#### **MOD 3 WING COORDINATES**





TABLE 2 (CONT) MOD 3 WING COORDINATES

Y-10.5904



ORIGINAL PAGE IS OF POOR QUALITY

Preceding page blank

31


BI GEN-24221


## TABLE 2 (CONT)MOD 3 WING COORDINATES

Y=13.9735			Y-17.3585		
×	Y <sup>1</sup>	Z	×	۲	Z
22.679883	13.973500 13.973500	-0.380840	24.331223 22.981155	17.356491 17.356491	-0.287610
21.241409 19.834808	13.973500	-0.127530	21.652679	17.356491	-0.185980 -0.102070
18.456696	13.973500	-0.033600	20.351105	17.356491	-0.032560
17.112411	13.973500	0.033020	19.081497	17.356491	0.002130
15.887320	13.973500	0.075130	17.848892	17.356491	0.021900
14.546550	13.973500	0.094580	16.658142	17.356491	0.021910
13.335060	13.973500 13.973500	0.091360	15.51 <b>3960</b> 14.429840	17.356491	0.002170 -0.035870
11.078910	13.973500	0.019470	13.383130	17.356491	-0.0368/0
10.043160	13.973500	-9.946979	12.404910	17.356491	-0.168928
9.074490	13.973500	-0.132730	11.490040	17.356491	-0.260130
8.176720	13.973500	-0.236570	10,642130	17.356491	-0.366440
7.353399	13.973500	-0.357910	9.864540	17.356491	-0.487330
6.607760	13.973500	-0.496080	9.160330	17.356491	-0.622160
5.942770	13.973500	-0.649450	8.532270	17.356491	-0.769520 -0.928850
5.361040	13.973500	-0.817250 -0.998650	7.982850 7.514230	17.356491	-1.099558
4.456210	13.973500	-1.192140	7 120200	17.356491	-1.279870
4.136678	13.973598	-1.397010	7.128289 6.826589	17.356491	-1.468970
3.997530	13.973590	-1.611900	6.610029	17.356491	-1.665400
3.769680	13.973500	-1.833570	6.479890	17.356491	-1.865650
3.723688	13.973500	-2.064290	6.436440	17.356491	-2.070780
3.769680	13.973500	-2.295470	6.479890	17.356491	-2.276280
3.997530	13.973590	-2.538080	6.610080	17.356491	-2.499700
4.136670 4.456210	13.973500	-2.783540	6.826500	17.356491	-2.707750 -2.927450
4.864860	13.973500	-3.282660	7.128280 7.514230	17.356491	-3.147920
5.361040	13.973500	-3.533300	7.982850	17.356491	-3.367700
5.942770	13.973500	-3.782690	8.532270	17.356491	-3.584748
6.607760	13.973500	-4.028050	9.168339	17.356491	-3.798300
7.353399	13.973500	-4.269810	9.864540	17.356491	-4.007360
8.176720	13.973500 13.973500	-4.505470	10.642130	17.356491	-4.210510
9.074499 10.043160	13.973500	-4.734050	11.490040	17.356491	-4.406950
11.072910	13.973500	-4.954100 -5.164330	12.404910 13.383130	17.356491 17.356491	-4.595460 -4.775250
12.177660	13.973544	-5.363710	14.420350	17.356491	-4.945620
13.335660	13.973500 13.973500	-5.550510	15.513950	17.356491	-5.105490
14.546540	13.973500 13.973500	-5.723140	16.658142	17.356491	-5.253830
15.807320	13.973500	-5.280490	17.848892	17.356491	-5.329890
17.112411	13.973500 13.973500	-6.020890	19.0B1497	17.356491	-5.512540
18.456680 19.834808	13.973500	-6.139830 -6.234190	20.351089	17.356491 17.356491	-5.618440
21.241409	13.973500	-6.301648	21.652679 22.981155	17,356491	-5.768890
22.670883	13.973500	-6.342700	24.331223	17.356491	-5.808360

81-GEN-24216

TABLE 2 (CONT)





81-GEN-24217

#### TABLE 2 (CONT) MOD 3 WING COORDINATES

	Y-27.5057			Y•30.8888	
x	Y	z	×	۲	z
29.312332	27.505692	-8.997899	30.972717	30.888779	0.085340
28.200485	27.505692	-0.010250	29.940262	30.888779	0.048330
27.106400 26.034454	27.505692 27.505692	-0.025680 -0.053440	28.924316 27.928999	30.888779 30.888779	-0.000220 -0.058409
24.988846	27.505692	-0.090560	26.957977	30.828779	-0.121450
23.973724	27.505692	-0.137790	26.015335	30.888779	-0.191020
22.993057	27.505692	-0.196070	25.104706	30.888779	-9.268730
22.050751	27.595692	-0.265410	24.229691	30.888779	-9.354688
21.150513	27.595693	-0.345488	23.393738	30.888779	-0.448358
20,295883	27.505692	-0.435830	22.660143	30.888779	-0.549650
19.490265	27.505692	-0.535020	21.852051	30.888779	-0.657040
18.736801	27.505692	-0.642320	21.152405	30.888779	-0.769720
18.038513	27.505692	-0.756040	20.503967	30.888779	-0.885910
17.398117	27.505692	-0.875560	19-909302	39.888779	-1.004980
16.818146	27.505692	-1,000350	19-379758	30.889779	-1.126460
16.300919	27.505692	-1.129730	18.890457	30.888779	-1.249810
15.848440	27.505692	-1.263650	18.476291	30.888779	-1.375260
15.462500	27.505692	-1.402240	18-111908	30.888779	-1.503140
15.144650	27.505692	-1.543888	17.816757	30.888779	-1.630810
14.896110	27.505692	-1.684830	17.585968	30.889779	-1.756790
14.717870	27.505692	-1.825890	17.420456	36.889779	-1.879390
14.610650	27.505692 27.505692	-1.961820 -2.090240	17.329892	30.888779 30.888779	-1.993960
14.610650	27.565692	-2.218690	17.329892	30.888779	-2.096730 -2.199500
14.717870	27.505692	-2.348570	17.429456	30,888779	-2.301190
14.896110	27.505692	-2.480320	17.585968	39,888779	-2.404590
15.144650	27.505692	-2.612910	17.816757	34.888779	-2.508060
15.462500	27.505692	-2.743680	18.111903	30.888779	-2.608930
15.848440	27.505692	-2.878986	18.470291	30.888779	-2.705300
16.388919	27.505692	-2.992650	18.898457	30.888779	-2.795290
16.818146	27.505692	-3,199946	19.370758	30.888779	-2.879290
17.398117	27.505692	-3.220010	19.909362	39.888779	-2.957560
18.038513	27.595692	-3.325610	20.503967	30.888779	-3.030640
18.736801	27.595692	-3.425630	21.152405	30.888779	-3.098530
19.490265	27.505692	-3.519530	21.852951	30.888779	-3.166890
20.295883	27.505692	-3.642000	22.669143	30.888779	-3.218920
21.150513	27.505692	-3.691348	23.293738	30.889779	-3.273250
22.050751	27.505692	-3.770410	24-829691	30.888779	-3.325390
22.993057	27.505692	-3.845870	25.104706	30.888779	-3.376550
23.973724	27.505692	-3.918990	86.015335	30.888779	-3.427500
24.988846 26.034454	27.505692 27.505692	-3.987470	26.957977	30.888779	-3.479120
27.106400	27.505692	-4.054250	27.928909	30.888779	-3.532850
28.200485	27.505692	-4.119470 -4.170240	28.924316	30.889779	-3.590200
29.312332	27.505692	-4.295310	29.948262 30.972717	30.829779 30.888779	-3.670970
63.316336	C 043036	-4.040310	30.0/2/1/	34.999(13	-3.014914

81-GEN-24218

81-GEN-24219

#### TABLE 2 (CONT) MOD 3 WING COORDINATES

Y-34.4630			Y-38.0373		
	1-34.4030			1-38,03/3	-
×	Ý	2	×	¥ .	Z
33.245972	34.462982	9.088360	35.519333	38.037338	0.087380
32.258194	34.462982	0.051400	34.576218	38.037338	0.054470
31.286209	34.462982	0.005540	33.648193	38.037338	0.011290
30.333862	34.462982	-0.049490	32.738922	38.037338	-0.040580
29.404938	34.462982	-0.109650	31.852005	38.037338	-0.097840
28.503098	34.462982	-0.176630 -0.252210	30.990952 30.159134	38.037338	-0.162240
27.631866	34.462982 34.462982	-0.335920	29.359833	38.037338 38.037338	-0.235680
26.794768	34,462982	-0.427360	29.596207	38.037338	-0.406380
25.994919 25.235672	34.462992	-0.525990	87.871292	38.037338	-4.542320
24.519943	34.462982	-0.630460	87.187943	38.037338	-0.603880
23.850571	34,462982	-0.740110	26.548843	38.037338	-0.710500
23.239194	34.462982	-0.853460	25.956528	38.037338	-0.821020
22.661255	34.462982	-0.970360	25.413315	38.037338	-0.935750
22.146011	34.462982	-1.090500	24.921371	38.037338	-1.054550
21.686493	34.462982	-1.212340	24.482635	38.037338	-1.174870
21.284500	34.462982	-1.335360	24.098831	38.037338	-1.295469
20.941635	34.462982	-1.459190	23,771469	38.037338	-1.415240
20.659241	34.462982	-1.588840	23.501946	38.037338	-1.539879
20.438446	34.462982	-1.699460	- 23.291031	38.037338	-1.642130
20.280090	34.462982	-1.814820	23.139847	38.037338	-1.748660
20.184845	34.462982	-1.922480	23.048904	38.037338	-1.851010
20.153076	34.462982	-2.021910	23.018585	38.037338	-1.947090
20.184845	34.462982	-2,121340	23.048904	38.037338	-2.043170
20.280090	34.462982	-2.218250	23.139847	38.037338	-2.135310
20.438446	34.462982	-2.315170	23.291931	38.037338	-2.225760
20.659241	34.462982 34.462982	-2.412840	23.501846	38.037338 38.037338	-2.317620 -2.498560
20.941635	34.462982	-2,508740	23.771469	38.037338	-2.497290
21.686493	34.462982	-2,688639	24. <b>698</b> 831 24. 482635	38.037338	-2.581960
22.146011	34,462982	-2.770529	24,921371	38.037338	-2.661750
22.661255	34.462982	-2.846540	25.413315	38.037338	-2.735510
23.230194	34.462982	-2.917570	25.956528	38.037338	-2.884498
23.856571	34.462982	-2.983670	26.548943	38.037338	-2.868810
24.519943	34.462982	-3,044670	27.187943	38.037338	-2.928460
25.235672	34.462982	-3.1015R0	27.871292	38. 037338	-2.984240
25,994919	34.462982	-3.154980	28.596207	39. 477338	-3.036550
26.794768	34.462982	-3.205798	29,359833	38.037338 38.037338	-3.086180
27.631866	34.462952	-3.255666	30.159134	38.037338	-3.133570
28.503098	34.462958	-3,383229	38,999952	38.037338	-3.179060
29.404938	34.462952	-3,351339	31,852865	38.037338	-3.223530
30.333862	34.462982	-3,400250	32.738922	38.037338	-3.267650 -3.312560
31.286209	34.462982	-3.451680	33.648193	38.037338	-3.312560
32.258194	34.462982	-3,493250	34.576218	38.037338	-3.349110
33.245972	34.462982	-3.522940	35.519333	38.037338	-3.374999

OF POOR QUALITY



FIGURE 1. NASA MODEL INSTALLED IN AMES 14-FOOT TUNNEL

81-GEN-23245

PRECEDING PAGE BLANK NOT FILMED






FIGURE 2. SIMULATOR TEST INSTALLATION

Preceding page blank









## FIGURE 4. SIDE VIEW OF UNDERWING NACELLE

81 GEN 23204












FIGURE 7. CHORDWISE PRESSURE DISTRIBUTIONS FOR ORIGINAL TURBOPROP CONFIGURATIONS AT  $M_0 = 0.7$ 

.




FIGURE 8. CHORDWISE PRESSURE DISTRIBUTION FOR ORIGINAL TURBOPROP CONFIGURATION AT  $M_{o} = 0.78$ 




FIGURE 9. CHORDWISE PRESSURE DISTRIBUTIONS FOR ORIGINAL TURBOPROP CONFIGURATION AT  $M_0 = 0.8$ 




FIGURE 10. CHORDWISE PRESSURE DISTRIBUTION OR ORIGINAL TURBOPROP CONFIGURATION AT  $M_0 = 0.82$ 




FIGURE 11. PRESSURE DISTRIBUTION AT REDUCED ANGLE OF ATTACK FOR M<sub>0</sub> = 0.8 AND ORIGINAL CONFIGURATION






FIGURE 12. PRESSURE DISTRIBUTION AT INCREASED ANGLE OF ATTACK FOR M<sub>0</sub> = 0.8 AND ORIGINAL CONFIGURATION



 $M_0 = 0.75$  $\alpha = 2 DEG$ WINDMILL UPPER SURFACE

81-GEN 23184A

FIGURE 13. OIL FLOW PHOTOGRAPH AT  $M_0 = 0.75 - WINDMILL CONDITIONS$ 



 $M_0 = 0.8$   $\alpha = 2 DEG$ WINDMILL UPPER SURFACE

81 GEN 23181A

FIGURE 14. OIL FLOW PHOTOGRAPH AT M<sub>o</sub> = 0.8 – WINDMILL CONDITIONS

OF POOR QUALITY





FIGURE 15. PROPELLER SWIRL AND TOTAL PRESSURE RATIO CHARACTERISTICS – ONE BLADE


CHORD DOWNSTREAM – BLADE ANGLE,  $\beta$  = 57 DEGREES



 $M_0 = 0.75$  $\alpha = 2 DEG$ 8100 RPM UPPER SURFACE

81 GEN 23183A

FIGURE 16. OIL FLOW PHOTOGRAPH AT  $M_o = 0.75 - MAXIMUM POWER$ 



 $M_0 = 0.8$  $\alpha = 2 DEG$ 8500 RPM UPPER SURFACE

81 GEN 23182A

FIGURE 17. OIL FLOW PHOTOGRAPH AT M<sub>o</sub> = 0.8 – MAXIMUM POWER




FIGURE 18. COMPARISON OF WING SECTION LIFT DISTRIBUTIONS AT M<sub>0</sub> = 0.7

URIGINAL PAGE IS OF POOR QUALIT




FIGURE 19. COMPARISON OF WING SECTION LIFT DISTRIBUTIONS AT Mo = 0.8




FIGURE 20. LIFT DISTRIBUTION USED FOR INDUCED DRAG CALCULATION







FIGURE 21. COMPARISON OF SIMULATOR EXIT CONDITIONS AND ISOLATED PROPELLER DATA AT  $\beta$  = 59 DEGREES
















FIGURE 25. COMPARISON OF SIMULATOR AND PROPELLER DATA AT M \_ = 0.8 AND  $\eta$  = 0.5




FIGURE 26. COMPARISON OF SIMULATOR AND PROPELLER SECTION LIFT DISTRIBUTION AT  $\rm M_{o}$  = 0.7






FIGURE 27. COMPARISON OF SIMULATOR AND PROPELLER SECTION LIFT DISTRIBUTION AT M = 0.8








ł



 $\begin{array}{c} M = 0.70 \\ \alpha \approx 1.88 \text{ DEGREE} \end{array}$ 










FIGURE 31. COMPARISON OF WING SECTION LIFT DISTRIBUTIONS WITH LIFTING LINE THEORY - '
PROPELLER MODEL



81 GEN 23191

## FIGURE 32. NEUMANN PANELING FOR SIMULATOR MODEL










FIGURE 34. SIMULATOR/NEUMANN SECTION LIFT COEFFICIENT COMPARISON




# FIGURE 35. NEUMANN PANELING FOR PROPELLER MODEL





Ср

81-GEN-23198

# FIGURE 36. COMPARISON OF NEUMANN AND DATA FOR CLEAN WING
















FIGURE 39. COMPARISON OF NEUMANN AND DATA FOR CLEAN WING




81-GEN-23195


FIGURE 40. COMPARISON OF NEUMANN AND DATA FOR WING AND NACELLE - NO POWER


















FIGURE 44. COMPARISON OF NEUMANN AND DATA FOR WING/NACELLE NO POWER AT  $\alpha = 2$  DEGREES



¥

FIGURE 45. COMPARISON OF NEUMANN AND DATA WITH POWER AT  $\alpha$  = 2 DEGREES



81 GEN-24186

FIGURE 46. COMPARISON OF NEUMANN AND DATA FOR CLEAN WING AT  $\alpha$  = 2 DEGREES






FIGURE 47. COMPARISON OF NEUMANN AND DATA FOR WING NACELLE NO POWER AT  $\alpha$  = 2 DEGREES




81-GEN 24187

#### FIGURE 48. COMPARISON OF NEUMANN AND DATA WITH POWER AT $\alpha$ = 2 DEGREES








81-GEN-23243A

FIGURE 50. COMPARISON OF JAMESON AND EXPERIMENTAL CHORDWISE PRESSURE DISTRIBUTIONS FOR CLEAN WING CONFIGURATION  $M_{a}$  = 0.800








FIGURE 52. COMPARISON OF JAMESON AND EXPERIMENTAL CHORDWISE PRESSURE DISTRIBUTIONS – WITH POWER  $M_0 = 0.7$ 




FIGURE 53. EXPERIMENTAL WING SECTION LIFT COMPARISON WITH THEORY AT  $M_0 = 0.7$ 




FIGURE 54. COMPARISON OF JAMESON AND EXPERIMENTAL CHORDWISE PRESSURE DISTRIBUTIONS FOR POWERED PROP CONFIGURATION




FIGURE 55. COMPARISON OF JAMESON AND EXPERIMENTAL CHORDWISE PRESSURE DISTRIBUTIONS FOR POWERED PROP CONFIGURATION AT  $M_0 = 0.8$ 




FIGURE 56. WING SECTION LIFT COMPARISON WITH THEORY AT  $M_{o} = 0.8$ 




FIGURE 57. PLANFORM MODIFICATION




FIGURE 58. MOD 2 AND MOD 3 AIRFOILS AT  $\eta = 0.120$ 

81-GEN 24195






FIGURE 59. MOD 2 AIRFOIL AT  $\eta = 0.350$ 









81-GEN-23226

FIGURE 62. MOD 3 AIRFOIL AT  $\eta = 0.43$ 




FIGURE 63. COMPARISON OF CALCULATED CHORDWISE PRESSURE DISTRIBUTIONS USING JAMESON - CLEAN WING M<sub>o</sub> = 0.800




FIGURE 64. COMPARISON OF JAMESON CALCULATED CHORDWISE PRESSURE DISTRIBUTIONS FOR POWERED CONFIGURATIONS  $\rm M_{\Lambda}$  = 0.800





FIGURE 65. SECTION LIFT CHANGE DUE TO WING MOD 2 AND MOD 3



СР








FIGURE 67. INCOMPRESSIBLE JAMESON AT  $\eta$  = 0.42








## PERCENT CHORD


81-GEN-23236

FIGURE 69. PRESSURE DISTRIBUTION FOR WINGS PLUS NACELLE WITHOUT POWER AT  $\eta = 0.37$ 



81-GEN-23235


FIGURE 70. PRESSURE DISTRIBUTION FOR WINGS WITH NACELLES AND POWER AT  $\eta$  = 0.37



Cp


81-GEN-23234

FIGURE 71. PRESSURE DISTRIBUTION FOR CLEAN WINGS AT  $\eta$  = 0.41




81-GEN-23233

FIGURE 72. PRESSURE DISTRIBUTION FOR WINGS PLUS NACELLE WITHOUT POWER AT  $\eta$  = 0.41







81-GEN-23232

FIGURE 74. PRESSURE DISTRIBUTION OUTBOARD OF NACELLE, WITH NACELLE AND POWER  $\eta = 0.56$ 







FIGURE 75. COMPARISON OF SECTION LIFT DISTRIBUTION CALCULATED USING NEUMANN







## FIGURE 77. PRESSURE DISTRIBUTION FOR WINGS PLUS NACELLE WITHOUT POWER $\eta$ = 0.37 AND $\alpha$ = 2 DEGREES



81-GEN-24188










FIGURE 79. PRESSURE DISTRIBUTION FOR CLEAN WINGS AT  $\eta$  = 0.41 AND  $\alpha$  = 2 DEGREES












FIGURE 82. CLEAN WING STREAMLINE - PROFILE VIEW

81-GEN-23203





FIGURE 83. CLEAN WING STREAMLINES – PLAN VIEW



## FIGURE 84. STREAMLINE CONTOURED LOWER SURFACE AFT NACELLE





FIGURE 85. EFFECT OF CONTOURING AFT PORTION OF UNDERWING NACELLE

ORIGINAL PAGE IS OF POOR QUALITY



81-GEN-23211

FIGURE 86. SUBSCALE MOCKUP OF POTENTIAL UNDERWING NACELLE CONTOURING




FIGURE 87. SIDE VIEW NONCONTOURED OVERWING NACELLE




FIGURE 88. PLAN VIEW OF OVERWING CONTOURED NACELLE





FIGURE 89. SIDE VIEW OF OVERWING CONTOURED NACELLE



81-GEN-24196









FIGURE 91. PRESSURE DISTRIBUTION COMPARISON FOR CONTOURED NACELLE AT  $\eta$  = 43 PERCENT









1. Report No.	2. Government Accession No.	3. Recipient's Catalog No.		
NASA CR 166214				
4. Title and Subtitle Analysis of Mach Number 0.8 Turboprop Slipstream		5. Report Date		
		August 6, 1981		
Wing/Nacelle Interactions		6. Performing Organization Code		
7. Author(s) H. Robert Welge, Dan H. Neuhart, John A. Dahlin		8. Performing Organization Report No.		
		ACEE-25-FR-1564		
		10. Work Unit No.		
9. Performing Organization Name and Address		· · · · · · · · · · · · · · · · · · ·		
Douglas Aircraft Company 3855 Lakewood Blvd. Long Beach, Ca 90846		11. Contract or Grant No.		
		NAS2-10881		
		13. Type of Report and Period Covered		
12. Sponsoring Agency Name and Address				
National Aeronautics and Space Administration		Contract Final Report		
Ames Research Center		14. Sponsoring Agency Code		
Moffett Field, CA 94035				
15. Supplementary Notes				
Technical Monitor: Al Levin (227-2)				
NASA Research Center				
Moffett Field, CA 94035				
16. Abstract	· · ·			
An experimental test program of a powered propeller and nacelle mounted on a				
supercritical wing was condu				
tunnel. Analysis of this data by the Douglas Aircraft Company, under contract to				
NASA with Al Lavin as the program manager, is contained in this report. The design				
condition for this study was	$M_0 = 0.8.$			
Analysis of the data indicated that the installation of the nacelle significantly				
affected the wing flow and that the flow on the upper surface of the wing is separate				
near the leading edge under powered conditions. Comparisons of various theories with				
the data indicated that the Neumann surface panel solution and the Jameson transonic				
solution gave results adequate for design purposes. A modified wing design was de-				
veloped (Mod 3) which reduces the wing upper surface pressure coefficients and sec-				
tion lift coefficients at powered conditions to levels below those of the original wing without nacelle or power. A contoured over-the-wing nacelle is described that				
can be installed on the original wing without any appreciable interference to the				
can be moturiou on the orig	mar wing wrinout any apprec			

17. Key Words (Suggested by Author(s)) Turboprop Propfan Wing Design Propulsion Integration	18. Distribution Unrestr		
19. Security Classif. (of this report)	20. Security Classif. (of this page)	21. No. of Pages	22. Price*
Unclassified	Unclassified		

\* For sale by the National Technical Information Service, Springfield, Virginia 22151

A ...

a yes

4.5

wing upper surface pressures.

.

. .

·

. .

. .

. .

·

## DOUGLAS AIRCRAFT COMPANY

3855 Lakewood Boulevard, Long Beach, California 90846 (213) 593-5511

MCDONNELL DOUGLAS

Printed in U.S.A. 8/81 S81-2445