NASA TM X-3545

brought to you by **CORE**

FECH LIBRARY KAFB, NM

TO

AR'

NASA TM X-3545 2.1

AN COPY:

AFWL TECHNIC

NASA TECHNICAL MEMORANDUM

EFFECT OF GYRO VERTICALITY ERROR ON LATERAL AUTOLAND TRACKING PERFORMANCE FOR AN INERTIALLY SMOOTHED CONTROL LAW

Jerry J. Thibodeaux Langley Research Center Hampton, Va. 23665

4

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION . WASHINGTON, D. C. . JUNE 1977



						0152182]
1	Report No	2 Government Access	sion No	3	Recipie	nts Catalog ivu	•
	NASA TM X-3545						
4	Title and Subtitle			5	Report		
	EFFECT OF GYRO VERTICAL	RAL		June	e 1977		
	AUTOLAND TRACKING PERFOR		6 Pe	Perform	Performing Organization Code		
	INERTIALLY SMOOTHED CONTROL LAW						
7	Author(s)		8	Perform	ning Organization	Report No	
	Jerry J. Thibodeaux				L_1	1428	
			10	Work L			
9	Performing Organization Name and Address				513-52-01-19		
	NASA Langley Research Center						
	Hampton, VA 23665		11	Contrac	t or Grant No		
				13		f Report and Per	
12	Sponsoring Agency Name and Address	d Space Administ			Tecl	hnical Memo	al Memorandum
	National Aeronautics and Washington, DC 20546	ation	14	Sponso	ring Agency Code	e	
	masiitiig voii, DC 20340					5 <u>5</u> ,	
5	Supplementary Notes			A			· · · · · · · · · · · · · · · · · · ·
16	Abstract						
	This poport process	to the secults of					
	This report present						
	the effects of gyro vert	ticality error on	lateral au	toland t	racki	ng and land	ding
	the effects of gyro vert performance. A first-on	ticality error on rder vertical gyr	lateral au o error mod	itoland t del was u	racki sed to	ng and land o generate	ding the
	the effects of gyro vert performance. A first-on measurement of the roll	ticality error on rder vertical gyr attitude feedbac	lateral au o error mod k signal no	itoland t del was u ormally s	racki sed to uppli	ng and land o generate ed by an 11	ding the nertial
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The	ticality error on rder vertical gyr attitude feedbac lateral autoland	lateral au o error mod k signal no law used r	itoland t del was u ormally s nere was	racki sed to uppli an in	ng and land o generate ed by an 18 ertially s	ding the nertial moothed
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a	lateral au o error mod k sıgnal no law used h ngular gyro	itoland t del was u ormally s nere was o tilt er	racki sed to uppli an in rors	ng and land o generate ed by an 11 ertially su (2°, 3°, 40	ding the nertial moothed ^o , and
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5° , introduced prior to	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu	lateral au o error mod k signal no law used h ngular gyro re, were in	itoland t del was u ormally s here was o tilt er hvestigat	racki sed to uppli an in rors ed by	ng and land o generate ed by an 11 ertially st (2°, 3°, 40 use of a s	ding the nertial moothed ^o , and small
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep	itoland t del was u ormally s nere was o tilt er nvestigat oresent t	racki sed to suppli- an in- rors ed by he de	ng and land o generate ed by an 11 ertially st (2°, 3°, 40 use of a st viations wh	ding the nertial moothed ^o , and small hich
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft so could occur in the conve	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as	atoland t del was u prmally s pere was p tilt er nvestigat present t a result	rackin sed to uppli an in rors ed by he de of t	ng and land o generate ed by an in ertially su (2°, 3°, 40 use of a su viations when maneuver	ding the nertial moothed ⁰ , and small hich r-
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft so could occur in the conve induced spin-axis misals	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results	atoland t del was u prmally s nere was o tilt er nvestigat present t a result showed t	rackin sed to suppli- an in- rors ed by he de of th hat fo	ng and land o generate ed by an in ertially st (2°, 3°, 40 use of a s viations wh he maneuver or a 1.05°	ding the nertial moothed ^o , and small hich r- per
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft so could occur in the conve induced spin-axis misals minute erection rate and	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, "	atoland t del was u prmally s nere was o tilt er nvestigat present t a result showed t 'ON COURS	rackin sed to appli- an in- rors ed by he dev of to hat fo E" au	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont	ding the nertial moothed ^o , and small hich r- per trol
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft so could occur in the conve induced spin-axis misals	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atta	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft so could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied.	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er nvestigat present t a result showed t 'ON COURS V COURSE"	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
7	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied control loop gains and b	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON	atoland t del was u prmally s here was o tilt er hvestigat present t a result showed t 'ON COURS N COURSE" tion and	rackin sed to uppli an in rors ed by he de of to hat fo E" au mode	ng and land o generate ed by an in ertially sr (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded	ding the nertial moothed ^o , and small hich r- per trol high
7	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misalis minute erection rate and logic was not satisfied control loop gains and l able beam standoff at to	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a b localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti- localizer beam pa	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON th integrat	atoland t del was u ormally s here was o tilt er hvestigat oresent t a result showed t 'ON COURS I COURSE" tion and	rackin sed to uppli an in rors ed by he dev of to hat fo E" au mode resul	ng and land o generate ed by an in ertially sr (2°, 3°, 40 use of a s viations wh he maneuver or a 1.05° toland cont precluded ted in unac	ding the nertial moothed ^o , and small hich r- per trol high
7	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misalis minute erection rate and logic was not satisfied. control loop gains and I able beam standoff at to Key Words (Suggested by Author(s)) Control systems	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a o localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti localizer beam pa ouchdown.	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON th integrat	atoland t del was u prmally s here was o tilt er hvestigat present t a result showed t 'ON COURS N COURSE" tion and	rackin sed to uppli an in rors ed by he dev of to hat fo E" au mode resul	ng and land o generate ed by an in ertially sr (2°, 3°, 40 use of a s viations wh he maneuver or a 1.05° toland cont precluded ted in unac	ding the nertial moothed ^o , and small hich r- per trol high
7	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misalis minute erection rate and logic was not satisfied. control loop gains and J able beam standoff at to Key Words (Suggested by Author(s)) Control systems Automatic landing system	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a o localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti localizer beam pa ouchdown.	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON th integrat	atoland t del was u ormally s here was o tilt er hvestigat oresent t a result showed t 'ON COURS I COURSE" tion and	rackin sed to uppli an in rors ed by he dev of to hat fo E" au mode resul	ng and land o generate ed by an in ertially sr (2°, 3°, 40 use of a s viations wh he maneuver or a 1.05° toland cont precluded ted in unac	ding the nertial moothed ^o , and small hich r- per trol high
7	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misalis minute erection rate and logic was not satisfied. control loop gains and I able beam standoff at to Key Words (Suggested by Author(s)) Control systems	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a o localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti localizer beam pa ouchdown.	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON th integrat	atoland t del was u ormally s here was o tilt er hvestigat oresent t a result showed t 'ON COURS I COURSE" tion and	rackin sed to uppli an in rors ed by he dev of to hat fo E" au mode resul	ng and land o generate ed by an in ertially sr (2°, 3°, 40 use of a s viations wh he maneuver or a 1.05° toland cont precluded ted in unac	ding the nertial moothed ^o , and small hich r- per trol high
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied. control loop gains and J able beam standoff at to Key Words (Suggested by Author(s)) Control systems Automatic landing system Vertical gyros	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a o localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti localizer beam pa puchdown.	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON th integrat	atoland t del was u ormally s here was o tilt er hvestigat oresent t a result showed t 'ON COURS N COURSE" tion and	Unlin	ng and land o generate ed by an in ertially st (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded ted in unac	ding the nertial moothed ⁰ , and small hich r- per trol high ccept-
	the effects of gyro vert performance. A first-on measurement of the roll navigation system. The control design. The eff 5°), introduced prior to perturbation aircraft si could occur in the conve induced spin-axis misals minute erection rate and logic was not satisfied. control loop gains and J able beam standoff at to Key Words (Suggested by Author(s)) Control systems Automatic landing system Vertical gyros	ticality error on rder vertical gyr attitude feedbac lateral autoland fect of initial a o localizer captu imulation. These entional attitude inement and drift d a 5° initial ti . Failure to atti localizer beam pa ouchdown.	lateral au o error mod k signal no law used h ngular gyro re, were in errors rep sensor as . Results lt error, " ain the "ON th integrat	atoland t del was u ormally s here was o tilt er hvestigat oresent t a result showed t 'ON COURS I COURSE" tion and	Unlin	ng and land o generate ed by an in ertially st (2°, 3°, 4° use of a s viations wh he maneuver or a 1.05° toland cont precluded ted in unac	ding the nertial moothed ⁰ , and small hich r- per trol high ccept-

-

٠

•

•

.

* For sale by the National Technical Information Service Springfield Virginia 22161

EFFECT OF GYRO VERTICALITY ERROR ON

LATERAL AUTOLAND TRACKING PERFORMANCE FOR AN

INERTIALLY SMOOTHED CONTROL LAW

Jerry J. Thibodeaux Langley Research Center

SUMMARY

This report presents the results of a simulation study performed to determine the effects of gyro verticality error on the simulated lateral autoland tracking and landing performance of a small twin-jet short-haul commercial transport. A vertical gyro error model was used to generate the roll attitude signal which was used with the inertially smoothed control law in a small perturbation simulation. The influence of initial angular gyro tilt errors $(2^{\circ}, 3^{\circ}, 4^{\circ}, and$ 5°) introduced prior to localizer capture for a 1.05° per minute gyro erection rate was investigated. These errors were used to simulate deviations which may occur in the attitude sensor as a result of the cumulative effects of maneuverinduced spin-axis misalinement and drift. Results showed that for a 5° initial tilt error, the lateral "ON COURSE" autoland control logic was not satisfied and thereby localizer beam path integration was precluded and unacceptable beam standoff at touchdown occurred.

INTRODUCTION

Throughout the evolution of automatic landing systems for aircraft, it became apparent to designers that landing decision heights could be decreased by means of increased navigation data accuracy. The current impetus toward reduced civil aircraft landing minima has sharply brought into focus the demand for such noise-free highly accurate navigation information in the form of vehicle attitude, position, velocity, and acceleration. The introduction of the microwave landing system (MLS) promises to provide accurate position data. Because of this system, the potential exists for obtaining accurate estimates of position, velocity, and acceleration information for guidance and control by processing MLS data with relatively low-cost onboard sensors such as bodymounted accelerometers and standard attitude gyros. If this potential can be achieved, acceptable automatic landing performance may be attained by using the MLS and low-cost onboard sensors in lieu of high-cost inertial platforms. However, because of new flight techniques for approach to landing which may consist of much terminal area maneuvering, a general concern has arisen as to the effects of maneuver-induced errors of conventional sensors on automatic control systems.

Although it is true that inertial systems have fulfilled the data accuracy requirements, expensive purchasing and maintenance costs are discouraging to aircraft operators to say the least. Thus, a simulation study was undertaken

to investigate the lateral performance of an inertially smoothed control law by using a conventional vertical gyro which simulated maneuver-induced tilt errors. It was assumed in this study that other guidance data such as lateral position, velocity, and acceleration information were accurately obtained. In other words, no error models were incorporated for these data in the simulation.

The purpose of this paper is to present the results of a study showing the influence of simulated maneuver-induced gyro verticality error on the lateral tracking performance of an automatic landing system of a small twin-jet short-haul commercial transport (fig. 1). Reference 1 provides detailed information on this control law. This class of error occurs in attitude gyros subjected to low-frequency oscillations associated with preapproach maneuvering during curved or decelerating approaches. In particular, tests were directed toward determining the effects of various initial gyro tilt errors (2° , 3° , 4° , and 5°) for a vertical gyro erecting at 1.05° per minute. This erection rate is typical of many of the present-day commercially available vertical gyros. Particular attention was devoted to the lateral tracking performance while on a short 8334 m (4.5 n. mi.) approach. The tilt errors and erection rate were simulated by the use of a first-order vertical gyro error model.

SYMBOLS

Values are presented in both SI and U.S. Customary Units. Calculations were made in U.S. Customary Units.

c	local level acceleration, g units
g	acceleration constant due to gravity, m/sec^2 (ft/sec ²)
h	altıtude, m (ft)
hR	radio altitude, m (ft)
κ _η	filter gain
к _{ψG}	gain on ground heading through transient-force gain changer
s	Laplace transform
v	total airspeed, m/sec (ft/sec)
V _G	total groundspeed, m/sec (ft/sec)
X,Y	x- and y-coordinates in X and Y Earth axes, m (ft)
Ý	cross-track velocity, m/sec (ft/sec)
β	glideslope error, deg
δ _a	aileron position, deg

2

••

δ_{ac}	aileron command, deg
δ _e	elevator position, deg
δ _{ec}	elevator command, deg
δ _r	rudder position, deg
δ_{sp}	spoiler position, deg
$\delta_{\texttt{stab}}$	stabilizer position, deg
δ_t	thrust, N (1b)
δ_{tc}	thrust command, N (1b)
η	angular displacement, deg
n _{est}	filtered angular displacement, deg
nloc	localızer beam angular displacement, deg
ո _p	angular displacement that has been gain programed as a function of altitude, deg
θ	pitch attitude, deg
τ	time constant, sec
φ	true roll attitude, deg
φ _c	bank angle command, deg
φ _m	measured roll attitude from vertical gyro model, deg
ψ	heading, deg
ΨG	ground heading, deg
Subscript	;s:
ILS	instrument landing system

lim limit

,

•

.

٠

Dots (\cdot) over symbols indicate differentiation with respect to the independent variable time.

A caret (^) over a symbol denotes output of minimum value discriminator.

SIMULATION PROGRAM

A block diagram of the simulation program is shown in figure 2 and consists of the inertially smoothed control laws and servo dynamics into which thrust, aileron, and elevator commands were input. Linear aircraft equations of motion in perturbed state form were written in order to determine vehicle position. velocity, acceleration, and attitude information. These equations were written to form the vehicle model used in the flight critical control laws to compute errors from the desired flight. This study was conducted by use of a digital simulation of a small twin-jet research aircraft whose systems are described in references 2 and 3. The trajectory for this study was a 61.73 m/sec (120-knot), 3° descent to touchdown. Based on these deviations from this trajectory, control commands were introduced to the respective servos of the vehicle control system. Utilization of roll attitude feedback was made after being corrupted by the vertical gyro error model. Shown in figure 2 are the blocks representing the longitudinal and lateral autoland systems. Spoiler input was formulated by a 1.73 gain on the alleron signal. First-order lag models were used to describe engine thrust response. The control signals thus derived together with the yaw damper output were introduced into the aircraft perturbation equations of motion which were written in state variable form.

The perturbation states in vehicle stability axes were pitch attitude θ , normalized inertial velocity u', angle of attack α , pitch rate q, bank angle ϕ , heading ψ , sideslip β , roll rate p, and yaw rate r. The control vector consisted of perturbed elevator position δ_e , perturbed stabilizer position δ_{stab} , perturbed thrust δ_t , perturbed alleron position δ_a , perturbed spoiler position δ_{sp} , and perturbed rudder position δ_r . Aerodynamic data were obtained by use of a data program package at the Langley Research Center for the aircraft in the landing configuration, that is, gear down, flaps 40° down, 61.73 m/sec (120 knots) airspeed, and a weight of 400 kN (90 000 lb).

Gyro Error Model

Figure 3 is a block diagram showing the fundamental elements of the single degree of freedom vertical gyro error model. The errors associated with a conventional vertical gyro (ref. 4) are a result of three distinct effects:

(1) Cumulative drift effects: Because of mass unbalance, bearing friction, Earth rotation rate, and coriolis acceleration, the gyro spin axis becomes misalined with the true local vertical.

(2) Maneuver-induced spin-axis alinement with a false vertical: During periods of accelerated flight (forward or centripetal acceleration present), the gimbal-mounted electrolytic bubble sensors cause the gyro to be alined with a false vertical. This false or apparent vertical is the vector addition of vehicle acceleration and gravity.

(3) Propogation error in turns: This effect predominantly occurs in aircraft turns during which time the gyro spin axis tends to maintain a fixed spatial orientation as the airplane and gimbals rotate about the gyro. The result of this phenomena is that any existing pitch error while on a northern heading translates to a roll error when heading is changed to east or west.

The fundamental components of the gyro model (fig. 3) are the erection rate limiter and cutout and the torque motor. The cutout threshold for these tests was set to a lateral acceleration corresponding to a 6° bank angle. In other words, whenever the apparent lateral acceleration sensed by the roll bubble exceeded the acceleration corresponding to 6° roll, erection cutout occurred. The angular position error is then formed by the addition of the drift and the erection signal from the torque motor. Finally, this error was added to the true attitude for formulation of the measured roll attitude signal.

Tests

The initial setup for this study is shown in figure 4. A relatively short straight-in final approach was used after the aircraft was started at capture in straight and level flight but offset by 365.76 m (1200 ft). It was also given a 20° localizer intercept angle. Initial condition errors between the spin axis and the local vertical (see fig. 3) were injected prior to commencing the problem. All these gyro tilt errors (2° , 3° , 4° , and 5°) were positive, that is, right wing down which simulates a worse case situation. Also, gyro drift and Earth rates were assumed to be positive. Vehicle automatic tracking performance was monitored through touchdown for each tilt error and the selected erection rate. Wind velocity was considered to be zero in these tests.

RESULTS AND DISCUSSION

The lateral autoland tracking performance was examined for a gyro erection rate of 1.05⁰ per minute after initial gyro tilt errors were induced prior to localizer capture. Figure 5 shows the lateral tracking performance when the inertial roll attitude feedback that would be expected from a stabilized platform is used. It is realized that because of preapproach maneuvering, maximum roll attitude errors of the order of 0.1^o are possible with stabilized platforms, but in the context of this paper they were considered to be insignificant. In other words, the inertial platform attitude signal was deemed to be perfect. Figures 6 to 9 show the effect of the various tilt errors on the final approach trajectory. Tracking and overshoot errors observed in figures 6 to 8 are due to the initial gyro tilt errors which are not completely eliminated by erection. The lower plot gives the variation of tilt error with respect to time. It should be noted that although the induced lateral displacement errors (due to initial 2°, 3°, and 4° gyro tilt) at touchdown are small, they are systematic and may be significant percentagewise when compared with the influence of other environmental and landing system errors. For the 5° tilt error (fig. 9), unacceptable standoff and divergence from the runway center line were observed. The lateral touchdown dispersion for 2° , 3° , and 4° tilt errors are plotted in figure 10 and vary from -0.45 m (-1.47 ft) to -0.53 m (-1.74 ft). For the 5° tilt error where the control logic was not satisfied, the lateral deviation at touchdown was 101.98 m (334.57 ft) and is unacceptable.

The behavior of figure 9 can be understood if the lateral autoland control loop (fig. 11) is studied. Three logic criteria must be satisfied in order to acquire the "ON COURSE" state. In order to satisfy all criteria ("ON COURSE" set to true in the simulation), the localizer beam angle must be less than $\eta_{1,m}$ (see insert (A) in fig. 11) and the beam rate less than 0.027° per second. Also, the bank angle must be less than 3° . When all criteria are satisfied, "ON COURSE" is set to true and the appropriate switch closures result. Of these three criteria, the last two are readily satisfied; however, the first requirement depends on beam deviation and may or may not be satisfied depending on the tilt error encountered at localizer capture. Because the beam acceptance limit η_{lim} is a function of altitude and decreases rapidly relative to tilt error reduction, it was found that the localizer angular displacement η did not become sufficiently small compared with η_{lim} for the 5° tilt error. As a result, the localizer beam integration loop whose primary function is to reduce the steady-state beam displacement error to zero is never incorporated into the control law. Also, the high loop gains (inserts (C) and (D) in fig. 11) are not attained; thereby less precise tracking and unacceptable beam standoff at touchdown result.

CONCLUDING REMARKS

The results of this study indicate that vertical gyro tilt errors, which may be substantial because of terminal area maneuvering and gyro imperfections, can degrade lateral autoland tracking performance measurably. In addition, for the control law examined, there is an error threshold which, if exceeded, precludes localizer capture because the "ON COURSE" logic criteria could not be satisfied.

Langley Research Center National Aeronautics and Space Administration Hampton, VA 23665 May 6, 1977

REFERENCES


- Bleeg, Robert J.; Tisdale, Henry F.; and Vircks, Robert M.: Inertially Augmented Automatic Landing System. Autopilot Performance With Imperfect ILS Beams. FAA-RD-72-22, Apr. 1972. (Available from DDC as AD 742 967.)
- 2. Reeder, John P.; Taylor, Robert T.; and Walsh, Thomas M.: New Design and Operating Techniques for Improved Terminal Area Compatibility. Preprint 740454, Soc. Automot. Eng., Apr.-May 1974.

٠

3

4


- 3. Salmırs, Seymour; and Tobie, Harold N.: Electronic Displays and Digital Automatic Control in Advanced Terminal Area Operations. AIAA Paper No. 74-27, Jan.-Feb. 1974.
- 4. Blakelock, John H.: Automatic Control of Aircraft and Missiles. John Wiley & Sons, Inc., c.1965.




~

Figure 1.- Dimensions of simulated aircraft.

•










•



ſ

Figure 4.- Test situation and sign convention.




Figure 5.- Lateral tracking performance using inertial roll attitude feedback.





Figure 6.- Lateral tracking performance for a 2⁰ vertical gyro tilt error prior to localizer capture.



1 05° per minute erection rate

Figure 7.- Lateral tracking performance for a 3^o vertical gyro tilt error prior to localizer capture.







Figure 8.- Lateral tracking performance for a 4° vertical gyro tilt error prior to localizer capture.





ł

Figure 9.- Lateral tracking performance for a 5° vertical gyro tilt error prior to localizer capture.









۰.

¢

ę

,

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION WASHINGTON, D.C. 20546

> OFFICIAL BUSINESS PENALTY FOR PRIVATE USE \$300

SPECIAL FOURTH-CLASS RATE BOOK

POSTAGE AND FEES PAID NATIONAL AERONAUTICS AND SPACE ADMINISTRATION 451



A 770610 S00903DS 433 001 C1 U DEPT OF THE AIR FORCE AF WEAPONS LABORATORY ATTN: TECHNICAL LIBRARY (SUL) KIRTLAND AFB NM 87117

If Undeliverable (Section 158 Postal Manual) Do Not Return

"The aeronautical and space activities of the United States shall be conducted so as to contribute ... to the expansion of human knowledge of phenomena in the atmosphere and space. The Administration shall provide for the widest practicable and appropriate dissemination of information concerning its activities and the results thereof."

-NATIONAL AERONAUTICS AND SPACE ACT OF 1958

NASA SCIENTIFIC AND TECHNICAL PUBLICATIONS

TECHNICAL REPORTS: Scientific and technical information considered important, complete, and a lasting contribution to existing knowledge.

TECHNICAL NOTES: Information less broad in scope but nevertheless of importance as a contribution to existing knowledge.

TECHNICAL MEMORANDUMS:

Information receiving limited distribution because of preliminary data, security classification, or other reasons. Also includes conference proceedings with either limited or unlimited distribution.

CONTRACTOR REPORTS: Scientific and technical information generated under a NASA contract or grant and considered an important contribution to existing knowledge.

TECHNICAL TRANSLATIONS: Information published in a foreign language considered to merit NASA distribution in English.

SPECIAL PUBLICATIONS: Information derived from or of value to NASA activities. Publications include final reports of major projects, monographs, data compilations, handbooks, sourcebooks, and special bibliographies.

TECHNOLOGY UTILIZATION

PUBLICATIONS: Information on technology used by NASA that may be of particular interest in commercial and other non-aerospace applications. Publications include Tech Briefs, Technology Utilization Reports and Technology Surveys.

Details on the availability of these publications may be obtained from: SCIENTIFIC AND TECHNICAL INFORMATION OFFICE NATIONAL AERONAUTICS AND SPACE ADMINISTRATION Washington, D.C. 20546