

8-2017

Flume Tests on Fluvial Erosion Mechanisms in Till-bed Channels

Peter Ashmore
pashmore@uwo.ca

Follow this and additional works at: <https://ir.lib.uwo.ca/geographypub>



Part of the [Geography Commons](#)

Citation of this paper:

Ashmore, Peter, "Flume Tests on Fluvial Erosion Mechanisms in Till-bed Channels" (2017). *Geography Publications*. 350.
<https://ir.lib.uwo.ca/geographypub/350>

**Flume tests on fluvial erosion mechanisms in till-bed
channels**

Journal:	<i>Earth Surface Processes and Landforms</i>
Manuscript ID	ESP-16-0186.R2
Wiley - Manuscript type:	Research Article
Date Submitted by the Author:	27-Mar-2017
Complete List of Authors:	Pike, Leila; McGill University, Department of Civil Engineering and Applied Mechanics Gaskin, Susan ; McGill University, Department of Civil Engineering and Applied Mechanics; McGill University Ashmore, Peter; University of Western Ontario, Geography
Keywords:	rivers, geomorphology, semi-alluvial, tills, erosion

Flume tests on fluvial erosion mechanisms in till-bed channels

L. Pike¹, S. Gaskin¹, P. Ashmore²

1. *Department of Civil Engineering, McGill University, Montreal, Quebec, Canada*
2. *Department of Geography, University of Western Ontario, London, Ontario, Canada*

Abstract

Semi-alluvial stream channels eroded into till and other glacial sediments are common in areas of extensive glacial deposition such as the Great Lakes region and northern interior plains of North America. The mechanics of erosion and erosional weakness of till results in the dominance of fluvial scour and spontaneous fracture at planes of weakness under shearing flow. There have been few controlled tests looking at erosional mechanisms and resistance of till in river channels. We subjected small blocks of till to unidirectional flows in a laboratory flume to measure the threshold shear stress for erosion and observed the erosion mechanics. Critical shear stress for erosion varied from 7 – 8 Pa for samples with initial saturated moisture content in which a combination of fluvial scour and mass cracking/block erosion dominated. When dried, micro-fissures occurred in the sample and erosional resistance of the till was extremely low at < 1 Pa with erosion appearing to be by fluvial scour. When mobile gravel was added to the test conditions, the gravel reduced the erosion threshold slightly because of the enhanced scour around and below the gravel particles and the tendency for the gravel to aid in crack enlargement. Thus a partial or thin gravel cover over the till may provide no protection from erosion. The erosion processes and effects reflect the complex and contingent mechanics and properties of till, and suggest that the erosion characteristics of till bed semi-alluvial channels differ from abrasion or plucking dominated processes in more resistant bedrock.

Keywords: rivers, geomorphology, semi-alluvial, tills, erosion

Introduction

In depositional landscapes formed by continental ice sheets, such as those in the depositional zone of the Laurentide Ice Sheet of North America, modern river valleys are commonly eroded into glacial sediments rather than into the underlying bedrock (Ashmore and Church, 2001; Gran et al, 2013; Phillips and Desloges, 2014, 2015; Thayer and Ashmore, 2016). These glacial sediments are exposed in river channel boundaries. The glacial deposits vary in composition and origin and include till, glacio-fluvial and glacio-lacustrine sediments. In many cases, especially in till deposits, the material is cohesive but also contains sand and gravel, and may include large clasts up to boulder size even in low relief landscapes. Some of these glacially-derived boundary materials are easily eroded and yield non-cohesive sediments that form local alluvial deposits. Consequently, river banks may include both glacial and alluvial layers, and channel beds may be fully exposed (cohesive) glacial sediments or have a (transient) cover of alluvial deposits varying in extent, thickness and grain size that include rounded clasts of eroded cohesive glacial sediments (Ashmore and Church, 2001, Gran et al., 2013; Thayer and Ashmore, 2016). The combination of non-alluvial (but highly erodible) boundaries and morphological adjustability led Ashmore and Church (2001) to refer to rivers of this type in glaciated landscapes as “semi-alluvial” (see also Meshkova et al, 2011; Khan and Kostaschuk, 2011; Phillips and Desloges, 2014; Thayer and Ashmore, 2016). Although this term has also been used to with resistant bedrock boundaries and partial alluvial cover (Turowski et al., 2008), the two types of channel (bedrock and cohesive glacial sediments) are quite distinct with respect to geomorphic history, morphology (e.g. downstream hydraulic geometry), boundary material mechanics, adjustability to changing flow regime, and erosion processes.

1
2
3 An important practical issue is that semi-alluvial rivers of this type, while constrained by
4 the cohesive boundary materials at moderate flows, are likely to respond to extreme high
5 flows and other exogenic changes in a manner, and at a rate, much like alluvial channels
6 (Ashmore and Church, 2001; Thayer et al, 2016). Predicting these adjustments, mitigating
7 adverse erosion effects from, for example, urbanization, modeling long-term landscape
8 development (Gran et al., 2013) and understanding fluvial history and current influences
9 on river dynamics (Phillips and Desloges, 2015; Thayer et al., 2016), all require greater
10 understanding of the geomorphology of this type of river. A fundamental component is
11 explaining and predicting erodibility and erosion mechanisms of various glacially-derived,
12 cohesive boundary materials.
13
14
15
16
17
18
19
20
21
22
23
24
25
26

27
28 Recent research on erosion of bedrock in river channels has resulted in significant
29 observational and theoretical advances in understanding fluvial erosion of rock beds
30 (Turowksi, 2012; Whipple et al. 2000, 2013; Hodge, 2017). Erosion mechanisms and
31 resistance vary substantially with rock properties and include mass erosion (block
32 separation and detachment), fluvial scour (hydraulic surface erosion) and micro- and
33 macro-abrasion (Chatanantavet and Parker, 2009). Macro-abrasion is defined as erosion
34 of blocks of bedrock due to particle impacts fracturing the bedrock into pluckable sizes
35 (Chantanantavet and Parker, 2009). Overall resistance to erosion has been shown to
36 relate to bulk properties of the rock such as compressive strength (Stock et al. 2005).
37 Much of the focus of research on long-term fluvial incision into bedrock has been on
38 abrasion mechanisms (Whipple et al, 2013), which are assumed to dominate in most
39 settings where resistance to clear-water fluvial scour is so high as to make it largely
40 ineffective. Observations to date (Kamphuis et al., 1990; Gaskin et al., 2003; Khan and
41 Kostaschuk, 2011, Mier and Garcia, 2011) suggest that for glacial diamicts such as till,
42 fluvial scour and block separation at low stresses are much more effective than in most
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

1
2
3 rock bed channels and this is an important difference in understanding the morphology
4
5 and development of semi-alluvial channels eroded into glacial deposits.
6
7

8
9 Variability in composition and structure of till and other glacial diamicts makes the
10
11 development of general predictions of erodibility difficult. However, analysis of a sufficient
12
13 range of materials may provide some general empirical guidance and expected ranges of
14
15 values and behaviour. Erosion testing of glacial sediments has been done using either
16
17 small intact samples in a laboratory flume or *in situ* jet testing devices. Tests have
18
19 concentrated on erosion by clear-water fluid stress and by mass erosion, which are
20
21 assumed to be the dominant mechanisms. Flume tests of minimally disturbed samples of
22
23 large enough size will include the effect of both hydraulic shear stress and of the structure
24
25 of the glacial material evident in the mass erosion (due to spontaneous failure at planes of
26
27 weakness and block formation and detachment) also observed in the field (Kamphuis et
28
29 al., 1990; Gaskin et al., 2003; Mier and Garcia, 2011). *In situ* jet testing devices
30
31 overcome the problem of sample damage and modification during removal, but focus
32
33 only on fluvial scour and do not subject a large enough sample area to shear stress to
34
35 include the effect of the material's structure on the erosion threshold (Hanson and Cook,
36
37 1997; Shugar et al, 2007; Khan and Kostaschuk, 2011).
38
39
40
41
42
43
44
45
46
47

48
49 Surface erosion from fluid shear stress is an important component of erosion of glacial
50
51 diamicts such as till (Kamphuis et al., 1990; Mier and Garcia, 2011). Surface erosion is
52
53 known to be one of the major mechanisms of erosion for cohesive sediment, manifesting
54
55 as smoothing or pitting of the surface (Krone, 1999), and surface erosion of stony till can
56
57 also reveal embedded gravel and pockets vacated by gravel particles (Mier and Garcia
58
59 2011). Flume erosion and jet tests both yield a distinct threshold shear stress for surface
60
61 <http://mc.manuscriptcentral.com/esp>
erosion and limited testing to date gives threshold stresses that are typically less than 10

1
2
3 Pa (Table 1). The presence of sand or gravel particles in the water column has also been
4
5 shown to decrease the critical shear stress of a till sample due to abrasion of the sediment
6
7 and these abrasion effects relative to clear water stress need further assessment
8
9
10 (Kamphuis, 1983; Kamphuis et al., 1990). Mass erosion of blocks due to spontaneous
11
12 fracture at planes of weakness or irregularities in the sediment structure under shearing
13
14 flow and their subsequent “plucking” by the flow is also an important and distinct erosion
15
16 mechanism in glacially-derived cohesive material (Gaskin et al., 2003) and may occur with
17
18 very little applied stress because of the inherent weakness of the material due to its
19
20 structure. Evidence comes from the presence of fracture and joint planes in till and glacio-
21
22 marine clays observed as flaking and block separation in the field and in laboratory flume
23
24 erosion tests (Kamphuis et al., 1990; Gaskin et al., 2003; Mier and Garcia, 2011) with the
25
26 resulting detached clasts of till or glacio-marine clays lying on the stream bed.
27
28
29
30
31

32 Wetting-drying conditions can have a significant effect on erodibility in this type of material
33
34 (Gaskin et al., 2003) (as it may also in some types of bedrock (Montgomery, 2004)).
35
36

37 Cycles of wetting and drying can greatly increase the erodibility of bank toe sites and
38
39 frequently exposed channel areas in very short time periods (Shugar et al., 2007). In
40
41 dried and rewetted samples of Champlain Sea Clays, micro-fissures formed greatly
42
43 reducing the critical shear stress of the samples (Gaskin et al., 2003). Factors
44
45 contributing to higher intensity and temporal variability of flows, and hence increasing
46
47 wetting and drying cycles, such as spring floods, heavy rainstorms, and increased surface
48
49 runoff due to climate change and urbanization, will all cause increased susceptibility to
50
51 erosion of cohesive tills and clays compared to alluvial sediments.
52
53
54
55

56
57 **Table 1:**
58
59
60

1
2
3 Alluvial cover develops on a river bed when the sediment supply to the river channel
4
5 reach is higher than the capacity of the channel to transport that material (Chatanantavet
6
7 and Parker, 2008). The cover affects rates of fluvial incision into bedrock as a function of
8
9 several variables related to channel hydraulics, grain size and bed roughness (Sklar and
10
11 Dietrich, 2004; Johnson and Whipple, 2007 and Chatanantavet and Parker, 2008;
12
13 Whipple et al., 2013). An important overall governing relationship in erosion of bedrock
14
15 channels by abrasion (Sklar and Dietrich, 2004) is the “tools and cover” effect whereby the
16
17 maximum erosion rate occurs at some intermediate condition between no cover (absence
18
19 of abrasion tools) and full cover (rock bed is fully protected from abrasion impacts). In till-
20
21 bed channels, while full cover may protect the bed from erosion, partial or no cover
22
23 exposes the till to fluvial scour and block separation so that high erosion rates may occur
24
25 with minimal cover and low bed stress. In this way the erosional conditions for till beds
26
27 may differ from that for many bedrock channels. In addition, fluvial scour of till yields
28
29 particles from the diamict in the exposed bed that can contribute to the formation of the
30
31 cover, and to block separation. Further studies are needed to elucidate the complex
32
33 relationship between the gravel particles embedded within the till, the erosion of the till
34
35 material, and the formation and movement of the alluvial cover. This must involve
36
37 understanding and predicting erosion susceptibility of till and also the effect of loose
38
39 gravel cover on till erosion. A long term goal is to develop a mechanistic understanding of
40
41 erosion and morphological development and response to changes in hydrology and
42
43 sediment delivery in rivers of this type especially for geomorphic and engineering
44
45 prediction and design for river stability.
46
47
48
49
50
51
52
53
54
55
56
57
58

59 The primary objective of this research, in the analysis of semi-alluvial channel morphology
60 and processes, is to observe erosional mechanisms and define the critical shear stress for

1
2
3 erosion of intact till samples from a river incised into cohesive glacial diamict (till) using
4
5 controlled tests in a laboratory flume. These tests add to the limited evidence base for
6
7 these types of materials. The tests extend previous observations especially by including
8
9 the initial observations of the effects of wetting-drying and of gravel cover on erosion
10
11 processes and susceptibility.
12
13
14
15
16
17
18

19 **Field Sampling and observations**

20
21
22 Intact samples of glacial diamicton (Dorchester Till) were collected in September 2012
23
24 from the river bed of Medway Creek, a tributary of the Thames River in London, Ontario
25
26 (Figure 1). The valley of Medway Creek is eroded into Late Wisconsinan age glacial
27
28 sediments that are up to 50 m thick overlaying Middle Devonian Dundee Limestone.
29
30 Beneath the floor of Medway Creek valley, the bedrock is covered by 10-20 m of glacial
31
32 sediments. Tills in this location are associated with a combination of Erie and Huron lobes
33
34 of the Laurentide Ice Sheet. The till at lower elevations in the valley is interpreted to be
35
36 Dorchester Till (Dreimanis et al., 1998) deposited by the Erie Lobe of the Port Bruce
37
38 Stade (approximately 15000-14000 years B.P. (Licciardi et al., 1999). The Erie Lobe
39
40 advanced westward along the Lake Erie Basin giving distinctive geochemical provenance.
41
42 The Dorchester Till is overlain by Tavistock Till, both of which are also interpreted to have
43
44 affinities with Catfish Creek Till (Whittaker, 1986; Dreimanis et al., 1998). Catfish Creek
45
46 Till lies directly below the Dorchester Till and may also be exposed in the lower elevations
47
48 of the Medway valley. These lower tills are overlain by glaciolacustrine sand and silt,
49
50 above which is Arva Moraine Till deposited by the Huron Lobe advancing from the north,
51
52 which is capped with glacio-lacustrine silt. This sequence of glacial deposits is exposed in
53
54 bluffs along the Medway valley (Whittaker, 1986; Dreimanis et al., Figure 4 and Table 2)
55
56 and the lower tills occur in the river channel bed and banks. The tills contain both local
57
58
59
60
<http://mc.manuscriptcentral.com/esp>

1
2
3 materials derived from older tills and material transported from the source regions of lobes
4
5 of the Laurentide Ice Sheet to the north and east. Lithological composition of the
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
Dorchester Till gravel component is about 60-75 % limestone and dolostone with over
10% metamorphic rock (Dreimanis et al., 1998), and the matrix (< 63 microns) is 40%
carbonate (based on tests using Chittick apparatus quoted in Whittaker, 1986 and
Dreimanis et al., 1998). There are no genetic interpretations of the tills (e.g. lodgement
versus ablation) but they are assumed to be basal in origin.

Medway River has a catchment area of approximately 200 km². Water Survey of Canada
has operated a gauging station near the sampling site since 1947 at which the mean
annual discharge is 2.8 m³/s, and maximum daily and instantaneous discharges are 117
and 146 m³/s respectively. Annual maximum daily mean discharge with 2.3 and 5 year
recurrence intervals are approximately 60 and 80 m³/s. Till is exposed in the bed and
banks along the sampled reach and in places is covered by a layer of alluvial gravel-
cobble up to 0.3 m thick (Hrytsak, 2012) (Figure 2).

Samples were collected by hand in the form of large blocks of till that had previously been
dislodged from the river bed and were resting on the bed submerged in the river. Care
was taken to prevent damage to the samples and maintain their initial moisture content
during extraction and transport by wrapping them with plastic bubble wrap and cushioning
them inside plastic bins. The samples were transported by road to the hydraulics
laboratory in Montreal and subsequently stored in a humid room until used (Hydraulics
and Geotechnical Laboratories, Civil Engineering, McGill University).

1
2
3 A sample of the gravel cover was collected from the edge of the river to be used in the
4
5 flume tests. The median particle size (D_{50}) for the 78 collected gravel particles was 23
6
7 mm. The study reach has many boulders and large gravel particles which were not
8
9 collected as they were too large to use in the flume tests. The actual D_{16} , D_{50} and D_{85}
10
11 values for the reach are 14mm, 45 mm and 140 mm respectively, calculated by Hrytsak
12
13 (2012) (23 mm represents the D_{30}). These were determined from Wolman transects with
14
15 100-400 pebbles per sample area for a total of over 4000 pebbles in a reach of about 200
16
17 m.
18
19
20
21
22
23
24
25

26 The un-weathered till was very dense and hard both on the bed (under water) and
27
28 exposed in the bank toe. It could not be penetrated with a shovel by hand and the specific
29
30 gravity of the samples was later calculated to be an average of 2.36. There is strong field
31
32 evidence of both mass erosion (block separation and detachment) and hydraulic surface
33
34 erosion of the till. Observations indicated that the till has natural planes of weakness and
35
36 defined fractures. In some cases, these fractures were similarly oriented and fracture
37
38 planes were observed (Figure 3) in the bed and banks. The apparent structure of the
39
40 material and the abundance of blocks of till on the bed where erosion had taken place was
41
42 evidence of mass erosion. Mass erosion was also observed as block separation under
43
44 the water (Figure 4) and mass failure of till blocks from the banks also occurs. The
45
46 wetting-and-drying cycle weathers the material and increases erosion by causing tension
47
48 cracks (at a very fine scale) during drying and then a break-down of the cohesive
49
50 character when re-wetted. This had a visible effect on the banks before and after a short
51
52 flood event during sampling. Before the flood, the banks down to the water level were dry,
53
54 cracked and rough on the surface. After the flood, till that had been submerged had a
55
56
57
58
59
60

1
2
3 smooth surface, indicative of surface erosion, and the eroded material had slumped down
4
5 towards the bank toe.
6
7
8
9

10
11 Larger gravel and cobbles could be seen embedded in the till and pockets were visible
12 where embedded particles had been removed. The till is therefore a principle source of
13 the gravel-cobble cover on the bed, in addition to the thin gravel layers in the eroding
14 banks. Loose gravel mantles some areas of the bank toe and a discontinuous gravel-
15 cobble alluvium with occasional boulders covers the river bed (Figure 5). Previous
16 sampling in the reach (Hrytsak, 2012) showed that 50-70% of the bed area has some
17 cover. In some areas the cover is only one grain thick, but thicker (and finer-grained) bar
18 deposits also occur. Averaged over the reach, gravel cover thickness is 0.3 m (Hrytsak,
19 2012).
20
21
22
23
24
25
26
27
28
29
30
31
32
33

34 **Laboratory tests**

35
36
37 Erodibility tests in a hydraulic flume allowed observation of erosion mechanisms in a set-
38 up as close as possible to that in the field with the samples subjected to tangential
39 stresses equivalent to those at the bed of the channel. A 4 m x 0.4 m x 0.15 m
40 recirculating hydraulic flume was used to test the samples (Figure 6).
41
42
43
44
45
46
47

48 Discharge was measured with a flow meter placed between the recirculation pump and
49 the upstream tank. Two valves were installed immediately downstream of the pump: the
50 first valve set the flow rate and the second valve allowed for gradual starting and stopping
51 of the flow. The slope of the flume was adjusted over a range of 0.031-0.046 using
52 mechanical jacks at the upstream end of the flume and measured using a surveying level.
53
54
55
56
57
58
59 Bed shear stress, τ_b , was calculated assuming uniform flow as
60

$$\tau = \gamma RS \quad (1)$$

where γ is the specific weight of water, R is the hydraulic radius and S is the slope of the channel. Flow depth was measured just upstream of the sample using a manual point gauge.

A total of six samples were tested to obtain the critical shear stress: two samples at their initial saturated moisture content, two samples that were air-dried before testing to determine the impacts of wetting and drying, and two samples at their initial saturated moisture content with gravel present in the flow to observe the interaction between the loose gravel and underlying sample. Given the small initial sample masses, only two replicates of each test were possible, resulting in a limitation in our ability to define the magnitude of the uncertainty in the observed critical shear stresses.

Each sample was placed in the flume such that the top surface of the sample was flush with the channel floor. This was achieved by placing the sample on a height-adjustable platform beneath the flume's plexiglass false floor in a 10 cm x 10 cm hole located at a distance of 2.5 m from the upstream end of the channel (Figure 6). The platform was adjusted throughout testing to maintain the erosion surface of the sample level with the flume floor at all times – the frequency of adjustment depended on the erosion rate ranging from seldom to every few minutes.

The samples were prepared for the flume tests by removing them from storage in the humid room and allowing the moisture content of the sample to return to that of the submerged conditions in the river bed by submerging them in water for at least 12 hours. Samples were cut into 0.10 m x 0.10 m blocks with heights varying from 0.07 – 0.10 m, depending on the uncut shape of the till block. A diamond-blade masonry saw allowed for

1
2
3 cutting through the large gravel particles in the sample without causing any apparent
4
5 damage to the sample. To simulate the effect of the till drying between high flow events in
6
7 the channel, samples 3 and 4 were air-dried in place on the platform in the flume for
8
9 approximately 48 hours before testing began. Bulk density, specific gravity and particle
10
11 size distribution were measured using material removed from each sample during sample
12
13 preparation. The till material was very brittle and clean breaks along pre-existing planes
14
15 of weakness were common. Consequently the material was handled very carefully and
16
17 some samples were re-cut prior to testing to ensure that the samples were free from
18
19 obvious initial cracks. Worm holes were also common and test samples were selected to
20
21 be free of worm holes on the cut surfaces, however for sample #6 worm holes in the
22
23 interior of the sample were exposed during testing. The bulk density of the samples
24
25 ranged from 2490 – 2660 kg/m³ (2.49 – 2.66 g/cm³). Moisture content after testing was
26
27 10-11% in the samples at the initial saturated moisture content and 23-24% in the pre-
28
29 dried samples (tests 3 and 4). Particle size distributions indicated 8% gravel within a fine
30
31 matrix of 20% sand, 29% silt and 43% clay (International Wentworth scale).
32
33
34
35
36
37
38
39
40
41
42

43 Each sample was placed in the flume and subjected to a unidirectional current
44
45 (supercritical flow) applying a uniform shear stress to the surface of the material. The
46
47 shear stress on the sample was increased incrementally (0.5-1.0 Pa) by increasing the
48
49 flow rate and erosional effects at each applied shear stress were observed. The critical
50
51 shear stress was taken as the shear stress at which erosion was first visible. At each
52
53 given shear stress (flow rate), if no erosion was apparent after 15 minutes, or if erosion
54
55 ceased, the shear stress (flow rate) was then increased. Testing stopped after the sample
56
57 had either been eroded completely, if it had been subjected to the highest possible shear
58
59 stress (approximately 8.9 Pa), or if all erosion had ceased. Observations and pictures
60

1
2
3 were taken at each applied shear stress to determine the critical shear stress and to
4
5 describe the erosion process.
6
7

8
9 Samples 5 and 6 were tested to observe the interaction between the loose gravel cover
10
11 and the erosion of the cohesive till. The gravel was placed in the flume upstream of the till
12
13 sample and a collection cage was used at the downstream end of the flume to collect the
14
15 transported gravel particles. Gravel particles collected downstream were transferred
16
17 upstream to maintain a continuous supply of gravel during testing.
18
19
20
21
22
23

24 **Erosion test results**

25
26
27 The critical shear stress values for the six samples obtained from the hydraulic flume
28
29 studies are summarized in **Figure 7**. Critical shear stress ranged from 0.9 – 8.3 Pa. (Table
30
31 2). Critical shear stress was almost an order of magnitude lower for the two air-dried
32
33 samples (3 and 4) compared to the samples at the initial saturated moisture content, and
34
35 the presence of loose gravel moving over the till reduced critical shear stress slightly
36
37 compared to the absence of gravel. The plot of applied stress over time for samples 5 and
38
39 6 reflects the fact that at times the samples were completely covered by gravel and it was
40
41 assumed that stress on the till surface was effectively zero under those conditions.
42
43
44
45
46
47

48 Table 2

49
50 Samples 1 and 2 showed similar erosion behaviour (**Fig 8**). Sample 1 eroded by a mass
51
52 erosion process in which spontaneous fracturing delineated small blocks of till, which
53
54 eventually detached from the sample. The first sign of weakening of the till sample was a
55
56 crack developing down the middle of the sample at an applied shear stress of 6.7 Pa,
57
58 appearing to split the entire sample in half. With a further increase in the applied shear
59
60

1
2
3 stress to 7.9 Pa, a block of till adjacent to the crack became detached and eroded - this
4
5 point was assumed to be the critical shear stress of the sample. Further increase in the
6
7 critical shear stress did not yield more mass erosion (block separation and detachment),
8
9 however, embedded gravel pieces within the surface of the sample were slowly revealed
10
11 as fluvial scour (surface erosion) of the clay matrix occurred. In Sample 2, very small
12
13 gravel pieces were eroded from the surface of the sample by first becoming more
14
15 exposed by surface erosion of the matrix and then being plucked from the surface at a
16
17 shear stress of 6.7 Pa. With a further increase to 7.6 Pa, cracks began forming at the
18
19 surface, including a large crack originating from a large gravel piece and extending to the
20
21 edge of the sample. At 8.3 Pa, blocks of till began detaching from the cracked areas, and
22
23 this was taken to be the critical shear stress of the sample. As the applied shear stress
24
25 increased to 8.8 Pa, more large cracks formed along the surface and the sample
26
27 continued to undergo mass erosion (block separation and detachment).
28
29
30
31
32
33
34
35
36
37

38 Erosion of the air-dried samples (3 and 4) occurred by fluvial scour/surface erosion as
39
40 soon as the sample was subjected to flow at the minimum shear stress of 1.2 and 0.9 Pa
41
42 for both samples. Surface erosion began immediately at the edges of the sample and
43
44 around large gravel particles embedded in the sample. Gravel particles detached from the
45
46 sample when they became fully exposed. On sample 4, erosion also occurred by removal
47
48 of very small pieces of the fine-grained matrix. Within 30 minutes both samples had lost a
49
50 large proportion of their initial mass (Fig 9). Erosion of the air-dried samples was
51
52 effectively by disintegration of the sample into sub millimeter particles delineated by the
53
54 microfissures, the larger scale mass failure and cracking seen in the initial moisture
55
56 content samples did not occur The observed moisture content of the air-dried sample after
57
58 testing (a mass of very small particles) had increased to 23-24% (compared to 10-11% of
59
60

1
2
3 the initial water content sample) due to the microfissures resulting in a higher surface area
4 and allowing for increased absorption of water. These observations show that wetting and
5
6
7
8 drying has a substantial effect on the erosional resistance, as seen in a comparison of
9
10 Figures 8 and 9.

11
12
13 Samples 5 and 6 were tested with mobile gravel particles in the flow to obtain an initial
14 understanding of the effect on till erosion of rolling particles and of a gravel cover layer in
15 protecting the till from hydraulic erosion. The gravel particles were initially placed
16 upstream of the sample. As the flow rate and applied shear stress were increased, the
17
18 gravel particles moved to cover the sample, and then eventually began rolling
19
20 downstream (at velocities much lower than the flow velocity), causing damage to the
21
22 sample surface and initiating mass erosion (block separation and detachment).
23
24
25
26
27
28
29
30

31 In test 5, when the applied shear stress was increased to approximately 3-4 Pa, the gravel
32 particles moved downstream and covered the sample. Erosion could not be observed
33 while the gravel particles covered the sample. When the average applied shear stress
34
35 was increased to approximately 5 Pa, the gravel particles moved a small amount on the
36
37 sample causing damage to the corners of the sample. When the average applied shear
38
39 stress increased to 6.8 Pa, the gravel particles started rolling down the flume. At this point
40
41 mass erosion (block separation and detachment) started and this was taken to be the
42
43 critical shear stress. Block separation and detachment occurred at the downstream corner
44
45 of the sample due to cracks caused by impacts from the gravel particles and from
46
47 enlargement of cracks. The presence of the gravel particles also caused a noticeable
48
49 increase in surface erosion by first pitting and subsequently smoothing the surface
50
51 compared to clear water conditions. The upstream side of the sample 5 underwent more
52
53 erosion than the downstream side.
54
55
56
57
58
59
60

1
2
3 Sample 6 showed similar effects, including erosion of the till while it was covered with
4 gravel (Fig 10), which occurred at shear stresses below 7.9 Pa. At higher stresses the
5 rolling gravel caused the sample to erode more quickly by first cracking, the cracks
6 delineating blocks, and finally separation and detachment of the blocks in a mass erosion
7 process. Blocks detaching from the sample caused irregularities in the surface of the
8 sample that was subsequently smoothed by the gravel particles. The shear stress versus
9 time trajectory for samples 5 and 6 has gaps as shear stress values on the till surface
10 were unknown due to the presence of the gravel. The gravel increased the flow depth,
11 channeled the flow and/or protected the till from exposure to the shear stress. Static
12 gravel cover may aid erosion by increasing turbulence, and mobile particles affect both
13 mass erosion as block separation and detachment of the material and surface erosion by
14 particle impacts..
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38

39 Discussion

40
41
42 The field observations and flume tests performed on the till samples of Medway Creek
43 exposed the natural structure of the till and demonstrated that mass erosion as block
44 separation and detachment is the dominant erosion mechanism, although surface erosion
45 due to fluvial scour also occurs. The structure of the material, as termed by Lefebvre et
46 al. (1985), was readily apparent in the field, and in the handling and testing of the material.
47 Fractures could develop in the sample where there was no apparent origin, indicative of
48 an existing plane of weakness within the sample, or near gravel particles embedded in the
49 sample. These observations are similar to those from some previous studies (Kamphuis
50 et al., 1990, Mier and Garcia, 2011, Gaskin et al., 2003, Lefebvre et al. 1985) in which the
51
52
53
54
55
56
57
58
59
60

1
2
3 till or clay was eroded by blocks of material first being delineated by fractures, at planes of
4
5 weakness or close to discontinuities, and subsequently detaching from the sample.
6
7 However, erosion is not immediate once critical shear stresses are achieved because
8
9 actual detachment is preceded by a phase of fracturing. The erosion proceeded as
10
11 described in previous studies (Kamphuis et al. 1990; Gaskin et al. 2003; Mier and Garcia,
12
13 2011). At the a given shear stress, cracks formed spontaneously, then slowly widened
14
15 over time, leading to the delineation of blocks of till followed by mass erosion through
16
17 separation and detachment of the blocks. The initial fracturing of the sample would
18
19 happen quickly, but most of the erosion occurred as block detachment after a relatively
20
21 long delay related to crack propagation and widening. There was only one phase of crack
22
23 propagation and separation and detachment of blocks after which erosion ceased at a
24
25 given shear stress.
26
27
28
29
30
31
32
33
34
35

36 While mass erosion, defined as block separation and detachment, was the dominant
37
38 erosion process in the till, surface erosion due to fluvial scour had an important role. In the
39
40 flume studies, small gravel particles detached from the surface after first becoming
41
42 exposed due to a lowering of the till surface by fluvial scour, similar to the surface erosion
43
44 observed by Mier and Garcia (2011). New irregularities in the sample surface could
45
46 become locations for initiation of block separation and detachment. The amount of surface
47
48 erosion that occurred was less than a centimeter, but it played a significant role in
49
50 exposing gravel pieces. The distribution of particle sizes within till material influences the
51
52 erosion – the silts and clays are responsible for its cohesive nature and the larger particles
53
54 supply the alluvial cover. The full particle size distribution was not available as the small
55
56 size of the sample precluded sampling the larger gravels and boulders.
57
58
59
60

1
2
3 The critical shear stress value for till at its initial saturated moisture content with clear flow
4
5 conditions was determined to be approximately 8 Pa, which is higher than values in
6
7 previous tests. Kamphuis et al. (1990) and Mier and Garcia (2011) both found lower
8
9 critical shear stress values (0.65-4.1 Pa for Kamphuis et al. (1990) and 4.2 Pa for Mier
10
11 and Garcia (2011)) for their tested clay and till samples, with two of the samples by
12
13 Kamphuis et al. (1990) an order of magnitude less. The difference could be due to the
14
15 wide variation of clay and till properties(size distribution). However, the critical shear
16
17 stress values are within the range of values determined by Gaskin et al. (2003) for
18
19 Champlain Sea clay, albeit a wide range was observed.
20
21
22
23

24
25 Although the critical shear stress values from the two *in situ* jet-tester studies (Shugar et
26
27 al., 2007; Khan and Kostaschuk, 2011) are similar in magnitude, there are reasons to
28
29 question the reliability of this type of test. The critical shear stress in those tests was
30
31 determined by the flow conditions at the time when the first block of material detached
32
33 from the sample. As discussed above, mass erosion through block separation and
34
35 detachment is due to the structure of the cohesive material matrix and irregularities in the
36
37 surface. Therefore, tests that do not allow the full progression of erosion to occur, such as
38
39 jet testers, will not get an accurate representation of the critical shear stress. The flume
40
41 tests more accurately represented real flood conditions by having a flow rate, and thus,
42
43 shear stress value, that slowly increased over time, making the obtained critical shear
44
45 stress values more reliable. In addition, the area of the sample eroded by the jet testers is
46
47 smaller than that needed to allow for mass erosion through block separation and
48
49 detachment and hence to observe the mass erosion of sample due to its structure.
50
51
52
53
54
55
56 Further limitations of the jet test are inherent in its design. The basic principle of the jet
57
58 tester method is that the incident jet stress is converted to a tangential stress on the
59
60 surface to yield an erodibility value (Hanson and Cook 1997). In some cases the jet test

1
2
3 tends to drill a hole in the surface so does not directly assess shear stress on the surface
4 of the material (Khan and Kostaschuk, 2011). Additionally, after each measurement, the
5 operator must remove large particles, or gravel pieces, in the test hole to accurately
6 assess the maximum erosion depth from which threshold shear stress is calculated
7 (Shugar et al. 2007). Abrasion due to particles trapped in the hole during the test could
8 also affect the results. Results from jet testing of till erosion in southern Ontario rivers
9 have given highly variable (5 orders of magnitude) values for the threshold shear stress
10 (Shugar et al., 2007; Khan and Kostaschuk, 2011), which may also be a reason to
11 question its reliability. Consequently, flume tests which better reproduce conditions in the
12 channel and dominant erosion mechanisms are preferred to *in situ* jet testing for this type
13 of material.
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29

30 Physical weathering by air-drying of the sample has a dramatic effect on critical shear
31 stress and extreme effects on the erosion process. With drying, the critical shear stress
32 was reduced from 8 Pa to less than 1 Pa, in agreement with the Gaskin et al. (2003) study
33 on the effect of drying Champlain Sea clay. There were no visible cracks within the
34 sample during or after the drying process, however micro-fissures formed within the
35 sample. This was evident when flume testing began and erosion occurred quickly in the
36 form of very small pieces of till flaking away from the surface. Micro-fissuring was
37 apparent along the dried banks of the river on the Medway Creek field site, which
38 penetrated up to 15 cm. It was clear from the final texture of the material after flume
39 testing that the samples had lost their cohesive structure during drying and evident in the
40 subsequent wetting by the flow (weathering). This is in agreement with the study by
41 Govers and Loch (1992) in which lower initial water content led to more micro-fissuring
42 and less resistance to erosion due to a weakening of the cohesive nature of the material.
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
The extreme effects that drying has on the erodibility of till put the lower banks of till rivers

1
2
3 at the greatest risk of erosion. These areas are exposed to the most frequent wetting-
4
5 and-drying cycles from changing river stage. More frequent wetting-drying cycles, for
6
7 example in urban runoff regimes, would exacerbate this risk. This is clearly an important
8
9 effect that does not affect erosion in channels in resistant bedrock and therefore an
10
11 important difference to be considered in developing erosion theory and models for glacial
12
13 diamicts and similar materials.
14
15
16
17
18
19
20

21 The presence of alluvial gravel during laboratory flume tests increased the erosion of the
22
23 till sample, and decreased the critical shear stress slightly from about 8 Pa to less than 7
24
25 Pa. The impacts from the gravel particles eroded the till sample whose surface was
26
27 subsequently smoothed by fluvial scour. The gravel particles also caused considerable
28
29 turbulence while they were on top of the sample, and in some cases this caused
30
31 additional hydraulic erosion. In the context of the river bed, as till is eroded at higher bed
32
33 shear stress, more gravel particles will be released from the till and potentially enhance
34
35 erosion of the till if gravel cover is thin. In the case of till, the erosional influence of the
36
37 extent of alluvial cover may be different in some respects from that observed particularly
38
39 for abrasion-dominated bedrock cases (Sklar and Dietrich, 2004; Johnson and Whipple
40
41 2007). In the absence of cover direct fluvial scour causes rapid erosion even at very low
42
43 bed stresses. Erosion of the till itself yields low-velocity, saltating particles that may
44
45 contribute to bed erosion. The wetting-drying behaviour adds another complexity to
46
47 predicting erosion mechanisms and rates in this type of channel.
48
49
50
51
52
53
54

55 **Conclusions**

56
57
58 Flume erosion tests of glacial diamict (till) taken from the channel of Medway Creek,
59
60 Ontario, Canada, has extended previous observations of fluvial erosion mechanisms and

1
2
3 erosion resistance in this type of material. Critical shear stress for erosion was determined
4
5 to be approximately 8 Pa. This value is greatly reduced when the material is subjected to
6
7 physical weathering in the form of wetting-and-drying. Air-dried samples were determined
8
9 to have a critical shear stress < 1 Pa. The till material had an internal structure, which led
10
11 to mass erosion by block separation and detachment to be the dominant form of erosion.
12
13 Block separation and detachment initiated around irregularities and planes of weakness
14
15 within the internal structure, and could also originate at embedded gravel particles. The
16
17 presence of an alluvial cover in the form of a single layer of gravel particles lowered the
18
19 critical shear stress value to less than 7 Pa. Saltating gravel particles impacted the
20
21 sample and created areas of weakness for increased erosion to take place causing both
22
23 incision and smoothing of the surface. When the gravel particles remained stationary and
24
25 covered the till, turbulence around the gravel created localized high areas of shear stress
26
27 which eroded the sample beneath the gravel. Clearly till-bed channels are extremely
28
29 erodible and the presence of thin gravel cover over the till may enhance rather than
30
31 protect the bed from erosion. Because of the nature of the erosion mechanism, direct
32
33 flume testing of samples is preferred to *in situ* jet testing of erodibility of glacial diamicts.
34
35 Erosion mechanisms and the role of alluvial cover differ significantly from typical bedrock
36
37 channels and consequently existing models of bedrock erosion mechanics and incision
38
39 are not transferable to analysis of rivers eroded into cohesive glacial sediments such as
40
41 till. Channel design and geomorphic engineering for erosion mitigation must also take
42
43 these characteristics into account.
44
45
46
47
48
49
50
51

52 53 54 55 56 57 **Acknowledgments**

58
59
60 The authors acknowledge funding for this project from NSERC Discovery Grant (RGPIN
<http://mc.manuscriptcentral.com/esp>
203125). Thanks to James Thayer for assistance in field sampling and to John Bartczak

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

for assistance in flume testing. Figure 1 was prepared by Karen VanKerkoerle. The authors declare no conflict of interest.

For Peer Review

References

- Ashmore, P., and Church, M., 2001. The impact of climate change on rivers and processes in Canada. Geological Survey of Canada, Bulletin 555. DOI: 10.4095/211891
- Chatanantavet, P. and Parker, G. 2008. Experimental study of bedrock channel alluviation under varied sediment supply and hydraulic conditions. *Water Resources Research*, 44: 1-19. DOI: 10.1029/2007WR006581
- Chatanantavet, P. Parker, G. 2009. Physically-based modeling of bedrock incision by abrasion, plucking, and macroabrasion. *Journal of Geophysical Research* 114: F04018. DOI: 10.1029/2008JF001044
- Dreimanis, A., Winder, C.G. and Aaltonen, R.A. 1998. London, Ontario: Geology, Geomorphology and Geodata. In: P.F. Karrow and O.L. White (Eds) *Urban Geology of Canadian Cities*. Geological Association of Canada Special Paper 42, Geological Association of Canada, St. John's NF.
- Gaskin, S. J., Pieterse, J., Al Shafie, A., and Lepage, S. 2003. Erosion of undisturbed clay samples from the banks of the St. Lawrence River. *Canadian Journal of Civil Engineering*, 30: 585-595. DOI: 10.1139/l03-008
- Govers, G., and Loch, R.J. 1993. Effects of initial water content and soil mechanical strength on the runoff erosion resistance of clay soils. *Australian Journal of Soil Research*, 31:549–566. DOI: 10.1071/SR9930549
- Gran, K.B., Finnegan, N., Johnson, A.L., Belmont, P., Wittkop, C., Rittenour, T. 2013. Landscape evolution, valley excavation, and terrace development following abrupt postglacial base-level fall. *Geological Society of America Bulletin*, 125: 851-864. DOI: 10.1130/B30772.1
- Hodge, R.A. 2017. Sediment processes in bedrock-alluvial rivers: Research since 2010 and modelling the impact of fluctuating sediment supply on sediment cover. In: Tsutsumi, D. & Laronne, J. *Gravel-Bed Rivers: Process and Disasters*. Wiley-Blackwell.
- Hrytsak, T.N. 2012. Alluvial cover dynamics in a semi-alluvial channel: a case study of Medway Creek, London, ON. MSc Thesis, University of Western Ontario.
- Johnson, J. P. and Whipple, K. X. 2007. Feedbacks between erosion and sediment transport in experimental bedrock channels. *Earth Surface Processes and Landforms*, 32: 1048-1062. DOI: 10.1002/esp.1471
- Kamphuis, J.W., Gaskin, P.N., and Hoogendoorn, E. (1990). Erosion tests on four intact Ontario clays. *Canadian Geotechnical Journal*, 27: 692–696. DOI: 10.1139/t90-082

- 1
2
3 Khan, I. and Kastaschuk, R. 2011. Erodibility of cohesive glacial till bed sediments in
4 urban stream channel systems. *Canadian Journal of Civil Engineering*, 38: 1363-
5 1372. DOI: 10.1139/I11-099
6
7
8 Krone, R.B. 1999. Effects of bed structure on erosion of cohesive sediments. *ASCE*
9 *Journal of Hydraulic Engineering*, 125: 1297–1301
10
11 Lefebvre, G., Rohan, K., and Douville, S. 1985. Erosivity of natural intact structured
12 clay: Evaluation. *Canadian Geotechnical Journal*, 22: 508–517. DOI:
13 10.1139/t85-071. 10.1061/(ASCE)0733-9429
14
15
16 Lefebvre, G., Rohan, K., and Milette, J.-P. 1986. Erosivity of intact clay: influence
17 on the natural structure. *Canadian Geotechnical Journal*, 23: 427-434. DOI:
18 10.1139/t86-072
19
20
21 Licciardi, J.M., Teller, J.T. and Clark, P. 1999. Freshwater routing by the Laurentide
22 Ice Sheet during deglaciation. Mechanisms of Global Climate Change at Millennial
23 Time Scales. In Clark, P., Webb, R.S., Keigwin, L.D. (Eds) American Geophysical
24 Union Geophysical Monograph 112: 177-202.
25
26
27 Meshkova, L. V, Carling, P. A., and Buffin-Belanger, T. 2012. Nomenclature,
28 complexity, semi-alluvial channels and sediment-flux-driven bedrock erosion. In M.
29 Church, P. M. Biron, and A. Roy (eds.), *Gravel-bed Rivers: Processes, Tools,*
30 *Environments* (pp. 424 432). John Wiley & Sons, Ltd. DOI:
31 10.1002/9781119952497.ch31
32
33
34 Mier, J. M., and Garcia, M. H. 2011. Erosion of glacial till from the St. Clair River (Great
35 Lakes basin). *Journal of Great Lakes Research*, 37: 399-410. DOI:
36 10.1016/j.jglr.2011.06.004
37
38
39 Montgomery, D.R., 2004. Observations on the role of lithology in strath terrace formation
40 and bedrock channel width. *American Journal of Science*, 304, 454-476.
41
42
43 Ontario Geological Survey, Ministry of Northern Development and Mines
44 [http://www.mndm.gov.on.ca/en/mines-and-minerals/applications/ogsearth/bedrock-](http://www.mndm.gov.on.ca/en/mines-and-minerals/applications/ogsearth/bedrock-topography-and-overburden-thickness)
45 [topography-and-overburden-thickness](http://www.mndm.gov.on.ca/en/mines-and-minerals/applications/ogsearth/bedrock-topography-and-overburden-thickness).
46
47
48 Phillips R. and Desloges J.R. 2014. Glacially conditioned specific stream powers in low-
49 relief river catchments of the southern Laurentian Great Lakes. *Geomorphology* 206,
50 271-287.
51
52
53 Phillips, R.T.J. and Desloges, J.R. 2015. Glacial legacy effects on river landforms of the
54 southern Laurentian Great Lakes. *Journal of Great Lakes Research* 41, 951–964.
55
56
57 Shugar, D., Kostaschuk, R., Ashmore, P., Desloges, J. and Burge, L. 2007. In situ jet-
58 testing of the erosional resistance of cohesive streambeds. *Canadian Journal of Civil*
59 *Engineering*, 34: 1192-1195. DOI: 10.1139/I11-099
60
61 Sklar, L. S. and Dietrich, W. E. 2004. A mechanistic model for river incision into
62 bedrock by saltating bedload. *Water Resources Research*, 40: 1-21. DOI:
63 10.1029/2003WR002496

- 1
2
3
4 Stock, J.D., Montgomery, D.R., Collins, B.D., Dietrich, W.E., Sklar, L. 2005. Field
5 measurements of incision rates following bedrock exposure: Implications for
6 process controls on the long profiles of valleys cut by rivers and debris flows.
7 Geological Society of America Bulletin, 117: 174-194. DOI: 10.1130/B25560.1
8
9
10 Thayer, J.B., Ashmore, P., 2016. Floodplain morphology, sedimentology, and
11 development processes of a partially alluvial channel. *Geomorphology*, 269, 160-
12 174. <http://dx.doi.org/10.1016/j.geomorph.2016.06.040>
13
14
15 Thayer, J., Phillips, R. and Desloges J.R. 2016. Downstream channel adjustment in a
16 low-relief, glacially conditioned watershed. *Geomorphology* 262, 101–111.
17 doi:10.1016/j.geomorph.2016.03.019
18
19
20 Turowski, J. M, Hovius, N., Wilson, A., and Horng, M.-J. 2008. Hydraulic geometry,
21 river sediment and the definition of bedrock channels. *Geomorphology*, 99: 26-
22 38. DOI: 10.1016/j.geomorph.2007.10.001.
23
24
25 Turowski, J.M., 2012. Semi-alluvial channels and sediment-flux-driven bedrock
26 erosion. In M. Church, P. M. Biron, and A. Roy (eds.), *Gravel-bed Rivers:*
27 *Processes, Tools, Environments* (pp. 401-218). John Wiley & Sons, Ltd. DOI:
28 10.1002/9781119952497.ch 29.
29
30
31 Whipple, K.X., Hancock, G.S. and Anderson, R.S., 2000. River incision into bedrock:
32 Mechanics and relative efficacy of plucking, abrasion and cavitation. *Bulletin of*
33 *the Geological Society of America*, 112, 490-503.
34
35
36 Whipple, K.X., DiBiase, R.A. and Crosby, B.T., 2013. Bedrock Rivers. In, Shroder, J.
37 (Editor in Chief) Wohl, E. (Ed.) *Treatise on Geomorphology*. Academic Press,
38 San Diego, CA vol. 9, Fluvial Geomorphology 550-573.
39
40
41 Whittaker, W.A., 1986. Till geochemistry and glacial geology of lower Medway valley,
42 London, Ontario. MSc Thesis, University of Western Ontario, 166p.
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60

Table 1: Critical shear stress of undisturbed samples of tills and clays


Study	Apparatus	Material	Average Critical Shear Stress (Pa)
Kamphuis et al. (1990)	Flume	Silty Clay	2.56 – 4.1
		Glaciolacustrine Silty Clay	0.88
		Silty Till	0.65
Gaskin et al. (2003)	Flume	Champlain Sea Clay (St. Lawrence River) Initial saturated moisture content	6 – 20
		Air dried sample	<< 5
Mier and Garcia (2011)	Flume	St. Joseph's Till (St. Clair River)	4.2
Shugar et al. (2007)	<i>in situ</i> Jet-Tester	Halton Till (Fletcher's Creek)	2.28
Khan and Kostachuck (2011)	<i>in situ</i> Jet-Tester	Halton Till (Fletcher's Creek)	5.43
		Sunnybrook Till (Highland Creek)	22.7

Table 2: Critical shear stress from flume tests of till samples from Medway Creek

Sample	Test Description	Critical Shear Stress (Pa)
1	Initial saturated moisture content clear water flow	6.9
2	Initial saturated moisture content clear water flow	8.3
3	Air dried, clear water flow	1.4
4	Air dried, clear water flow	0.9
5	Initial saturated moisture content Gravel in flow	6.8
6	Initial saturated moisture content Gravel in flow	4.3 – 6.1

Figures and captions

- 1
2
3
4
5
6 Fig 1 Field site location (Medway Creek) and thickness of glacial overburden in
7 southern Ontario (source: Ontario Geological Survey)
8
9 Fig 2 a) Medway Creek bank showing till in lower bank with overlying sand and
10 gravel
11 b) Till at base of bank extending across the bed below the water
12
13 Fig 3 a) Till in lower bank showing fissures and embedded gravel particles
14 b) Eroded till blocks at edge of channel
15 c) Fracture and failure of till in banks
16
17 Fig 4 a) Till exposed in the channel bed with indications of erosion by fluvial
18 scour and block separation
19 b) Close up view of mass erosion (block separation and detachment) of till
20 on channel bed
21
22 Fig 5 a) Overview of channel showing exposed till (light patches) and thin gravel
23 cover layer
24 b) Close up view of till patch exposed beneath gravel cover
25
26 Fig 6 a) Plan view of flume and sample location
27 b) Photo of flume photo showing block placement
28
29 Fig 7 Flume erosion test results of the applied shear stress versus time (—, ---, --
30 -, -) and the critical shear stress (\times , \circ , Δ) for each sample type: initial
31 saturated moisture content, air dried and initial saturated moisture content
32 with gravel abrasion.
33
34 Fig 8 Sample 2, initial saturated moisture content clear water flow, a) before and
35 b) after erosion test top view, c) before and d) after erosion test side view.
36
37 Fig 9 Sample 4, air dried clear water flow, a) before and b) after erosion test
38
39 Fig 10 Sample 6, initial saturated moisture content gravel abrasion, a) before and
40 b) after erosion test
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60



33 Figure 1 Field site location (Medway Creek) and thickness of glacial overburden in southern
34 Ontario (source: Ontario Geological Survey)
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60



a)

b)

Figure 2 a) Medway Creek bank showing till in lower bank with overlying sand and gravel
b) Till at base of bank extending across the bed below the water




Figure 3 a) Till in lower bank showing fissures and embedded gravel particles
b) Eroded till blocks at edge of channel
c) Fracture and failure of till in banks



a)

b)

Figure 4 a) Till exposed in the channel bed with indications of erosion by fluvial scour and block separation
b) Close up view of mass erosion of till on channel bed




19
20 a)



40 b)

41
42
43
44 Figure 5 a) Overview of channel showing exposed till (light patches) and thin gravel cover
45 layer (Photo by Tatiana Hyrtsak)
46 b) Close up view of till patch exposed beneath gravel cover
47
48
49
50
51
52
53
54
55
56
57
58
59
60



a)



b)

Figure 6 a) Plan view of flume and sample location
b) Photo of flume photo showing block placement




Figure 7. Flume erosion test results of the applied shear stress versus time (—, ···, ---) and the critical shear stress (*, ○, △) for each sample type: initial saturated moisture content, air dried and initial saturated moisture content with gravel abrasion.

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60



a)



b)



c)



d)

Figure 8 Sample 2, initial saturated moisture content clear water flow, a) before and b) after erosion test top view, and c) before and d) after erosion test side view.





Figure 9 Sample 4, air dried clear water flow, a) before and b) after erosion test

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60



a)

b)

Figure 10 Samples 6, initial saturated moisture content gravel abrasion, a) before and b) after erosion test

Or Peer Review