

Missouri University of Science and Technology Scholars' Mine

International Conference on Case Histories in Geotechnical Engineering

(2013) - Seventh International Conference on Casé Histories in Geotechnical Engineering

09 Mar 1998 - 12 Mar 1998

Past Proceedings: Fourth International Conference on Case Histories in Geotechnical Engineering (1998)

Multiple Authors

Follow this and additional works at: https://scholarsmine.mst.edu/icchge



Part of the Geotechnical Engineering Commons

Recommended Citation

Authors, Multiple, "Past Proceedings: Fourth International Conference on Case Histories in Geotechnical Engineering (1998)" (2010). International Conference on Case Histories in Geotechnical Engineering. 4. https://scholarsmine.mst.edu/icchge/7icchge/session09/4

This Article - Conference proceedings is brought to you for free and open access by Scholars' Mine. It has been accepted for inclusion in International Conference on Case Histories in Geotechnical Engineering by an authorized administrator of Scholars' Mine. This work is protected by U. S. Copyright Law. Unauthorized use including reproduction for redistribution requires the permission of the copyright holder. For more information, please contact scholarsmine@mst.edu.

FOURTH INTERNATIONAL CONFERENCE ON CASE HISTORIES IN GEOTECHNICAL ENGINEERING March 8-12, 1998

i

TABLE OF CONTENTS

Preface	
Disclaimer	
Steering Committee	
Organizing Committee	
Paper Review Committee	
Conference Program	
Guest Speakers	
Meet Our Authors	
First Case Histories Conference 19	984
Second Case Histories Conference	1988
Third Case Histories Conference 1	993
Keynote Lecture	
Ralph B. Peck (USA)	Creating Case Histories the Hard Way. KN00
State of The Art Lectures	
E. W. Brand (China)	Forensic Engineering Applied to Slope Failure in Hong Kong. SOA-1*

*Withdrawn

Jean-Lou Chameau

(USA)

Measurement and Analysis of Civil Engineering

Vibrations. SOA-2

W. D. Liam Finn

(Canada)

Estimating Post-Liquefaction Displacements in Embankment Dams and

Prioritizing Remediation Measures. SOA-3

Dr. Susumu lai

(Japan)

Rigid and Flexible Retaining Walls During Kobe Earthquake.

SOA-4

Suzanne LaCasse

F. Nadim (Norway)

Risk and Reliability in Geotechnical Engineering. SOA-5

R. H. Ledbetter

(USA)

Remediation of Major Earth Dams. SOA-6**

Robert Mair

(UK)

Recent Experiences of Tunnelling and Deep Excavations in

London. SOA-7

Tamotsu Matsui

(Japan)

Foundation Damage of Structures in Kobe Earthquake and

Remediation, SOA-8

R. Kerry Rowe

(Canada)

Past and Future of Landfill Engineering Through Case

Studies. SOA-9

Joseph P. Welsh

(USA)

State of the Art of Soil Improvement with Case Histories.

SOA-10

John H. Schmertmann

John A. Hayes Thomas Molnit Jorg Osterberg (USA) O-Cell Testing Case Histories Demonstrate the Importance of Bored Pile (Drilled Shaft) Construction Technique. SOA-11

Special Lectures Clyde N. Baker

(USA)

Foundation Design and Performance of the World's Tallest Building,

Petronas Towers. SPL-1

K. Rainer Massarch

(Sweden)

Soil Improvement Projects. SPL-2*

Dr. Pedro Simao Seco e Pinto

(Portugal)

A Recent Difficult Foundation Problem: The Case of the New

Teja Bridge. SPL-3

R. S. Steedman

(UK)

Seismic Design of Cellular Cofferdams. SPL-5

^{*}Withdrawn

^{**} Not received.

March 9-12, 1998

Session I "Case Histories of Foundations"

R. David Charles

Case History of Two Buildings Experiencing Large Post Construction

iii

(USA)

Settlements, Wilmington, Delaware. 1.01

A. B. Fadeev V.N. Paramonov Settlements of Neighboring Buildings During Piling Works. 1,04

V.K. Inozemtcev V.A. Lukin

E.M. Perley (Russia)

Amer A. Al-Rawas

A Case Study on Expansive Soils and Rocks of Al-Khod in

M. Oamaruddin (Sultanate of Oman) Northern Oman, 1.05

Braja M. Das

(USA)

Cyclic Load-Induced Settlement of Foundations on Clay. 1.07

Eun Chul Shin (South Korea)

John R. Davie Kenneth R. Bell

M. B. Fitzsimmons Daniel A. Haggerty

(USA)

Heavy Crane Foundations on Soft Clay. 1.09

Md. Nurul Amin Sabina Shahnaz Sonia Shahnaj (Bangladesh)

Performance of Bored Cast-In-Situ R.C.C. Piles

in Bangladesh. 1.10

Chu-Eu Ho Ching-Heng Lim (Singapore)

Barrettes Designed as Friction Foundations:

A Case History, 1.11

Bouafia Ali (Algeria)

Experimental Analysis of Large Lateral Displacements of

Piles in Centrifuge. 1.12

K. M. Murtagh E. B. Kinner

Expansion and Rehabilitation of The State Fish Pier in

R. E. Bertolino

Gloucester, Massachusetts. 1.13

C. Soydemir

(USA)

D. S. Tolia (India)

Validity of Peck, Hanson and Thornburn's SPT Correction

Method and Soil Pressure Chart. 1.16

iν

Sven Hansbo Leif Jendeby (Sweden)	A Follow-Up of Two Different Foundation Principles. 1.17
J.L.M. Clemente A. Desai H. Senapathy L.W. Young, Jr. (USA)	Foundation Performance of Large Diameter Tanks. 1.18
F. Colleselli G. Cortellazzo (Italy)	Behavior of the Underpinning of a Building in Venice. 1.19
N. Thasnanipan W. Teparaksa A.W. Maung Ganeshan Baskaran (Thailand)	Design, Construction and Behavior of Bored Cast In-Situ Concrete Piles in Bangkok Sub Soil. 1.20
Alan J. Lutenegger Michael T. Adams (USA)	Bearing Capacity of Footings on Compacted Sand. 1.21
Nasser Massoudi (USA)	Foundation Construction on Random Fill. 1.22
Roy E. Olson Magued G. Iskander (USA)	Axial Load Capacity of Piles in Sand. 1.23
Gary Axelsson (Sweden)	Long-term Increase in Shaft Capacity of Driven Piles in Sand. 1.25
Carole L.B. Mitchell (USA)	Design and Construction of The Seattle Symphony's Benaroya Hall Above an Old Railroad Tunnel. 1.27
G. Ramasamy G. Kalaisclvan (India)	A Case Study on Settlement of Oil Storage Tank Foundations. 1.33
Martin B. Hudson (USA)	Osterberg Load Cell Testing of a Deep Reinforced Concrete Pile. 1.36
Gerald P. Raymond (Canada)	Track and Support Rehabilitation 1975 on Black Mesa & Lake Powell Railroad. 1.38
P. C. Su Y. C. Chen J. Lin C. F. Chen	Soil Improvement for Storage Tank Foundations 1.40

(Taiwan)

٧

W. Akili

Robert M. Jackson

(Qatar)

Shallow Foundations on a Diagenetic Limestone

Formation in Qatar. 1.41

Failure of Buildings on Mound- A Case Study. 1.42

U. N. Sinha (India)

Jie Han (USA) Ground Modification by a Combination of Dynamic Compaction,

Consolidation, and Replacement. 1.44

K. Zand Parsa (Iran)

Foundations Reinforcement of Old Ala Building. 1.47

Sasha D. Milovic Zuhtu S. Ozden George S.W. Chow (Canada) Calculated and Observed Settlements of Multistory Building

Founded on Loess. 1.48

Elias Sotiropoulos Elias Alkalais (Greece)

Foundation Problems of a Cable Stayed High Bridge and Its Approaches. 1.49

Takahide Horiuchi Yukihiko Kani (Japan)

Deformation Modulus of Soil at the Tip of a Bored Pile. 1.50

Raghu N. Dass Vijay K. Puri (Illinois) Load Tests on Drilled Shafts for Highway Bridges. 1.52L

S. Sudarshan C.S. Viswanatha T. S. Nagaraj (India) Restoration of Equalization and Aeration Tanks of Effluent Treatment Plant at the Mysugar Factory, Mandya, Karnataka, India. 1.54N

Shamsher Prakash (USA) M. H. Chen (Taiwan) Non-Linear Lateral Pile Deflection Predictions in Clays. 1.55

Session II "Case Histories of Slopes, Dams and Embankments"

Buddhima Indraratna I. W. Redana (Australia) Effect of Smear Due to Vertical Drains on the Behavior of Two Embankments Constructed on Soft Clay. 2.04

David J. Kerkes (USA)

Lessons Learned from the Analysis of a Wet Core Dam. 2.05

vi

Masaki Kawasaki Yoshikazu Yamaguchi Hitoshi Yoshida Grouting in Consideration of Predominant Direction of Joints in Rock Masses, 2.06

(Japan)

(India)

Indra Prakash A. B. Yyas Geotechnical Problems and Treatment of Weathered Rock Seams Occurring in the

Foundation of Karjan Dam, Western India. 2.07

L. A. Bressani

A. V. D. Bica

W.Y.Y. Gehling M. R. Bianchini

(Brazil)

A Slope Instability Case History Involving Swelling Clay

in Southern Brazil. 2.10

Y. Yamaguchi

Y. Imabayashi Hitoshi Yoshida T. Sakamoto (Japan) Survey of Seepage Through Heightened Earthfill Dam with

High-Density Electrical Prospecting Method. 2.11

Bujang B.K. Huat

(Malaysia)

An Investigation of an Embankment Failure in Soft Clay. 2.14

A. K. Gupta D. S. Tolia (India) Major Landslides in Sikkim-Analysis, Correction and

Protective Measures: A Case Study. 2.15

Dipak Mukherjee Satish Kumar

(India)

Use of Geofabrics for Controlling Landslides-

Case Histories. 2.17

Isao Nagayama Michio Ota Yosuke Niitaka Masahiko Yamashita

A Study on Prediction of Improvement of Watertightness

of Rock Mass by Grouting. 2.18

Michael Long John Godden

(Ireland)

(Japan)

The Performance of Turlough Hill Upper Reservoir. 2.20

A.N. Hussein (Malaysia) A. McGown (UK) The Behavior of Two Trial Embankments at Perlis, Malaysia

with Different Rates of Construction. 2.22


vii

K. N. Gunalan Thomas S. Lee Si Sakhai (USA)	Stage 1 Geotechnical Studies for Interstate 15 Reconstruction Project, Salt Lake County, Utah. 2.24
Brent H. Carter Richard A. Link (USA)	Safety of Dams Modifications of Ochoco Dam Crooked River Project, Oregon. 2.25
Mary P. Perlea Kathleen E. Lust Robert L. Pearce Charles W. Detrick (USA)	Repair of Scour Holes and Levees after the 1993 Flood. 2.26
Richard L. Bateman Francke C. Walberg (USA)	Pile Design Procedure for Stabilizing Channel Slopes. 2.28
W. H. Gu R. F. Dawson N. R. Morgenstern P. K. Robertson (Canada)	A Case History of Liquefaction Flow Failures in Mountainous Mine Waste Dumps. 2.29
Dwikorita Karnawati (Indonesia)	Natural Slope Failure on Weathered Andesitic Breccia in Samigaluh Area, Indonesia. 2.34
Zbigniew Mlynarek Wojciech Tschuschke Jedrzej Wierzbicki (Poland)	Procedure for In-Situ Evaluation of Geotechnical Parameters of High Dams. 2.37
D. V. Singh Jai Bhagwan (India)	Case Study on Landslide Investigations in Himalayas. 2.38
Kishor Kumar R. K. Panigrahi (India)	Instrumentation, Monitoring and Analysis of A Landslide-A Case Study. 2.40
Russell L. Owens (USA)	Seismic Evaluation, Soil-Cement Mix Wall and Outlet Pipe Installation, Ivins Bench Dam, Utah. 2.43

Groundwater Conditions and Drainage of a Large Slide. 2.44

E. Sotiropoulos

P. Papanikolaou (Greece) B. Dendrou (USA)



viii

Anton Chirica Rolland Mlenajek Andrei Olteanu Cristian Banciu (Romania)

Study of Ground Movement in a Mining Area. 2.50L

Shri Pal (India) Arresting the Moving Slopes of Andamans-A Case Study. 2.51L

W. Ken Beck (USA)

The Tale of Two Slides. 2.52L

Kenneth M. Berry Thomas L. Cooling (USA) Landslides on Shale in Southern Illinois, 2.53

Khaldoun Fahoum Philip A. Jozwiak (USA) Remediation of River Des Peres Slope Failure-A Case History. 2.56

Sanjeev Kumar (USA)

Stabilization of an Existing Slope Supporting Underground Storage Tanks at the Top. 2.58

Session III "Case Histories of Geotechnical Earthquake Engineering"

Vassilios K. Magginas (USA)

Case History on the Foundation and Site Liquefaction Potential

Evaluation for the Renovation of a One-Hundred Year Old Building. 3.01

Gerald Kasman Marshall Lew Paul Elliott (USA)

Investigation of Ground Cracking at the Van Gogh Street School,


Granada Hills, California. 3.05

Carlos M. Sevilla Joseph M. Gilroy John Jenkins (USA) Results of Dynamic Testing on Friction H-Piles. 3.06

Tomoya Iwashita Akira Nakamura Shinji Yokoyama Norihisa Matsumoto Hitoshi Yoshida (Japan)

Factor Analysis of Damage to Small Earth Dams Due to the

1995 Hyogoken-Nambu Earthquake. 3.07



ix

Shyamal Mukerjee Bhagwat Lavania (India) Soil Liquefaction in Nepal-Bihar Earthquake of August 21, 1988. 3.08

Katsumi Ozeki Ikuo Katayama (Japan) On the Behavior of Longitudinal Strain of a Buried Pipe Subjected to Ground Spread Caused by Liquefaction Observed in Centrifuge Model Tests. 3.11

Jagadish R. Joshi Richard C. Lee (USA) Ground Motion Measurements from the Demolition of Steel Towers. 3.15

Narendra Kumar V.K. Talwar R. K. Pal (India) Sinkholes in Earth Dam Kota Barrage (India). 3.16

Masayuki Sato Hiroyuki Watanabe Satoshi Katayama (Japan)

Study on Mechanism of Caisson Type Sea Wall Movement During Earthquake. 3.18

Takahiro Sakata Kenji Matsui Yoshito Maeda Hidetoshi Ochiai (Japan) Lateral Loading Tests in the Pit for A Large-Diameter Deep Pile. 3.19

Ray Knox David Stewart (USA) Morphoseismic Features in the New Madrid Seismic Zone (Central USA) and their Implications for Geotechnical Engineering. 3.22

A. Elgamal R. Dobry Z. Yang (USA) E. Parra (Venezuela) Soil Dilation and Shear Deformations During Liquefaction. 3.24

Session IV "Case Histories of Engineering Vibrations"

Shamsher Prakash

Y. Tseng (USA)

Predictions of Vertically Vibrating Foundation Response with Modified

Radiation Damping. 4.02

Herke G. Stuit

(The Netherlands)

Test Track Low Frequency Vibrations Reducing Measure Near

Vibration Mitigation for Brewery Stockhouse Demolition. 4.04

Oosthuizen, 4.03

William J. Prosser George Manyando Thomas J. Mottin

Gary M. Andruska

(USA)

Case Histories and Vibratory Characteristics of

Vibro-Driven Piles. 4.05

Hideo Tsuboi Tamotsu Matsui (Japan)

Yang Xianjian Jiang Bei (China) Radiation Damping of Soil -Foundations Systems. 4.06

Kiyoshi Hayakawa Yukihiko Kani Noriyuki Matsubara Tamotsu Matsui

(Japan)

Richard Woods

(USA)

Ground Vibrations Isolation by PC Wall-Piles. 4.07

Shamsher Prakash D.Nampoothiri

(USA)

On Prediction of Dynamic Response of Horizontal Vibrations. 4.09

Session V "Case Histories of Retaining Structures and Deep Excavations"

M. S. Wang (China)

X. Wu

M. C. Wang

(USA)

Failure of Excavation Bracing System for New World Plaza

at Changchun in China. 5.01

Linbang Wang

(USA)

An Anchored Band Bracing System for Deep Excavations in Clay, 5.02

Х

хi

Wanchai Teparaksa Narong Thasnanipan Aung Win Maung Wei Shixin (Thailand)

Prediction and Performance of Short Embedded Cast In-Situ Diaphragm Wall for Deep Excavation in Bangkok Subsoil. 5.04

Young-Nam Lee Seung-Won Lee (Korea) Excavation Behaviour of Soft Marine Clay Deposit in

South Korea. 5.06

Carole L.B. Mitchell Monique A. Nykamp (USA)

Shoring Analysis, Design and Construction at the Seattle Symphony's Benaroya Hall. 5.08

Cai Yuanqiang Wu Shiming Chen Yunmin Xu Changjie (China) Behavior of Double-Row Pile Retaining Structure for Deep Excavation in Soft Clay. 5.09

Kevin W. McLain (USA)

Soil Nailing: The MoDot Experience. 5.10

Xu Changjie Cai Yuanqiang Wu Shiming (China)

Behavior of Braced Deep Excavation in Soft Soils. 5.11

Jean-Claude Blivet Jean-Pierre Gourc (France) Large Retaining Structure Reinforced by Geosynthetics

French Case Histories. 5.12

Thomas S. Lee Steven H. Brandon (USA) Geotechnical and Geologic Features of U.S. 189 in Provo Canyon, Utah. 5.13

Theodore A.
Thomson,Jr.
Alan J. Lutenegger
(USA)

Passive Earth Pressure Tests on an Integral Bridge Abutment. 5.15

Minh Phong Luong (France)

Abnormal Wall Movements of a Steel Silo Caused by Paddy Rice Storage. 5.17

Wolfgang H. Roth Alexander Delnik (USA) Numerical Modeling of a Crib-Wall Failure. 5.18

J. K. Jain A. K. Saxena Sanjay Kumar Shrivastava (India) Pier Failure of Bridge and Geotechnical Investigation -

A Case Study. 5.19L

xii

Session VI "Case Histories of Geological, Rock and Mining Engineering including Underground Structures and Excavations"

Nina N. Fotieva Nikolay Bulychev Case Histories of Designing Tunnel Linings in Seismic Regions. 6.01

(Russia)

B. Huang Design, Construction and Monitoring for the Excavation of L. Mohammad Shanghai World Plaza. 6.04

L. Mohammad (USA)

Jianming Zhu
Xiaoping Zhu
(China)

David L. Mathews Erosion and Repair of Unlined Spillway Chute Excavated in Rock. 6.05

Vlad G. Perlea
Francke Walberg
Douglas R. Anderson
(USA)

Massoud Palassi Tunnex: An Expert System for Tunneling Through Rock. 6.06

John A. Franklin (Canada)

Experiences of the Support Designs in the Two Large Underground Openings in

J. L. Jethwa India. 6.07

A. K. Dube (India)

R. K. Goel

J. C. Chern Tunneling in Squeezing Ground. 6.08

C. W. Yu H. C. Kao (Taiwan)

(USA)

(Greece)

Siamac Vaghar Comparison of Two Excavation Support Systems in Clay;
Dan J. Bobrow Central Artery/Tunnel, Boston, Massachusetts, USA. 6.09

Edmund Medley Christopher Delp (USA)

Of Sewers, Sinkholes, and Safes: The Investigation of the Sea Cliff Incident, December 11, 1995, San Francisco, California. 6.10

Michael Kavvadas

Analysis and Performance of the Natm Excavation of an Underground Station for the Athens Metro. 6.11

Borut Petkovsek Lojze Bevc (Slovenia) Remedial Works in the Ljubelj Tunnel. 6.12

Paul M. Santi

Stability and Permeability of Fluid Retention Berms Constructed

(USA) from Highly Weathered Bedrock. 6.16N

xiii

S. Kwon

Investigation of the Influence of the Clay Seams Around an Underground Excavation

J. W. Wilson

in Rock Salt. 6.17

(USA)

Hong Li

A Computer Aided Rock Mass Classification for Rock Slopes. 6.18N

Gang Li (China)

Session VII

"Case Histories of Soil Improvement, Grouting, Geosynthetics, Dynamic Compaction, Vibroflotation, Blasting and other Methods including Geo Economics"

I. I. Broid

Use of Jet Grouting Method for Elimination of Suffusional Destructions

G. V. Melnik

of Sand Backfilling of Sheet Pile Wharf. 7.01

(Russia)

Suji Somasundaram

Ground Improvement at the Queensway Bay Downtown Harbor,

Gamini Weeratunga

Long Beach, California. 7.03

Kris Khilnani (USA)

G. Varosio (Italy)

A Non Destructive Testing Program for a Group of Jet

Grouting Columns. 7.04

Joy J. Lee

Selection and Design of Foundations for the I-15/US 95 Interchange,

John M. Tehaney

(USA)

Stage II Improvements - A Case Study. 7.05

Kaushik Mukherjee

(India)

Performance Prediction and Uses of PV Band Drains under the

Embankments on Soft Marine Clays of Bangkok. 7.06

A. Benslimane

Seismic Retrofitting Using Micropile Systems Centrifugal Model

Studies. 7.07

I. Juran

S. Hanna

S. Drabkin

(USA)

S. Perlo

R. Frank

(France)

Lime Slurry Injection, Lime Piles and Stone Columns for

A. K. Gupta Satish Kumar

Improvement of Soft Soils- Field Trials. 7.10

D. S. Tolia

(India)

John Conway

Grouting Evaluation Program of the Best Methods for Use of Microfine


(Puerto Rico)

and Portland Cements During Treatment of the Rock Foundation

Tom Novak

at the Portugues Dam. 7.11

(USA)



xiv

Kejing Chen Robert Lo (Australia) Huishan Liu

Treatment of Soft Soils by Dynamic Compaction. 7.12

Xiaohong Bai

(China)

Jungang Jia Qiuxue Yang (China)

A Case History of Ground Treatment for a Power Station

in China. 7.13

Steven J. Winter Victor Omelchenko

(USA)

Red Onion Mountain Maximum Security Prison- A Case Study

in Ground Improvement. 7.14

Eun C.Shin

Bang-Woong Shin

(Korea)

Construction of Inchon International Airport. 7.17

Roberto A. Lopez Mathew J. Francis

Kyle M. Rollins Scott W. Davis Zoran Batchko (USA)

Composite Ground Modification System: Vibroreplacement and Dynamic Compaction, Salt Lake County Detention Center,

Utah. 7.18

Alan J. Lutenegger Gerald A. Miller (USA)

Tension Tests On Drilled Micropiles In A Stiff Clay. 7.20

A. K. Gupta Jai Bhagwan B. C. Joshi (India)

Observations on Landslide Incidences in Himalayas

in Kashmir Area, 7.21

A.K. Gupta O.P. Yadav Jai Bhagwan (India)

Field Experiments on Jute Soil Stabilisers. 7.23

Carlos S. Oteo Jose M. Delgado German Burbano Luis M. Sopena (Spain)


Soil and Site Improvements of the Marsh Soils in Puerto De Santa

Maria Highway (Cadiz, Spain). 7.24

Kyle Rollins Kenneth Murphy Shaun Dustin Jerry Bishop (USA)

Soil-Nailed and Tie-Back Wall Construction Using Hollow

Nails. 7.25



Guidelines for Sealing Geotechnical Exploratory Holes. 7.27

XV

Cameran Mirza

(Canada)

Robert K. Barrett

(USA)

Shri Pal (India)

Protection of Kamorta Island From Coastal Erosion -

A Case Study. 7.34L

Ion Stanculescu

Florian Braniste Ion Borsaru (Romania)

Investigation of Landslides Affecting a Romanian Railway. 7.35N

Mike Alizadeh Sanjeev Kumar

(USA)

Soil Improvement in Flood Plain of the Mississippi River Using Pre-Load Fill. 7.37

Session VIII "Case Histories of Forensic Engineering "Where Things Went Wrong"

An Investigation into the Causes of Building Cracks on the

V. S. Hope

C.R. I. Clayton

M. C. Matthews

(UK)

J. Richard Cheeks

(USA)

It's Not What You Pay; It's What It Costs You

Rear Scarp of a Major Landslip. 8.01

A Geotechnical Engineering Case Study. 8.02

Walter W. Hays

(USA)

Case Histories of Damaging Earthquakes. 8.04

Matthew A. Dettman

(USA)

Sinkhole Dropouts Due to Underground Utility Installation

on Construction Sites. 8.06

Wayne A. Ericson

Ted J. Smith (USA)

Is It A Sinkhole? 8.08

Session IX "Case Histories of New Solutions to Traditional Geotechnical Problems"

Case Histories for Settlement Analysis in Ground Improved

Takaharu Shogaki

by Vertical Drain. 9.01

Hayato Moro Minoru Matsuo

(Japan)

Steel Industry-Wastes as New Materials for Road

Sudhir Mathur Praveen Kumar

Construction. 9.03

A.V.S. R. Murty

(India)

xvi

Ph Gotteland G. Bossonney D. Coulon (France) An Ecotechnical Alternative: An Embankment of Incinerated

Municipal Solid Waste. 9.04

Wei Xinjiang Xia Tangdai (China)

Research on Crack Depth Measurement in Concrete by Using Rayleigh Waves. 9.05

Thomas Blackburn Tom M. Farrell (USA) Shopping Center Saved by Short Aggregate Piers. 9.06

John M. Benson Donald R. Snethen (USA) Experimental Approach Embankments at Salt Fork River Bridges on US 177 and Their Initial Performance. 9.07

Anthony L. DiPiero Richard D. Lewis Robert Ross S. R. Honeycutt (USA) Identification of Potential Seepage Locations Along the Herbert Hoover Dike, Lake Okeechobee FL.,by Electromagnetic Geophysical Method; Prediction and Confirmation. 9.08

T. C. Kim S. Q. Ahmad T. J. Kazmierowski

(Canada)

A Case Study of the Application of Lightweight Fill for the

Restoration of an Interchange Ramp. 9.10

Carsten H. Floess H.Moo-Young, Jr Thomas F. Zimmie Warren A. Harris, IV (USA) A Municipal Landfill Cover with a Paper Sludge Barrier

Layer. 9.13

Lenka S. Timiovska (Macedonia)

Geotechnical Risk and Reliability from Theory to Practice. 9.15

D. G. Anderson C. C. Sundberg R. J. Robertson (USA) Failure of a Pipeline in an 800-Year Old Debris Fill. 9.16L

Anton Chirica Mircea Galer (Romania) Stability Analysis Corresponding to a New Bridge Abutments. 9.17L

xvii

Session X

"Case Histories of Geotechnical and Hydrological Management and Remediation of Solid, Hazardous and Low-Level Radioactive Wastes, including Liner Cover Systems"

Y. Sheng

Capping of an Extremely Soft Neutralised Uranium Tailings

P. Peter

- A Case History in Environmental Geomechanics. 10.01

Y. Wei

A. R. Milnes

(Australia)

Romeo Ciubotariu

Marie Wilson

(Canada)

C. E. Schneeberger (Switzerland)

William J. Hague

(USA)

The Environmental Remediation of Clark Island -A Former

Allied Signal, Inc. Site. 10.02

Ronald C. Chaney

Kenneth Demars Gregory N. Richardson

(USA)

Design of Contaminated Dredged Fills Utilizing Geosynthetics. 10.04

Niu Zhirong Zhou Changyong

(China)

Case Histories of Two Kinds of Composite Foundation -Constructing Buildings Over-Crossing Canals. 10.05

Wayne R. Bergstrom

Patrick Dugan

(USA)

Test Fill to Determine the Compression Behavior of a Closed

Industrial Waste Landfill, 10.07

D. L. Shah

A. V. Shroff

(India)

Effect of Effluents of Industrial Waste on Soil Properties

(A Case Study of Nandesari Area, Vadodara). 10.08

F. Colleselli

M. Macoratti

(Italy)

A Particular Foundation Problem on a Waste Fill. 10.09

L.M. Pissarra

N. Guedes

J. Garrido

M. L. Lopes

C. C. Freitas

(Portugal)

Victor A. Modeer

Alcanena Industrial Waste Landfill - Description of a

Portuguese Case History. 10.10

Mary C. Lamie

(USA)

Regulatory, Environmental and Geotechnical Solutions to Construction


of a Roadway Embankment over a Landfill. 10.11

Sanjeev Kumar

(USA)

Procedure to Predict Settlement of Solid Waste Landfills Using Power Creep Law.

10.12



xviii

Session XI "Case Histories of Non-Destructive Evaluation of Drilled Shafts, Auger Cast Piles and Driven Piles"

Raymond J. Castelli

Pile Foundation Construction for the Buckman Bridge

Mohamad Hussein

Jacksonville, Florida. 11.01

(USA)

Narong Thasnanipan Aung Win Maung

Sonic Integrity Test on Piles Founded in Bangkok Subsoil

Ganeshan Baskaran

Signal Characteristics and their Interpretations. 11.02

(Thailand)

Session XII SPECIAL SESSION "GEOTECHNICAL ENGINEERING PRACTICE IN THE 21st CENTURY"

Walter W. Hays

Toward Earthquake Resilient Cities in the 21st Century:

(USA)

Reduction of Community Vulnerability. 12.01

xix

GENERAL REPORTS

A. J. Lutenegger Carole L.B.Mitchell (USA)

Case Histories of Foundations. Paper No. GR-1

Vlad Perlea Mary P. Perlea (USA) B.B.K. Huat

Case Histories of Slopes, Dams and Embankments.

Paper No. GR-II

Ahmed-W Elgamal Marshall Lew

(USA)

(Malaysia)

Case Histories of Geotechnical Earthquake Engineering.

Paper No. GR-III

George Manyando Sanjeev Kumar (USA) Case Histories of Engineering Vibrations. Paper No. GR-IV

R. V. Siddharthan (USA)

Arni E. Rafnsson (Iceland)

Case Histories of Retaining Structures and Deep Excavations.

Paper No. GR-V

C. G. Mueller Baoshan Huang (USA)

(USA) M. Kavvadas (Greece) Case Histories of Geological, Rock and Mining Engineers Including Underground Structures and Excavations.

Paper No. GR-VI

Steven J. Winter

(USA)

Case Histories of Soil Improvement, Grouting, Geosynthetics, Dynamic Compaction, Vibroflotation, Blasting and other Methods

Including Geo Economics. Paper No. GR-VII

R.W. Stephenson (USA)

Case Histories of Forensic Engineering "Where Things Went Wrong".

Paper No. GR-VIII

Vijay K. Puri Tom Blackburn John M. Benson (USA) Case Histories of New Solutions to Traditional Geotechnical Problems.

Paper No. GR-IX

Carsten H. Floess Mary C. Lamie W.R. Bergstrom (USA) Case Histories of Geotechnical and Hydrological Management and Remediation of Solid, Hazardous and Low-Level Radioactive Wastes, including Liner Cover Systems. Paper No. GR-X