

Kulturbau and Mall

case study
By Ziwen Wang

Location: Koblenz, Germany



Architect: Benthem Crowel Architects

Owner: N/A

Year of completion: 2013

Climate: Temperate seasonal climate

Material of interest: Concrete

Application: Exterior

Properties of material:

The volume has an double façade with a Structural-Glazing construction of white silk-screened glass, which embraces the building like a second skin.

Sources:

ArchDaily: http://www.archdaily.com/350774/kulturbau-and-mall-benthem-crowel-architekten?ad_medium=widget&ad_name=category-museums-and-exhibit-article-show

