

Modern Art Museum of Fort Worth

case study
By Yuhui Xiong

Location: Fort Worth, Texas, United States



Architect: Tadao Ando

Owner: N/A

Year of completion: 2002

Climate: Humid subtropical climate (Cfa)

Material of interest: Concrete

Application: Exterior/Interior

Properties of material: The use of concrete indicates Ando's passion in planes and sharp, clean edges that the material allows.

Sources:

<https://www.archdaily.com/213084/flashback-modern-art-museum-of-fort-worth-tadao-ando>