Recent Research in Science and Technology 2014, 6(1): 48-50 ISSN: 2076-5061 Available Online: http://recent-science.com/



Analysis of water quality using physico-chemical parameters in Charcha colliery, Korea district, Chhattisgarh, India

Pratima Rani Dwivedi¹, M. R. Augur² and Anita Agrawal³

- ¹ Research Scholar, Deptt. Of Chemistry, Dr. C.V. Raman University, Bilaspur, C.G.
- ²Asstt.Prof., Deptt. Of Chemistry, Govt. Agrasen College, Bilha, Bilaspur, C.G.
- ³ H.OD.Department pf Chemistry, RITEE, Raipur, C.G.

Abstract

This study was aimed to estimate current status of physico-chemical characteristic of Charcha colliery, at Korea District, Chhattisgarh. Monthly variation in physico-chemical parameters such as water temperature, pH, turbidity, total dissolved solids, total hardness, chlorides, phosphate, nitrates, dissolved oxygen and biological oxygen demand were analyzed for a April-may month 2012. The results indicated that physico-chemical parameters of the water were within the permissible limits and can be used for domestic, irrigation and pisciculture.

Keywords: Charcha colliery, Physico-chemical parameters, Monthly variation, DO

INTRODUCTION

Water plays an essential role in human life. Although statistics, the WHO reports that approximately 36% of urbanand 65% of rural Indian were without access to safe drinking water Fresh water is one of the most importantresources crucial for the survival of all the living beings. It is even more important for the human being as theydepend upon it for food production, industrial and waste disposal, as well as cultural requirement. Human andecological use of ground water depends upon ambient water quality.

Fresh water has become a scarce commodity due to over exploitation and pollution ofwater. Increasing population and its necessities have lead to the deterioration of surfaceand sub-surface water. Groundwater is the major source of drinking water in both urbanand rural areas. The importance of groundwater for the existence of human society cannotbe overemphasized. Besides, it is an important source of water for the agricultural andindustrial sector. Till recently it had been considered a dependable source ofuncontaminated water. Groundwater crisis is not the result of natural factors. It has beencaused by human actions. Much of ill health which affects humanity, especially in the developing countries can be traced to lack of safe and whole some water supply. The quality of ground water is the resultant of all the processes and reactions that act on thewater from the moment it condensed in the atmosphere to the time it is discharged by a wellor spring and varies from place to place and with the depth of the water. Groundwater is particularly important as it accounts for about 88% safe drinking water in ruralareas, where population is widely dispersed and the infrastructure needed for treatment andtransportation of surface water does not exist. Standard desirable limit of water quality

parameters in drinking water prescribed bydifferent agencies is shown in Table 2. In Charcha colliery, coal mine and urbanizationhave major impact on groundwater environment. In areas of Charcha, there are open and underground coal mine. The effluents from these greatly distress the geochemistry of the soil. The discharged chemicals interact with ground water and alter the pH and otherwater quality parameters. Hence the areas of Charcha colliery were selected to studythe effect of sanitary conditions on ground water quality. The social relevance of theproblem has encouraged us in carrying out this work.

EXPERIMENTAL Study area

The physicochemical parameters of ground water of 5 stations in Charcha Colliery were studied. The groundwater was collected from the sources (bore wells) the months of April to may 2012. The sampling locations, source and corresponding habitats are shown in Table 2.

Preparation of water samples

The samples were collected in clean polythene bottles without any air bubbles. The bottleswere rinsed before sampling and tightly sealed after collection and labeled in the field. The temperatures of the samples were measured in the field itself at the time of samplecollection.

Table 2.Sampling locations and corresponding habitats

- 1. Churcha Basti Drinking Water
- 2. Churcha Colony Drinking Water (Before Treatment)
- 3. Churcha Colony Drinking Water (After Treatment
- 4. Shivapur Village Drinking Water
- 5. Churcha Colony Inside Bore Well Water (Hand Pump)

Research Scholar, Deptt. Of Chemistry, Dr. C.V. Raman University, Bilaspur, C.G.

Email: dpratima69@yahoo.com

^{*}Corresponding Author Pratima Rani Dwivedi



Fig 1. Map of Korea district in Chhattisgarh And Chhattisgarh in India.

Analysis of water sample

Analysis was carried out for various water quality parameters such as pH, total dissolvedsolids, total hardness, total alkalinity, calcium, chloride and chemical oxygen demand(COD) as per standard procedures.

Determination of water quality parameters

The water quality parameters analyzed were; pH- measured using standard pH meter, totaldissolved solids (TDS) by standardmethods, calcium content by EDTA titrimetricmethod, chloride content by argentometric method, total hardness (TH) by EDTA, alkalinity by titrimetric method, and metals by spectrophotometric method.

Results and Discussion

Table 2.

BDL – Below Detection Limit All Parameters are in mg/l unless specified

	IOW Detection Limit	7111 010	annotoro aro in mi	g/i uriless specified				
S.N.	Parameter	Sampling Stations					IS:10500	Below
		1	2	3	4	5	Desirable Limit	Detection Limit
1	Colour	Colourless	Colourless	Colourless	Colourless	Colourless		
2	Odour	Unobjection able	Unobjectio nable	Unobjectio nable	Unobjection able	Unobjection able	Unobjection able	
3	Taste	Agreeable	-	Agreeable	Agreeable	Agreeable	Agreeable	
4	рН	7.69	8.34	7.42	7.56	7.75	6.5-8.5	<0.01
5	Alkalinity	112	56	44	164	176	200	<0.5
6	Total Hardness	196	104	84	284	292	300	<0.5
7	Iron	BDL	BDL	BDL	BDL	BDL	0.3	< 0.05
8	Chlorides	32	14	18	74	88	250	< 0.25
9	Dissolved Solids	338	198	148	Nil	Nil	500	<5.0
10	Calcium	46.4	24.0	19.2	484	492	75	< 0.02
11	Manganese	BDL	BDL	BDL	BDL	BDL	0.1	< 0.05
12	Sulphate	90	21	48	BDL	BDL	200	<1.0
13	Nitrate	-	-	=	58	79	45	<0.01
14	Fluoride	0.53	0.42	0.32	-	-	1.0	<0.01
15	Selenium	BDL	BDL	BDL	0.38	0.42	0.01	<0.01
16	Arsenic	BDL	BDL	BDL	BDL	BDL	0.05	<0.01
17	Lead	BDL	BDL	BDL	BDL	BDL	0.05	< 0.05
18	Zinc	0.1	0.1	0.09	BDL	BDL	5	< 0.005

The results of the physicochemical analysis of the groundwater samples S1 to S5, collected from 5 places in Charcha Colliery are presented in Table 2.

Temperature

The temperature was found to be in the range between 26.3 to 27.2°C during study. Thehigher value of water temperature observed in the present study could be attributed to theearly summer months prevailed during the period of investigation.

pН

pH is considered as an important ecological factor and provides an important piece of information in many types of geochemical equilibrium or solubilitycalculation. pH is an important

parameter in water body since most of the aquaticorganisms are adapted to an average pH and do not withstand abrupt changes. The pH values fluctuated between 7.42 to 8.34(Table 2). The limit of pH value fordrinking water is specified as 6.5 to 8.5. The pH shows slightly alkaline trend. GenerallypH of water is influenced by geology of catchments area and buffering capacity of water.

Total alkalinity

The standard desirable limit of alkalinity in water is 220 mg/L. The maximumpermissible level is 600 mg/L. The mean value of alkalinity in the ground water of Charcha area was 110.4 mg/L (Table 2) which is within the desirable limit in all stations .The value of alkalinity in water provides an idea of natural salts present in water. These factors are characteristics of the source of water and natural processes taking place at any given time.

50 Dwivedi et al.,

Chloride

Chlorides are important in detecting the contamination of ground water by waste water. The permissible limit of chloride in drinking water is 250mg/L. The values of chlorideobserved in S1, S2, S3,S4 and S5 were very low *i.e.* within the permissible limit. The presence of chloride in slightly higher amounts may be due tonatural processes such as the passage of water through natural salt formations in the earth orit may be an indication of pollution from industrial or domestic use.

Total hardness (TH)

ISI has specified the total hardness to be within 300 mg/L of $CaCO_3$. Regarding totalhardness fluctuating trends in its value were observed in all the 5 stations. The observedtotal hardness values were well within the limits. S5 has comparatively high TH value (292 mg/L) than others.

Total dissolved solids (TDS)

The average value of TDS in the ground waters of Charcha was 338 mg/L. ISIprescribed the desirable limit of TDS is 500 mg/L. The maximum permissible level is 2000mg/L. TDS values observed in S1, S2, S3,S4and S5 were within the desirable limit. TDS in ground watermay be due to ground water pollution when waste waters from both residential and dyeing unitsare discharged into pits, ponds and lagoons enabling the waste migrate down to the water table.

Calcium

Calcium concentrations were found to vary from 19.2 to 492 mg/L. The upper limit of calciumconcentration for drinking water is specified as 75 mg/L (ISI, 1983). The calcium hardnessobserved in all the S1, S2 and S3 stations are well within the desirable limits with a minimum of 19.2/L in S3 to a maximum of 46.4 mg/L in S1 whereas S4 and S5 shows very high concentration of Calcium.

Manganese

Mn concentration were found to below detection limit . The Mn concentration observed in all the sample are well within the permissible limit.

Sulphate

Sulphate concentration were found vary from 21 mg/l to 90 mg/l And the concentration were found within the desirable limits.

Nitrate

Nitrate concentration were found vary from 21 mg/l to 90 mg/l and the concentration were found within the desirable limits.

Fluoride

Fluoride concentration were found vary from 58 mg/l to

90mg/I And the concentration were found slightly higher from the desirable limits.

Selenium

Selenium concentration were found vary from 0.38 mg/l to 0.42 mg/land which is slightly higher than permissible limit.

Arsenic

Selenium concentration were found below the detection limit which indicate the water purity and samples are within limit.

Lead

Selenium concentration were found below the detection limit which indicate the water purity and samples are also within limit.

Zinc

Selenium concentration were found vary from 0.09 mg/l to 0.1 mg/l which indicate the water purity and samples are within limit

CONCLUSION

The analysis of the water quality parameters of groundwater from five different stations in Charcha Colliery in Korea district shows that the pH TDS, alkalinity chloride ion, totalhardness, calcium, all other values are well within the permissible limits. In conclusion fromthe results of the present study it may be said that the groundwater of Charcha Collieryisthough fit for domestic and drinking purpose need no treatments to minimize as no contamination found. There isan increasing awareness among the people to maintain the groundwater at their highest qualityand purity levels and the present study may prove to be useful in achieving the same.

REFERENCES

- [1]Jain CK, Bhatia KKS and Vijay T, 1995. Ground water quality monitoring andevaluation in and around Kakinada, Andhra Pradesh, Technical Report,CS (AR) 172,National Institute of Hydrology, Roorkee, 1994-1995.
- [2]Kumar A, 2004. Water Pollution. Nisha Enterprises New Delhi. pp 1-331.
- [3]APHA, 1989.Standard methods for the examination of water and waste water, AmericanPublic Health Association, Washington.
- [4]ISI, 1983. Indian Standard specification for drinking water, IS10500, ISI, New Delhi.
- [5]W.H.O, 1984. Guidelines for drinking water quality, Vol.1, Recommendations WHO.Geneva.
- [6] Sharma M R, 2004. J Pollut Res., 23(1), 131-134.
- [7] Renn C E, 1970. Investigating water problems, Educational Products Division, LaMotte Chemical Products Company, Maryland.
- [8] Rani, D F G, Geetha S and Ebanazar, 2003. J Pollut Res., 22(1), 111-115.