

2-21-2008

Structures in the Municipality of Andover, 2008

Maine Department of Transportation

Follow this and additional works at: https://digitalmaine.com/mdot_docs

Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Andover, 2008" (2008).
Transportation Documents. 2465.
https://digitalmaine.com/mdot_docs/2465

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact statedocs@maine.gov.

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	7 Good
BRIDGE NO.:	5081	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	7 Good
LOCATION:	1.4 MI N'LY RUMFORD	YEAR BUILT	1930	DECK CONDITION	7 Good
BRIDGE NAME	GORDON BRIDGE	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	4 Poor
OWNER:	1 State DOT	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	7 Good
FEATURE ON:	ROUTE 5	STRUCTURE LENGTH IN FEET	33	DATE OF INSPECTION:	1/12/2006
FEATURE UNDER	GARDINER STR			FEDERAL SUFFICIENCY RATING	97.6
ROAD INV NO:	000000005X	POSTING STATUS:	1 Open		
ROUTE NO:	00005	POSTING TYPE:	0 None needed		
ROAD WIDTH	34 FEET				
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	7 Good
BRIDGE NO.:	5080	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	7 Good
LOCATION:	1.8 MI SO 120	YEAR BUILT	1929	DECK CONDITION	8 Very Good
BRIDGE NAME	HALL	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	6 Satisfactory
OWNER:	1 State DOT	SPAN TYPE:	3 Slab	CULVERT CONDITION:	N Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	8 Very Good
FEATURE ON:	#5	STRUCTURE LENGTH IN FEET	21	DATE OF INSPECTION:	7/13/2005
FEATURE UNDER	LONE BROOK			FEDERAL SUFFICIENCY RATING	97.8
ROAD INV NO:	000000005X	POSTING STATUS:	1 Open		
ROUTE NO:	00005	POSTING TYPE:	0 None needed		
ROAD WIDTH	34				
	FEET				
CLASS:	MINOR SPAN ON STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	N		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	5 Fair
BRIDGE NO.:	3996	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	5 Fair
LOCATION:	0.3 MI N OF JCT RTE 5	YEAR BUILT	1949	DECK CONDITION	5 Fair
BRIDGE NAME	BRICKETT	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	9 Excellent
OWNER:	1 State DOT	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	7 Good
FEATURE ON:	N MAIN ST	STRUCTURE LENGTH IN FEET	92	DATE OF INSPECTION:	1/11/2006
FEATURE UNDER	WEST BR ELLIS R			FEDERAL SUFFICIENCY RATING	61
ROAD INV NO:	0001700305	POSTING STATUS:	1 Open		
ROUTE NO:	00000	POSTING TYPE:	0 None needed		
ROAD WIDTH	22 FEET				
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	4 Poor
BRIDGE NO.:	3971	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	6 Satisfactory
LOCATION:	2.2 MI W JCT 5&120	YEAR BUILT	1951	DECK CONDITION	6 Satisfactory
BRIDGE NAME	STONEY BROOK	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	3 Serious
OWNER:	1 State DOT	SPAN TYPE:	3 Slab	CULVERT CONDITION:	N Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	4 Poor
FEATURE ON:	EAST HILL ROAD	STRUCTURE LENGTH IN FEET	29	DATE OF INSPECTION:	9/19/2006
FEATURE UNDER	STONEY BR			FEDERAL SUFFICIENCY RATING	48.6
ROAD INV NO:	0001700306	POSTING STATUS:	1 Open		
ROUTE NO:	00000	POSTING TYPE:	0 None needed		
ROAD WIDTH	22 FEET				
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

			CONDITION RATINGS			
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	7	Good
BRIDGE NO.:	3337	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	6	Satisfactory
LOCATION:	1 MI W TL	YEAR BUILT	1936	DECK CONDITION	6	Satisfactory
BRIDGE NAME	BLACK BROOK RTE 120	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	4	Poor
OWNER:	1 State DOT	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N	Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	8	Very Good
FEATURE ON:	RTE 120	STRUCTURE LENGTH IN FEET	28	DATE OF INSPECTION:	1/11/2006	
FEATURE UNDER	BLACK BROOK			FEDERAL SUFFICIENCY RATING	80.8	
ROAD INV NO:	000000120X	POSTING STATUS:	1 Open			
ROUTE NO:	00120	POSTING TYPE:	0 None needed			
ROAD WIDTH	29					FEET
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y			

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	6 Satisfactory
BRIDGE NO.:	3336	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	7 Good
LOCATION:	0.5 MI W'LY OF ROXBUR	YEAR BUILT	1936	DECK CONDITION	5 Fair
BRIDGE NAME	ANDOVER FALLS	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	6 Satisfactory
OWNER:	1 State DOT	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	5 Fair
FEATURE ON:	RTE 120	STRUCTURE LENGTH IN FEET	55	DATE OF INSPECTION:	1/11/2006
FEATURE UNDER	ELLIS RIVER			FEDERAL SUFFICIENCY RATING	54.2
ROAD INV NO:	000000120X	POSTING STATUS:	1 Open		
ROUTE NO:	00120	POSTING TYPE:	0 None needed		
ROAD WIDTH	22 FEET				
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS		
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	6	Satisfactory
BRIDGE NO.:	3215	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	5	Fair
LOCATION:	0.3 MI E'LY JCT ROUTE 5	YEAR BUILT	1935	DECK CONDITION	5	Fair
BRIDGE NAME	MERRILL	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	7	Good
OWNER:	1 State DOT	SPAN TYPE:	5 Truss	CULVERT CONDITION:	N	Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	5	Fair
FEATURE ON:	ROUTE 120	STRUCTURE LENGTH IN FEET	94	DATE OF INSPECTION:	10/20/2005	
FEATURE UNDER	WEST BRANCH ELLIS RV			FEDERAL SUFFICIENCY RATING	36.3	
ROAD INV NO:	000000120X	POSTING STATUS:	1 Open			
ROUTE NO:	00120	POSTING TYPE:	0 None needed			
ROAD WIDTH	20					FEET
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y			

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	5 Fair
BRIDGE NO.:	2249	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	6 Satisfactory
LOCATION:	1.5 MI S JCT 120	YEAR BUILT	1933	DECK CONDITION	7 Good
BRIDGE NAME	EAST ANDOVER	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	4 Poor
OWNER:	1 State DOT	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	5 Fair
FEATURE ON:	E ANDOVER RD	STRUCTURE LENGTH IN FEET	51	DATE OF INSPECTION:	10/20/2005
FEATURE UNDER	ELLIS R			FEDERAL SUFFICIENCY RATING	59.3
ROAD INV NO:	0001700347	POSTING STATUS:	1 Open		
ROUTE NO:	00000	POSTING TYPE:	0 None needed		
ROAD WIDTH	18 FEET				
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	<input type="text" value="Andover"/>	TOWN2	<input type="text" value="No town 2"/>	SUBSTRUCTURE CONDITION	<input type="text" value="4"/> <input type="text" value="Poor"/>
BRIDGE NO.:	<input type="text" value="1001"/>	MAINT REGION	<input type="text" value="Western"/>	SUPERSTRUCTURE CONDITION	<input type="text" value="7"/> <input type="text" value="Good"/>
LOCATION:	<input type="text" value=".2 MI E JCT 5"/>	YEAR BUILT	<input type="text" value="1868"/>	DECK CONDITION	<input type="text" value="6"/> <input type="text" value="Satisfactory"/>
BRIDGE NAME	<input type="text" value="LOVEJOY"/>	SPAN MATERIAL	<input type="text" value="3 Wood"/>	CHANNEL CONDITION:	<input type="text" value="5"/> <input type="text" value="Fair"/>
OWNER:	<input type="text" value="1 State DOT"/>	SPAN TYPE:	<input type="text" value="5 Truss"/>	CULVERT CONDITION:	<input type="text" value="N"/> <input type="text" value="Not Applicable"/>
MAINTAINER	<input type="text" value="1 State DOT"/>	NUMBER OF MAIN SPANS	<input type="text" value="1"/>	APPROACH CONDITION:	<input type="text" value="5"/> <input type="text" value="Fair"/>
FEATURE ON:	<input type="text" value="COVERED BRIDGE ROA"/>	STRUCTURE LENGTH IN FEET	<input type="text" value="75"/>	DATE OF INSPECTION:	<input type="text" value="8/16/2005"/>
FEATURE UNDER	<input type="text" value="ELLIS RIVER"/>			FEDERAL SUFFICIENCY RATING	<input type="text" value="27.9"/>
ROAD INV NO:	<input type="text" value="0001700343"/>	POSTING STATUS:	<input type="text" value="3 Posted"/>		
ROUTE NO:	<input type="text" value="00000"/>	POSTING TYPE:	<input type="text" value="5 Weight & Underclearance"/>		
ROAD WIDTH	<input type="text" value="16"/> FEET	FEDERAL BRIDGE INDICATOR:	<input type="text" value="Y"/>		
CLASS:	<input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>				

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	5 Fair
BRIDGE NO.:	0785	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	5 Fair
LOCATION:	0.2 MI FROM IMV ROAD	YEAR BUILT	1957	DECK CONDITION	6 Satisfactory
BRIDGE NAME		SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	6 Satisfactory
OWNER:	4 Municipal	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	4 Municipal	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	_
FEATURE ON:	STONE FARM RD	STRUCTURE LENGTH IN FEET	42	DATE OF INSPECTION:	7/23/1986
FEATURE UNDER	SANTIAGO BROOK			FEDERAL SUFFICIENCY RATING	33.5
ROAD INV NO:	-1	POSTING STATUS:	1 Open		
ROUTE NO:	00000	POSTING TYPE:	0 None needed		
ROAD WIDTH	14 FEET				
CLASS:	LOW USE/REDUNDANT BRIDGE	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	4 Poor
BRIDGE NO.:	0757	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	4 Poor
LOCATION:	200FT N UPTON(E-HILL?)	YEAR BUILT	1950	DECK CONDITION	4 Poor
BRIDGE NAME	CROCKER BR	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	8 Very Good
OWNER:	4 Municipal	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	4 Municipal	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	5 Fair
FEATURE ON:	CROSS ROAD	STRUCTURE LENGTH IN FEET	59	DATE OF INSPECTION:	10/3/2005
FEATURE UNDER	W BRANCH ELLIS RIVER			FEDERAL SUFFICIENCY RATING	41.7
ROAD INV NO:	0001701092	POSTING STATUS:	3 Posted		
ROUTE NO:	00000	POSTING TYPE:	1 Weight Limit		
ROAD WIDTH	16 FEET				
CLASS:	LOW USE/REDUNDANT BRIDGE	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	N Not Applicable
BRIDGE NO.:	0756	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	N Not Applicable
LOCATION:	0.5 MI NE B HILL RD	YEAR BUILT	1987	DECK CONDITION	N Not Applicable
BRIDGE NAME	AKERS	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	5 Fair
OWNER:	1 State DOT	SPAN TYPE:	4 Culvert	CULVERT CONDITION:	6 Satisfactory
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	2	APPROACH CONDITION:	6 Satisfactory
FEATURE ON:	CROSS ROAD	STRUCTURE LENGTH IN FEET	30	DATE OF INSPECTION:	10/20/2005
FEATURE UNDER	ABBOTT BROOK			FEDERAL SUFFICIENCY RATING	99
ROAD INV NO:	0001701092	POSTING STATUS:	1 Open		
ROUTE NO:	00000	POSTING TYPE:	0 None needed		
ROAD WIDTH	0 FEET				
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	8 Very Good
BRIDGE NO.:	0649	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	8 Very Good
LOCATION:	1.1 MI N AKERS RD	YEAR BUILT	2003	DECK CONDITION	8 Very Good
BRIDGE NAME	LEARNED	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	7 Good
OWNER:	4 Municipal	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	4 Municipal	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	5 Fair
FEATURE ON:	SAWYER RD	STRUCTURE LENGTH IN FEET	38	DATE OF INSPECTION:	10/3/2005
FEATURE UNDER	SAWYER BROOK			FEDERAL SUFFICIENCY RATING	77.2
ROAD INV NO:	0001700305	POSTING STATUS:	1 Open		
ROUTE NO:	00000	POSTING TYPE:	0 None needed		
ROAD WIDTH	14 FEET				
CLASS:	LOW USE/REDUNDANT BRIDGE	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	9 Excellent
BRIDGE NO.:	0641	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	9 Excellent
LOCATION:	2.5 MI N ROUTE 120	YEAR BUILT	2005	DECK CONDITION	9 Excellent
BRIDGE NAME	BLACK BROOK BRIDGE	SPAN MATERIAL	2 Concrete	CHANNEL CONDITION:	8 Very Good
OWNER:	1 State DOT	SPAN TYPE:	3 Slab	CULVERT CONDITION:	N Not Applicable
MAINTAINER	1 State DOT	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	7 Good
FEATURE ON:	SOUTH ARM ROAD	STRUCTURE LENGTH IN FEET	50	DATE OF INSPECTION:	9/19/2006
FEATURE UNDER	BLACK BROOK			FEDERAL SUFFICIENCY RATING	78.9
ROAD INV NO:	0001701889	POSTING STATUS:	1 Open		
ROUTE NO:	00000	POSTING TYPE:	0 None needed		
ROAD WIDTH	21				
	FEET				
CLASS:	BRIDGE ON TOWN WAY OR STATE AID ROAD	FEDERAL BRIDGE INDICATOR:	Y		

Structures in the Municipality of Andover

				CONDITION RATINGS	
TOWN1:	Andover	TOWN2	No town 2	SUBSTRUCTURE CONDITION	6 Satisfactory
BRIDGE NO.:	0638	MAINT REGION	Western	SUPERSTRUCTURE CONDITION	5 Fair
LOCATION:	0.1 MI NW AKERS RD	YEAR BUILT	1983	DECK CONDITION	5 Fair
BRIDGE NAME	AKERS RD BRIDGE	SPAN MATERIAL	1 Steel	CHANNEL CONDITION:	6 Satisfactory
OWNER:	4 Municipal	SPAN TYPE:	1 Girder	CULVERT CONDITION:	N Not Applicable
MAINTAINER	4 Municipal	NUMBER OF MAIN SPANS	1	APPROACH CONDITION:	5 Fair
FEATURE ON:	WYMAN HILL RD	STRUCTURE LENGTH IN FEET	17	DATE OF INSPECTION:	10/3/2005
FEATURE UNDER	ABBOTT BROOK			FEDERAL SUFFICIENCY RATING	56.8
ROAD INV NO:	0001701102	POSTING STATUS:	3 Posted		
ROUTE NO:	00000	POSTING TYPE:	1 Weight Limit		
ROAD WIDTH	10 FEET				
CLASS:	MINOR SPAN ON TOWN WAY	FEDERAL BRIDGE INDICATOR:	N		