

2-21-2008

## Structures in the Municipality of Grand Lake Stream Plantation, 2008

Maine Department of Transportation

Follow this and additional works at: [https://digitalmaine.com/mdot\\_docs](https://digitalmaine.com/mdot_docs)

---

### Recommended Citation

Maine Department of Transportation, "Structures in the Municipality of Grand Lake Stream Plantation, 2008" (2008). *Transportation Documents*. 2649.  
[https://digitalmaine.com/mdot\\_docs/2649](https://digitalmaine.com/mdot_docs/2649)

This Text is brought to you for free and open access by the Transportation at Digital Maine. It has been accepted for inclusion in Transportation Documents by an authorized administrator of Digital Maine. For more information, please contact [statedocs@maine.gov](mailto:statedocs@maine.gov).

## Structures in the Municipality of Grand Lake Stream Plt

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Grand Lake Stream Plt"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>BRIDGE NO.:</b> <input type="text" value="3584"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>LOCATION:</b> <input type="text" value="6.8 MI W PASSAMAQUODDY T"/>	<b>YEAR BUILT:</b> <input type="text" value="2010"/>	<b>DECK CONDITION:</b> <input type="text" value="9"/> <input type="text" value="Excellent"/>
<b>BRDGNAME:</b> <input type="text" value="MILFORD STREET"/>	<b>SPAN MATERIAL:</b> <input type="text" value="7 Precast Concrete"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="1"/>	<b>APPROACH CONDITION:</b> <input type="text" value="4"/> <input type="text" value="Poor"/>
<b>FEATURE ON:</b> <input type="text" value="MILFORD ST"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="88"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="6/13/2011"/>
<b>FEATURE UNDER:</b> <input type="text" value="GRAND LAKE STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="77"/>
<b>ROAD INV NO:</b> <input type="text" value="0002900822"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="18"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON TOWN WAY OR STATE AID ROAD"/>		

## Structures in the Municipality of Grand Lake Stream Plt

### CONDITION RATINGS

<b>TOWN1:</b> <input type="text" value="Grand Lake Stream Plt"/>	<b>TOWN2:</b> <input type="text" value="No town 2"/>	<b>SUBSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>BRIDGE NO.:</b> <input type="text" value="2596"/>	<b>BRIDGE REGION:</b> <input type="text" value="Eastern"/>	<b>SUPERSTRUCTURE CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>LOCATION:</b> <input type="text" value="0.5 MI E TOWN LINE"/>	<b>YEAR BUILT:</b> <input type="text" value="1997"/>	<b>DECK CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>BRDGNAME:</b> <input type="text" value="MUSQUASH"/>	<b>SPAN MATERIAL:</b> <input type="text" value="1 Steel"/>	<b>CHANNEL CONDITION:</b> <input type="text" value="8"/> <input type="text" value="Very Good"/>
<b>OWNER:</b> <input type="text" value="1 State DOT"/>	<b>SPAN TYPE:</b> <input type="text" value="1 Girder"/>	<b>CULVERT CONDITION:</b> <input type="text" value="N"/> <input type="text" value="Not Applicable"/>
<b>MAINTAINER:</b> <input type="text" value="1 State DOT"/>	<b>NUMBER OF MAIN SPANS:</b> <input type="text" value="2"/>	<b>APPROACH CONDITION:</b> <input type="text" value="7"/> <input type="text" value="Good"/>
<b>FEATURE ON:</b> <input type="text" value="GRAND LAKE STREAM"/>	<b>STRUCTURE LENGTH IN FEET:</b> <input type="text" value="131"/>	<b>DATE OF INSPECTION:</b> <input type="text" value="2/6/2013"/>
<b>FEATURE UNDER:</b> <input type="text" value="MUSQUASH STREAM"/>	<b>POSTING STATUS:</b> <input type="text" value="1 Open"/>	<b>FEDERAL SUFFICIENCY RATING:</b> <input type="text" value="90.6"/>
<b>ROAD INV NO:</b> <input type="text" value="0002900822"/>	<b>POSTING TYPE:</b> <input type="text" value="0 None needed"/>	
<b>ROUTE NO:</b> <input type="text" value="00000"/>		
<b>ROAD WIDTH:</b> <input type="text" value="30"/> <b>FEET</b>	<b>FEDERAL BRIDGE INDICATOR:</b> <input type="text" value="Y"/>	
<b>CLASS:</b> <input type="text" value="BRIDGE ON STATE HIGHWAY"/>		